December 18, 2015

Ms. Kathryn DeCristofaro Capital Program Manager Massachusetts School Building Authority 40 Broad Street Boston, Massachusetts 02109

### Re: Peebles Elementary School

Preliminary Design Program Submission to the MSBA

Dear Kathryn:

Attached please find the Module 3 Preliminary Design Program (PDP) package submission to the MSBA. The team has followed the guidelines set forth in Module 3 to develop this submission.

As Owner's Project Manager, we certify that we have reviewed and coordinated the materials, the submittal is complete and confirm that the District has approved the materials for submission to MSBA.

We look forward to reviewing the information contained in this submission with you and your team to move toward the Preferred Schematic Study submission.

Please contact me at 617-520-9403 if you have any questions, comments, or would like to schedule a meeting.

Thank you.

Very truly yours,

### SMMA | Symmes Maini & McKee Associates

Joel G. Seeley, AIA Principal

cc: James Potter, SBC Chair (MF)

enclosures: Preliminary Design Program

JGS/sat /P:\2015\15041\05-TRANS\L\_Kathryndecristofaro@MSBA\_Pdpsubmission\_18December2015.Doc



Bourne, Massachusetts

SMMA No. 15041

PRELIMINARY DESIGN PROGRAM REPORT

### **Table of Contents**

### Volume I

### 1.3.1.1 Introduction

- A. Executive Summary
- B. Overview of Statement of Interest (SOI)
- C. Invitation to Conduct Feasibility Study/MSBA Board Action Letter
- D. Agreed upon Design Enrollment
- E. Capital Budget Statement
- F. Project Directory
- G. Updated Project Schedule

### 2.3.1.2 Educational Program

- A. Grade and School Configuration Policies
- B. Class Size Policies
- C. School Scheduling Method
- D. Teaching Methodology and Structure
- E. Teacher Planning and Room Assignment Policies
- F. Lunch Programs
- G. Technology Instruction Policies and Program Requirements
- H. Art Program
- I. Music/Performing Arts Program
- J. Physical Education
- K. Special Education
- L. Vocational Education
- M. Transportation Policies
- N. Functional and Spatial Relationships and Adjacencies
- O. Security and Visual Access Requirements
- P. Educational Visioning
- **3.**3.1.3 Initial Space Summary
  - A. Itemization of Program MSBA Templates
  - B. Variance between Program and MSBA Guidelines
  - C. Existing Floor Plans
- 4.3.1.4 Evaluation of Existing Conditions
  - A. Property Title
  - B. Statement that Property can be Developed
  - C. Historical Impacts on Property
  - D. Determination of Development Restrictions
  - E. Existing Conditions Reports
  - F. Code Evaluation
  - G. MAAB/ADA Evaluation
  - H. Proposed Soils Exploration
  - I. Traffic Impact Study
  - J. Phase I ESA
  - K. Hazardous Materials Assessments

<sup>\*</sup> The bolded numbers 1.1 through 1.6 indicate the tab number for each section located in the binder.

PRELIMINARY DESIGN PROGRAM REPORT

### **Table of Contents**

### Volume II

- 5.3.1.5 Site Development Requirements
  - A. Site Development Narrative
  - B. Zoning and Setbacks
  - C. Preliminary Site Survey and Wetlands
  - D. Emergency Vehicle Access
  - E. Safety and Security

### 6.3.1.6 Preliminary Alternatives

- A. Analysis of School District Student School Assignment Practices
- B. Tuition Agreements with Adjacent School Districts
- C. Rental or Acquisition of Existing Buildings
- D. Base Repair Option
- E. Renovation and Addition Options
- F. New Construction Options
- G. Conceptual Cost Estimates
- H. Evaluation of Design Alternatives
- 7.3.1.7 Local Actions and Approvals
  - A. Local Actions and Approval Letters
  - B. Building Committee Meeting Notes
  - C. Public Presentations

### 8. Appendix

- A. Copy of Statement of Interest
- B. Copy of MSBA Board Action Letter
- C. Copy of MSBA Enrollment Letter
- D. Cost Estimate Details

\* The bolded numbers 1.1 through 1.6 indicate the tab number for each section located in the binder.

### **13.1.1** Introduction

- A. Executive Summary
- B. Overview of Statement of Interest (SOI)
- C. Invitation to Conduct Feasibility Study/MSBA Board Action Letter
- D. Agreed Upon Design Enrollment
- E. Capital Budget Statement
- F. Project Directory
- G. Updated Project Schedule



### A. EXECUTIVE SUMMARY

On September 22, 2015, Flansburgh Architects was hired to prepare a Feasibility Study and Schematic Design for the Town of Bourne according to Modules 3 and 4 of the MSBA guidelines. The first part of work consisted of reviewing the Statement of Interest, preparing an existing conditions report, and developing a needed space program that would fit within the MSBA space guidelines.

The existing conditions report which is in section 3.1.4 of this report expands on and verifies most of the items mentioned in the SOI and concludes that although the Peebles Elementary School has been well maintained, most of it is over 62 years old and is in need of significant work. Although structurally sound, the systems and finishes have reached the end of their useful life. Some of the more significant issues are; lack of a fire sprinkler system, no insulation or cavity in the exterior walls, numerous handicap accessibility problems, several code issues, and asbestos in several locations that will need to be abated. The seven year old Bournedale Elementary School is in comparatively good condition with minor envelope water infiltration issues, acoustical concerns and storage issues.

While the existing conditions study was being prepared, a series of "visioning" sessions were held to establish some of the key goals of the educational program as well as the space needs for the school. This was then followed by a series of interviews with key staff, teachers, and students to understand specific space needs and adjacency requirements. From these interviews, the space programs were developed that are in section 3.1.3 of this report. Four different grade configurations were studied with options for new or renovation/addition for each configuration for a total of seven options. All seven options show that there is a lack of space required for proper 21st Century education. This additional needed space can be resolved either with a new addition and renovation or a new building.

Functional relationship diagrams were then developed showing how the building could be organized from information developed at both the visioning sessions and interviews.

The desire to keep a small school "feel" suggests breaking the school into "neighborhoods" in the larger sized options.

This Preliminary Design Program Report concludes with a summary of seven proposed alternatives plus a "Base Repair" option, which have been narrowed down to the following four options in Section 3.1.6 H of this report:

- 1. Grades K-4 250 Students
- 2. Grades PK-4 725 Students
- 3. Grades PK-5 885 Students
- 4. Grades K-5 410 Students

Further study of these four options and costs will occur in the Preferred Schematic Study (PSR) phase.

B. Overview of Statement of Interest (SOI)

### 3.1.1 Introduction

### B. OVERVIEW OF STATEMENT OF INTEREST (SOI)

The original Peebles Elementary School Statement of Interest emphasized five key issues:

- 1. The school is in very poor physical condition;
- 2. There is overcrowding due to lack of proper educational spaces;
- 3. The school is not fully accessible;
- 4. HVAC and electrical systems are outdated and at the end of their useful life;
- 5. Need to provide educational spaces that will provide a full range of programs for 21st Century Education.

The Peebles Elementary School was built in 1953 with an addition in 1959. All of the infrastructure components consist of original equipment that has reached the end of its useful life. This is causing issues of imminent failures, poor interior air quality, code compliance issues, and an educational delivery system that is in poor condition.

In addition, there are several handicap accessibility issues, cracking of the exterior brick work, settlement of floor slabs and many more building and site problems.

Space needs were identified as follows:

- Undersized classrooms;
- Small, under-equipped media center
- Lack of Music and Band spaces

The original Statement of Interest (SOI) is attached in the Appendix of this report.

C. Invitation to Conduct Feasibility Study / MSBA Board Action Letter

## Massachusetts School Building Authority

**Steven Grossman** *Chairman, State Treasurer* 

John K. McCarthy Executive Director

January 14, 2015

Mr. Thomas M. Guerino, Town Administrator Bourne Town Hall 24 Perry Avenue, Room 101 Buzzards Bay, MA 02532-3441

Re: Town of Bourne, James F. Peebles Elementary School

Dear Mr. Guerino:

I am pleased to report that the Board of the Massachusetts School Building Authority (the "MSBA") has voted to invite the Town of Bourne (the "Town") to collaborate with the MSBA in conducting a Feasibility Study for the James F. Peebles Elementary School. The Board's vote follows the Town's timely completion of all of the requirements of the MSBA's Eligibility Period.

I do want to emphasize that this invitation to collaborate on a Feasibility Study is *not* approval of a project, but is strictly an invitation to the Town to work with the MSBA to explore potential solutions to the problems that have been identified. Moving forward in the MSBA's process requires collaboration with the MSBA, and communities that "get ahead" of the MSBA without MSBA approval will not be eligible for grant funding. To qualify for any funding from the MSBA, local communities must follow the MSBA's statute, regulations, and policies which require MSBA collaboration and approval at each step of the process.

During the Feasibility Study phase, the Town and the MSBA will collaborate pursuant to the terms of the Feasibility Study Agreement to find the most fiscally responsible and educationally appropriate solution to the problems identified at the James F. Peebles Elementary School. The Feasibility Study, which will be conducted pursuant to the MSBA's regulations and policies, requires the Town to work with the MSBA on the procurement of an Owner's Project Manager and Designer, which will help bring the Town's Feasibility Study to fruition.

We will be contacting you soon to discuss these next steps in more detail. In the meantime, however, I wanted to share with you the Board's decision and provide a brief overview of what this means for the Town of Bourne.

Page 2 January 14, 2015 Bourne Board Action Letter

I look forward to continuing to work with you as part of the MSBA's grant program. As always, feel free to contact me or my staff at (617) 720-4466 should you have any questions.

Sincerely,

ohn K. McCarthy **Executive Director** 

Cc: Legislative Delegation Peter J. Meier, Chair, Bourne Board of Selectmen Christopher Hyldburg, Chair, Bourne School Committee Steven Lamarche, Superintendent, Bourne Public Schools Edward Donoghue, Director of Business Services, Bourne Public Schools File: 10.2 Letters (Region 6) D. Agreed-upon Design Enrollment

### MASSACHUSETTS SCHOOL BUILDING AUTHORITY

### TOWN OF BOURNE JAMES F. PEEBLES ELEMENTARY SCHOOL STUDY ENROLLMENT CERTIFICATION

As a result of a collaborative analysis with the Massachusetts School Building Authority (the "MSBA") of enrollment projections and space capacity needs for the proposed project at the James F. Peebles Elementary School, the Town of Bourne hereby acknowledges and agrees that the design of preliminary options which may be evaluated as part of the feasibility study for the proposed project at the James F. Peebles Elementary School shall be based in accordance with the following:

Enrollment for Grades K-5 at a District-wide elementary school	Enrollment for Grades K-4 at a District-wide elementary school	Enrollment for Grades K-4 at the James F. Peebles Elementary School
885 students	725 students	250 students

The space allowance for each alternative evaluated shall assume no more than the enrollments as detailed in the table above. The Town of Bourne acknowledges and agrees that it has no right or entitlement to any particular study enrollment, square feet per student space allowance, or total square footage referenced in the table above for the preliminary options, and further acknowledges and agrees that it shall not bring any or action, legal or equitable, against the MSBA, or any of its officers or employees, for the purpose of obtaining an increase in the study enrollment of the James F. Peebles Elementary School that it has acknowledged and agreed herein. The Town of Bourne further acknowledges and agrees that the study enrollment presented herein is only applicable to the evaluation of preliminary options conducted as part of the feasibility study for the proposed James F. Peebles Elementary School project. Upon receipt of the District's recommendation of a Preferred Schematic Design for the proposed James F. Peebles Elementary School project, and subject to the MSBA's review of such recommendation, the MSBA shall forward a Design Enrollment Certification with a design enrollment specific to the recommended and approved Preferred Schematic Design, which shall supersede this certification.

The undersigned, for themselves and the Town of Bourne, hereby certify that they have read and understand the contents of this Study Enrollment Certification and that each of the above statements is true, complete and accurate. The undersigned hereby certify that they have been duly authorized by the appropriate governmental body to execute this Certification on behalf of the Town of Bourne and to bind the Town of Bourne to its terms.

. Uh Chief Executive Officer

4 Date Superintendent of Schools 12.16.2014 Date

Duly Authorized Representative of School Committee

12-16-14

Date

### MASSACHUSETTS SCHOOL BUILDING AUTHORITY

### TOWN OF BOURNE JAMES F. PEEBLES ELEMENTARY SCHOOL STUDY ENROLLMENT CERTIFICATION

As a result of a collaborative analysis with the Massachusetts School Building Authority (the "MSBA") of enrollment projections and space capacity needs for the proposed project at the James F. Peebles Elementary School, the Town of Bourne hereby acknowledges and agrees that the design of preliminary options which may be evaluated as part of the feasibility study for the proposed project at the James F. Peebles Elementary School shall be based in accordance with the following:

Enrollment for Grades K-5 at a District-wide Elementary School	Enrollment for Grades K-4 at a District-wide Elementary School	Enrollment for Grades K-4 at the James F. Peebles Elementary School including District-wide Grade 5	Enrollment for Grades K-4 at the James F. Peebles Elementary School
885 students	725 students	410 students	250 students

The space allowance for each alternative evaluated shall assume no more than the enrollments as detailed in the table above. The Town of Bourne acknowledges and agrees that it has no right or entitlement to any particular study enrollment, square feet per student space allowance, or total square footage referenced in the table above for the preliminary options, and further acknowledges and agrees that it shall not bring any or action, legal or equitable, against the MSBA, or any of its officers or employees, for the purpose of obtaining an increase in the study enrollment of the James F. Peebles Elementary School that it has acknowledged and agreed herein. The Town of Bourne further acknowledges and agrees that the study enrollment presented herein is only applicable to the evaluation of preliminary options conducted as part of the feasibility study for the proposed James F. Peebles Elementary School project. Upon receipt of the District's recommendation of a Preferred Schematic Design for the proposed James F. Peebles Elementary School project, and subject to the MSBA's review of such recommendation, the MSBA shall forward a Design Enrollment Certification with a design enrollment specific to the recommended and approved Preferred Schematic Design, which shall supersede this certification.

The undersigned, for themselves and the Town of Bourne, hereby certify that they have read and understand the contents of this Study Enrollment Certification and that each of the above statements is true, complete and accurate. The undersigned hereby certify that they have been duly authorized by the appropriate governmental body to execute this Certification on behalf of the Town of Bourne and to bind the Town of Bourne to its terms.

lle Chief Executive Officer

11/18/2015

Date Superintendent of Schools

11.18.2015

Date

Duly Authorized Representative of School Committee

Nov 18, 2015

Date



E. Capital Budget Statement

### E. CAPITAL BUDGET STATEMENT

The preliminary estimated project cost ranges from approximately \$37.35 million to \$46.12 million depending on the final preferred alternative chosen. The local share of debt service is planned to be funded via debt exclusions supported by the tax levy of the Town.

The base reimbursement share for this project from MSBA is 43.84% of eligible costs. The following are the incentive points that are being considered: Renovation (dependent upon which alternative chosen), High Efficiency Green School Program, Best Practices for Routine and Capital Maintenance, and Use of CM-at-Risk. The remaining percentage would be locally funded as explained above.



#### TOWN OF BOURNE PEEBLES ELEMENTARY SCHOOL FEASIBILITY STUDY PROJECT DIRECTORY SMMA NO. 15041 Date: June 1, 2015

December 14, 2015

Updated:

PROJECT MANAGEMENT

**SMMA** 

Cell Number **Contact and Address School Building Committee** James L. Potter, SBC Chair 508-759-1630 onsetjp@juno.com Peter L. Meier, Chair of Boston of Selectmen 508-274-7184 pmeier@townofbourne.com Christopher Hyldburg, Chair of School Committee 508-254-1715 chrish@alpha-1.com Laura Scena, School Committee Member 508-759-3961 laurascena@yahoo.com Natasha Scarpato, Member-At-Large 774-269-5014 scarpato4@comcast.net Richard A. Lavoie, Member of Finance Committee 508-728-9094 Richl.Lavoie@gmail.com William Meier, Building Trade Expert 508-759-8237 dusty22752@aol.com Mary Jo Coggeshall, Member-At-Large 508-776-5404 mjcoggeshall@gmail.com 508-563-3616 Frederick H. Howe, Board of Health rickhowe9@gmail.com / howejr@aol.com 774-994-1434 Steven M. Lamarche, Superintendent of Schools, BPS slamarche@bourneps.org Edward S. Donoghue, Director of Business Services, BPS 781-424-0467 edonoghue@townofbourne.com Thomas M. Guerino, Town Administrator 508-509-1377 tguerino@townofbourne.com Jonathan Nelson, Director of Facilities 508-566-1349 jnelson@townofbourne.com 508-369-9818 Elizabeth A. Carpenito, Principal ecarpenito@bourneps.org

Kathy Anderson, Elementary/Special Education Secretary

kanderson@bourneps.org

508-317-3464

### **TOWN OF BOURNE** PEEBLES ELEMENTARY SCHOOL FEASIBILITY STUDY PROJECT DIRECTORY SMMA NO. 15041

PROJECT MANAGEMENT

**SMMA** 

June 1, 2015 Date: Updated: December 14, 2015

	Contact and Address	Cell Number
School Committee	Christopher Hyldburg, Chairperson <u>chyldburg@bourneps.org</u> Heather DiPaolo, Vice Chairperson	
	hdipaolo@bourneps.org	
	Anne-Marie Siroonian, Secretary asiroonian@bourneps.org	
	Judith Froman jfroman@bourneps.org	
	Mitch McClain mmcclain@bourneps.org	
	Laura Scena Iscena@bourneps.org	
	Matthew Stuck mstuck@bourneps.org	
Owner's Project Manager	Symmes Maini & McKee Associates, Inc. (SMMA) 1000 Massachusetts Avenue Cambridge, MA 02138	617-547-5400
	Joel G. Seeley, Project Manager jseeley@smma.com	x403
	Antone Dias, CS, Onsite Representative adias@smma.com	x660
	Sarah A. Traniello, Reports Manager straniello@smma.com	x240
Architect	Flansburgh Architects, Inc. 77 North Washington Street Boston, MA 02114-1910	617-367-3970 617-720-7873
	Kent Kovacs, AIA, LEED AP, Principal-In-Charge kkovacs@flansburgh.com	x270
	Jorge M. Cruz, AIA, LEED AP, Project Manager jcruz@flansburgh.com	x290
	Betsy Farrell Garcia, AIA, LEED AP BC+D, Project Architect bgarcia@flansburgh.com	x244
Site Survey/Civil Engineering/Traffic Engineering	Nitsch Engineering, Inc. 2 Center Plaza, Suite 430 Boston, MA 02108-1928	
Site Survey	Alexander D. Diotte, PLS Project Manager	617-338-0063 617-338-6472
Civil	Aaron A. Gallagher, PE, CFM, LEED AP BD+C Project Manager	
Traffic	Nijdeh Havan, PE, PTOE Traffic Engineering	
Landscape Architecture	Waterman Design Associates, Inc. 31 East Main Street Westborough, MA 01581	508-366-6552
	Michael Dowhan, Senior Landscape Architect mjd@vwassoc.com	508-366-6506

### TOWN OF BOURNE PEEBLES ELEMENTARY SCHOOL FEASIBILITY STUDY PROJECT DIRECTORY SMMA NO. 15041

**SMMA** 

SMMA NO. 15041 Date: June 1, 2015 Updated: December 14, 2015

	Contact and Address	Cell Number
Structural Engineering	Boston Building Consultants 241A Street, Suite 220 Boston, MA 02210 James Balmer, Principal Structural Engineer ibalmer@bbcboston.com	617-542-3933 617-426-8922
Fire Protection Engineering/ Plumbing Engineering/ HVAC Engineering/Electrical Engineering	Garcia Galuska & DeSousa 370 Faunce Corner Road North Dartmouth, MA 02747 Carlos G. DeSousa, P.E. Principal, Electrical Engineering carlos_desousa@g-g-d.com Christopher M. Garcia, P.E., CFPS Principal, Plumbing & Fire Protection Engineer chris_garcia@g-g-d.com Dominick B. Puniello, PE, CEM, LEED AP Principal, HVAC Engineer dom_puniello@g-g-d.com	508-998-5700 508-998-0883
Data/Communications/Technology/ Security Consultant	Edvance Technology 3 Summer Street Chelmsford, MA 01824 300 Brickstone Square, Suite 201 Andover, MA 01880 Scott Goodrich sgoodrich@edvancetech.com	978-256-9900 978-560-1711
Geotechnical and GeoEnvironmental Engineering	Geotechnical Services Inc. (GSI) 55 North Stark Highway Weare, NH 03281 Harry K. Wetherbee, P.E. President / Principal Engineer <u>hwetherbee@geotechserve.com</u> Glen Zoladz, P.E. Senior Geotechnical Engineer	603-529-7766
Hazardous Materials & Environmental Permitting	Fuss & O'Neill EnviroScience, LLC.         50 Redfield Street, Suite 100         Boston, MA 02122         Robert L. May, Jr., President         rmay@fando.com         Dustin A. Diedricksen, Project Manager/Scientist         ddiedricksen@fando.com	617-282-4675 800-286-2469
Cost Estimating	Project Management & Cost (PM&C) 59 South Street Hingham, MA 02043 Peter Bradley peterbradley@pmc-ma.com	781-740-8007 781-740-1012
Food Service Consultant/ Laboratory Consultant/ Furniture, Fixtures and Equipment Consultant	Tavares Design Associates         8 Winchester Place, Suite 301         Winchester, MA 01890         Manuel J. Tavares, Principal         mjt@tavaresdesign.com         Robert Fogarty, CAD Designer         rob@tavaresdesign.com	781-729-5541

### TOWN OF BOURNE PEEBLES ELEMENTARY SCHOOL FEASIBILITY STUDY PROJECT DIRECTORY SMMA NO. 15041

PROJECT MANAGEMENT


**SMMA** 

 SMMA NO.
 15041

 Date:
 June 1, 2015

 Updated:
 December 14, 2015

	Contact and Address	Cell Number
Acoustical Consultant	Acentech 33 Moulton Street Cambridge, MA 02138 Nicole Cuff ncuff@acentech.com	617-499-8000 617-499-8074
Educational Programming Consultant	New Vista Designs for Learning 32 Sheridan Street, Suite #2 Jamaica Plain, MA 02130 David Stephen, M.ED., Architect david@newvistadesign.net	617-477-4660 617-477-4660 617-733-0847
Construction Specifications Consultant	Lund Associates 51 Monument Street Wenham, MA 01984-1310 David Lund, CSI, CCS, AWI President david@lundassociates.com	978-468-5141
Sustainability Consultant	James Carr Architecture & Design 1385 Cambridge Street Cambridge, MA 02139 James Carr, AIA, LEED AP BD+C Architect & Owner jcarr@alum.mit.edu	617-595-6351
Code / Accessibility Consultant	R.W. Sullivan Engineering The Schrafft Center 529 Main Street, Suite 203 Boston, MA 02129 Kevin S. Hastings, P.E., LEED AP Principal / Sullivan Code Group Director	617-523-8227 617-523-8016
Theatrical Consultant	Theatre Projects Consultants         47 Water Street         South Norwalk, CT 06854         Millie Dixon         Principal, Connecticut office         mdixon@theatreprojects.com	203-299-0830 203-299-0835



### 3.1.1 Introduction

### G. UPDATED PROJECT SCHEDULES

The Project Schedule anticipates MSBA Board of Director's approval to proceed into Schematic Design at their May 25, 2016 meeting and MSBA Board of Director's approval of the Project Scope and Budget Agreement at their September 28, 2016 meeting. District-wide appropriation voting will take place during the period of October and November 2016. The Project Schedule is appended to the end of this section.

Jpdated: June 25, 2015 TOWN OF BOURNE, MASSACHUSETTS Levised: December 4, 2015 PEEBLES ELEMENTARY SCHOOL PROJECT SCHEDULE										
	Task Name	Duration	Start	Finish	2015 2016	2017	2018	2019	2020	2021
1	RETAIN OPM	58 days	3/18/2015	6/8/2015	<b>V</b>					
2	Submit OPM Proposals	0 days	3/18/2015	3/18/2015	♣ 3/18					
3	OPM Interview	2 days	4/8/2015	4/9/2015	I					
4	Negotiate OPM Contract	7 days	4/9/2015	4/17/2015	1					
5	Submit Documents to MSBA OPM Panel	0 days	4/29/2015	4/29/2015	♦ 4/29					
6	MSBA OPM Panel Meeting	0 days	6/8/2015	6/8/2015	6/8 🔵 MSBA OPM Panel Meeting					
7	RETAIN DESIGNER	86 days	5/27/2015	9/23/2015						
8	Draft Designer RFS and Submit to MSBA	11 days	5/27/2015	6/10/2015						
9	MSBA Approve Draft RFS	9 days	6/10/2015	6/22/2015						
10	Submit to Central Register	0 days	6/23/2015	6/23/2015	♦ 6/23					
11	Notice in Central Register	0 days	7/1/2015	7/1/2015	♦ 7/1					
12	Briefing Session	0 days	7/14/2015	7/14/2015	♦ 7/14					
13	Submit Designer Proposals	0 days	7/21/2015	7/21/2015	♦ 7/21					
14	MSBA DSP Proposal Review Meeting	0 days	9/1/2015	9/1/2015	9/1  MSBA DSP Proposal Review					
15	MSBA DSP Interview Meeting (if required)	0 days	9/15/2015	9/15/2015	9/15 🔴 MSBA DSP Interview Meeti	ng (if required)				
16	Negotiate Designer Contract	5 days	9/17/2015	9/23/2015	<u> </u>					
17	FEASIBILITY STUDY (FS)	178 days		5/25/2016						
18	Develop Preliminary Design Program (PDP)	65 days	9/15/2015	12/15/2015						
19	Community Presentations	37 days	10/26/2015	12/16/2015	10/20					
20 21	Community Forum 1: Visioning	0 days	10/26/2015 11/16/2015	10/26/2015 11/18/2015	10/26 🔶					
21	Community Forum 2: Existing Conditions Community Forum 3: Options	3 days 3 days	12/14/2015	11/18/2015	· · · · · · · · · · · · · · · · · · ·					
22 23		0 days	12/14/2015	12/18/2015	12/18 Gubmit PDP to MSB	A Staff				
23 24	Submit PDP to MSBA Staff	84 days	12/18/2015	4/15/2016		A Staff				
24 25	Develop Preferred Schematic Report (PSR) Community Presentations	44 days	2/1/2016	4/13/2016						
25 26	Community Presentations Community Forum 1	0 days	2/1/2016	2/1/2016	2/1					
20 27	Community Forum 2	0 days	3/1/2016	3/1/2016	3/1					
27 28	Community Forum 2 Community Forum 3	0 days	4/1/2016	4/1/2016	4/1					
20 29	Submit PSR to MSBA FAS	0 days	4/7/2016	4/7/2016	4/7  Submit PSR	to MSBA FAS				
30	MSBA Board Meeting	0 days	5/25/2016	5/25/2016	5/25 • MSBA Bo					
31	SCHEMATIC DESIGN (SD)	90 days	5/25/2016	9/28/2016		ard meeting				
32	Develop Schematic Design	47 days	5/25/2016	7/28/2016						
33	Submit Final Budget to MSBA	1 day	7/28/2016	7/28/2016						
34	Submit Schematic Design to MSBA	0 days	8/11/2016	8/11/2016	8/11 – Sub	mit Schematic Design	to MSBA			
35	MSBA Board Meeting	0 days	9/28/2016	9/28/2016		WSBA Board Meeting				
36	LOCAL VOTES	39 days	10/17/2016	12/8/2016	_					
37	Local Voting	22 days	10/17/2016	11/15/2016						
38	Debt Exclusion Votes	17 days	11/16/2016	12/8/2016		-				
39	DESIGN AND CONSTRUCTION (TBD)	929 days	12/8/2016	6/30/2020						
40	Design Documentation	211 days	12/8/2016	9/28/2017			I			
41	Bidding and Award	44 days	9/29/2017	11/29/2017						
42	Construction		11/29/2017	6/30/2020						
43	Option 1A	-	11/29/2017	12/2/2019					Option 1A	
44	Building		11/29/2017	6/28/2019						
45	Demo / Site Work		6/28/2019	12/2/2019						
16	Option 1G		11/29/2017	6/30/2020					V Op	tion 1G
47	Phased Renovation and Additions		11/29/2017	6/30/2020						
8	Option 2A	-	11/29/2017	2/28/2020					Option 2A	
9	Phased Renovation and Additions		11/29/2017	2/28/2020						
50	Option 3A	-	11/29/2017	4/30/2020					Option	3A
i1	Phased Renovation and Additions	-	11/29/2017	4/30/2020						<b>~</b> D
52	Option 3B		11/29/2017	4/30/2020					Option	38
3	Phased Renovation and Additions	-	11/29/2017	4/30/2020					Omtion 14	
i4	Option 4A		11/29/2017	12/2/2019					Option 4A	
55	Building		11/29/2017	6/28/2019						
56	Demo / Site Work		6/28/2019	12/2/2019					- <b>^</b>	tion 4P
57	Option 4B		11/29/2017	6/30/2020					Op	tion 4B
58	Phased Renovation and Additions	675 days	11/29/2017	6/30/2020						

### 3.1.2 Educational Program

- A. Grade and School Configuration Policies
- B. Class Size Policies
- C. School Scheduling Method
- D. Teaching Methodology and Structure
- E. Teacher Planning and Room Assignment Policies
- F. Lunch Programs
- G. Technology Instruction Policies and Program Requirements
- H. Art Program
- I. Music/Performing Arts Program
- J. Physical Education
- K. Special Education
- L. Vocational Education
- M. Transportation Policies
- N. Functional and Spatial Relationships and
  - Adjacencies
- O. Security and Visual Access Requirements
- P. Educational Visioning

A. Grade and School Configuration Policies

### 3.1.2 Educational Program

### A. GRADE AND SCHOOL CONFIGURATION POLICIES

Bourne is a small rural community that is uniquely known as the access point to and from Cape Cod, MA by crisscrossing the Cape Cod Canal via the Bourne or Sagamore bridges. The Bourne Public Schools (BPS) have over 2,000 students attending Pre-Kindergarten through grade 12. There are two collaborating elementary schools, Peebles Elementary (K-4) and Bournedale Elementary (PreK-4), offering community-based experiences for our youngest students. The Bourne Middle School (5-8) is based on a middle school pedagogy and the Bourne High School (9-12) is rich in tradition with emerging innovative experiences and programs for our oldest students who then enter higher education or the workforce.

Elementary students are assigned to a respective elementary school as determined by the location of the student's residence. Students in grade 1-4 who reside on the north or mainland side of the Cape Cod Canal attend Bournedale Elementary School and students in grade 1-4 who reside on the south or cape side of the Cape Cod Canal attend Peebles Elementary School. This includes members of the armed forces who reside at Joint Base Cape Cod. We have recently opened four sections of full-day kindergarten, 2 at each elementary school and for those selected through our lottery system the aforementioned delineation location is the same. All integrated pre-kindergarten students and half-day kindergarten students attend the Bournedale Elementary School.

All town students in grades 5-8 attend the Bourne Middle School as is the same for high school students in grades 9-12.

# BOURNE PUBLIC SCHOOLS DISTRICT IMPROVEMENT DIALON DISTRICT



### **Bourne Public Schools District Improvement Plan**

### I. Introduction

### Acknowledgements

The District Improvement Plan is a publication of the Bourne Public Schools under the following leadership:

### **School Committee**

Christopher Hyldburg, Chair
Heather DiPaolo, Vice-Chair
Anne-Marie Siroonian, Secretary
Matthew Stuck
Laura Scena
Mitch McClain
Judith Froman

### **District Leadership Team**

Steven M. Lamarche, Superintendent Susan Sleasman, Assistant Superintendent for Learning and Teaching Edward Donoghue, Director of Business Services Christina Stuart, Director of Special Education and Student Services

### **School Building Leadership Team**

Amy Cetner, Bourne High School Principal Jordan Geist, Bourne High School Assistant Principal Melissa Ryan, Bourne Middle School Principal David Lundell, Bourne Middle School Assistant Principal Elizabeth Carpenito, Bournedale Elementary School Principal Jane Norton, Peebles Elementary School Principal Leslie Sullivan, Student Services Director 7-12 Erin Halperin, Student Services Director 1-6 PES/BMS Allyson Sawicki-Davis, Student Services Director Early Childhood Ed. PreK – K BES/PES and 1-4 BES Lisa DiBiasio, Humanities Director 7-12 Christine Borning, STEAM Director 7-12

### **Table of Contents**

#### Introduction

Acknowledgments
Overview of the Strategic Planning Process
Goal and Purposes of the District Improvement Plan
District Core Values and Guiding Themes
Maintaining the District Improvement Plan
Conclusion

### **DIP Initiatives**

Curriculum Articulation and Improvement	8
Assessment	10
Science/ Technology Engineering Program Update	12
Math Professional Development	14
RTI Implementation	16
Teacher Induction Program	18
Partnerships	19
Resources	20
District Culture	22
School Building Program	23

### **School Council BHS**

Sam Baresford, Student Jack LaCasse, Student Emma Strode, Student Laurie McAnaugh, Parent Bill Dow, Teacher Belinda Rubinstein, Parent Jillian Donovan, Parent Sandra LaCasse, Parent

### School Council BMS

Susan Blunt, Community Member Mike Collela, Teacher Kate Conlon, Teacher Susan Cook, Parent Meg Correira, Parent Erika Fitzpatrick, Parent Lisa Irish, Parent Andrew Mather, Teacher Natasha Scarpato, Parent Sarah Tribuzio, Parent

### **School Council BES**

Maura Dankert, Parent Deni Garabedian, Community Member Carol Maley-Makrys, Teacher Abby Downing, Teacher

### **School Council PES**


Judy Ariagno, Parent Natasha Scarpato, Parent Sue Cook, Parent Ann Marie Ridings, Teacher Courtney Costa, Teacher

Acknowledgement also goes to the teachers and staff of the Bourne Public Schools who read drafts and offered comments and feedback, they helped plant the seed for a new systemic plan for continuous improvement.

### **Overview of the Strategic Planning Process**

A Strategic Plan (SP) is a document developed through broad-based participation that expresses an organization's foundational beliefs and, through goals, objectives, and action plans, provides a "blueprint" for long-term decision-making. Typically, a Strategic Plan embodies a statement of core values, a mission, and a vision. In education, core values are a set of fundamental beliefs of a district and its personnel about children and learning that serve as guiding principles for behavior and action. Core values offer a sense of what is right and wrong and often generate a level of outrage when violated. A mission statement is a statement of a district's primary purpose and reason for existing. Often just a sentence or two, it communicates a sense of direction for the entire district and is intended to remain relatively unchanged over time. The vision is a description of the intended future for a district and its school community if the plan is realized.

The District Improvement Plan (DIP) builds upon the foundational principles of the Strategic Plan and expresses goals, objectives, and strategies that, if accomplished, lead to the achievement of the vision. The DIP, in turn, inspires initiatives in individual School Improvement Plans (SIP.) The SIPs define the efforts made at the school level to achieve district-wide goals, though independent school-based goals are also included. The graphic below depicts the relationship among the SP, DIP, and SIPs.



### **Goal and Purpose of the District Improvement Plan**

The overall goal of the Strategic Plan, District Improvement Plan, and the individual School Improvement Plans is to build systemic and sustainable capacity to carry out data-supported planning going forward. Planning helps prioritize major initiatives and may impact farreaching areas including curriculum development, teaching and learning, assessment, organization, facilities improvement, and data management.

The Bourne Public School District can improve student learning and system effectiveness by engaging in a cycle of continuous improvement to manage its performance. To support this purpose, we have developed a multi-year District Improvement Plan that includes processes to support schools, students, and staff in their performance management efforts. The DIP has been designed to meet local, state, federal, and program accountability requirements.

Our District Improvement Plan must be evaluated and revised annually based on a number of components including but not limited to:

- Correlating Core Values
- Initiative Titles
- Goals
- Objectives
- Action Steps
- Resources
- Description of staff responsible for overseeing accomplishment of initiatives
- Outcomes or Products
- Timelines for implementation/completion of strategies

### **District Core Values and Guiding Themes**

The Core Values of the Bourne Public Schools that serve as the foundation for continued planning are offered below:

- All students can learn
- All decisions are made in the best interests of students
- All students learn best when actively involved in the learning process
- Learning will be more successful when school experiences have meaning for students

Guiding Themes that characterize the educational processes and culture in the Bourne Public Schools are articulated in the district Strategic Plan and include the following areas:

- Student Achievement
- Personal Growth
- School Climate
- Collaborations and Partnerships
- Resources

### **Maintaining the DIP**

In the spring of each school year, the DIP should be reviewed in its entirety and the plan updated for the new school year. This should precede the development of School Improvement Plans, produced by the individual school's School Council, that are closely linked to the updated DIP. Goals and objectives that have been accomplished may be eliminated from the future plan. Those goals that have not been completed should be carried over into the new plan. Any new goals that will be acted upon in the new school year will be supported minimally by articulated objectives, strategies, and person(s) responsible. This planning cycle, when successfully and routinely adopted, will maintain focus and stability over time.

### Conclusion

For purposes of clarity, this district improvement planning process starts as a series of separate initiatives intended to be congruent. While the initiatives generally should be sequentially intertwined, they will not necessarily always coincide but may overlap between the phases and steps to accomplish each. As such, identified persons responsible for implementation should not feel bound to strictly interpret action steps as sequentially listed. They should feel empowered to "tweak" the initiative to fit the specific as the work evolves.

Finally, all district and school staff should remember the purpose of the district improvement planning process: to focus and provide a plan of action that consistently reinforces student learning and achievement.

### **II. DIP Initiatives**

**Core Values:** All students can learn; all decisions are made in the best interest of students; all students learn best when actively involved in the learning process; and learning will be more successful when school experiences have meaning for students

Guiding Theme: Student Achievement

Initiative Title: Curriculum Articulation and Improvement

Type: Ongoing



Goal	Ensure curriculum alignment with the 2011 MA Curriculum Frameworks in applicable subject areas.
Objectives	Develop curriculum maps using ATLAS mapping software.
	Share model lessons through the collaborative use or ATLAS software.
	Provide clarity about learning objectives and targets, and promote increased student engagement.
Action Steps	Complete Stages 1 and 2 of all courses posted to Atlas
	Identify learning objectives and resources.
	Conduct annual review for adjustments.
	Promote the backwards design process through use of the Bourne Model of Instruction Lesson Planning templates.
Resources Needed	Common planning time
	Summer curriculum development time
	A clear structure for oversight of mapping contents and annual review
Person(s) Involved	All teachers and administrators Assistant Superintendent of Schools
Outcome(s) or Product(s)	Alignment of curriculum with the 2011 MA Curriculum /Frameworks
	A curriculum that is horizontally and vertically aligne with appropriate learning transitions from grade to grade and course to course
	Clarity about what students know, understand, are able to do, and can transfer
	An articulated process to reflect on and improve our curriculum each year
	Establishment of a teacher-driven sharing network through the effective use of ATLAS
Year(s) of Completion	Ongoing

**Core Values:** All students can learn; all decisions are made in the best interest of students; all students learn best when actively involved in the learning process; and learning will be more successful when school experiences have meaning for students

Guiding Theme: Personal Growth

Initiative Title: Assessment

**Type:** Ongoing

Goal	Establish components of the district's assessment system and procedures to ensure accurate measurement of student growth in specific areas in real time and longitudinally.
Objectives	Measure student growth in specific disciplines and grade levels periodically through time to inform curricular and instructional adjustments.
	Encourage real time measures of student growth that allow students to demonstrate and transfer understandings, knowledge, and skills.
Action Steps	Develop common assessments to be components of the mapping process in specific disciplines.
	Promote increased use of formative assessments to enable instructional adjustments and interventions as needed to meet the unique learning needs of individual students.
	Extract DDMs, as warranted, from the common assessments to support the educator evaluation process.
	Identify, acquire, or build a data repository and analysis application that can produce timely reports on student performance and also meet the requirements of the educator evaluation process.
	Establish a district-wide Data Team to help establish district-wide data collection and reporting priorities; oversee the processes for data input; and to provide a forum for discussion on all issues of data access and analysis.

Resources Needed	ATLAS software and professional development as needed to complete action steps
	Time commitment to develop common assessments where appropriate
	Data collection and analysis tool that integrates with the Student Information System
Person(s) Involved	All teachers and administrators Assistant Superintendent of Schools Data Team
Outcome(s) or Product(s)	A robust, appropriate, assessment program in place to measure student growth in specific disciplines across all grades
	Formative assessments developed and available for progress monitoring and real time measures of studen growth to inform instruction
	A Data Team consisting of teachers, administrators, and curriculum leaders to oversee and provide easy access to, and direction for, the district's data gathering and analysis
Year(s) of Completion	Ongoing



**Core Values:** All students can learn; all decisions are made in the best interest of students; all students learn best when actively involved in the learning process; and learning will be more successful when school experiences have meaning for students.

Guiding Theme: Student Achievement

Initiative Title: Science/ Technology Engineering Program Update

Goal	Embed scientific inquiry and engineering design skills to support project-based learning PreK-12.
Objectives	Develop a plan for roll-out of the PreK–12 Science Standards.
	Provide professional development support and resources to initiate implementation of the MA Draft/ Revised Science Standards in each grade level.
Action Steps	Coordinate efforts of the Major Resource Team (MRT) and the STEAM Director to develop an MA Draft/ Revised Science Standards implementation plan with a focus on introducing those science strands at various grade levels that are not currently taught.
	Reorganize the schedules necessary in elementary schools to accommodate additional time needed for full implementation of MA Draft/Revised Science Standards.
	Support participation in the state science fair.
	Assign a project-based teaching/learning coach (Innovation Studio Teacher) to establish school-based teams that support K–12 science instruction.
	Based upon grade level science/ tech engineering units to be taught, develop an inventory of required resources.
	Maintain science equipment inventory information on a database. Identify a person in each school to maintain inventory information and to oversee annual replenishment and ordering.

	In the elementary level, allocate professional development time for grade level teams to collaboratively develop new units of study.
Resources Needed	Equipment and resources for teaching the identified science/ technology units identified in the planning effort
Person(s) Involved	Assistant Superintendent STEAM Director MRT
Outcome(s) or Product(s)	Curriculum map for Science/ Technology Engineering reflecting the new MA Standards (based on MA Draft/ Revised Science Standards)
	Effective building level schedules that provide adequate time for implementation of science standards
	Participation in the state science fair
	An inventory and annual ordering system for science resources in each building
	Increased student engagement and fostering of curiosity
	Increased student participation in the Elementary Science Expo
	Increased participation in local, regional, and state science fairs
Year(s) of Completion	2015 - 2018

Guiding Theme: Student Achievement

Initiative Title: Math Professional Development

	Goal	Improve the capabilities of PreK-6 instructional staff to teach conceptual understanding in mathematics.
	Objectives	Prepare PreK-5 teachers to use the Eureka math curriculum as aligned with the MA Curriculum Frameworks in Mathematics.
	Action Steps	Ensure that elementary teachers are provided with Eureka math resources and are provided with a curriculum overview experience as soon as resources are available.
		Create a PreK-5 elementary math committee for developing a plan and action steps for effective implementation of Eureka math.
		Using the MA Curriculum Frameworks as a resource, develop a set of math Power Standards for each grade level that includes conceptual development skills to serve as the focus for professional development activities.
		Charge the Elementary Learning Coach with creation and implementation of a professional development model for PreK-5 teachers that focuses on conceptual development in math; PreK-5 learning coach models Eureka lessons.
		In grade five through eight, involve the STEAM and Humanities Director in identifying high priority, conceptual development skills

· · · · · · · · · · · · · · · · · · ·	Develop formative assessment strategies and test items for identified conceptual understanding of identified math Power Standards in grades 2-4
	Establish the position of PreK-4 Elementary Curriculum Director to coordinate with 7-12 Director and to oversee the implementation of the new math curriculum and adoption of the MA Curriculum Frameworks for Science and Technology/Engineering.
	Consider best options for grade 6 in terms of math materials and professional development
	Ensure ATLAS curriculum maps reflect Eureka curriculum in addressing MA State Frameworks
	Access to the MA Curriculum Frameworks in Mathematics
	Teaching resources as identified through the curricular planning and implementation of Eureka mathematics, acquired in grades PreK-5
Involved	PreK-5 Teachers Assistant Superintendent STEAM and Humanities Director Elementary Learning Coach PreK-4 Curriculum Director
	A list of Power Standards by grade that help direct instruction in mathematics
	A professional development plan/model for training elementary instructional staff at each grade level to successfully teach conceptual development skills aligned to the MA Frameworks in math
	Common unit-based formative assessments in each grade level that support conceptual development skills
Year(s) of Completion	2015 – 2017

**Guiding Theme:** Student Achievement

**Initiative Title:** RTI Implementation

Develop an effective RTI model at elementary and secondary grade levels across major subject areas
Build Tier One and Tier Two models of intervention in math and literacy in elementary grades, using AIMSWeb and PowerSchool for assessment and performance data maintenance.
Use formative assessments as a tool for grouping strategies. (e.g. evolve flexible grouping)
Continue to support Guided Reading as an approach to literacy instruction.
Continue to use Reading Street in grades 3-4 as an intervention strategy. Identify a program for intervention in grades PreK-2.

Action Steps	Conduct RTI awareness sessions for teachers in subject areas/grade levels that have not previously participated.
	Identify RTI training consultant(s) to help the schools define an appropriate RTI model for each level and develop or identify effective formative assessments at selected grade levels with initial focus on literacy and math skills; continue to develop understanding and use of formative assessment.
	Provide ongoing training in Guided Reading approach at the elementary level as needed.
	Enhance flexible grouping options to address student needs.
	Ensure schedules support tiered instruction.
Resources	RTI consultant
Needed	AIMSWeb or other assessment and a performance data analysis and repository tool
	Time to conduct training in RTI and classroom management for intervention strategies.
Person(s) Involved	Teachers Building Principals Assistant Superintendent
Outcome(s) or Product(s)	Teachers develop an understanding of the RTI model and processes and how it impacts their particular teaching assignment
	Teachers participating in training that will assist them in identifying formative assessment strategies and implementing Tier One and Tier Two strategies in their classroom environments
	Software identified or developed for formative assessment and performance data maintenance at the elementary levels
Year(s) of Completion	2015 – 2018

Guiding Theme: Student Achievement

**Initiative Title:** Teacher Induction and Mentoring Program

Goal	To improve readiness, focus, and ongoing support of newly hired teachers as they are brought into the Bourne Public Schools.
Objectives	Develop and implement an updated teacher induction/ mentoring program to include appropriate training for both mentor and mentee roles.
Action Steps	Develop an action plan to guide the work.
	Develop a 10-hour training for mentors and post on ATLAS.
	Develop and use mentor application and surveys for new teachers to better match mentors/mentees.
	Focus induction and mentee experiences on learning and teaching; post this curriculum on ATLAS.
	Develop specific plans for 50 additional hours of mentee training in second year.
Resources	Wong and Wong texts for beginning teachers
Needed	Funds to support Induction Program breakfasts and lunches

Person(s) Involved	Assistant Superintendent Teacher Mentor Coordinators
Outcome(s) or Product(s)	Improved mentor skills Retention of beginning teachers Fully compliant and effective Induction and Mentoring Program for both mentors and mentees
Year(s) of Completion	2016-2017



**Core Value:** All decisions are made in the best interest of students

**Guiding Theme:** Collaborations and Partnerships

**Initiative Title:** Partnerships

	1
Goal	Expand relationships and partnerships with local businesses and community resources.
Objectives	Increase involvement with WHOI, Mass Maritime, and Joint Base Cape Cod.
	Explore opportunities to interface with the community at large.
Action Steps	Assign the role of building and expanding partnerships to a specific person or persons including a PreK-4 Director.
	Conduct on-site meetings with contacts from WHOI, Mass Maritime, and Joint Base Cape Cod to identify opportunities for expanded partnerships.
	Connect with the Council on Aging to jointly explore the Bridges Together inter-generational program.
Resources Needed	Time provided to district representative to meet and explore expanded relationships
Person(s) Involved	Building Principals and Superintendent

Outcome(s) or Product(s)	Partnership endeavors revived and/or expanded with WHOI, Mass Maritime, and Joint Base Cape Cod Consideration given to starting a Bridges Together program in Bourne in collaboration with the Council on Aging
Year of Completion	2017



Initiative Title: Resources

Goal	Identify resources needed to meet the demands of established curricula, professional growth, and general operations in schools and district-wide
Objectives	Ensure that science curriculum resources are available to support the upcoming adoption of the MA State Frameworks for Science and Technology/Engineering. Inventory all resources for literacy and ELA district- wide, organize the inventory by grade level, and coordinate the use of literature and texts at all levels; elementary literacy (leveled and guided readers) closets organized appropriately. Review available social studies resources as aligned to the grade level curricula, providing additional resources as needed. Consider the adoption of a dropout prevention program. Devise a schedule that provides some common planning time among high school staff by department.
	Appropriately discard materials not being used or needed.

Action Steps	Identify, through examination of the curriculum, the required resources in K -12 science, social studies and ELA, capturing data on a spreadsheet application.
	Assign building level personnel to inventory currently available resources within science, social studies, and ELA. Match results with requirements to identify gaps.
	Prioritize curriculum resource needs and develop a multi-year plan for refreshment.
	Engage secondary ELA staff in defining the single grade level in which various books/novels are to be assigned.
	Acquire sufficient copies of titles and develop a schedule so that sharing does not impede instruction.
	Ensure that elementary literacy closets are well organized with leveled reading resources and that new acquisitions are accurately stored.
	Establish team consisting of instructional staff, guidance staff, administration and other resource personnel to research effective dropout prevention programs.
	Ensure that this team contacts other districts in which programs of interest are being implemented.
	Ensure that staff involved with high school scheduling attempt to build in a parameter that ensures some common planning time among teachers within a department who teach similar or related courses.

Resources Needed	Development of spreadsheets or databases that can import data on required curriculum resources, including quantities and ordering information Sufficient budget allocations for refreshing and acquiring needed instructional and curriculum resources on an annual basis Dropout intervention/prevention program acquisition and training
Person(s) Involved	Persons identified in each building that are willing to work on inventory and ordering within a given subject area or department Major Resource Team (MRT)
Outcome(s) Product(s)	<ul> <li>Required curriculum resources available in sufficient quantities for teaching staff</li> <li>Budgeting for curriculum resources accomplished based upon need rather than annual allocation</li> <li>Instructional resources organized in each building to accommodate sharing and to eliminate waste</li> <li>Guided reading adequately supported through schoolbased collections of leveled readers that are well organized and refreshed regularly</li> <li>A dropout program identified and implemented in an effort to reduce the dropout rate</li> <li>High school teachers and specialist staff within a discipline or across disciplines that have common courses or common students provided with some opportunity to meet during the school day</li> </ul>
Year of Completion	2017

### Guiding Theme: School Climate

### Initiative Title: District Culture

### Type: Future

Goal	Improve the culture in both in schools and at the district level.
Objectives	Identify sources of mistrust and dissatisfaction among staff where they exist.
	Reduce levels of personal mistrust and paranoia where they exist; reduce the "us vs. them" mentality.
Action Steps	Formulate a working definition of district culture; in particular, as culture impacts student learning.
	Form a working group with representatives of teachers, administrators, parents, other staff, and include the voices of students as appropriate.
	Consider the use of Doug Fisher's Five Pillars as a common resource that considers the relationships with and among students as a foundation for building a culture of respect and achievement.
	Revisit how to measure quality of culture in schools.
	Review recent attempts to evaluate the culture and reassess, as the working group feels necessary.
	Consider the use of a reputable consultant who specializes in dealing with district/school culture issues.
	Establish research-based protocols and structures for supporting professional collaboration in endeavors such as looking at student work, teaching practices, and assessment issues

Resources Needed	TBD
Person(s) Involved	Central and building-based administration Teaching staff
Outcome(s) or Product(s)	Improved school and district culture with diminished "us vs. them" mindset.
Year(s) of Completion	2016 – 2017



**Core Value:** All decisions are made in the best interest of students

### **Guiding Theme:** Resources

Initiative Title: School Building Program

### **Type:** Future

Goal	Build a new school to accommodate approximately 250 general education students.	
Objectives	Provide additional facilities to relieve over crowdedness in existing buildings and to expand educational opportunities through improved flexibility of space.	
Action Steps	Massachusetts School Building Authority Framework	
Resources Needed	TBD	
Person(s) Involved	Bourne School Building Committee, teachers, staff, School Committee, and the community	
Outcome(s) or Product(s)	A new vision for elementary education in the Bourne community.	
Year(s) of Completion	2020	



### **THE BOURNE SCHOOLS**

Bourne High School Principal, Amy Cetner acetner@bourneps.org

Bourne Middle School Principal, Melissa Ryan mryan@bourneps.org

Peebles Elementary School Principal, Jane Norton jnorton@bourneps.org

Bournedale Elementary School Principal, Elizabeth Carpenito ecarpenito@bourneps.org

### **SCHOOL COMMITTEE**

Christopher Hyldburg, Chair Heather DiPaolo, Vice Chair Anne-Marie Siroonian, Secretary Matthew Stuck Laura Scena Mitch McClain Judith Froman Audrey Kelleher, Student Representative Dawson Prophett, Student Representative

### **CONTACT**

Steven M. Lamarche, Superintendent 36 Sandwich Road Bourne, MA 02532

P. (508) 759-0660 F. (508) 759-1107

slamarche@bourneps.org www.bourneps.org

# BOURNE PUBLIC SCHOOLS STRATEGIC PLAN

HOME OF THE

### **ABOUT BOURNE SCHOOLS**

Bourne is a small rural community that is uniquely known as the access point to and from Cape Cod, MA by crisscrossing the Cape Cod Canal via the Bourne or Sagamore bridges. The Bourne Public Schools (BPS) have over 2,000 students attending Pre-Kindergarten through grade 12. There are two collaborating elementary schools, Peebles Elementary (K-4) and Bournedale Elementary (PreK-4), offering community-based experiences for our youngest students. The Bourne Middle School (5-8) is presented as a middle school philosophy and the Bourne High School (9-12) is rich in tradition with emerging innovative experiences and programs for our oldest students who then enter higher education or the workforce.

## **OUR MISSION**

The mission of the Bourne Public Schools is to connect individuals to their success; engage the community in new ways to facilitate student achievement; guarantee a relevant, viable curriculum; and assure universal accountability that supports the success of all students.

## **OUR VISION**

We are a committed community where one hundred percent of Bourne Public School students graduate with the knowledge, habits and skills to compete and collaborate effectively as society evolves. The Town of Bourne is enthusiastically committed to empower students and staff to achieve personal goals and demonstrate life-long learning.

## **OUR CORE VALUES**

- All students can learn
- All decisions are made in the best interest of students
- All students learn best when actively involved in the learning process
- Learning will be more successful when school experiences have meaning for students

## **GUIDING THEMES**

- Student Achievement: Our community schools will provide challenging, engaging academic experiences to advance the individual student's aptitude and ensure his/her preparedness for future successes
- Personal Growth: We believe our students will contribute to their community and the world around them through reflective academic, social and emotional practices that complement their growth, responsibility and respect for the learning and teaching process
- School Climate: The community is reflected in our schools through accepted norms of behavior, interpersonal and social interactions of respect and an appreciation for organizational processes and expectations
- Collaborations and Partnerships: Our students' success is heightened with the awareness and recognition of responsive and collaborative partnerships with parents/caregivers and the community at-large
- Resources: Our community will be responsible investors in the advancement of student achievement, personal growth, school climate and collaborations/partnerships

## SCHOOL COMMITTEE OBJECTIVES

- Increase opportunities that foster community engagement experiences for all students at all levels
- Support all students to demonstrate acquired knowledge, understandings, and skills reflected in PreK-12 curriculum maps in all disciplines
- Empower students to establish and practice reflective learning habits

## SUPERINTENDENT'S MESSAGE

The future for our students, parents/caregivers, staff and the community will bring its own mix of successes and challenges, but our direction is clear and we know what we must do. We must have the courage to focus intently on placing students at the heart of everything we do. We must provide the best teaching service and most comprehensive learning solutions available to all of our students. We must commit ourselves to evolve with the changing needs of our students by determining what we can control as an educational community. Through a collaborative, deliberate effort in strategic and improvement planning we control the objectives and goals. As we then review and analyze our outcomes through reflective practices we will model the resolve to identify calculated adjustments and make a difference for every student in the Bourne Public Schools. Our students' successes in turn are our successes

Steven M. Lamarche Superintendent of Schools







Brandeis University Materials Research Science and Engineering Center

> The Gateway Project Boston Museum of Science

Office of Ingenuity, and Newton Public Schools

Cape Cod Community College

Cape and Islands STEM Network

And many individual contributors interested in promoting and inspiring all Bourne students through hands-on project-based learning.

www.bourneps.org/iSTUDIO



36 Sandwich Road Bourne, MA 02532 www.bourneps.org

### WHAT IS THE INNOVATION STUDIO?

The Bourne Public Schools Innovation Studio is an educational environment that provides opportunities for students to engage in hands-on, interdisciplinary learning experiences. Students in all grades, kindergarten through high school, utilize the studio to explore and create across all subject areas. By designing solutions to problems linked to their courses of study, students develop, grow, acquire 21st century skills that are essential for today's high school graduates.

The Innovation Studio contains elements of computer science, textiles, crafts, electronics, robotics, art, music, science and woodworking. The Studio is designed to facilitate collaboration and provide opportunities for students to explore, create, analyze and problem-solve using a wide variety of resources. These resources spark student curiosity and creativity, allow students to connect to their individual interests, and inspire all students to be active learners.

Work in the Innovation Studio integrates the Engineering Design Process across the curriculum. Inherent components of the Design Process are: conceptualizing and communicating ideas, planning and creating a solution, risk-taking, reflection and analysis, and learning from mistakes by repeating and revising design. Each component of the design process engages students to reflect on their own learning.

## HOW IS THE INNOVATION STUDIO UTILIZED?

- Content-integrated project based learning: K-12
- Independent and capstone projects: high school
- Introductory design challenges: elementary/middle school

## Teacher professional development K-12:

- Curriculum-embedded co-planning and teaching
- Professional development workshops
- Student expositions and displays of student work
- Student, staff, and community project exhibits

### How can you get involved?

### Share your expertise:

- Provide subject specific knowledge and skills to teachers and students.
- Serve as a mentor for individual or small group projects
- Be available to answer questions or provide resources for teachers and students

### Contribute materials and tools:

- Recycled household items egg cartons, paper tubes, etc.
- Excess fabric/wood stock
- Craft supplies
- Legos, K'Nex, Erector sets, etc.

Please contact us before making donations as we have limited storage space.



### Partnerships and Financial Support:

We are excited to partner with local businesses and organizations for materials, expertise, and financial support for the Innovation Studio.

### **Current Partners include:**


Nye Enrichment Grant Town of Bourne Capital Outlay Committee AW Joyal Company Citizens of Bourne

See how your organization can get involved in this exciting educational initiative, contact the Innovation Studio at 508.759.0670 x256.

www.bourneps.org/iSTUDIO

School to Career Internship Program Overview:

- Open to Juniors and Seniors
- Students earn 1 Elective credit: Internships can be paid or unpaid
- Duration is typically a semester; however, extensions are possible
- Students must have their own transportation to and from placement
- A student's commitment, academic progress, attendance, and discipline records are considered for participation
- Students follow the school calendar
- Internship site supervisors communicate with school faculty through an initial and an end-of-semester meeting, plus phone calls, emails, and mid-semester meetings, as needed –note that CORI forms are required as part of the initial orientation of supervisors
- Students submit weekly time sheets signed by their site supervisor to document their attendance and receive course credit
- Students work with the Internship Coordinator and site supervisor to establish specific project goals that benefit the organization and the student
- A Massachusetts Work-Based Learning Plan, provided by the MA Dept. of Elementary & Secondary Education, is used to assess student learning
- Students attend weekly class seminars and complete weekly journal prompts
- Students present a final project and/or PowerPoint presentation at the end of their internship



### School to Career Program Options

Local businesses and organizations can help our youth engage in career training throughout the school year by participating in:

### STC Job Shadow

One (3-6 hour) visit by a BHS student is arranged on an individual basis. Students will spend the day observing their mentor on the job and asking questions about their profession.

### STC Internship

Approximately 8 hours per week during Fall and/or Spring semester. STC students must complete a project under the guidelines of the Massachusetts Work-Based Learning Plan and attend a weekly course seminar. To learn more visit: http://www.doe.mass.edu/connect

### Role of the STC Program Office

Students work with the internship coordinator to establish employer/worksite matches based on their career goals. The coordinator approves the internship placement, creates academic requirements, and assigns grades, in addition to the following:

- Communicate with each site supervisor to solicit performance feedback
- Facilitate the implementation of the MA WBLP
- Serve as an advisor to interns throughout the semester
- Submit a final grade based on the quality of classwork, attendance and participation in the internship, and the site supervisor's MA WBLP evaluations

For more information contact **School** to **Career** INTERNSHIP PROGRAM

## **BOURNE HIGH SCHOOL**

75 Waterhouse Rd, Bourne, MA 02532 internships@bourneps.org (508) 759-0676 | www.bourneps.org/schooltocareer

## BOURNE HIGH SCHOOL

School to Career



### PARTNERING EDUCATION WITH PRACTICE

### What is an Internship?

An internship is a structured and supervised hands-on learning experience providing local students with practical work knowledge. Interns are motivated students who desire to learn new skills while expanding their knowledge of a chosen career.

Internships are beneficial to employers, students, schools and communities as a whole, therefore helping Cape Cod retain an educated and skilled workforce. An internship is jointly evaluated by school and worksite staff and concludes in a final project or presentation.



### How will my company or organization benefit?

As a participant in the School to Career program, you are investing in the future of young people in our area. You have the opportunity to assist with the development of tomorrow's productive workforce by providing cost-effective work without a long-term commitment.

### By agreeing to participate in our program, you will:

- Make a positive contribution to the community
- Utilize the highest-rated recruiting strategy for employers (Gardner, Chao, and Hurst 2008)
- Make schools more responsive to the needs of business and industry
- Impact classroom curriculum and instructional practices
- Advance workforce skill levels by encouraging students to stay in the local community

### What are the Intern's responsibilities?

- Attend all scheduled internship classes at school and internship sessions with employer
- Complete project assignments and internship-related school assignments on time
- Actively seek guidance and constructive feedback from the internship site supervisor
- Act professionally by adhering to the internship schedule, arriving on time, dressing appropriately, and following through on projects and tasks in a timely and diligent manner

### Employer Responsibilities and Expectations

- Make the intern feel a part of the workplace and orient them to your specific professional environment
- Identify goals and activities to demonstrate progress and facilitate a student project or set of planned activities
- Help develop and monitor a MA Work-Based Learning Plan to evaluate the student's activities and performance
- Instruct and supervise the student, providing them with real-life work responsibilities
- Provide honest and constructive feedback on student
   progress
- Allow the student to express his or her thoughts and questions through regular meetings

## Meaningful internships have the power to change the course of a young person's life.

### Internship Benefits

- Build connections between the classroom and the workplace
- Gain a positive experience with hands-on learning
- Increase self-esteem by assuming responsibilities in real work settings
- Earn a sense of accomplishment
- Graduate high school with the academic, technical and job skills needed for success in college & careers



B. Class Size Policies

### B. CLASS SIZE POLICIES

The Bourne Public Schools continuously monitors class size at all levels. Starting at the middle level through high school, student/parent choice or course selection due to the availability of varied studies dictates oftentimes class size. Varied studies would include accelerated pathways, music, world languages and elective studies beginning in the middle school but more substantial at the high school level.

At the elementary level every effort is made to maintain class size at or around 20 students per classroom teacher. Absent school committee policy and with a complicated formula in our collective bargaining agreement, elementary class size up to and at 24 will engage discussions specific to deeper demographic projections and determining if an additional class section is necessary in the short term as well as long term scenario.


Collective Bargaining Agreement with the Bourne School Committee and the Bourne Educators Association Article XI Working Conditions Section 3. Class Size states the following.

The School Committee and the Association recognize that class size can be an important factor in good education and will strive, subject to educational, administrative, and budgetary considerations under the Committee's direction and control, to maintain classroom pupil/teacher ratios consistent with the parameters established by the Department of Education.

Elementary:	Grades 1-8	40 classroom teachers per 1000 students
Secondary:	Grades 9-12	60 classroom teachers per 1000 students

Any teacher who has a class wherein the pupil/teacher ratio exceeds the above parameters with the exception of physical education, home economics, shop, art, and other classes of a special nature shall have the right to discuss the situation with his/her immediate superiors.

Every effort will be made to place all students fairly and equitably across all grades, teams, caseloads, and subjects.



#### C. SCHOOL SCHEDULING METHOD

#### Elementary School Scheduling

Full-day or half day kindergarten (K) classes have motor group on a rotating schedule; Full Day K students attend music instruction twice in a calendar week. Additionally full-day kindergarten students attend art, Community Connections, You're a Writer, and computer instruction twice in a calendar month.

The following bullets outline details pertinent to scheduling all other elementary students grades 1- 4 at Peebles and Bournedale:

- Each class is scheduled for Physical Education and Music Instruction twice per calendar week for 45 minutes per class.
- You're A Writer!, Health/Wellness, art, and computer instruction are scheduled for 45 minutes twice per calendar month.
- Students also receive a 25 minute library block once per calendar week.
- Each grade level attends recess for 20 minutes prior to a 20 minute lunch block.
- Grade four teachers are piloting platooning and have been scheduled to provide equity of time in the morning and afternoon to support the platooning model.

### Bourne Middle School Scheduling

The Bourne Middle School schedule is organized into seven periods of class each day. Students experience two rotations in their weekly schedule, a six-day/seven period rotation with a 1/2/3 class rotation. All students have five classes that meet every day (math, English language arts, science, social studies, and seminar). The sixth class period for students in grades 5-7 is a Unified Arts class. Unified Arts classes meet every day for a quarter and include art, digital literacy, coding, and engineering technology. Students in grade 8 are scheduled for either a world language (French or Spanish) or seminar for their sixth class period. The seventh class period for all students will be health/music/physical education, meeting every third day.

#### Bourne High School Scheduling

- 1. Each year every student is required to take a minimum of six subjects per semester. Of these six required subjects a minimum of three must be academic courses. An academic course is defined as any subject taken in the following departments: English, mathematics, science, social studies, and world languages
- 2. Students are required to take English, mathematics, and physical education all four years.

Students may not take two required English courses in one year. Exceptions may be granted for extenuating circumstances, and require prior administrative approval. In order for a student to be promoted to the next grade, he/she must successfully complete the appropriate level English class.

It is highly recommended that students planning to attend a four-year college take the following number of high school courses in each subject at the academic, honors and/or AP levels:

- 4 Credits of English
- 4 Credits of Math
- 4 Credits of Social Studies
- 4 Credits of World Language

Students are encouraged to work with their guidance counselors to select the most appropriate and challenging academic level suited for them. Below are a number of elective offerings at Bourne High School.

2-D/3-D Design Advanced Mathematical Decision Making Anatomy and Physiology Creative Mixed Media Criminal Law Drawing

**AP Biology** AP European History **AP Physics** AP Psychology/Psychology **AP Statistics** AP Studio Art Art I, II, III, IV Astronomy Band **Broadcast Journalism** Chorus Civil Law **Coastal Studies** Music Theory Oceanography Peer Leadership **Personal Finance Physics** Piano Keyboarding Print Journalism Robotics I & II

### Peebles Elementary School


**Economics** Engineering Technology **Environmental Science** Film & Digital Photography First Aid & CPR **Forensic Science** French Graphics I & II Guitar I & II Healthy Lifestyles **International Studies** Introduction to Dance and Movement Meteorology & Global Climate Change Spanish Statistics **Theater Arts** United Nations I & II Web Design Using HTML and Java Script Web Design using WordPress Wellness



### D. TEACHING METHODOLOGY AND STRUCTURE

Instruction in the Bourne Public Schools is based on the practices of backwards design as advocated by Wiggins and McTighe in their Understanding by Design research and teaching/learning paradigm. Units of instruction based on the Massachusetts State Frameworks in all disciplines are mapped PreK-12 and a variety of learning experiences and assessments (formative and summative) are based on what students should know, understand, be able to do, and transfer as indicated in the maps. Various student-centered instructional strategies are used to meet the needs of all learners, most notably flexible grouping and problem-based learning. We have deliberately infused the principles of engineering design and inquiry-based learning into many of our learning activities to ensure engagement and relevance for 21st century learners. Included in learning activities are opportunities for our students to learn and apply the habits of mind and skills needed for working in teams, persisting, and becoming self-reflective life-long learners.

Research show that embedded professional development has a significant impact on student growth and achievement. Bourne Public Schools is committed to ensuring all teachers have adequate time for meaningful collaboration linked to curriculum and learning targets, and for self-reflection to continually improve their practice. Additionally, on site instructional coaches at all schools facilitate collaborative professional learning in the classrooms, laboratories, and innovative learning environments such as our iStudio, Aquaponics Lab, and emerging Learning Commons areas.



## E.

Teacher Planning and Room Assignment Policies

### E. TEACHER PLANNING AND ROOM ASSIGNMENT POLICIES

Elementary pre-kindergarten through middle school have grade clusters for classroom assignments. As you are aware each facility is not able to create perfect clustering, therefore there are outliers, i.e.; around a corner or ground floor vs. second floor. Grade level clusters change in section size with the ebb and flow of school age demographics.

High School grades 9-12 room assignments are specific to disciplines with the exception of special areas like drama, music, physical education and more recently learning lab environments. A traditional woodshop was converted to a problem based learning Innovation Studio. A general education classroom has been converted to an Aquaponics Lab through a grant from BioGen. A general education classroom was converted to a music keyboarding lab for our fine arts students. Lastly, a double classroom environment was reconstructed and converted in to Robotics Lab.

In addition, through prior and most recent school construction at Bournedale Elementary (2007/09) and Bourne Middle School (1999/00) unique spaces and adjacencies were constructed for special studies, i.e.; art, music, library/media centers, computer laboratories, family and consumer science, large teacher workrooms, and to provide students with disabilities related services as well as intensive services. We recently received a grant from Extron Electronics to assist us with plans to convert some of the Bourne Middle School Library/Media Center into a learning commons as a wireless collaboration gateway through a digital sources control system.

Bourne Middle School (1999/00) was constructed with foresight to accommodate a middle school pedagogy by creating favorable grade clusters/teaming on the second floor, however special areas and adjacencies are all on the first floor. Additionally, due to limited, equitable instructional space for students with special needs and related services, we are cited corrective action planning from the Department of Elementary Quality Program Review process. We have been granted waivers due to our limitations.

Throughout the ebb and flow of middle school demographics classroom teachers have been placed on itinerary carts traveling from room to room for classroom instruction. In more recent years, teachers have been assigned to unique repurposed spaces for instruction. For example, a constructed large team room with a partitioned wall has become the permanent home of two instructional health and wellness classes. An art room was converted to a pre-engineering room due to the room size and amenable features to support problem-based/engineering design processes with collaborative work stations water utilities (sinks) and area for student exhibitions.

Every attempt is made for all classroom teachers to have an assigned classroom. Currently at the elementary level in the Bournedale Elementary School and Peebles Elementary School our applications extension course teachers for all students grade 1-4 (You're a Writer!) do not have a classroom and provide their instruction to students in various unscheduled/open classrooms.

Most teachers are able to prepare and provision for instruction in their assigned classroom. We do have itinerary teachers at the elementary level that share space outside of the classroom for said purpose.



### F. LUNCH PROGRAMS

All Bourne Public Schools are part of the National School Lunch Program and offer breakfast and lunch. Peebles and Bournedale Elementary schools offer Breakfast in the Classroom which is a bag breakfast that students take to the classroom to eat in the first 10 minutes of school. All schools follow an "offer vs. serve" policy whereby all five meal components are offered; students have the option of making three choices, one of which must be a fruit or vegetable. All schools have a daily, self-serve "fruit and vegetable bar" at breakfast and lunch that offers a variety of fresh fruits, vegetables, legumes, salads and canned/frozen fruits.

Breakfast at all Bourne Schools offer daily: one hot entrée (all whole grain pancakes, waffles, French toast, and breakfast sandwiches) and "continental breakfast" items (all whole grain muffins, bagel, cereals, string cheese, yogurt, juice). There is also a fruit bar and two types of milk available.

Peebles and Bournedale Elementary Schools offers daily: one hot entrée/main meal, two alternate sandwiches/salads (turkey, ham, chicken Caesar salad, PB&J). Á la carte items sold include bottled water, fresh baked cookies and baked/reduced fat chips. All Á la carte items are on the Massachusetts "A List" of approved Á la carte items put out by the John Stalker Institute.

Bourne Middle School offers daily: hot entrée/main meal, "grab and go" grill sandwiches, entrée salads and wraps that are packaged "to go" and 3 types of pizza. A la carte items include: bottled water, bottled seltzer water, fresh baked cookies, baked/reduced fat chips, crackers, yogurts and parfaits. All Á la carte items are on the Massachusetts "A List" of approved ala carte items put out by the John Stalker Institute.

Bourne High School offers daily: hot entrée/main meal, "grab & go" premium meals, 3 types of pizza, deli bar and salad bar. Ala Carte items include: bottled water, bottled seltzer water, fresh baked cookies, baked/ reduced fat chips, crackers, yogurts and parfaits. All Á la carte items are on the Massachusetts "A List" of approved ala carte items put out by the John Stalker Institute.

- Elementary lunches are scheduled as follows:
  - At Bournedale Elementary School there are five lunches that run 20 minutes each.
  - At Peebles Elementary School there are four lunches that run 20 minutes each.
- There are two lunch periods of 30 minutes at Bourne Middle School for grades seven and eight. Students in grades five and six have 20 minutes for lunch and 20 minutes for recess.
- At Bourne High School there are two lunch periods of 30 minutes

G.

Technology Instruction Policies and Program Requirements

### G. TECHNOLOGY INSTRUCTION POLICIES AND PROGRAM REQUIREMENTS

The Bourne Public Schools has been overhauling established belief systems and systemic practices for the use and support of instructional technology. At the heart of our efforts are three guiding principles: 1. Increase automation without adding staff, 2. Eliminate ineffective/feckless redundancies, and 3. Identify proven technologies with no or limited recurring costs. The Bourne Public Schools has established the following priorities:

- 1. Infrastructure
- 2. Bandwidth/accessibility
- 3. Instructional technology blended with all instruction, [not something unique]
- 4. Instructional equity to hardware
- 5. Pilot/experiment vs. all-in approach
- 6. Identification of public domain efficiencies
- 7. Shared best practices
- 8. Movement to the cloud.

All of our schools have district owned fiber LAN and WAN providing high speed internet access with a coax backup. Bourne High School, Bourne Middle School and Bournedale Elementary school are full Wi-Fi environments. Peebles Elementary School is a pocket and portability Wi-Fi environment. Classroom teachers at all schools and across all levels have LCD projectors, document cameras, desktop computers, and access to portable personal devices such as Chromebooks or iPads.

H. Art Program

### H. ART PROGRAM

The Bourne Public Schools offers a comprehensive art program Kindergarten through 12th grade with instruction in all elements of art: line, shape, form and texture. Bourne High School students are offered an array of art electives (see section C).

Music/Performing Arts Program

1.

### I. MUSIC/PERFORMING ARTS PROGRAM

The Bourne Public Schools offers a comprehensive music program Kindergarten through their high school experience. As students' progress through the middle years, more options for specific music interest is available to students including the ability to select a musical instrument or participate in a choral program. As student enter the high school more varied music opportunities spider out from initial opportunities at the middle school as evidenced by the list of music electives (see section C.)

Bourne Public Schools provides an incredible opportunity for our students of all ages to participate and learn in the dramatic performing arts. Our elementary students in grades three and four are able to participate in an annual drama musical program titled "All-Star Revue". Well over one hundred third and fourth grade students participate in the annual event. Our middle school students have access to an annual drama performance and our high school students have access to an award winning drama program. J. Physical Education

### J. PHYSICAL EDUCATION

All students have access to physical education at every level and our district has put forth a concerted effort to establish a wellness program for students elementary through high school. The Bourne Public Schools School Committee acknowledges the direct correlation between health and academic success as indicated in research conducted by the Center for Disease Control. Therefore, we provide the necessary resources in nutrition, health and physical education, school based activities and food services to promote healthy lifestyles and maximize student performance.

K. Special Education

### K. SPECIAL EDUCATION (Specialized Instruction)

Bourne Public Schools does not discriminate on the basis of race, color, sex, gender identity, religion, national origin, sexual orientation, disability, or homelessness.

The Department of Student and Special Education Services facilitates full access to the general education curriculum and the school/community learning environment for every student based on student potential and identified special needs. The district's goal is to provide support services in the least restrictive environment which, for the majority of students, is the regular education classroom. Eligibility is reevaluated every three years and a review of current services is conducted annually. Teachers, special education providers, and parents/guardians/caregivers are integral members of the team process. Placement in special education is based on the Individualized Education Program (IEP) as written for each student identified as eligible within the IEP team process. The goal of the Special Education Department at Bourne Public School is that all students are educated in classrooms that meet their diverse learning needs, styles, and abilities.

For our youngest students with identifiable disabilities, ages three and four, our preschool program offers a safe and nurturing environment based on developmentally appropriate practices. It is an environment that encourages social development and teaches our children to be respectful. Our integrated setting offers students a chance to learn things from one another, no matter what challenges they face. We teach our students to be self-reliant and self-confident, sensitive to others, and respectful of peers and adults. We strive to challenge all students to improve in the areas of communication skills, manipulation of objects, conceptualization and representation of ideas, movement skills, and to think of learning as fun. Our students leave our preschool well prepared for kindergarten and their community with the ability to act positively with others and a desire to be lifelong learners.

The preschool is a four day program which runs Monday-Thursday. There are three classrooms, two are half-day programs and one is a full-day program. The half-day programs are designed to offer an integrated preschool setting for students with and without Individual Education Plans. Morning sessions are from 9:00-11:30. Afternoon sessions are from 12:30-3:00. The full-day program is a substantially separate program for children on Individual Education Plans and runs from 9:00-3:00.

Related Service is provided in class and in adjacencies grades pre-kindergarten through twelfth grade.

- Speech K-4
- Speech PK
- OT
- Adapted PE
- PT
- Social Worker: Social Skills Groups

Intensive Learning Centers (ILC)

The Bourne Public Schools provided an Intensive Learning Center (ILC) Program for students in prekindergarten through twelfth grade. Students who begin in the pre-kindergarten ILC are in an integrated setting where peers come into their classroom. Modeling is done in a familiar space throughout the morning with our students with intensive needs. In the afternoon, the peers attend a half-day session of prekindergarten in another classroom while students in the ILC receive discrete trials to best fit their individual academic and behavioral needs.

In Kindergarten, students who are able to work in a kindergarten classroom attend a morning half day program with typically developing peers. In the afternoon, the students go to the ILC classroom to receive discrete trials and smaller group instruction, again based on their academic and behavioral needs.

In first through fourth grade, students who are able to be mainstreamed into the general education classroom are placed there with any supports for success deemed necessary by the IEP team. If a student is not ready

or is only able to integrate during certain times of the day, these arrangements are also made. Each year the program evolves and changes as it is always based on the needs of the students. At any time with students who are in the ILC, data is gathered and students have been successfully mainstreamed into general education classrooms which is the ultimate goal.

For students in grades five through twelve who demonstrate deficits in the moderate to severe range of intellectual abilities we have established highly specialized instruction in order to access the curriculum at their instructional level. Curriculum is designed to meet the needs of each individual student's current academic performance level and emphasizes academic content, communication skills, behavioral strategies, social skills and activities of daily living. Students and staff work to develop the skills necessary to foster ongoing academic growth and promote school-specific social awareness. Student services (occupational therapy, physical therapy, adapted physical education, and speech/language services) are determined by the IEP team and may include services in the general education classroom as well as in a special education setting.

#### In-Class Services

This program serves students (grades k-12) with identified disabilities whose formal and informal assessments show discrepancies in achievement as determined by the IEP team. These students are provided academic skills reinforcement, organization, and study skill strategies in the general education classroom and during seminar. The goal of this program is to ensure the greatest possible acquisition of age-appropriate academic skills; to internalize strategies that reduce the impact of the disability on learning and to foster emotional/social/academic independence.

### Alternative Learning Center

This program serves students in grades five through twelve and focuses interventions on the social, emotional, and behavioral needs of students with qualifying disabilities while providing instruction to support students' participation and progress in the general curriculum. Individualized behavior intervention plans are developed and maintained to meet the needs of each student. Students are integrated into the general education classrooms whenever possible while working towards mastery of general content standards as measured by state assessments. Social Skills instruction is used to develop and improve students' social and behavioral skills.

#### Title I

Title One services are provided for students in two of our four school based on need and qualifying demographics. The schools are Peebles and Bourne Middle School.

The Title 1 reading curriculum is designed to address the five critical reading skill areas (Phonemic Awareness, Phonics, Vocabulary, Fluency, and Comprehension) which are identified by the National Reading Panel (2007). Specific areas of targeted reading instruction are determined for students on an individual basis through analysis of individual student performance on school-wide standardized reading assessments.

Students in this reading program are taught life-long learning strategies to facilitate reading comprehension and language organization. Special emphasis is placed upon the development of active reading strategies that can be applied to both narrative and expository text. Students learn to apply these strategies directly to their content area materials, texts, and project.

The Title 1 math program provides extended learning opportunities, individualized support, and alternative instructional strategies in math for qualifying students. Concepts and skills based on grade level and student ability are retaught and reviewed. Title 1 instruction challenges students to make connections with prior knowledge and to real world situations. It assists learners to create and use multiple problem solving pathways, and engage them in mathematical tasks that reflect grade-level and cognitive demands. Students

work in groups, partners, and independently based on class size and learning activities.

The Bourne Public Schools offers an extensive summer program for students with disabilities who are at risk of regression during the summer break. Summer programs include summer tutoring sessions to meet qualifying needs.

- Data is collected on students throughout the year in all grades to determine eligibility for summer school programs. Regression during school vacations is often one of the indicators.
- Bournedale Elementary School currently houses all summer programs and most of the summer tutoring for students pre-kindergarten through twelfth grade.
- In addition, the Bourne Public Schools works with the Bourne Recreation Department to provide a "Slide Into Learning" as a community-run academic program that our students have access too.

### **English Language Learners**

The goal of our English Language Education Program is to provide students with instruction that is inclusive and honors the various language and cultures found within our student population. Bourne Public Schools has followed all federal and state laws and guidelines in developing the program, and continues to adhere to federal and state laws and guidelines in implementing the program.

We offer Sheltered English Immersion, an inclusionary instructional program in which English Language Learners are placed in classes with native English speakers. Classroom teachers are trained to implement a variety of effective strategies to meet the unique needs of our English Language Learners. ELL students also benefit from direct instruction provided by a certified ESL teacher that is scheduled according to need and to ensure no instructional time in the SEI classroom is missed.

### Section 504 of the Rehabilitation Act

Section 504 is a federal statute that prohibits discrimination based upon a handicap. Obligations for school districts start when federal funds are received.

Section 504 covers eligible students, employees, and other individuals with handicapping impairments by providing necessary accommodations that enable them to work, learn or participate in school programs. Student accommodations go beyond those outlined in our district Curriculum Accommodation Plan (CAP) which are available to all students. A team, knowledgeable of the person, gathers information to determine if the individual meets eligibility criteria. This law applies to our school district as receive Federal financial aid therefore it covers all programs and activities that we offer. The responsibility of our district is to identify, evaluate, and provide appropriate services to those individuals who meet the criteria set forth by the Act.



L. Vocational Education

### L. VOCATIONAL EDUCATION

The Bourne Public Schools is a member town of the independent LEA Chapter 74 Upper Cape Cod Technical High School located in the community of Bourne. Other member towns include Sandwich, Marion, Falmouth and Wareham. There are no plans to create or duplicate Chapter 74 programs in the Bourne Public Schools.

### Innovation Studio

As the 2014-2015 school year commenced we opened our district Innovation Studio at Bourne High School. The Studio is an educational environment that provides opportunities for students to engage in hands-on, interdisciplinary problem-based learning experiences. Students in all grades, kindergarten through high school, utilize the studio to explore and create across all subject areas. By designing solutions to problems linked to their courses of study, students develop, grow, and acquire 21st century skills that are essential for today's high school graduates.

The Innovation Studio contains elements of computer science, textiles, crafts, electronics, robotics, art, music, science and woodworking. The Studio is designed to facilitate collaboration and provide opportunities for students to explore, create, analyze and problem-solve using a wide variety of resources. These resources spark student curiosity and creativity, allow students to connect to their individual interests, and inspire all students to be active learners.

Work in the Innovation Studio integrates the Engineering Design Process across the curriculum. Inherent components of the Design Process are: conceptualizing and communicating ideas, planning and creating a solution, risk-taking, reflection and analysis, and learning from mistakes by repeating and revising design. Each component of the design process engages students to reflect on their own learning.

How is the Innovation Studio utilized?

- Content-integrated project based learning K-12
- · Independent and capstone projects for high school students
- Introductory design challenges for elementary/middle school students
- Teacher professional development K-12 including workshops
- Curriculum-embedded co-planning and co- teaching
- · Student expositions and displays of student work
- · Student, staff, and community project exhibits

Early College Experience Program (ECEP)

In the summer of 2013 Bourne Public Schools established an Early College Experience Program (ECEP) in partnership with Cape Cod Community College.

The Early College Experience Program (ECEP) was developed for motivated students who would like to get a jump start on college. The goal of ECEP is to provide high school students the opportunity to earn their high school diploma and an Associate's Degree while completing their junior and senior year at CCCC. Admission into this program is a competitive and students take all courses at CCCC. The primary goals of this program are:

- To address the needs of motivated students who would like to enroll in college courses prior to high school graduation.
- To graduate students with a high school diploma and an Associate degree.
- To allow students the opportunity to fulfill their educational dreams.

Students satisfy all state and educational requirements to obtain a high school diploma and an Associate's Degree, which includes passing the MCAS. All ECEP students are considered Cape Cod Community

College students and have access to CCCC services including counseling, advising, career services, fitness center, and leadership activities offered by Student Life.

Financial Obligation and Eligibility

The ECEP program covers the cost of course tuition and fees for enrolled students. Students are responsible for their books and school supplies. Current high school students are ineligible to receive Federal financial aid, but financial assistance may be provided by the Bourne Public Schools.

Students must reside in Massachusetts, possess a minimum high school GPA of 3.0 (cumulative, based on a 4.0 scale), be at least 16 years old and entering Grade 11 by the start of the fall semester, be recommended by the high school and complete the ECEP application process and attend an information session. Students who have not passed the MCAS will be scheduled to take the appropriate test at Bourne High School. Students must be willing to enroll in classes during all available CCCC semesters, including Fall, Intersession, Spring, and Summer sessions, in order to complete diploma and Associate degree requirements.

### School to Career Program (Internships)

As the 2013-2014 School Year commenced, we reestablished a School to Career Internship program through a grant from the Grace Swift Nye Foundation. The program is a structured and supervised hands-on learning experience providing local students with practical career field experience. We sought motivated students who desire to learn new skills while expanding their knowledge of a chosen career.

For students seeking an internship, a BHS Guidance Counselor will guide them towards the best career exposure to meet their interest. Students submit a completed application with attached resume and personal essay prior to course registration. Students are then required to outline a planned internship based upon the criteria identified in the application. Once students complete the application, a School to Career Internship placement will be established by meeting with the Internship Coordinator and the students Guidance Counselor.

Internships are beneficial to employers, students, schools and communities as a whole, therefore helping Cape Cod retain an educated and skilled workforce. An internship is jointly evaluated by school and worksite staff and concludes in a final project or presentation.

An overview of this district program is below;

- Open to Juniors and Seniors
- Students earn one elective credit and internships can be paid or unpaid
- Duration is typically a semester; however, extensions are possible
- Internships are approximately 8 hours per week plus a weekly seminar
- · Students must have their own transportation to and from placement: carpooling is not permitted
- A student's commitment, academic progress, attendance, and discipline records are considered for participation: application and permission forms must be received in time for course registration
- · Students follow the school calendar
- Internship site supervisors communicate with school staff through an initial and an end-ofsemester meeting, telephone calls, emails and mid-semester meetings, as needed - note that a CORI form is required as part of the initial orientation of supervisors
- Students submit weekly time sheets signed by their site supervisor to document their attendance and receive course credit
- Students work with the Internship Coordinator and site supervisor to establish intentional learning goals and specific project goals that benefit the organization and the student
- A Massachusetts Work-Based Learning Plan, provided by the Massachusetts Department of Elementary & Secondary Education, is used to assess student learning

- Students attend weekly class seminars and complete weekly journal prompts designed for the student to ask reflective and practical business questions of their supervisor
- Students present a final project and/or PowerPoint presentation at the end of their internship to advisor and classmates.

M. Transportation Policies

### M. TRANSPORTATION POLICIES

For our in district transportation we use a 3 tier system (HS, MS and Elementary) consisting of 18 buses. We have half day Kindergarten with full day as an option for a modest fee. We charge a fee (\$150 per student/\$300 cap per family) for our HS (9-12) transportation. We transport all our in district special needs students (PreK -12) with our 5 mini buses.

The district uses a computer generated route optimization software package to assist in developing a safe, efficient and cost effective plan for bus routing. In computing the distance for transportation eligibility the most direct route used by the school bus is used by the district's computer software. Modifications to the bus assignments, routes and bus stops may change from year to year based on enrollment.

The Bourne Public Schools has a number of policies specific to transportation of students as follows:

Student Transportation Services

Policy # EEA

STUDENT TRANSPORTATION SERVICES

The major purpose of the school system's transportation services is to aid students in getting to and from school in an efficient, safe, and economical manner.

The school system will contract for transportation services. Contracts will be awarded on a competitive bid basis by the School Committee. Bus contractors, who will be held responsible for the safe operation of school buses, will comply with all applicable state laws and regulation, including but not limited to:

- 1. Specifications for school bus design and equipment
- 2. Inspection of buses
- 3. Qualifications and examinations of bus drivers
- 4. Driving regulations
- 5. Small vehicle requirements, if applicable
- 6. Insurance coverage
- 7. Adherence to local regulations and directives as specified in bid contracts

The Superintendent, working with the bus contractor and other appropriate administrators, will be responsible for establishing bus schedules, routes, stops, and all other matters relative to the transportation program.

Policy References:

M.G.L. 40:5; 71:7A, B and C; 71:37D; 71:48A; 71:68; 71:71A; 71B:4; 71B:5; 71B:8, 74:8A; 76:1; 76:12Bi; 76:14

School Bus Scheduling and Routing

Policy # EEAB

FILE: EEAB

SCHOOL BUS SCHEDULING AND ROUTING

Routes and time schedules shall be determined by the transportation Coordinator or Superintendent's designee and any change shall be in accordance with the attached guidelines.

Every reasonable effort shall be made to locate bus stops at points where pupils can be loaded and discharged with a reasonable degree of safety and convenience with consideration for the age of the pupil.

FILE: EEA

A parent or guardian who feels that the safety of their child is unreasonably endangered and who cannot reach an accord with the Transportation Coordinator will have the right to file a written appeal to the Business Manager of the Bourne Public Schools and the Transportation Issues Committee, and subsequently, to the Superintendent whose determination will be final.

School Bus Scheduling and Routing Regulations

Policy # EEAB-R

FILE: EEAB-R

### SCHOOL BUS SCHEDULING AND ROUTING REGULATIONS

- 1. The Transportation Coordinator or Superintendent's designee shall be responsible for designating bus route and stops that are consistent with Bourne School Committee policy.
- 2. Where pupils live within a reasonable distance of each other, they may be required to go to certain designated bus stops at intervals along the route.
- 3. In congested or high traffic areas, routes should be designed, within reasonable limits, to prevent students crossing those roads unnecessarily.
- 4. Stops should be planned away from busy intersections whenever possible to avoid a distracted motorist from passing a bus while it is loading or discharging passengers.
- 5. When unavoidable obstacles or dangers exist, the Transportation Coordinator must make an effort to have them removed.
- 6. The recommended distance that stops may be established from the students' homes are as follows:

up to 1/2 mile

up to <sup>3</sup>/<sub>4</sub> mile

- a. Kindergarten through grade 4
- b. Grades 5 through 8
  - Grades 9 through 12 up to 1½ miles
- 7. Routes and stops shall be published prior to the first day of school in a newspaper with local circulation to include notice to the parents or guardians that they have the responsibility to see that their child gets to the published stop safely and on time.
- 8. When such dangers are unavoidable, as determined by the Transportation Coordinator and the Police Department, stops may be extended but should be located at the closest reasonable location, and parents shall be responsible to see that their child gets to that stop safely and on time.
- 9. The parent or guardian of a student residing on private or unimproved ways, or on ways that present hazards that the Transportation Coordinator cannot reasonably overcome, is required to see that their child gets to the designated stop safely and on time.

### Bus Driver Examination and Training

C.

### Policy # EEAEA

### BUS DRIVER EXAMINATION AND TRAINING

The School Committee will reserve the right to approve or disapprove persons employed by the bus contractor to drive school transportation vehicles.

- 1. Courteous and careful drivers will be required.
- 2. Each driver will file with school officials a medical certificate and proof of freedom from tuberculosis.
- 3. No person under 18 years and only persons of high character will be allowed to operate school buses.
- 4. Only persons who are properly licensed by the state and have completed the driver training program will be permitted to drive school buses.
- 5. The contractor will furnish the School Committee with a list of names of drivers and their safety records for the last three years.

FILE: EEAE

- 6. In case of any permanent change of bus drivers, the contractor will notify school officials as soon as possible.
- 7. Each driver will be required to comply with the Department of Transportation regulations for drug and alcohol testing.

Policy References:

Highway Safety Program Standard No. 17

M.G.L. 90:7B; 90:8A; 90:8A 1/2

N. Functional and Spatial Relationships and Adjacencies

### N. FUNCTIONAL AND SPATIAL RELATIONSHIPS AND ADJACENCIES

(Refer to attached organizational diagrams in this section.)

O. Security and Visual Access Requirements

### 0. SECURITY AND VISUAL ACCESS REQUIREMENTS

The Bourne Public Schools has established practices that ensure the highest level of safety and security for students and staff during the school day and for community use of our facilities after school hours.

All doors are locked upon the commencement of school. Visitors must buzz at the front door of each school, buzz and visitors are monitored via closed video systems. If awareness is heightened due to a number of causes, individuals must verbally identify themselves and state their business.

With the exception of the Peebles Elementary School all, schools have visibility of individuals who enter the school after being permitted entrance via the aforementioned process. At the Peebles Elementary School an entering party must turn down an adjacent hallway to engage with office personnel.

After hours community access at Bourne High School and Bourne Middle School can be and is limited to the area utilized. Access is restricted to hallways that lead to classrooms. At the Bournedale Elementary School access is limited to individual classrooms on the first floor and stairwell access to the second floor. There is access to hallways on the first floor.



### P. EDUCATIONAL VISIONING

The visioning process involved meeting with a variety of stakeholders and synthesizing information from all parties, including an Educational Working Group from the school district comprised of the Superintendent, Principals, directors, and key staff; faculty and staff of Bournedale and Peebles; the School Building Committee; and the public in attendance at community forums.

### Workshops with Educational Working Group Oct 16, Nov 6

The project team held two visioning sessions with the Educational Working Group during the PDP study period, reviewing and refining district goals for teaching and learning, understanding program and space needs, and exploring design patterns that will best serve the district's goals in a new facility.

In the first workshop, the participants shared space and program goals for a new facility, highlighting physical and abstract aspects desired for successful spaces. Key programs and initiatives currently in place were documented as a baseline for future development. The participants evaluated district strengths, challenges, opportunities, and goals for leadership, programming, facilities, and involvement. New Vista presented characteristics of 21st century learning, and participants responded with goals that guide program and curriculum development. New Vista introduced imagery of design patterns utilized in a variety of school facilities, surveying participants regarding appropriateness and desirability for a Bourne facility.


The second workshop focused on prioritizing design patterns and guiding principles most appropriate for Bourne. Participants expanded on successful aspects of current facilities and highlighted areas for improvement, noting specific space requirements that informed refinement of the template. Precedents illustrating specific design patterns were reviewed, and those resonating with participants were noted. Through group discussion, FAI developed bubble diagrams illustrating space adjacencies and grade groupings, which served as the basis for preliminary planning exercises.

Interviews with faculty and staff Oct 21

Flansburgh and New Vista met with a range of faculty and staff to evaluate existing space uses and explore opportunities for improvement. Teachers, administrators, and support staff described advantages and limitations of the Bournedale and Peebles facilities; identified programming, teaching, and learning goals; and explained key adjacencies. Responses informed space requirements and preliminary design studies.

*Community Forums* Oct 26, Nov 17, Dec 8

The project team conducted three community forums to inform the community and invite public input on a variety of issues. Topics included review of project scope, MSBA process, results of visioning workshops, existing conditions findings, and preliminary design options. Community members were presented incremental updates at each forum and invited to respond with questions and concerns. New Vista presented 21st Century learning goals, guiding design principles, and design patterns to audiences in the elementary school cafeterias, sparking discussion on the future of education in Bourne.



# 3.1.3 Initial Space Summary

- A. Itemization of Program MSBA Templates
- B. Variance between Program and MSBA Guidelines
- C. Existing Floor Plans



Itemization of Program
- MSBA Templates

### 3.1.3 Initial Space Summary

### A. ITEMIZATION OF PROGRAM - MSBA TEMPLATES

The Feasibility Study for this proposed project will examine the following four options:

**Option 1:** Maintain the current James F. Peebles Elementary School grade configuration of grades K-4, which for the purposes of the design shall be based on no more than 250 students.

**Option 2:** Consolidate the District's grades K-4 population at a District-wide elementary school, which for purposes of the design shall be based on no more than 725 students;

**Option 3:** Consolidate the District's grades K-5 population at a District-wide elementary school, which for purposes of the design shall be based on no more than a total of 885 students;


**Option 4:** Consolidate the District's grade 5 population at the James F. Peebles Elementary School and maintain the current facility's grades K-4 population, which for purposes of the design shall be based on no more than a total of 410 students

The following MSBA space templates are based on the study scope noted above and reflect existing building findings and programmatic needs requested by the district.

# **MSBA Study Scope**

Option 1	Option 2	Option 3	Option 4
Grades K to 4	Grades PreK to 4	Grades PreK to 5	Grades K to 5
Neighborhood Elementary School	District-wide Elementary School	District-wide Elementary School	Neighborhood Elem. School with District- wide 5th grade
250 students	725 students	885 students	410 students

Flansburgh Architects



## Peebles Elementary School | Bourne, MA

## Flansburgh Architects

### Proposed Space Summary- Elementary School (K-4)

### DRAFT 1

\_\_\_\_\_

Option 1- Peebles																	
Bourne K-4	E	xisting Cond	itions	Existing to Remain/Renovated			New			Total			MSBA Guidelines (refer to MSBA Educational Program & Space Standard Guideline				
ROOM TYPE	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	Comments	
ORE ACADEMIC SPACES (List classrooms of different sizes separately)		0/021010	20,300			0		20520	14,400	5		14,400		11	10,950		
Last classrooms or onerent sizes separately) Pre-Kindergarten w/ tollet Kindergarten w/ tollet General Classrooms - Grade 1-4	950 VARIES	2 20	1,900 18,400				1,200 900	3 12	3,600 10,800	1,200 900	3 12	3,600 A 10,800 B	1,200 1,200 950	2 9	2,400 8,550	1,100 SF min - 1,300 SF max 1,100 SF min - 1,300 SF max 900 SF min - 1,000 SF max	
PECIAL EDUCATION	1		1,805	12.2.2.2.10.12		0	10000000		3,020	7.55.57		3,020			3,020		
(List rooms of different sizes separately) Self-Contained SPED Self-Contained SPED - toilet Resource Room Small Group Room / Reading	935 870	1	935				950 60 500 500	2 2 1 1	1,900 120 500 500	950 60 500 500	2 2 1 1	1,900 120 500 500	950 60 500 500	2 2 1 1	1,900 120 500 500	8% of pop. In solf-contained SPED 1/2 eize Gent. Cirm. 1/2 eize Gent. Cirm.	
RT & MUSIC Art Classroom - 25 seats Art Workroom w/ Storage & kiln Music Classroom / Large Group - 25-50 seats Music Practice / Ensemble	800	1	1,325 800 525			0	1,000 150 1,000 75	1	2,225 1,000 150 1,000	1,000 150 1,000	1	2,225 1,000 150 1,000 C	1,000 150 1,200	1	2,500 1,000 150 1,200	assumed schodulo 2 times / wook / student assumed schodulo 2 times / wook / student	
Music Practice / Ensemble EALTH & PHYSICAL EDUCATION Gymnasium Gym Storeroom Health Instructor's Office w/ Shower & Toilet	3,100	1	3,100 3,100			0	6,000 300	1	75 6,300 6,000 300 0	75 6,000 300	1	75 D 6,300 6,000 300 0	6,000 150 150	1	150 6,300 6,000 150 150	6000 SF Min. Size	
IEDIA CENTER Media Center / Reading Room INING & FOOD SERVICE	730	1	730 730 5,550			0	2,020	1	2,020 2,020 4,875	2,020	1	2,020 2,020 4,875	2,020	1	2,020 2,020 4,875		
Cafeteria / Dining Stage Chair / Table / Equipment Storage Kitchen	4,100	1	4,100				1,875 1,000 200 1,600	1	1,875 1,000 200	1,875 1,000 200	1	1,875 1,000 200	1,875 1,000 200	1 1	1,875 1,000 200		
Staff Lunch Room	350	1	350				200	1	1,600 200	1,600 200	1	1,600 200	1,600 200	1	1,600 200	1600 SF for first 300 + 1 SF/student Add'l 20 SF/Occupant	
IEDICAL Medical Suite Toilet Nurses' Office / Walting Room Examination Room / Resting	260	1	260 260			0	60 250 100	1	410 60 250 100	60 250 100	1 1 1	410 60 250 100	60 250 100	1 1 1	410 60 250 100		
DMINISTRATION & GUIDANCE General Office / Waiting Room / Toilet Teachers' Mail and Time Room Duplicating Room	270	1	1,195 270			0	300 250	1 1 1	2,015 300 250 0	30 25	0 1 0 1	<b>2,015</b> 300 250 0	300 100 150	1 1 1	2,015 300 100 150		
Records Room Principal's Office w/ Conference Area Principal's Secretary / Walting Assistant Principal's Office Supervisory / Spare Office Conference Room	600	VARIES	600				110 37: 12: 12:	5 1 5 1 1 1	110 375 125 120	11 37 12 12	5 1 5 1 0 1	110 375 125 120	110 375 125 120 120	1 1 1 0 1	110 375 125 - 120		
Guidance Office Guidance Storeroom Teachers' Work Room	325	1	325				250 150 35 300	1	250 150 35 300	25 150 35 300	0 1 1 1	250 150 35 300	250 150 35 300	1	250 150 35 300		
USTODIAL & MAINTENANCE Custodian's Office Custodian's Workshop			795			0	150 375	1	1,900 150 375	150 375	1	1,900 150 375	150 375	1	1,900 150 375		
Custodian's Storage Recycling Room / Trash Receiving and General Supply Storeroom Network / Telecom Room	130 485 45	1 1 4	130 485 180				375 400 200 200 200		375 400 200 200 200	200	1 1 1 1 1	375 400 200 200 200	375 400 200 200 200	1 1 1 1 1	375 400 200 200 200		
THER Innovation Lab (Tech/Sci/Art)			0			0	1,000	1	1,000	1,000	1	1,000 1,000 E	Stor Cond		0		
Total Building Net Floor Area (NFA)			35,060			0			38,165			38,165			33,990		
Proposed Student Capacity / Enroliment												250			250	2	
Total Building Gross Floor Area (GFA) <sup>2</sup> Grossing factor (GFA/NFA)			55,200 1.57									57,248 1.50 F			45,000 1.32		
		+	1.57		÷	·†·····		÷				1.50			1.32		

#### <sup>1</sup> Individual Room Net Floor Area (NFA)

Includes the net square footage measured from the inside face of the perimeter walls and includes all specific spaces assigned to a particular program area including such spaces as non-communal toilets and storage rooms.

<sup>2</sup> Total Building Gross Floor Area (GFA)

Includes the entire building gross square footage measured from the outside face of exterior walls

Architect Certification

I hereby certify that all of the information provided in this "Proposed Space Summary" is true, complete and accurate and, except as agreed to in writing by the Massachusetts School Building Authority, in accordance with the guidelines, rules, regulations and policies of the Massachusetts School Building Authority to the best of my knowledge and belief. A true statement, made under the penalties of perjury.

 Name of Architect Firm:
 Flansburgh Architects

 Name of Principal Architects:
 Kent D. Kovace AIA

Name of Principal Architect: Kent D. Kovacs AIA
Signature of Principal Architect:

Date: 9-Dec-15

Version 11.24.2010 28.5

### Proposed Space Summary- Elementary School (K-4)

### DRAFT 1

Option 2-Bournedale					PROPOSE					DIVITI							
Bourne K-4	E	xisting Conc	ditions	Existi	ing to Remain/	Renovated		New			Total			(refe	er to MSBA		Guidelines gram & Space Standard Guidelines)
ROOM TYPE	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals		ROOM NFA <sup>1</sup>	# OF RMS	area totals	Comments
CORE ACADEMIC SPACES	19/2/12/2 19/1		22,690			22,690			14,400	102 0.87		37,090			32	31,900	
(List classrooms of different sizes separately) Bournedale																	
Pre-Kindergarten wi tollet Kindergarten wi tollet General Classrooms - Grade 1-4	1,130 1,130 Varies	4 4 16	4,520 4,520 13,650	1,130 1,130 853	4 4 16	4,520 4,520 13,650	1,200 900	3 12	3,600 10,800	1,130	4 7 28	4,520 8,120 24,450	в	1,200 1,200 950	6 26	- 7,200 24,700	1,100 SF min - 1,300 SF max 1,100 SF min - 1,300 SF max 900 SF min - 1,000 SF max
SPECIAL EDUCATION (List rooms of different sizes separately)	-		2,950			0			8,050			8,050				8,050	
Bournedale Self-Contained SPED (one is a dedicated PK)	670	1	670				950	5	4,750	950	5	4,750		950	5	4,750	8% of pop. in self-contained SPED
Self-Contained SPED - toilet Resource Room Small Group Room / Reading	1,680 600	Varies Varies	1,680 600				60 500 250	5 4 4	300 2,000 1,000	60 500 250	5 4 4	300 2,000 1,000		60 500 500	5 4 2	300 2,000 1,000	1/2 tizo Goni. Cirm.
ART & MUSIC			2,258	11.72.51.000		1,215			3,250			4,465				5,075	
Bournedale Art Classroom - 25 seats	1,015	1	1,015	1,015	1	1,015	1,000	1 1	1,000		2	2,015		1,000	2	2,000	assumed schedulo 2 times / wook / student
Art Workroom w/ Storage & kiln Music Classroom / Large Group - 25-50 seats Music Practice / Ensemble	200 918 125	1	200 918 125	200	1	200	100 1,000 75	1 2 2	100 2,000 150	1,000 75	2 2 2	300 2,000 150	DE	150 1,200 75	2 2 5	300 2,400 375	assumed schedule 2 times / week / student
HEALTH & PHYSICAL EDUCATION Bournedale	15 KAMILING		3,150			3,150			3,150			6,300				6,300	
Gymnasium Gym Storeroom Health Instructor's Office w/ Shower & Toilet	2,980 170	1	2,980 170	2,980 170	1	2,980 170	3,020 130	1	3,020 130			6,000 300		6,000 150 150	1	6,000 150 150	6000 SF Min. Sizo
MEDIA CENTER Bournedale			3,775			0	CALC: C		3,933	024923		3,933				3,933	
Media Center / Reading Room Computer	2,815 960	1	2,815 960				3,933	1	3,933	3,933	1	3,933		3,933	1	3,933	
DINING & FOOD SERVICE Bournedale			4,950			4,950	F-1,801 112		4,961	ESTRATE!		9,911				9,185	
Cafeteria / Dining Stage	2,200	1	2,200	2,200	1	2,200	3238 1000	1	3,238 1,000	1,000	4	5,438 1,000		5,438 1,000	1	5,438 1,000	2 seatings - 15SF per seat
Chair / Table / Equipment Storage Kitchen Staff Lunch Room	2,750	1	2,750	2,750	1	2,750	442 281	1	442 281	281	1	442 2,750 281	F	442 2,025 281	1 1 1	442 2,025 281	1600 SF for fint 300 + 1 SFretudent Add1 20 SF/Occupent
MEDICAL Bournedale			491	142		0			610			610		THE REAL PROPERTY.		610	
Bournease Medical Suite Toilet Nurses' Office / Walting Room Examination Room / Resting	56 245 190	1	56 245 190				60 250 100	1 1 3	60 250 300	60 250 100	1 1 3	60 250 300		60 250 100	1 1 3	60 250 300	
ADMINISTRATION & GUIDANCE	E Para Bar		1,460			0			2,711			2,711				2,710	
Bournedale General Office / Waiting Room / Toilet Teachers' Mail and Time Room Duplicating Room (w/ mail above) Records Room	50		500 220				513 250 110	1	513 250 0 110	51: 250 111	0 1 0:	513 250		513 100 150 110	1	513 100 150 110	
Principal's Office w/ Conference Area Principal's Secretary / Walting	15	0 1	150				375 125	5 1	375 125	37 12	5 1	375 125		375 125	1	375	
Assistant Principal's Office Supervisory / Spare Office	15		150				120 120	0: 1	120 120 120	120	0 1	120 120 120		120 120		123 120 120	
Conference Room Guidance Office	120	2	240			+	250 150		250 300	25		250 300		250 150	1	250 300	
Guidance Storeroom Teachers Work Room	20	0 1	200				35 513	1	35 513	35	1 1	35 513		35 513	1	35 513	
CUSTODIAL & MAINTENANCE Bournedale			1,158			0		The set	0	10112019		2,325				2,325	
Custodian's Office Custodian's Workshop	130	11	130			+	150 375	1		150	1	150		150	1	150	
Custodian's Storage Recycling Room / Trash	338	1	338			+	375 375 400	1.1		375 375	1	375 375		375 375	1	375 375	
Receiving and General Supply Storeroom	200 300	1	200 300				400 342 483	1		400 342	1	400 342		400 342		400 342	
Network / Telecom Room	190	<u> </u>	190				483 200	1		483 200	1	483 200		483 200	1	483 200	
OTHER Innovation Lab (Tech/Sci/Art)			0			0	1,000	1	<b>1,000</b> 1,000	1,000	1	1,000 1,000	G			0	
Total Building Net Floor Area (NFA)			42,882			32,005			42,065			76,395	1			70,088	
Proposed Student Capacity / Enrollment												725				725	
Bournedale GFA			68,100														
Total Building Gross Floor Area (GFA) <sup>2</sup>			68,100									114,593				105,125	
Grossing factor (GFA/NFA)			1.59									1.50				1.50	

<sup>1</sup> Individual Room Net Floor Area (NFA)

Includes the net square footage measured from the inside face of the perimeter walls and includes all specific spaces assigned to a particular program area including such spaces as non-communal toilets and storage rooms.

-----

<sup>2</sup> Total Building Gross Floor Area (GFA)

Includes the entire building gross square footage measured from the outside face of exterior walls

rchitect Certification

I hereby certify that all of the information provided in this "Proposed Space Summary" is true, complete and accurate and, except as agreed to in writing by the Massachusetts School Building Authority, in accordance with the guidelines, rules, regulations and policies of the Massachusetts School Building Authority to the best of my knowledge and belief. A true statement, made under the penalties of perjury. Name of Architect Firm: Flansburgh Architects

Name of	Principal Arc	hitect: Kent	D. Kovacs AIA

16 Signature of Principal Architect:

Date: 12/9/15

Version 11.24.2010

### Proposed Space Summary- Elementary School (K-5)

### DRAFT 1

Option 3-Bournedale							1									
Bourne K-5	E	xisting Cond	itions	Existin	ng to Remain/I	Renovated		New			Total		(r	efer to MSBA	MSBA Educational Pro	Guidelines gram & Space Standard Guidelines
ROOM TYPE	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	Comments
ORE ACADEMIC SPACES (List classrooms of different sizes separately)	a a cardina		22,690			22,690		1	20,700	4-170 12		43,390		38	37,850	
Bournedale Pre-Kindergarten w/ toilet	1,130	A	4,520	1,130	4	4,520				1,130	4	4,520 A	1,200			
Kindergarten w/ toilet General Classrooms - Grade 1-4	1,130 Varies	4 16	4,520 13,650	1,130 853	4 16	4,520 4,520 13,650	1,200 900	3 19	3,600 17,100	1,130	4 7 35	4,520 A 8,120 B 30,750 C	1,200 1,200 950	7 31	8,400 29,450	1,100 SF min - 1,300 SF max 1,100 SF min - 1,300 SF max 900 SF min - 1,000 SF max
PECIAL EDUCATION (List rooms of different sizes separately)			2,950			0			9,060			9,060	(CPO)		9,060	
Bournedale Self-Contained SPED (one is a dedicated PK)	670	1	670				950	6	5 700	050	6	5 700				
Self-Contained SPED - tollet Resource Room	1,680	Varies	1,680				60 500	6	5,700 360	950 60	6	5,700 360	950 60	6 6	360	8% of pop. in self-contained SPED
Small Group Room / Reading	600	Varies	600				250	4	2,000 1,000	500 250	4	2,000 1,000	500 500	4	2,000 1,000	
RT & MUSIC Bournedale	100000000		2,258			1,215			4,475			5,690			6,300	
Art Classroom - 25 seats Art Workroom w/ Storage & kiln	1,015 200	1	1,015 200	1,015 200	1	1,015 200	1,000 125	2	2,000 250		3	3,015 450	1,000	3	3,000	assumed schedule 2 times / week / student
Music Classroom / Large Group - 25-50 seats Music Practice / Ensemble	918 125	1	918 125		, 	200	1,000 75	2 3	2,000 225	1,000 75	2 3	2,000 D 225 E	150 1,200 75	3 2 6	450 2,400 450	assumod schodulo 2 timos / wook / student
ALTH & PHYSICAL EDUCATION Bournedale			3,150	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	10.38.33	3,150		8000	3,150			6,300	(ndeed))		6,300	
Gymnasium Gym Storeroom	2,980 170	1-1	2,980 170	2,980 170	1	2,980 170	3,020 130	1	3,020 130			6,000 300	6,000 150	1	6,000 150	6000 SF Min. Sizo
Health Instructor's Office w/ Shower & Toilet												300	150	1	150	
EDIA CENTER Bournedale			3,775			0			4,653			4,653	I ALLOW		4,653	
Media Center / Reading Room Computer	2,815 960	1 1	2,815 960				4,653	1	4,653	4,653	1	4,653	4,653	1	4,653	
NING & FOOD SERVICE Bournedale			4,950			4,950			6,254			11,204			10,639	
Cafeteria / Dining Stage	2,200	1	2,200	2,200	1	2,200	4438 1000	1	4,438 1,000	1,000	1	6,638 1,000	6,638 1,000	1	6,638 1,000	2 soalings - 15SF por soal
Chair / Table / Equipment Storage Kitchen Staff Lunch Room	2,750	1	2,750	2,750	1	2,750	495 321	1	495 321	495 321	1	495 2,750 F 321	495 2,185 321	1	495 2,185 321	1600 SF for first 300 + 1 SF/student Add1 20 SF/Occupant
EDICAL Bournedale			491			0			710			710			710	
Medical Suite Toilet Nurses' Office / Walting Room Examination Room / Resting	56 245 190	1	56 245				60 250	1 1	60 250	60 250	1	60 250	60 250	1	60 250	
Examination Room / Resung	190		190				100	4	400	100	4	400	100	4	400	
DMINISTRATION & GUIDANCE Bournedale			1,460			0			3,021			3,021			3,020	
General Office / Waiting Room / Toilet Teachers' Mail and Time Room	500	1	500				593 250		593 250	593 250		593	593	1	593	
Duplicating Room (w/ mail above) Records Room	220	1	220				110	1	0		0	250	100 150	1	100 150	
Principal's Office w/ Conference Area Principal's Secretary / Walting	150	1	150				375	1	110 375	110 375	1	110 375	110 375	1	110 375	
Assistant Principal's Office Supervisory / Spare Office	150		150				125 120 120	1	125 120	125 120 120	1	125 120	125 120	1	125 120	
Conference Room Guidance Office	120	2	240				120 250 150		250	120 250 150		120 250	120 250	1	120 250	
Guidance Storeroom Teachers' Work Room	200	1	240				35 593	1	450 35	35	3	450 35	150 35	3 1	450 35	
	200		200				393	1	593	593		593	593	1	593	
USTODIAL & MAINTENANCE			1,158			0			2,485			2,485			2,485	
Bournedale Custodian's Office	130	1	130				150	1	150	150	1	150	150	1	150	
Custodian's Workshop Custodian's Storage	338	1	338				375 375	1	375 375	375 375	1	375 375	375 375	1	375 375	
Recycling Room / Trash Receiving and General Supply	200	1	200				400 395	1	400 395	400 395	1	400 395	400 395	1	400 395	
Storeroom Network / Telecom Room	300 190	1	300 190				590 200	1	590 200	590 200	1	590 200	590 200	1	590 200	
THER Innovation Lab (Tech/Sci/Art)			0			0	1.000		1,000			1,000			0	
Total Building Net Floor Area (NFA)			42,882		ļ	00.007	1,000	<u> </u>	1,000	1,000	1	1,000 G				
Proposed Student Capacity / Enrollment			42,862		ļ	32,005		<u>.</u>	55,508			87,513			81,016	
Bournedale GFA		÷	68,100					<u>.</u>							885	
Total Building Gross Floor Area (GFA) <sup>2</sup>			0 68,100									131,382			128,325	
Grossing factor (CCANICA)		÷			<u> </u>											
Grossing factor (GFA/NFA)		+	1.59					+			·	1.50 H			1.58	

#### <sup>1</sup> Individual Room Net Floor Area (NFA)

rchitect Certification

Includes the net square footage measured from the inside face of the perimeter walls and includes all specific spaces assigned to a particular program area including such spaces as non-communal tollets and storage rooms.

-----

<sup>2</sup> Total Building Gross Floor Area (GFA)

Includes the entire building gross square footage measured from the outside face of exterior walls

I hereby certify that all of the information provided in this "Proposed Space Summary" is true, complete and accurate and, except as agreed to in writing by the Massachusetts School Building Authority, in accordance with the guidelines, rules, regulations and policies of the Massachusetts School Building Authority to the best of my knowledge and belief. A true statement, made under the penalties of perjury.

Name of Ar	chitect Firm:	Flansburgh Architects

Name of Principal Architect: Kent D. Kovacs AIA Signature of Principal Architect:

Date: 12/9/15

Version 11.24.2010

### Proposed Space Summary- Elementary School (K-5)

### DRAFT 1

Option 4- Peebles				PROPOSED												
Bourne K-5	E	xisting Cond	itions	Existi	Existing to Remain/Renovated New								MSBA Guidelines (refer to MSBA Educational Program & Space Standard Guid			
ROOM TYPE	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totais	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	ROOM NFA <sup>1</sup>	# OF RMS	area totals	Comments
DRE ACADEMIC SPACES			20,300	1991 1991		0			20,700			20,700	310 (a) es	18	17,850	
(List classrooms of different sizes separately) Pre-Kindergarten w/ toilet		+						÷					1,200			
Kindergarten w/ toilet	950	2	1,900		1		1,200	3	3,600	1,200	3	3,600	1,200	3	3,600	1,100 SF min - 1,300 SF max 1,100 SF min - 1,300 SF max
General Classrooms - Grade 1-4	VARIES	20	18,400				900	19	17,100	900	19	17,100 A	950	15		900 SF min - 1,000 SF max
PECIAL EDUCATION		10100	1,805	THE PARTY NO.		0	10.1/10 IN 10.8		4,530	The second second		4,530		-	4,530	
(List rooms of different sizes separately)		1							4,000			4,550			4,530	
Self-Contained SPED Self-Contained SPED - toilet	935		935				950 60	3	2,850	950	3	2,850	950	3	2,850	8% of pop. in self-contained SPED
Resource Room	870	1	870			÷	500	2	180 1,000	60 500	2	180 1,000	60 500	3	180 1,000	1/2 sizo Goni, Cirm.
Small Group Room / Reading						1	500	ī	500	500	1	500	500	1	500	1/2 size Geni, Cirm.
RT & MUSIC			1,325			0		:								
Art Classroom - 25 seats	800	1	800			0	1,000	1	2,300	1,000	1 1	2,300	1,000	1	2,575	assumed schedule 2 times / week / student
Art Workroom w/ Storage & kiin		1					150	1	150	150	1	150	150	1	150	and a chouse a times / wook / sludent
Music Classroom / Large Group - 25-50 seats Music Practice / Ensemble	525	1	525		ļ		1,000	1	1,000	1,000	1	1,000 B	1,200	1	1,200	assumed schedule 2 times / week / student
							75	4	150	75	2	150 C	75	3	225	
EALTH & PHYSICAL EDUCATION			3,100			0			6,300			6,300	San Harden	10.00	6,300	
Gymnasium Gym Storeroom	3,100	1	3,100				6,000 300	1	6,000 300	6,000 300	<u>1</u> i	6,000 300	6,000		6,000	6000 SF Min. Sizo
Health Instructor's Office w/ Shower & Toilet							300	·····	300	300	+l	300	150 150	····-	150 150	
					1									· · · · · · · · · · · · · · · · · · ·		
EDIA CENTER Media Center / Reading Room	730	1	730 730			0	2,515	1	2,515	2,515		2,515 2.515	2,515		2,515	
NING & FOOD SERVICE	100	1	5,550	Augura concern		0	2,010	; 1	6,325	2,515		2,515 6,325	2,515	1	2,515 6,324	Contraction of the Contraction of the
Cafeteria / Dining	4,100	1	4,100				3,075	1	3,075	3,075	1	3,075	3,075	: 1	3,075	2 seatings - 15SF per seat
Stage Chair / Table / Equipment Storage					ļ		1,000 337	1	1,000 337	1,000 337	1	1,000 337	1,000	1	1,000	
Kitchen	1,100	1	1,100				1,710	+	1,710	1,710		1,710	337 1,710	1 1	337 1,710	1600 SF for first 300 + 1 SF/student Add'l
Staff Lunch Room	350	1	350				203	1	203	203	1	203	203	1	203	20 SF/Occupant
EDICAL			260			0			510			510		1		
Medical Suite Toilet							60	1	60	60	1	510	60	1	510 60	
Nurses' Office / Waiting Room Examination Room / Resting	260	1	260		ļ		250 100	1	250	250	1	250	250	1	250	
Examination Room? Resting		+					100	÷	200	100	2	200	100	2	200	
DMINISTRATION & GUIDANCE	1010116124		1,195			0		Concesses	2,125		La suesti	2,125	500.502		2,125	
General Office / Walting Room / Toilet Teachers' Mail and Time Room	270	1	270				355	5: 1	355 250	355	1	355 250	355	1	355	
Duplicating Room							230		250	200		250	100	·····	100 150	
Records Room Principal's Office w/ Conference Area		Vabies			ļ		110		110	110	1	110	110	1	110	
Principal's Secretary / Waiting		VARIES	600				375 125		375 125	375 125		375 125	375 125	1	375 125	
Assistant Principal's Office		1			1						1		120	0	-	
Supervisory / Spare Office Conference Room					ļ		120 250		120 250	120 250		120	120	1	120	
Guidance Office		+			·		150	1	150	150		250 150	250 150	1 1	250 150	
Guidance Storeroom Teachers' Work Room	325		325		[		35	1	35	35	1	35	35	1 1	35	
reachers work Room	325	- 1	325				355	+1	355	355	1	355	355		355	
ISTODIAL & MAINTENANCE			795	101-914-62		0	to state of		2,010	SALTINO DES		2,010			2,010	
Custodian's Office Custodian's Workshop					ļ		150	1	150	150	1	150	150	1	150	
Custodian's Storage		+			<u> </u>		375 375	÷	375 375	375 375	1	375 375	375 375	· · · · · · ·	375 375	
Recycling Room / Trash		1			\		400	<u>† 1</u>	400	400	1	400	400	· · · · · ·	400	
Receiving and General Supply Storeroom	130 485	1	130 485				237 273	1	237 273	237 273	1	237	237	1	237	
Network / Telecom Room	465	4	485				2/3	+	273	273	1 1	273 200	273 200	1 1	273 200	
					1	1		1						1	200	
HER Innovation Lab (Tech/Sci/Art)			0			0	1,000	1	<b>1,000</b> 1,000	1,000	1	1,000 1,000 D	Con March 19		0	
Total Building Net Floor Area (NFA)			35,060			0		+	48,315			48,315			44,739	
						1		1			1					
Proposed Student Capacity / Enrollment												410			410	
Total Building Gross Floor Area (GFA) <sup>2</sup>			55,200					÷				72,473		· <del>}</del> · · · · · · · · · ·	68,538	
					1			1						+		
Grossing factor (GFA/NFA)		1	1.57		1	1		1		1	1	1.50 E			1.53	

### <sup>1</sup> Individual Room Net Floor Area (NFA)

Includes the net square footage measured from the inside face of the perimeter walls and includes all specific spaces assigned to a particular program area including such spaces as non-communal toilets and storage rooms.

244

<sup>2</sup> Total Building Gross Floor Area (GFA)

Includes the entire building gross square footage measured from the outside face of exterior walls

Architect Certification

I hereby certify that all of the information provided in this "Proposed Space Summary" is true, complete and accurate and, except as agreed to in writing by the Massachusetts School Building Authority, in accordance with the guidelines, rules, regulations and policies of the Massachusetts School Building Authority to the best of my knowledge and belief. A true statement, made under the penalties of perjury. Name of Architect Firm: Flansburgh Architects 

Name of Principal Architect: Kent D. Kovacs AIA Signature of Principal Architect:

Date: 12/9/15

Version 11.24.2010

B. Variance between Program and MSBA Guidelines

### 3.1.3 Initial Space Summary

### B. NARRATIVE FOR VARIANCE BETWEEN PROGRAM AND MSBA GUIDELINES

Throughout the early PDP phase, the design team has conducted bi-weekly Educational Design meetings with district to advance the educational program. Discussions of best practice and optimal use with the Superintendent, Principals, directors, and school staff contributed to the understanding of program requirements and space allocation. The following proposed variations to the MSBA space template are a result of those conversations.

Please find attached the draft space templates for the 250 enrollment (Opt. 1), 725 enrollment (Opt. 2), 885 enrollment (Opt. 3), 410 enrollment (Opt. 4), with noted variations noted per option below.

### Opt. 1 - K4 w/ 250 enrollment

**A:** Kindergarten - One additional classroom over the template. *This accommodates the required 3 classrooms to maintain balance with the upper grade student population* 

**B**: General Classrooms - Three additional general classrooms are provided over the template. *This accommodates the required 3 classrooms per grade 1 through 4.* 

C: Music Classroom – Reduce from 1,200 sf to 1,000sf

**D:** Music Practice – Reduce from two practice rooms to one practice room

**E:** Innovation Studio – One classroom at 1,000sf. *The innovation lab is a fully equipped MakerSpace where students in grades K-12 can explore, build, design, and innovate using low and high tech tools. This is a current elementary school program.* 

**F:** Grossing Factor – A grossing factor of 1.50 has been applied to the net square footage. *This is a reasonable factor for this project to accommodate walls, building infrastructure, toilets, circulation, and other non-programed areas.* 

### Opt. 2 - K4 w/ 725 enrollment

A: Pre-Kindergarten – Four current classrooms to remain totaling 4,520 sf

**B**: Kindergarten - One additional over the template. *This accommodates the required 7 classrooms to maintain balance with the upper grade student population* 

**C:** General Classrooms - two additional general classrooms over the template. *This accommodates the required 7 classrooms per grade 1 through 4.* 

**D:** Music Classroom – Reduce both music classrooms from 1,200 sf to 1,000sf for a total reduction of 400 sf.

E: Music Practice – Reduce from five practice rooms to two practice room

F: Kitchen – The existing kitchen is 2,750 sf resulting in 725 sf over the template.

**G:** Innovation Studio - This a current elementary school program to be incorporated. *Refer to above for description* 

### Opt. 3 - K5 w/ 885 enrollment

A: Pre-Kindergarten - The 4 current classrooms to remain totaling 4,520 sf

**B**: Kindergarten – there is a reduction in square footage due to the constraints of the existing space

**C:** General Classrooms - four additional general classrooms over the template. *This accommodates the required 7 classrooms per grade 1 through 5.* 

**D:** Music Classroom – Reduce both music classrooms from 1,200 sf to 1,000sf for a total reduction of 400 sf.

**E:** Music Practice – Reduce from six practice rooms to three practice rooms

F: Kitchen – The existing kitchen is 2,750 sf resulting in 725 sf over the template.

K: Innovation Studio - This a current elementary school program to be incorporated. *Refer to above for description* 

**F:** Grossing Factor – A grossing factor of 1.50 has been applied to the net square footage. *This is a reasonable factor for this project to accommodate walls, building infrastructure, toilets, circulation, and other non-programed areas.* 

### B. NARRATIVE FOR VARIANCE BETWEEN PROGRAM AND MSBA GUIDELINES

### Opt. 4 - K5 w/ 410 enrollment

**A:** General Classrooms - Four additional general classrooms are provided over the template. *This accommodates the required 3 classrooms per grade 1 through 4. Grade 5 accommodates the required 7 classrooms* 

B: Music Classroom – Reduce from 1,200 sf to 1,000sf


**C:** Music Practice – Reduce from two practice rooms to one practice room

**D**: Innovation Studio – One classroom at 1,000sf. The innovation lab is a fully equipped MakerSpace where students in grades K-12 can explore, build, design, and innovate using low and high tech tools. This is a current elementary school program.

**E:** Grossing Factor – A grossing factor of 1.50 has been applied to the net square footage. *This is a reasonable factor for this project to accommodate walls, building infrastructure, toilets, circulation, and other non-programed areas.* 

<u>General:</u> The preliminary programs are "idealized" at this stage. When various options for renovation/ addition and new construction are designed, these square footages will vary according to the existing building configurations and grossing factor efficiency.





**Peebles Elementary School** Bourne, Massachusetts

# **Flansburgh** Architects




## 55,190 SF TOTAL BUILDING GROSS AREA:

- 35,165 SF TOTAL BUILDING NET AREA:
- 795 SF
- 1,195 SF
- 260 SF
- 5,550 SF
- 975 SF

3,100 SF

- 730 SF
- 1,325 SF
- 20,300 SF 935 SF
- PEEBLES ELEMENTARY SCHOOL



**Bournedale Elementary School** Bourne, Massachusetts

# **Flansburgh** Architects



- 42,947 SF 68,100 SF
- 1,158 SF
- 1,460 SF
- 491 SF
- 5,015 SF

2,258 SF

- 2,815 SF 960 SF
- PHYSICAL EDUCATION 3,150 SF
- 2,950 SF
- 3,390 SF 22,700 SF

# 3.1.4 Evaluation of Existing Conditions

- A. Property Title
- B. Statement that Property can be Developed
- C. Historical Impacts on Property
- D. Determination of Development Restrictions
- E. Existing Conditions Reports
- F. Code Evaluation
- G. MAAB/ADA Evaluation
- H. Proposed Soils Exploration
- I. Traffic Impact Study
- J. Phase I ESA
- K. Hazardous Materials Assessments




ORDERED by the Board of Berealmen of the Tota of Bourne, that there is false by dwinent domain on behalf of said town four parcels of land in that part of said town known as Bourne Village, bounded and described as follows (1) Beginning at a cement bound on the South Easterly side of county way known as Trowbridge Road at a point where the southwesterly boundary of land of David O. Handy intersects the south-easterly boundary of said Trowbridge Road and thence running south 59°-54'-20" East to a point at the dividing line of land of said Handy and land of Richard B. and Georgetta Nye Materhouse 329.99 Test; thence running south 59°-54'-20" gast by land of said Waterhouse to the Westerly boundary of MacArthur Boulevard, also known as Route 28 and 329:99 feet; thence running south 59°-541-20" gast by land of said Waterhouse to the Westerly boundary, of MacArthur Boulevard, also known as Route 28 and as the State Highway, 1630.31 feet; thence turning and running south 1094061-10" East by said MacArthur Boulevard to remaining land of Estate of Laurence B. Jackson by two bounds, 272.65 feet and 367.36 feet respectively; thence turning and running North 610-21'-25" West byremaining land of said Jackson, 305.
07 feet; thence turning and running South 280-171-10" West again by land of Jackson, 244.15 feet to land of Freston L and Katherine M. Blackwell; thence turning and running south 280-171-10" West again by the northerly boundary of land of Preston L. and Katherine M. Blackwell; thence turning north 53°-131-20" West by sold land of Young Northeasterly and easterly by said Cotuit Road, and sold thence running north 63°-56'-j5" East by said thence running north 63°-56'-j5" East by said thence running north 63°-56'-j5" East by said Troybridge Road 403.35 feet to the roint of beginning. Boing the thence running north 63°-56'-j5" East by said Troybridge Road 403.35 feet to the roint of beginning. Boing the state of Laurence B. Jackson" on a plan entitled "Fian of Land To Be Acquired By The Town of Bourns in Bourns Village" dated Cotober 15, 1952; Nawell B. Show. Englight :12. 800 Ë Ь of Land To Be Acquired By The Town of Bourne in Bourne Village" dated Cotober 15, 1952, Newell Be Show, Engineer to be necorded herewith. 3 (2) Also, a ceptain parcel of land shown on said plan as a lot containing 2.4% acres more or loss and being bounded and described as shown on said plan as follows Northensterly by land of said Richard B. and Georgetta Nys Waterhouse by a line running South 590-531-200 East 390.81 fest; Southerly by said Trowbridge Road by two bounds 354.60 fest and 143.01 feet respectively; Southwesberly by a curved line at the intersection of said Trowbridge Þ 6 Р ť Hold and said Uctvit Hoad with an ard with a radius of 50 feet, 121.59 fest; Westerly by said Cotuit Road 225.74 feet; and Northwesterly by land of Harold L. and Marie D. Czarnetzki by three bounds running North 640-564-555 Horth 340-551-05" East 56.36 feet. ט (3) Also, a certain triangular parcel of land shown as lot "G" on said plan, situated on the Northerly side of said Trowbridge Road and bounded and described as shown on said plan Southerly by said Trowbridge Road 52 feet more or less; Westerly by land of Heirs of Mercy E. MoDermot 66 feet more or less; and Northeasterly by land marked on said plan "Ordello R. Swift to Town of Bourne-1920 Book 137" F. 159", 75 feet more or less.

peer L's

(A) Also, a certain parcel of Land shown as lot due of said plan, situated at the Mesterly corner of said Corject fond and Frowbridge Hoss, and Founded and described as separate plan as follows: 835

Easterly by a curved line at the junction of said roads with a radius of 36.46 feet, 86.47 feet; South-easterly by said Cotuit Road 2.32 feet; Southwesterly by land of Bassett by a line running North 580-131 20" west 54.41 feet; and Rorthwesterly by land of said Bassett by a line running North 230-171-35" East 34.31 feet. 835 458 The trace and bulldings, if any, on said parcels one SITNESS the heads of the Selecturen and the seal no this 2nd day to March , 19 Cove of Browns the 181 01 185 1983 THAN 18 3 Water and the second second second second 2 Soleo Man SI Ben 4 .... 1994 Barnstable, ss., Received March 3, 1953, and is recorded. OFDER OF TAKENS AND INLAD OF DAMAGES WITE 2 the Bornd of Selectmen of the fown of Bourne file on the Self day of October, 1972 lay out as from weys the ways known as Belance of Fower Lane to Schweit Lone and the way to share off Schweit Lone; Bay Drive from Fower Lane to Fier Bord and also remainder of Fier Road; way to share off Fier Road in seid town, and 102 WEREAS said Totr of Yourns, at a maeting duly called and worned for the purpose held on the 6th day of Fobru-ry, 1955 did accept said laying out and did authorize the Selectmen of said form to dequire by purchase or to take by eminent domain the land necessary for the location thereof, and did make an appropriation of money for the purpose of said purchase or taking, and did make provision for raising the same, and d) WHERE'S all of the other prelitingry requirements prescribed by law have been complied with, it is ¢ ORDERED that there be, and there hereby is, taken by eminent donain on behalf of the Town of Bourne a parcel of Land in said Town bounded and described as follows: ð the Town of Source & percel of Land in said Town bounded
as follows:
"Beginning at a point on the northwesterly line of Lot 233 as shown on a plan entitled "Town of Bourne, Roads in Taylors Point Shores, Buzzards Bay, Lsid out as Town Ways By the Selectmen, one hundred Sect to an inch, December 1952 213.96 feet; thence by a curve to the right of 224.46 feet thence by a curve to the left of 291.61 feet radius, 171.27 feet; thence 5 630-551-567 W, 70.00 fset; thence by a curve to the left of 291.61 feet radius, 150.97 ourve to the right of 260.58 feet radius, 220.37 feet; thence 5 620-431-404 W, 420.00 feet; thence by a curve to the left of 171.57 feet radius, 100.78 feet; thence 'S 490-041-200" W, 37.21 feet; thence S 400-041-200" W, 100.69 feet; thence S 400-041-200" Hence N 102-551-404 W, along lots 184 and 183, 140.00 feet; Thence N 102-551-404 W, along lots 184 and 183, 140.00 feet; Thence N 102-551-404 W, along lots 184 and 183, 140.00 feet; Thence by same course 240 feet more of left to mean logy And the second s the 1.1.1 2 1:



# Bk:10741-347 25379 05-09-1997 P 11:31

# COMMONWEALTH OF MASSACHUSETTS LAND COURT

# DEPARTMENT OF THE TRIAL COURT

Case No. 106810 T.L.

(SEAL)

Bourneda

# FINAL JUDGMENT IN TAX LIEN CASE

Town of Bourne

vs.

George E. Williams, Jr. and John J. Williams, Trustees of the Canalscape Partnership Realty Trust

#### JUDGMENT

This case came on to be heard and was argued by counsel, and thereupon, upon consideration thereof, it is

ADJUDGED and ORDERED that all rights of redemption are forever foreclosed and barred under the deed

given by	y the Collector of Taxes fo	or the Town		,
of	Bourne	in the County of	Barnstable	
and said Commonwealth, dated		August 29, 1994		and duly recorded in
Book	9340	Page	240	

By the Court (Trombly, Recorder)

Attest:

Dated March 13, 1997

n herein Caller

Jeanne M. Maloney DEPUTY Recorder

dm

A TRUE OOPM m. Maloney

BARNSTABLE REGISTRY OF DEEDS

DEPUTY RECORDER

(SEAL)

### 8k:10529-295 71302 12-18-1996 @ 10:31

# COMMONWEALTH OF MASSACHUSETTS LAND COURT DEPARTMENT OF THE TRIAL COURT

Case No.

Divon La de Out

104765 T.L.

# FINAL JUDGMENT IN TAX LIEN CASE

Town of Bourne

**VS**.

T. N. Paul Inc.

#### JUDGMENT

This case came on to be heard and was argued by counsel, and thereupon, upon consideration thereof, it is

ADJUDGED and ORDERED that all rights of redemption are forever foreclosed and barred under the deed

given by m	e Collector of Taxes fo	or the Town		
of	Bourne	in the County of	Barnstable	
and said Commonwealth, dated		September 14, 1989		and duly recorded in
Book	6880	Page	47	

By the Court (Trombly, Recorder)


Attest:

Dated November 8, 1996

Jeanne M. Maloney DEPUTY Recorder

dm

A TRUE COPY ATTEST: "BARNSTABLE REGISTRY OF DEEDS



#### B. STATEMENT THAT THE PROPERTY CAN BE DEVELOPED

#### Peebles Elementary School Site:

The Town of Bourne owns the land and school facilities known as Bourne High School at 75 Waterhouse Road, Bourne Middle School at 77 Waterhouse Road, Peebles Elementary School at 70 Trowbridge Road. The property is available for development of a renovated or new school since there would be no change in the existing use.

#### **Bournedale Elementary School Site:**

The Town of Bourne owns the land and school facilities known as Bournedale Elementary School at 41 Ernest Valeri Road. The property is available for development of a renovated or new school since there would be no change in the existing use.

C. Historical Impacts on Property

#### C. HISTORICAL IMPACTS ON THE PROPERTY

#### Peebles Elementary School Site:

The school site and existing school building have no known historic registrations. In addition, the areas surrounding the school's site along Trowbridge Road are not in a designated Historic District.

Refer to attached letter from the Massachusetts Historical Commission confirming no further review of this site is necessary.

#### Bournedale Elementary School Site:

The school site and existing school building have no historic registrations. In addition, the areas surrounding the school's site along Ernest Valeri Road are not in a designated Historic District.

Refer to attached letter from the Massachusetts Historical Commission confirming no further review of this site is necessary.



# The Commonwealth of Massachusetts William Francis Galvin, Secretary of the Commonwealth Massachusetts Historical Commission

December 14, 2015

Kent Kovacs Flansburgh Architects 77 North Washington Street, 6<sup>th</sup> Floor Boston, MA 02114

RE: Peebles Elementary School, 70 Trowbridge Road, Bourne, MA; MHC# RC.59180

Dear Mr. Kovacs:

Thank you for submitting a Project Notification Form (PNF) for the project referenced above, which was received at this office on November 18, 2015. The staff of the Massachusetts Historical Commission (MHC) have reviewed the information submitted and have the following comments.

The proposed project consists of either the demolition or the rehabilitation of the existing James F. Peebles Elementary School at 70 Trowbridge Road in Bourne. The information provided indicates that the project will use funding from the Massachusetts School Building Authority (MSBA).

Review of MHC's files indicates that the Peebles Elementary School is not included in MHC's Inventory of Historic and Archaeological Assets of the Commonwealth, nor listed in the National and State Registers of Historic Places. No further review by the MHC is required for the MSBA-funded project.

These comments are offered to assist in compliance with Massachusetts General Laws, Chapter 9, Sections 26-27C, as amended by Chapter 254 of the Acts of 1988 (950 CMR 71.00). Please do not hesitate to contact Linda Santoro of my staff, should you have any questions.

Sincerely,

Buna Brona Simon

State Historic Preservation Officer Executive Director Massachusetts Historical Commission

220 Morrissey Boulevard, Boston, Massachusetts 02125 (617) 727-8470 • Fax: (617) 727-5128 www.sec.state.ma.us/mhc



The Commonwealth of Massachusetts

William Francis Galvin, Secretary of the Commonwealth Massachusetts Historical Commission

December 14, 2015

Kent Kovacs Flansburgh Architects 77 North Washington Street, 6<sup>th</sup> Floor Boston, MA 02114

#### RE: Peebles Elementary and Bournedale Elementary School Consolidation, 41 Ernest Valeri Road, Bourne, MA; MHC# RC.59181

Dear Mr. Kovacs:

Thank you for submitting a Project Notification Form (PNF) for the project referenced above, which was received at this office on November 18, 2015. The staff of the Massachusetts Historical Commission (MHC) have reviewed the information submitted and have the following comments.

The proposed project consists of the expansion of the existing Bournedale Elementary School at 41 Ernest Valeri Road in Bourne. The information provided indicates that the project will use funding from the Massachusetts School Building Authority (MSBA).

Review of MHC's files indicates that the Bournedale Elementary School is not included in MHC's Inventory of Historic and Archaeological Assets of the Commonwealth, nor listed in the National and State Registers of Historic Places. No further review by the MHC is required for the MSBA-funded project.

These comments are offered to assist in compliance with Massachusetts General Laws, Chapter 9, Sections 26-27C, as amended by Chapter 254 of the Acts of 1988 (950 CMR 71.00). Please do not hesitate to contact Linda Santoro of my staff, should you have any questions.

Sincerely,

Brona Simon State Historic Preservation Officer Executive Director Massachusetts Historical Commission

220 Morrissey Boulevard, Boston, Massachusetts 02125 (617) 727-8470 • Fax: (617) 727-5128 www.sec.state.ma.us/mhc D.

Determination of Development Restrictions

#### D. DETERMINATION OF DEVELOPMENT RESTRICTIONS

#### **Peebles Elementary School:**

The desired location for the proposed building is adjacent to the current school building. It has been determined wetlands and the floodplain locations are not in the areas of the proposed work. The buildable site is limited by topography. The building will have to conform to the relevant zoning and land use rules and regulations that currently exist on the property.

#### **Bournedale Elementary School:**

The desired location for the proposed building is adjacent to the current school building. It has been determined wetlands and the floodplain locations are not in the areas of the proposed work. The buildable site is limited by topography to the east and west and by the septic leaching field to the south. The building will have to conform to the relevant zoning and land use rules and regulations that currently exist on the property.



# Existing Conditions Report

Peebles Elementary School

- A. Executive Summary
- B. Detailed Report
  - 1. Landscape
  - 2. Civil
  - 3. Architectural
  - 4. Structural
  - 5. HVAC
  - 6. Electrical
  - 7. Plumbing
  - 8. Fire Protection
  - 9. Furniture & Equipment
  - 10. Technology
  - 11. Hazardous Materials

# A. Executive Summary: Peebles Elementary School

#### General Overview

Peebles Elementary School has been well maintained; however, most of it is over 62 years old and is in need of significant work. Although structurally sound, the systems and finishes have reached the end of their useful life. Some of the more significant issues are lack of a fire sprinkler system, no insulation or cavity in the exterior walls, numerous handicap accessibility problems, several code issues, and asbestos in several locations that will need to be abated. The requirements to meet current codes will impact all spaces and effectively require a full renovation of the school to achieve compliance.

Upon the selection of a preferred option, additional testing and investigations will be required to further evaluate the existing conditions of the building and site.

The following additional investigations are anticipated:

- Catch basin and drainage structure inspection
- Grease trap inspection
- Structural investigation/testing of 1959 building (as there are no sufficient drawings available)
- Hydrant flow test
- Interior drainage and pipe inspection
- Brick tie investigation
- Roof cuts to determine roofing components and thicknesses
- Infrared roof scan
- Additional destructive testing for hazardous materials
- Additional Geotechnical test pits/borings

Working in conjunction with the Town of Bourne, Flansburgh Architects has prepared this existing conditions report. This report considers the quality and anticipated life of the physical plant of the school, the building's interior and exterior building components, play areas and site features, structural systems, mechanical/ electrical/plumbing systems, and technology infrastructure. The findings of this report will assist in finalizing the scope of the preferred option and assure that systems and materials left in place are sound and appropriate for the school's anticipated life. The process involved a physical survey of the buildings by the following qualified architects and engineers:

- Flansburgh Architects Architectural
- Garcia, Galuksa & DeSousa Mechanical, Plumbing, Electrical
- Boston Building Consultants Structural Engineers
- Nitsch Engineering Site/Civil
- Edvance Technology Consultants
- Waterman Design Landscape
- Tavares Design Equipment and Food Service Consultant
- Fuss & O'Neill Hazardous materials consultant

#### 1. LANDSCAPE/ SITE DESIGN

The existing vehicular and pedestrian circulation systems will require redesign to accommodate the design intent of the new facility and to reduce existing bus and car traffic congestion. Pavement and walkways require replacement due to their condition and improvements are required for handicapped accessibility and parking.

Exterior lighting, courtyards, site furnishings, site vegetation, and athletic fields need further review and discussion of how they are used and what improvements will be needed.

#### 2. CIVIL

#### Storm Water

The drainage system is minimal at best and water sheet flows into surrounding areas. A new storm water system is required to meet today's standards. Existing structures to remain will need to be inspected and any drain lines to remain should be cleaned.

#### <u>Water</u>

Existing exterior water lines for domestic use may remain, but this needs further review. A new water line for fire protection will be required to service the building.

#### <u>Sewer</u>

The existing waste water flows into the existing waste water treatment plant. Further investigation will be required to assure the combined flows are not exceeded.

#### <u>Natural Gas</u>

The recent moratorium on installing a new gas line into the school will be reviewed; confirmation will be necessary to ensure the pressure and flow will be adequate to accommodate a new facility from the existing gas line.

#### Permitting Considerations

Any expansion and renovation disturbing more than one acre will require a permit by the United States Environmental Protection Agency's National Pollution Discharge Elimination Systems Program.

#### 3. ARCHITECTURAL

Overall the building systems are in fair to poor condition, and are nearing the end of their useful life. The requirements to meet current codes will impact all spaces and effectively require a full renovation of the school to achieve compliance.

#### Exterior Wall

The exterior envelope is in fair condition. Some cracking and spalling of masonry components are evident. Under the current energy standards, the R-Value of the exterior wall is very low. Options need to be explored to increase the R-Value to meet today's standards. Increasing the exterior wall R-Value will reduce the size of the HVAC system and save energy.

#### <u>Windows</u>

Many of the original windows still exist; these single glazed windows require replacement. Steel lintels above the windows are deteriorating and many need to be replaced.

#### <u>Roof</u>

The asphalt shingle roof on the 1953 building was replaced in the late 1990's. The original roof areas have roofs with low R-Value and will require replacement; the new roof system will accommodate new penetrations and new roof top equipment during a renovation. It will be reviewed if the existing insulation can be retained. A new roof system with additional insulation and a new membrane and trim will improve the R-Value, save energy, and provide a new 20-30 year warranty.

#### Interior

The existing finishes have been well maintained throughout but are showing their age. A renovation that will include structural upgrades, new mechanical, electrical, plumbing and fire protection system installations throughout will require the replacement of all or most finishes.

New ceilings will improve acoustics in classrooms and corridors. New flooring will replace asbestos tiles, satisfy ADA Standards, and eliminate the need to protect existing flooring during renovation work, which

can be as expensive as new flooring. This approach also allows for full warranties throughout and the availability of "attic stock" for future repairs if necessary. It is anticipated that there will be a need to modify many spaces to include new walls and doors. As a result, all spaces should be repainted.

Building specialties, such as lockers, chalkboards, tack boards, casework, showers, toilets, etc. will be replaced to provide new components with full warranties and long life expectancies. Although many improvements have been made over the years for handicapped accessibility, it is anticipated that all required areas will need to be updated to meet today's standards.

The current door hardware knobs do not meet handicap accessibility code regulations and need to be replaced with levers. Several other handicap accessibility issues exist at doorways throughout the school requiring code compliant doors and frames.

The kitchen has many difficulties related to prep space, cooking, servery, storage and cleanup. Items such as crowded prep areas, drainage for equipment, lack of space for the servery, old and inefficient equipment, small dry storage room, dishwasher controls will need to be resolved and updated.

#### 4. STRUCTURAL

Since there will be no change in use, existing floors should be able to remain in use without any problems, unless a specific increase in loading is required.

Existing roofs will need to be reinforced for snow drift loading if adjacent additions have higher roofs, so for any portions of additions within about 10 feet of the existing building, we recommend limiting new roof heights to the height of the existing roof.

The most significant structural item is likely to be alterations to the lateral load-resisting system. We assume that the work area will exceed 50% of the building area. That will require existing unreinforced masonry walls to be tied into the floor and roof diaphragms.

The interior masonry partition walls, while generally not load-bearing, are part of the lateral load-resisting system. We understand that it may be necessary to rearrange these walls in order to increase classroom sizes. Removing these walls will clearly reduce the lateral load resistance, but it should be possible to add new walls to replace their effects.

If significant alterations are necessary to the original portion of the building, extensive structural investigation work, including selective demolition of finishes will be necessary to thoroughly evaluate the details of the existing framing system.

#### 5. HVAC

The School has received adequate maintenance on the heating system and equipment over the years. The heating system presently installed is original to the building with existing pneumatic control system. Overall equipment is functioning, however, is reaching the end of its serviceable life. We recommend the entire heating and ventilation system, including pneumatic controls, unit ventilators and piping be completely upgraded to achieve higher efficiencies and reduce energy consumption.

#### 6. ELECTRICAL

The existing electrical systems of this facility range from original vintage, approximately 60 years old, with upgrades/add-ons previously installed. While the facility is well maintained and clean, the systems do not reflect nor do they meet the needs of a modern day facility. Due to the incremental approach of having expanded these systems and the need to work around existing ongoing operations with budget constraints, there is an inadequate capacity for expansion of these systems. Also the code changes over the years have

resulted in existing systems that do not meet today's electrical codes and are not suited for expansion due to the incompatibility of new technologies. This facility should be upgraded to a system voltage of 277/480, 3-phase, 4-wire for the overall facility's distribution system.

#### 7. PLUMBING

The plumbing systems, while continuing to function, have served their useful life. The school plumbing systems could continue to be used with maintenance and replacement of failed components; however other non-dependent decisions will likely force the plumbing upgrade. Due to its age, a complete new water piping systems is recommended.

The plumbing fixtures are in fair condition. Attempts have been made to make bathroom fixtures accessible, however, the majority of fixtures do not meet current accessibility codes. In general, the fixtures appear to have served their useful life. All new fixtures are recommended.

Where visible, the cast iron pipe appears to be in fair condition. Smaller pipe sizes appear to be copper. In general, the drainage piping can be reused where adequately sized for the intended new use.

New domestic water heating systems with thermostatic mixing valves are recommended.

#### 8. FIRE PROTECTION

Currently, only portions of the building are covered by an automatic sprinkler system. The systems are vintage and in fair condition.

In general, Massachusetts General Law M.G.L. c.148, s.26G requires that any existing building over 7,500 square feet that undergoes major alterations or modifications must be sprinklered.

The proposed scope of work is considered a major alteration therefore an automatic combined sprinkler/ standpipe system is required for the building

A hydrant flow test will be required to evaluate water supply capacities.

#### 9. FURNITURE & EQUIPMENT

Furniture and equipment is older, outdated, and has sustained damage over the years. Library and Literacy spaces are housed in areas not intended for these uses. The kitchen layout is inefficient.

#### 10. TECHNOLOGY

The technology systems appear adequate for current use. Projecting use for the future requires additional considerations, such as:

- Air conditioning the technology rooms and computer labs
- Increasing the size of the technology rooms
- Adding security systems and replacing the PA/Master clock systems
- Improving the data cable quality and installation
- Provide more power where needed for technology equipment.

#### 11. HAZARDOUS MATERIALS

The hazardous materials report is appended to section 3.1.4 within section K.

## **B. Detailed Report**

#### 1. LANDSCAPE ARCHITECTURE - WATERMAN DESIGN ASSOCIATES

#### GENERAL

The Peebles Elementary School is located on Trowbridge Road, adjacent to single-family residential properties to the north (across Trowbridge Road), the Bourne High School to the southwest, and Bourne Middle School to the southeast playgrounds and a ball field to the north, and residential property to the east. The portion of the site populated by the existing building slopes up to the main entrance from Trowbridge Road, then slopes back down to the south east. The rear entrances of the building are accessed on the first floor level. The play areas to the north are elevated approximately 6' above the grade of the building. The site contains the original school building, along with the associated vehicular and pedestrian circulation systems, play areas, a lawn area to the northwest between the school and Trowbridge.



Road leading to Peebles Elementary

#### VEHICULAR ENTRANCES AND CIRCULATION

There exist one (1) curb cut accessing the site from Trowbridge Road. The circulation system accommodates bus and parent drop off at the main entrance at the west side of the building, and also accommodates faculty, staff and visitor access. No other vehicular access or egress routes exist on the site. Parent drop off and pick up occurs along the curb adjacent to the flag pole at the main entrance, then parents are to make a U-turn in order to exit the site. Buses follow a one way loop, pick up and drop off directly at the main entrance, then exit the site in the same fashion as parents. There is no formal vehicular connection to either the high school or the middle school, but a gravel maintenance drive exists at the east of the elementary school, and leads to the shared circulation system of the middle and high schools. The pavement condition of the vehicular entrances and interior circulation system ranges from good to fair throughout the site. There is little evidence of recent repairs or repaving operations.





Parent/Bus Drop Off

Parent/Bus Drop Off

#### PARKING LOCATION, ARRANGEMENT AND QUANTITY

Parking for faculty and staff is located to the north of the site, in close proximity to the main entrance,

with additional parking to the rear of the building. Designated visitors parking exists along the access drive directly adjacent to the main entrance. There exist approximately 79 striped spaces throughout the property. It is our understanding that the existing quantity of parking spaces is sufficient for normal school hours. Accessible parking spaces do not appear to comply with current MAAB standards (see Section 5 for further detail). The pavement condition of the parking areas mirrors that of the vehicular entrances, ranging from good to fair throughout the site, with little evidence of recent repairs.

#### PEDESTRIAN ACCESSIBILITY AND MAAB COMPLIANCE

A total of two (2) accessible parking spaces are located on the site. One is located adjacent to the main entrance of the building. It is a parallel parking space that does not include an access aisle. The second space is located at the rear (east) of the building, somewhat proximate to the accessible entrance. The parking spaces, signage, access aisle and accessible route to the accessible building entrance all do not appear to comply with current MAAB standards. None of the existing doors leading into the building appear to be MAAB compliant. There exist one (1) cross walks Trowbridge Road, none of which is accompanied by a curb cut ramp, and does not comply with current MAAB Standards.





Front Parking



Handicap Parking

Rear Parking



Handicap Parking

### PEDESTRIAN CIRCULATION

Pedestrian circulation for access to the west side of the school is accommodated by bluestone landing at the main entrance of the school, when then steps down directly into the vehicular circulation drive. A secondary entrance at the southwest corner of the building has a Portland cement concrete ramp, which also leads directly to the vehicular circulation route. There are no formal pedestrian circulation routes to the east side of the building, pedestrian circulation in that area is accommodated through the expansive paved free-play area, and vehicular circulation routes and through the existing parking areas. The entirety of the east side of the building is surrounded by pavement, and no specified pedestrian routes are marked. The

condition of the pavement around the entirety of the building ranges from good to fair to poor throughout.

#### LOADING DOCKS AND SERVICE AREAS

There is no loading dock associated with Peebles Elementary School.

#### COURTYARDS AND OTHER EXTERIOR STUDENT CONGREGATION AREAS

The paved area at the rear (southeast) of the building is striped as a play area. There is also a tot lot located to the easternmost portion of the asphalt play area with part of the surface treatment finished with rubber mulch, and a newer addition finished with poured-in-place resilient rubber surfacing. The accessible route to the tot lot does not meet current MAAB universal accessibility standards. The tot lot and does not appear to comply with current MAAB universal accessibility standards. Furthermore, the larger play structure does not appear to meet fall zone height requirements. The tot lot surface treatment and play structures are all in fair condition. There is an open lawn area to the west of the access drive, between the building and Trowbridge Road that not appears to be used as a play area, but does not provide a compliant accessible route to and from the building.





Play Area

Paved Free Play Area

#### SITE LIGHTING FOR BUILDING, VEHICULAR AND PEDESTRIAN AREAS

Exterior wall-mounted or overhead-mounted lighting exists at select entrance doors to the building, and some flood-lights mounted in higher corners of the building which illuminate the rear play area. However, no other pedestrian scaled lighting was observed at the site or within the tot lot area.

#### SITE VEGETATION

There exists very little mature vegetation throughout the site, except in the lawn area to the west. The site is abutted to the north and west along Trowbridge Road. There are mature trees lining the south side of the access drive, and a recent planting effort on the north side. Most of these trees appear to be in good to fair condition, but some are reaching maturity and are close to the early stages of decline because of age.

#### 2. CIVIL ENGINEERING - NITSCH ENGINEERING, Inc.

#### EXISTING SITE UTILITIES

The Peebles Elementary School is located on site that also houses Bourne Middle School and Bourne High School. Additionally there are shared athletic fields, driveways and pedestrian paths that connect the rest of the sites to the Peebles Elementary School site. The existing school is comprised of two stories and a two story connected wing off the back of the school. Based on record documents and site observations, the summary descriptions below represent the site utility conditions/assumptions as we understand them at this time.

#### STORM DRAINAGE

The existing Peebles Elementary School building sits at a high point on the site and area in front of the building generally slopes northwest towards Trowbridge Road. The area on the sides and behind the building generally slopes to the southeast towards the existing football field and track. The existing school roof run-off is collected in a gutter and downspout system and is discharged to the site surfaces around the building. Based on information gathered on the site visits and existing design plans there is a limited drainage collection system around the project site which is typical for schools constructed in this era. The runoff from paved areas generally flows overland towards grassed and landscaped areas. The soils in the area are mostly sandy soils which have highly infiltrative properties and it appears that once the runoff from the paved areas makes it to grassed and landscaped areas the majority of the runoff is infiltrated back into groundwater. The entry drive does have a catch basins at the confluence with Trowbridge Road. Visual inspection of the catch basins during the site visit did not identify sumps within the basins. It appears that the current drainage system is not in compliance with the current Department of Environmental Protection (DEP) Stormwater Regulations (2008).



Entryway Storm Drain

The building appears to be slab on grade, and based on the highly infiltrative nature of the site soils groundwater does not appear to be a substantial concern on this site.

Any renovation and/or new construction of the Peebles Elementary School site will require a new stormwater collection system with drainage inlets and structures that reduce or eliminate Total Suspended Solids (TSS), infiltrate run-off and reduce the overall rate and volume of stormwater traveling over the site. Any proposed work should include, at a minimum, the cleaning of the drainage system around the school site. However, Nitsch Engineering recommends that all existing catch basins and drainage structures should be inspected to determine if any structures need to be replaced.

#### WATER

Peebles Elementary School is connected to the same Municipal water system that also feeds the other schools (Middle and High Schools). An existing water line of unknown size and material appears to run north to south along the front of the existing school building. It eventually connects to an existing 6" CLDI water line that was installed as part of the Middle School construction. It is unknown if the existing water line is looped back to Trowbridge Road in the vicinity of the site driveway. No information was able to be obtained to determine where the water services to the existing building enter the school but it is assumed that it would be along either the west or north face of the building.

Currently, there are no indications that there are issues with the domestic water for the site. There is an

existing fire department connection standpipe installed to the left of the main entrance to the building.

One fire hydrant was observed to be within 300 feet of the existing school near the top of the main driveway from Trowbridge Road.

#### SEWER

Sanitary sewer for the Peebles Elementary School is conveyed via underground piping to the wastewater treatment plant located on the adjacent Middle School/High School site. Two service laterals serve the school. The first is a 6" lateral that exits the school from the north elevation into a grease trap. The second exits the building along its east elevation just south of the connector hall to the building addition. These two services combine around the back of the buildings and flow to a large underground tank located just off the southeast corner of the rear playground. A sewer main continues out of the large tank and flows south and east eventually ending up at the wastewater treatment plant. No exterior pumps discovered during the site walk so it is assumed that all flow is via gravity. There are internal grease traps located in the kitchen but as described above there is an external grease trap north of the existing main building.

#### NATURAL GAS

The site appears to be serviced by natural gas main based on there being a gas regulator that was visible during Nitsch Engineering's site visit (See Figure 5). The regulator is attached to the building just south of the building's main entryway. However, no record drawings were provided to Nitsch that showed the location of the gas line or where it is serviced from. The assumption would be that it comes up to the site from Trowbridge Road because the Middle School record drawings do not show a connection from that site to the Peebles site for natural gas. Refer to the MEP narrative for more information about natural gas service.

#### UNDERGROUND/ABOVE GROUND FUEL TANKS

A pair of above ground propane tanks are located on the north side of the existing school building. According to record drawings there is also an existing underground fuel tank located slightly south of the main entrance to the school. Additionally there is what appears to be the top of an existing underground tank located in the landscape area opposite the main entrance to the building. It is unknown what this tank may be as it is not shown on any record drawings and Nitsch was unable to open it during our site visit.



Pole Mounted Transformer

#### ELECTRICAL

Based on observations made during Nitsch Engineering's site visit the electric service for the existing school is fed via overhead service from Trowbridge Road to a pole mounted transformer located on the north side of the font parking lot (See Figure 8) The electric service then continues to another pole farther to the east and then runs overhead and enters the school building along its northern face. The transformer appears to be relatively old, and would likely require upgrade as part of this project. See MEP Narrative for more information about the electrical service.

#### **TELEPHONE SERVICE**

Based on observations made during Nitsch Engineering's site visit telephone service appears to be fed from the same utility pole as the electrical service. See MEP Narrative for more information about the telephone service.

#### CABLE SERVICE

Based on observations made during Nitsch Engineering's site visit cable service appears to be fed from the same utility pole as the electrical service. See MEP Narrative for more information about the cable service.

#### SITE CONDITIONS AND OPERATIONS

#### SOILS

Based on the Natural Resources Conservation Service (NRCS) Web Soil Survey (2011), the majority of the soils for the Peebles Elementary school site is Udipsamments, smoothed with other areas of loamy sand. Udipsamments, smoothed is not classified with a Hydrologic Soil group but all the soils in this area tend be in the classification as an "A" rated soil. Hydrologic Group A soils are described as soils having a high infiltration rate (low runoff potential) when thoroughly wet. These consist mainly of deep, well drained to excessively drained sands or gravelly sands. These soils have a high rate of water transmission. Further investigation will be needed to determine groundwater elevations and in-situ infiltration capacities to support new stormwater infrastructure.

#### PAVEMENT

The asphalt pavement in the parking lots, service drives, and walkways adjacent to the school were observed to be in fairly good condition but were showing age in some places with cracking, crumbling and degradation in some areas. There was no curbing observed within the project site.

#### SNOW REMOVAL

Snow is plowed and stored on site.

#### PRELIMINARY PERMITTING CONSIDERATIONS

#### WETLANDS PROTECTION ACT (310 CMR 10.00)

The Wetlands Protection Act ensures the protection of Massachusetts' inland and coastal wetlands, tidelands, great ponds, rivers, and floodplains. It regulates activities in coastal and wetlands areas, and contributes to the protection of ground and surface water quality, the prevention of flooding and storm damage, and the protection of wildlife and aquatic habitat.

A review of the Massachusetts Department of Environmental Protection (DEP) wetland layers available on the Massachusetts Geographic Information System (MassGIS), dated April 2007, appear to indicate that the Peebles Elementary School site does not contain any wetlands in the immediate area surrounding the school. There is small potential resource area located at the far southern end of the site on the other side of the football field along Macarthur Boulevard but the Peebles school site but it is far enough way that it would not affect development on the site. Nitsch recommends that a wetland scientist be brought on board to confirm that no wetlands are present.

Work performed within resource areas or buffer zones would require a filing of a Notice of Intent (NOI) or a Request for Determination of Applicability (RDA) with the local Conservation Commission and the Massachusetts Department of Environmental Protection.

#### SURFACE WATER SUPPLY PROTECTION (310 CMR 22.20)

The Massachusetts Department of Environmental Protection (DEP) ensures the protection of surface waters used as sources of drinking water supply from contamination by regulating land use and activities within critical areas of surface water sources and tributaries and associated surface water bodies to these surface

water sources.

A review of the Massachusetts DEP resource layers available on the MassGIS indicates the Peebles Elementary School site is not located within a Water Supply Protection Zone

#### NATURAL HERITAGE & ENDANGERED SPECIES PROGRAM

A review of the 13th Edition of the Massachusetts Natural Heritage Atlas prepared by the Natural Heritage and Endangered Species Program (NHESP), dated October 1, 2008, indicates that the High School site is NOT located within a Priority Habitat of Rare Species or an Estimated Habitat of Rare Wildlife and that there are no vernal pools on or adjacent to the site.

#### FLOOD PLAIN

Based on the Flood Insurance Rate Map (FIRM), Community Panel Number 255210 0502J, dated July 16, 2014, it appears that the project site falls within an Unshaded Zone X which is described as an area determined to be outside the 0.2% annual chance (500-year) floodplain.

#### ZONING

According to the Town of Bourne Zoning Map, the Peebles Elementary School is located in the R40 Zoning District. According to the Zoning Bylaw, Municipal Uses are allowed in R40 Zoning Districts but must be approved by the Planning Board as part of a Site Plan Review.

The Dimensional Requirements for the site under an R40 zoning are as follows:

Min. Lot Area of the first Dwelling Unit	40,000 square feet
Minimum Continuous Frontage	125 feet
Front Yard Setback	30 feet
Rear Yard Setback	15 feet
Side Yard Setback	15 feet
Building Height	35 feet
Maximum Building Lot Coverage	20%
Minimum Usable open space	20%

#### US EPA NPDES

Construction activities that disturb more than one acre are regulated under the United States Environmental Protection Agency's (EPA) National Pollution Discharge Elimination System (NPDES) Program. In Massachusetts, the USEPA issues NPDES permits to operators of regulated construction sites. Regulated projects are required to develop and implement stormwater pollution prevention plans in order to obtain permit coverage.

The project will disturb more than one (1) acre and is anticipated to require this permit.

#### SEWER CONNECTION PERMIT (314 CMR 7.00)

New connections to sanitary sewers, increases in flow to existing sanitary sewers, and discharges from businesses that are not considered to be "industrial wastewater" are subject to state requirements based on their expected discharge volume.

- Discharges ≤15,000 gallons per day (gpd) will need only local approvals (no approvals by MassDEP)
- Discharges >15,000 gpd but ≤50,000 gpd must file a one-time certification statement with MassDEP within 60 days after the connection starts to be used

• Discharges of > 50,000 gpd must obtain a MassDEP permit before construction

Permit	Permitting Authority	Anticipated Filing Date	Anticipated Approval Date
Request for Determination of Applicability (RDA)	Town of Bourne Conservation Commission	After 100% DD	Approval in 1 to 3 months
Planning Board Site Plan Review	Town of Bourne Planning Board	From SD to DD	On-going - Up to 6 months+
National Pollutant Discharge Elimination System (NPDES) with EPA Notice of Intent (NOI)	Environmental Protection Agency (EPA)	After 100% CD	Once Submitted; Close NOI at end of Construction
Municipal Separate Storm Sewer System (MS4)	Environmental Protection Agency (EPA)	After 100% CD	Once Submitted, ongoing; yearly reports required

#### PERMITTING TABLE TIMELINE

#### SUSTAINABLE SITE POSSIBILITIES

A new or reconstructed building provides opportunities to incorporate sustainable features which may help achieve Massachusetts Collaborative for High Performance Schools (MA-CHPS) points for funding.

*Bio-Swales* are grassed channels that capture runoff from parking lot and walkway that remove sediment from stormwater. Bio-swales can be used throughout the site, primarily along parking lot edges and access roads.

*Rain Gardens* use soils, plants, and microbes to treat stormwater before it is infiltrated and or discharged. Rain gardens are shallow depressions filled with sandy soil topped with a thick layer of mulch and planted with dense vegetation. Rain gardens can be utilized in parking islands and within the site to treat pavement run-off.

*Porous Pavement* is a paved surface with a higher than normal percentage of air voids to allow water to pass through it and infiltrate in the subsoil. Porous pavement, like all drainage systems, requires maintenance at least twice per year.

Subsurface Structures are underground systems that capture run-off (usually rooftop) and gradually infiltrate it into the groundwater. This method of infiltrating stormwater saves space by placing the system under parking lots or fields.

Based on the Natural Resources Conservation Service (NRCS) Web Soil Survey (2011) and record information, it appears that the site will provide opportunity for infiltration BMP's which can be a cost effective solution for stormwater infiltration into the ground.

Opportunities for rainwater reuse are possible at a renovated or new Peebles Elementary School. However, the initial capital required for tanks, pumps and dual plumbing may be prohibitive in providing payback for water reuse.

#### TRAFFIC ASSESSMENT

As part of the Feasibility Study for the Peebles Elementary School project located in Bourne, Massachusetts,

Nitsch Engineering worked with Flansburgh Architects (FA) to observe the existing traffic circulation and queue lengths on school campus and adjacent streets during drop-off and pick-up periods at two existing elementary schools in Bourne, and assess the site improvement options to be presented by FA. The 2 schools include:

- Peebles Elementary School, located at 70 Trowbridge Road, and
- Bournedale Elementary School, located at 41 Ernest Valeri Road

We have scheduled to collect Automatic Traffic Recorder (ATR) counts and Turning Movement Counts (TMC) for evaluation of roadway and intersection capacity analyses as part of the traffic study.

Figure 1 in the report is the Locus Map showing the proximity of each school and the surrounding roadway network.


#### TRAFFIC CIRCULATION

Nitsch Engineering conducted a site visit on Wednesday October 21, 2015 to observe the site circulation associated with the weekday morning drop-off, weekday afternoon pick-up and general queue lengths around each school site. The weekday morning drop-off observation occurred during partly cloudy conditions with a temperature of 48 degrees. The weekday afternoon pick-up activity occurred during partly cloudy conditions with a temperature of 58 degrees.

The following section includes figures that graphically depict the activity during the weekday morning and afternoon pick-up periods, and tables that quantify the parent and bus drop-off/pick-up totals for each school.

Туре	Par	ent	Βι	IS
Time	Drop-Off	Pick-Up	Drop-Off	Pick-Up
8:30 - 8:45	13			
8:45 - 9:00	63		8	
9:00 - 9:15	12			
9:15- 9:30	5			
2:00 - 2:15		2		
2:15 - 2:30		6		
2:30 - 2:45		16		
2:45 - 3:00		29		8
3:00 - 3:15		17		
3:15 - 3:30		3		
Total	93	73	8	8

#### Table 1 – Peebles Pick-Up/Drop-Off Quantity



# **Figure 5: Peebles Elementary School Site Circulation** Peebles Elementary School Bourne, Massachusetts

Data Source: MassGIS Nitsch Project #11078





**Figure 6: Peebles Elementary Parking Utilization** Peebles Elementary School Bourne, Massachusetts

Data Source: MassGIS Nitsch Project #11078



#### 3. ARCHITECTURAL - FLANSBURGH ARCHITECTS

#### **GENERAL DESCRIPTION**

#### BUILDING

- Organization: The original two-story school was constructed in 1953 with an addition a. constructed in 1959. The school is approximately 55,200 square feet and currently houses classrooms, a cafeteria, a kitchen, reception area, gymnasium, and offices.
- b. Circulation: The building is a multi-story school in a "long bar" plan, a double-loaded corridor with classrooms on both sides, and the cafeteria and gymnasium at one end of the school.
- Program and Space Issues: The Peebles Elementary School currently serves 391 students C. grades K through 4. The school's maximum class size goal is 24 students per classroom. Comparisons with current MSBA space standards indicate that classrooms and core academic spaces are undersized.

<u>Room</u>	MSBA Standards	Peebles Existing
Classrooms	850 - 950 s.f.	900 s.f.
Music	1,200 s.f.	525 s.f.
Library	2,020 s.f.	730 s.f.
Art	1,000 s.f.	800 s.f.
Gymnasium	6,000 s.f.	3,100 s.f.

d. Physical Conditions:

#### **EXTERIOR ENVELOPE - WALLS**

The thermal resistance of the exterior envelope is severely low compared to current codes:

Typical exterior wall assembly: exterior brick, air space, studs, and plaster

TOTAL R-VALUE	<u> </u>
1/2" Plaster	0.32
2x6 Studs	6.88
3/8" Air Space	1.01
4" Brick	0.44
Representative R-Values	

Typical Exterior Walls - Current Minimum Requirements

Face Brick	0.39
Air Space	2.02
Air/Vapor Barriers	0.15
1/2" gypsum sheathing	0.45
Insulation	19.00
Vapor Barrier	0.15
Interior Gypsum Board	0.45
TOTAL R-VALUE	22.46

The school is faced with red brick in a running bond pattern with stone elements located at the main entrances. Several areas around the perimeter have loose mortar in the brick joints. This results in water sitting in the open joint, causing spalling of the brick and possible water infiltration deeper into the cavity. Visible cracking of Cracked mortar under window sill



the brick is evident at several locations throughout the façade. The brick façade on the 1959 addition failed and a portion was replaced with textured T-11 exterior plywood siding. Some brick spandrel panels on the 1953 building have been replaced with vinyl siding.

Further investigation into increasing the R-value of the exterior envelope is required. Full repointing of the exterior masonry is necessary to prevent further water infiltration and deterioration of the wall assembly.

#### WINDOWS AND DOORS

The school's window and door systems are original to the building. The windows are single paned, with aged caulking and sealant joints. The thermal performance of this system is poor and lacks proper weatherproofing, creating a possible breach for water and air pollution. Additionally, the glazing does not appear to be tempered in units at grade.



Cracking masonry and foundation wall

The steel lintels are rusting, have peeling paint, lack proper flashing, and are void of a thermal break between the exterior and interior. This condition creates a weak link in the energy performance of the entire system.

Removal and replacement of all exterior windows, doors, and storefront with energy-efficient units is recommended. Replacement of all sealant joints is recommended.

#### **EXTERIOR ENVELOPE - ROOF**

The asphalt shingle roofing is in good condition, but the attic space lacks insulation and no soffit or ridge vents exist. The built-up roofing appears to be original to the building and lacks insulation to be an effective energy system.

Existing Flat Roof Construction		Roof Construction - Current Minimum Requirements	
Building Up Roofing Membrane 2" Fiberboard <u>Structure/Ceiling</u>	0.34 5.56 5.00	Rubber/PVC 4" Polyisocyanurate <u>Structure/Ceiling</u>	0.40 24.00 <u>5.00</u>
TOTAL R-VALUE	10.90	TOTAL R-VALUE	29.40

The existing asphalt shingle roofing appears in good condition. No active roof leaks were observed, although extensive water staining was present at ceilings.

The roof of the 1953 building was replaced in the late 1990's. This roof system warranty is still valid and the roofing manufacture should be contacted for a roof inspection prior to any renovation.

The built-up roofing is in poor condition and should be replaced. In the event of a full restoration, all roofing systems and flashings should be replaced.

#### INTERIOR

Finishes within the building have been reasonably maintained but are nearing the end of their useful life.


- e. Interior Partitions: In general, interior partitions appear to be in relatively good condition. The type of interior partitions vary throughout as follows:
  - Painted plaster
  - Tile
  - Brick exposed and painted
  - Painted CMU

In a renovation, various walls could be re-framed with steel studs and painted drywall to accommodate new electrical, plumbing and technology systems. If necessary, existing plaster and drywall walls to remain could be cut open to allow for new systems. All walls should have acoustical batt insulation installed wherever practical to improve acoustical performance.

- f. Flooring: In general, all flooring is in fair condition. Although some new VCT tile has been installed, the vast majority of existing tile remains. It should be replaced if the school is renovated, abating any asbestos containing materials. It has been our experience that replacing existing VCT flooring costs as much as the cost to protect it in place during the renovation process. As a result, we recommend new VCT flooring to replace existing after the revocation process has completed. This will allow for a full warranty throughout the school, and attic stock could be made available for future replacement due to damage, if necessary. The type of flooring that exists is as follows:
  - Vinyl tile (9x9 and 12x12)
  - Ceramic tile
  - Painted concrete
  - Carpeting
  - Wood (gym)
  - Epoxy flooring (cafeteria)



Patched Flooring



12x12 VCT patch within 9x9 VAT

- g. Wall Base: The wall base is mostly vinyl or rubber in various heights and in various conditions. At some walls the base is wood, at ceramic tile areas the base is ceramic. It is recommended that all base be removed and replaced with new base suitable for the flooring to be installed. This will provide for a warranty throughout and attic stock can be made available for future repairs as necessary.
- h. Ceilings: In general, the ceiling types vary throughout. Significant water damage exists throughout the building. In some cases the existing ceilings were glued to the underside of

the structure. New suspended ceilings have been installed below some existing ceilings. If the building is renovated, the work required for structural modifications, mechanical, electrical and plumbing upgrades as well as a new fire protection system will require new ceilings throughout.

- Glue up tile
- Suspended acoustical tile
- · Painted plaster
- · Exposed painted structure
- · Exposed non-painted structure
- i. Doors and Frames: Doors and frames vary in size and type both metal and wood. They vary in condition from poor to good. The project renovations will require replacement of many doors due to condition, ADA requirements, hardware issues and a low R-value at exterior doors. It is recommended that all doors be replaced to allow for a full facility warranty, compliance with handicapped accessibility requirements, and replacement of hardware systems.

Finish hardware consists of a mix of knobs and levers, hinges, panic devices, and locksets. A master key system does not exist. New hardware is required to meet handicap requirements.

- j. Fire Extinguishers: All existing fire extinguishers appear to be operational and certified. It appears that fire extinguishers are located in accordance with NFPA requirements.
- k. Tack Boards and Marker Boards: Both types of boards exist in various sizes and conditions. The recent fire code regulations do not allow for tack boards to be within 5 feet of egress doorways; some of the existing tack boards may need to be moved as a result. Marker boards are in good condition.
- I. Casework: Student storage in classrooms is not subdivided, and health issues have been a concern in the past, for instance, with the transmission of lice. Individual cubbies would be appropriate. Additionally, the sinks within classrooms lack knee space and are not ADA compliant.



Student Storage in classrooms

#### REGULATIONS

Refer to Code Evaluation appended to section 3.1.4 within Section F.

#### HANDICAP ACCESSIBILITY

Refer to MAAB/Accessibility Evaluation appended to section 3.1.4 within Section G.

#### 4. STRUCTURAL - BOSTON BUILDING CONSULTANTS, Inc.

#### **EXISTING CONDITIONS**

The Peebles School is essentially a one story building, situated on sloping portion of the site. The first floor level is at grade along the front, north side, of the building, and the basement level is at grade along the rear, south side, of the building. There is a crawl space under four of the first floor classrooms at the front of the building. From the 1953 grading plan, the original building appears to have been founded on natural soil.



Eroding Masonry

The first floor is typically framed with open web steel joists, spaced at 24" on center, with a 3-1/2" concrete topping. These joist are supported on unreinforced CMU bearing walls at the corridor, and a line of continuous W12 steel beams along the rear wall. The beams are supported on pipe columns, spaced about 13 feet on center. The multipurpose room is framed with 2x12 wood joist, supported by W24 and W30 steel beams, and pipe columns down through the cafeteria.

The roof and attic are framed with 2x wood joists, supported by built up engineered wood trusses that span across the building from exterior walls. The

trusses are space about 13 feet on center, and are supported by continuous W12 beams and pipe columns at both the north and south exterior wall. Typically, but not always, located under the ends of the roof trusses. The trusses generally looked in good condition, but we could not access the ends of the truss at their supports. This is where decay may be present from ice dams, roof leaks and gutter problems.

Exterior wall construction is shown consisting of brick veneer, a 1" cavity, 15# felt over wood sheathing, and 2x6 stud construction. The brick is shown anchored to the sheathing with bent, corrugated metal anchors, spaced about 24" on center. There is a supporting shelf angle to support the brick near the top flange of the beam, and also a hung shelf angle from the beam bottom flange. The steel angles are flashed, but the beam is not.





T-111 Replacing Brick on Both Sides of the Door Erodi

Eroding Masonry & Pavement

There appears to be a lot of distress in the exterior masonry, especially on the rear of the building. The shelf angles and lintels used were not galvanized, and they are exhibiting corrosion and causing some jacking of the masonry. Water entry has been a problem on the south elevation, and the brick spandrels have been covered with vinyl siding to minimize leakage. It is likely that the brick ties have disintegrated at this point. It is evident form the original caulking lines, that the brick work is moving outward away from their back up wall. As this is an active play area, this condition should be further investigated and stabilized, until a

permanent solution is made.

#### PEEBLES ADDITION

The addition appears to have been constructed in the early 1950's. It appears to be constructed of reinforced concrete, with a central roof area over an inner core area, which is framed with rigid steel frames and wood decking. There is a two story corridor connecting the addition to the original building.

The exterior wall of this addition are mostly brick veneer on the east and west elevations, and mostly curtain wall on the north and south elevations. Again, the masonry exterior south wall has exhibited problems. The brick problems are likely related to brick growth, thermal movements, and hard joints at the top of the panels, below the concrete roof beams. The brick overhangs the foundation approximately 1-5/8", and is also proud of the concrete roof beam. With this eccentric support, brick growth and thermal expansion will result in outward bowing of the masonry panels, and likely contributed to the failure of the removed panels. The condition of the brick ties is unknown. This condition should be monitored.

While the foundation walls and masonry do not exhibit evidence of settlement, the interior ground floor has settled noticeably, especially along the south rear wall. The egress stair at the south west corner is a potential hazard due to settlement of the stair landing. From reviewing the original drawing from the 1953 Building, it appears that the addition was constructed over the former leaching field. At that time a substantial amount of regrading was done, and the leaching field was likely not well compacted for better percolation. Additional fill was added when the addition was constructed.

#### CODE REQUIREMENTS

The Peebles School and Addition were built at a time when design procedures, material requirements and Building Code regulations were less stringent. At the time these buildings were constructed, un-reinforced masonry was allowed for load bearing elements, and lateral load analysis for wind was commonly ignored for low rise buildings, assuming that masonry walls and partitions would provide sufficient resistance. Seismic provisions were not a requirement. Existing wall anchorage, and transitions between the concrete and wood floors at the Multipurpose Room are not adequate by today's standards.

Chapter 34 of the 8th Edition of the State Building Code has adopted the International Existing Building Code, IEBC. This will control the renovation and re-use of these buildings. Repair and Renovation of these buildings can be done under the Prescriptive Method, or under the Work Area Method of this Code. Under both procedures, certain seismic improvements would be required, consistent with previous editions of the MA State Building Code. These include laterally bracing the tops of interior partitions, and anchoring exterior walls to roof and floor diaphragms.

Under the Prescriptive Method, alterations to masonry walls and partitions could be made, as long as the increase in Seismic demand for any existing element does not exceed 10%. This provision will require new interior seismic resisting systems to be installed only if there are changes to the current wall layout.

Under the Work Area Method, since the entire building would be involved in the renovation, the work would be considered a Level 3 renovation, per IEBC. Assuming minor structural alterations to the existing framing, any structural element with Seismic forces increased by less than 10%, are allowed. If more than 10%, the elements are allowed to comply with reduced Code Seismic forces.

Horizontal additions to these buildings is possible, but they will have to be isolated by an expansion joint. Vertical additions are not appropriate for the existing structures.

Given the total cost to renovate these simple buildings, the premium to make these structures fully comply with the Code Seismic provisions should be considered, given their occupancy.

### 5. HVAC - GARCIA, GALUSKA, DESOUSA, Inc.

#### **EXISTING CONDITIONS**

Presently, the HVAC Systems serving the building are: a duel fuel-fired steam boiler plant serving steam radiators & unit ventilators, general purpose exhaust fans,& hot-water radiation via steam-to-water heat exchangers w/ hot water pumps.

The majority of the HVAC systems are original to the building and its additions. Portions of the system have been updated as part of building renovation and upgrade projects. The HVAC systems, while continuing to function, have served their useful life. The school HVAC systems could continue to be used with maintenance and replacement of failed components; however the lack of controllability, the poor physical condition, and poor efficiency of the existing systems warrants a complete replacement of all the building HVAC systems.

#### **BOILER PLANT**

This boiler room is provided with two individual boilers. Boiler #1 is original to the building and approximately 60 years old and is an H. B. Smith cast iron sectional series 60 water tube boiler. This boiler is provided with a duel fuel burner and is also provided with all operating and safety controls and generates low pressure steam which distributes to a common overhead schedule 40 fiberglass insulated header. Boiler #2 is an H. B. Smith 450 mills cast iron sectional boiler installed approximately 20 years ago. This boiler is also provided with a duel-fuel burner and is also provided with all operating and safety controls and generates low pressure steam which ties into the same common header.

Boiler #1 was noted to have extensive surface corrosion on the boiler shell as well as each mud drum. Boiler #2 was also noted to have corrosion along the base of the boiler shell as well as on the mud drums. The overall condition of boiler #1 was noted to be poor and boiler #2 was considered average. No. 2 fuel oil is circulated to each burner through a schedule 40 uninsulated recirculating fuel oil distribution system & Natural gas is also piped to serve both boiler burners. Fuel oil is stored in a buried double wall fiberglass storage tank outside of the building which appears to have been installed during the boiler replacement of approximately 20 years ago. The maintenance staff indicated that fuel-oil use has been replaced by natural gas in recent years.





Heat Exchanger

Hot Water Pump

Also located within the Boiler Room is a leak containment monitoring system and duplex gear driven recirculating pumps. All piping and pumps appear to be original, however the leak monitoring system along with the tanks and the below ground piping appears to have been replaced approximately 20 years ago and does appear adequate at this time. Combustion air for the power plant is through a single horizontal discharge 100% outside air handling units located at the ceiling of the boiler room. This air handling unit is provided with a steam heating coil, supply fan, and a direct source of outside air through a wall mounted louver. Combustion air discharges from the air handling unit through a galvanized sheet metal duct terminating approximately 12 in. above the floor in front of each boiler. Although the entire system is

extremely antiquated, it does operate and provide adequate combustion air.

Breeching from each boiler is through a welded steel insulated breeching system which travels from each boiler to a masonry chimney. Located at the rear of each boiler is an induced draft fan as well as a barometric damper. The masonry chimney does appear to be of adequate height and size for the power plant, however based on its age we are not clear of it's structural condition or if an interior liner is installed. The chimney was provided with a cleanout door and does appear adequate. Steam is generated at approximately 8 lbs of steam pressure and distributes out to the entire building through a below floor trench to the individual pieces of heating equipment throughout the entire original building. All steam piping is schedule 40 black steel and is insulated with fiberglass with an all service jacket. All existing steam piping should be tested internally to examine for corrosion, as it has exceeded its expected serviceable life.

Condensate is returned to the boiler room through what appears to be a schedule 80 black steel fiberglassinsulated piping system also located within a trench circulating throughout the original building. All condensate is returned to a condensate feedwater receiver located in a below floor trench within the boiler room. Much of the condensate and feed water piping within the boiler room is not insulated. It does appear that the condensate receiver has been upgraded recently however no information was available on this unit. The tunnel which is routed beneath the entire building to house the steam and condensate distribution system is not provided with a vapor barrier and presently exists with an exposed earth floor.

Located to the left of boiler #1 is a steam to hot water heat exchanger which was installed during the 1959 addition. This exchanger converts thermal energy from the steam heating system to the hot water system for distribution to the addition through a schedule 40 black steel fiberglass insulated distribution piping system. The exchanger was noted to be in average condition however, the base mounted end suction pumps under the heat exchanger were noted to have extensive surface contamination and appear to be in extremely poor condition. Automatic temperature controls are of the pneumatic type and are provided with a single air storage tank with single tank mounted compressor and motor. The tank appeared to be in poor condition & what appeared to be oil leaks from the compressor/motor were observed. Located on an adjacent wall is an automatic temperature control board which does not appear to operate. More-recently installed was a simple Honeywell direct digital control monitoring system which appears to "start and stop" overall building functions as well as monitor the boiler room. As we understand it, the system does operate however, does not control overall space temperatures and is purely intended for offsite monitoring only.

#### **KITCHEN**

The kitchen is provided with a single wall stainless steel exhaust hood located over the entire cooking area which appears to be of adequate height over the cooking equipment. The kitchen hood is provided with fire protection heads, removable cartridge filters, and incandescent vapor tight lighting. The entire hood is considered clean and operating in good condition. The hood is vented through a single painted black steel duct which travels exposed within the space and up through the building to a roof mounted exhaust fan.



Kitchen Hood Exhaust Duct



Cafeteria Unit Ventilator

Also connected to this main duct is a branch duct which feeds over to an adjacent dishwasher. This branch duct is not code compliant as the dishwasher must be vented separately from the main kitchen exhaust hood. Heating of the kitchen is through a single horizontal unit heater exposed within the space which ties into the low pressure steam distribution system. Make-up air for the kitchen hood is provided through openings between the cafeteria and kitchen wall as there is no direct supply of make-up air or ventilation for the kitchen. This lack of ventilation within the kitchen is not code-compliant.

#### CAFETERIA

The cafeteria is provided with three vertical discharge classroom unit ventilators located along the exterior wall of the space. Each unit ventilator is provided with supply fans, a steam heating coil which ties into the steam distribution system below the slab, filters, return air drawn at the base of the unit, and a direct source of outside ventilation air drawn in through an exterior wall mounted louver. All unit ventilators are original to the building and have extensive surface contamination and slight damage. On the opposite wall is a central exhaust register located approximately 6 in. above the floor which communicates through a galvanized sheetmetal exhaust system to a roof mounted exhaust fan. Based on the size and the overall population of the space it does appear that the unit ventilators are undersized for the application. It would also appear that the outside air introduced at the cafeteria is intended as a source of make-up air for the kitchen; the cafeteria HVAC system is also undersized for this application.

#### AUDITORIUM/GYMNASIUM

This area is provided with two individual vertical discharge air-handling units located on each side of the stage. Each unit is typical in design and includes a supply fan, filters, low pressure steam heating coil with valve control, return air drawn directly back at the base of the air handling unit, and a direct source of outside ventilation air through a wall mounted louver. Supply air discharges vertically through an uninsulated galvanized sheet metal distribution system routed to two individual supply grilles located over the stage. Adjacent to the stage on each side are return air grilles which act as a transfer from the space to the stage area to allow return air flow when the curtains are closed. The supply registers were noted to be slightly soiled and all equipment does appear to be in excess of 60 years of age and has reached its maximum expected serviceable life. The stage area was not provided with any supply or exhaust ventilation air, leaving this area non-code compliant. The open area was provided with convectors recessed within the exterior wall which tie into the low pressure steam system below the slab. All convectors were original to the building and extremely antiquated. Located on the rear wall of the space is a central exhaust register which appears to communicate through a galvanized sheetmetal exhaust system to a roof mounted exhaust fan. Also located at the ceiling were very small exhaust registers which appear to tie into the same exhaust system. All systems are noted to have surface corrosion and appear to be in excess of their maximum serviceable life. The air-handling units appear to be undersized based on the population and size of the overall space.

#### ORIGINAL LOCKER AREAS

These areas are adjacent to the gymnasium and are presently used as a teacher's workroom, music room, and a computer classroom. The teachers' room was provided with a single wall mounted classroom unit ventilator which is provided with a supply fan, low pressure steam heating coil, filters, return air drawn directly back to the base of the unit, and a direct source of outside ventilation air through an exterior wall mounted louver. The music room and the computer classroom were provided with convection heat however, they were not provided with any source of ventilation air and based on the size and population of the space would be considered non-code compliant. The computer classroom has also not been provided with air conditioning, which is recommended for any space containing this amount of electrical equipment. All of the existing ventilation ductwork which at one time served the locker areas has been abandoned in place and should be removed.

#### PUBLIC TOILET AREAS

The public toilet areas all contain individual wall mounted exhaust registers generally adjacent to the plumbing fixtures. All registers communicate through galvanized sheetmetal exhaust system to various roof mounted exhaust fans. All systems appear original to the building and in excess of 50 years old and were noted to have extensive surface contamination and are extremely antiquated. Make-up air for the spaces is through a combination of operable windows in the rooms as well as louvers in the communicating doors between the corridors and the toilet rooms. The lack of make-up air provided for the communicating corridors is reducing the overall exhaust within the toilet spaces. Heating of the toilet rooms is through various sections of wall mounted convectors and fin tube radiation which ties into the low pressure steam distribution system within the original building and tie into the recirculating hot water system in the 1959 addition. We did not note any control of the fin tube radiation and it does appear to run wild and the possibly overheat the spaces.



Typical Toilet Exhaust Grille

Typical Toilet Exhaust Grille

#### ADMINISTRATION AREA

The administration area is not provided with any means of either supply or exhaust ventilation air. It does appear that the entire area is ventilated through the use of operable windows located along the exterior wall. Although this design does meet the minimum requirements of the building code it is generally ineffective during winter months when windows are not utilized. Heating of the individual spaces is through the use of wall mounted fin tube radiation which ties into the low pressure steam distribution system. All radiation was provided with individual control valves with pneumatic wall mounted thermostats, all of which appears original and in excess of 60 years old and extremely antiquated.

#### FRONT LOBBY AND SECONDARY EXITS

The front lobby contains two individual wall-mounted convectors located within the vestibule as well as two additional convectors located within the main lobby just inside of the vestibule. Considering the frequent and rapid use of this exit passage it would appear that the convectors are undersized for a rapid recovery of heat during peak passage times. The secondary entrances throughout the building were also provided with wall mounted convectors for heat, however these convectors also appear to be undersized during rapid use of the exit doorways. The convectors in the original building tie into the low pressure steam distribution system and convectors in the addition building tie into the recirculating hot water system. Considering their age, all equipment was noted to be in fair condition.

#### CLASSROOMS

The original building classrooms are provided with vertical discharge classroom unit ventilators located along the exterior wall of the building. Each unit ventilator is located to the side of each space and considering the

#### Peebles Elementary School

size of the actual space does promote uneven and inconsistent ventilation distribution patterns throughout the space. Each unit ventilator is provided with a supply fan, low pressure steam heating coil with valve control, filters, return air drawn back at the base of the unit and a direct source of outside ventilation air through an exterior wall mounted louver. It was noted that this wall louver is undersized to meet the standard ASHRAE II control cycle. Exhaust air for each classroom is through a ceiling exhaust register located within the closet in each classroom. These registers combine through common galvanized sheetmetal exhaust systems communicated to individual roof-mounted exhaust fans located throughout the building. Located adjacent to the unit ventilators is a continuous draft barrier which allows return air to flow through the top of the case work back to the unit ventilator to assist in offsetting any through-window draft. All unit ventilators, draft barrier, and exhaust registers was noted to have extensive surface & internal corrosion and appear to be original to the building in excess of 60 years old, exceeding their expected maximum serviceable life. The unit ventilators are controlled by a single pneumatic wall mounted thermostat also original to the building and in excess of 60 years old.

The addition building classrooms are provided with vertical discharge classroom unit ventilators generally located within the center of each classroom space. Each unit ventilator is provided with a supply fan, heating hot water coil with valve control, filters, return air drawn back at the base of the unit and a direct source of outside ventilation air through an exterior wall mounted louver. Adjacent to the unit ventilators is fin tube radiation which also ties into the hot water distribution system. It does appear that the unit ventilators are capable of operating in accordance with the ASHRAE II cycle. Exhaust air for each classroom is through a ceiling exhaust register located within the closet in each classroom. These registers connect to a common galvanized sheetmetal exhaust system and individual roof mounted exhaust fans located throughout the building. All systems were noted to have slight surface corrosion however do appear to operate. The unit ventilators and fin tube radiation are controlled by pneumatic wall mounted thermostats all of which appear to be antiquated.

#### MEDIA CENTER

The media center is provided with a single horizontal Vertical Discharge Air-Handling Unit discharge air handling unit located in an adjacent



Student Lockers in Rear of Classroom



storage room. This air handling unit is provided with a supply fan, heating hot water coil with valve control, filters, return air drawn through a single wall mounted grille directly below the supply grilles, and a direct source of outside air through a duct which travels to the roof. Supply air is provided through a galvanized sheetmetal uninsulated supply system which connects to two individual supply registers at one side of the room directly above the return. The supply and return grille locations suggest very poor air distribution patterns and poor heating, cooling, and ventilation effectiveness. All supply and return registers were noted to have slight surface corrosion and the entire air handling system appears to be original and approximately 50 years old, exceeding its expected maximum serviceable life.

#### RECOMMENDATIONS

We recommend the following HVAC system repairs and/or renovations:

Provide new means air-distribution for all spaces via Rooftop Air-handling Unit(s) with highefficiency direct expansion cooling section(s) & gas-fired furnace(s) to maintain code-required

ventilation rates and level of occupant comfort compliant with ASHRAE Standard 55.

- Provide new high-efficiency gas-fired heating plant to replace the existing in its entirety.
- Provide new Insulated hot-water distribution system to replace the existing steam and hotwater distribution systems in their entirety.
- Provide Building Management System for optimum control and monitoring of all building energy usage & HVAC systems.
- Provide new supplemental cooling systems for all computer classrooms.
- Provide new or upgrade existing building envelope to maintain desired interior environmental conditions.

#### 6. ELECTRICAL - GARCIA, GALUSKA, DESOUSA, Inc.

#### EXECUTIVE SUMMARY

Most of the general power equipment (wiring, panelboards, switches, and receptacles) is original to the building. Although there have been some upgrades to the lighting and emergency lighting, most of the equipment is not up to current industry standards, nor current energy efficiency or code requirements. Most panelboards are full and have no room for expansion. Lighting levels are poor in some locations although upgrades have been made to some select areas. The fire alarm system is addressable, but does not meet ADA requirements and is lacking coverage in some areas.

#### ELECTRICAL DISTRIBUTION SYSTEM

The existing electrical service consists of a 600 AMP, 120/208 volt, 3Ø, 4 wire main disconnect switch manufactured by Square D. The Classroom Unit Ventilator service is fed underground from a utility pole.



The existing 600 amp service is located in the boiler room. Service consists of main disconnect switch and



Circuit Breaker Panelboard



Circuit Breaker Panelboard

one (1) distribution fused switch panelboard.

Existing lighting and power panels are circuit breaker type and are rated at 120/208 volt, 3Ø, 4wire. Fuse type and circuit breaker panelboards are located throughout the school.

#### INTERIOR LIGHTING SYSTEMS

Existing classroom, corridor, kitchen, cafeteria and office lighting consists of 1' x 4' surface mounted prismatic fluorescent fixtures. Lighting in the boiler room consists of surface fluorescent fixtures. Toilet rooms have fluorescent surface mounted fixtures.

Lighting in the gym consists of pendant mount 2'x4' prismatic fluorescent fixtures. Computer classroom lighting consists of pendant mounted louvered fluorescent fixtures. Upper media center/library consists of pendant mounted prismatic fluorescent fixtures.

#### EMERGENCY LIGHTING SYSTEM

Emergency battery units and remote emergency lighting heads are located throughout the building.

Additional self-contained emergency lighting units are provided throughout the building.

#### SITE LIGHTING SYSTEM

Existing site lighting is by pole mounted lighting fixtures on utility poles and building mounted flood lights. Lighting fixtures are recessed and surface mounted in the canopy at the main entrance.

#### WIRING DEVICES

Existing classrooms have duplex outlets sparsely located throughout the rooms. Receptacle coverage in most office spaces is inadequate with cords typically running across the floor in these rooms.





Duplex Outlet

Duplex Outlet

#### FIRE ALARM SYSTEM

The building is equipped with an automatic addressable fire alarm system throughout the building. Existing strobes do not meet ADA for intensity. The fire alarm control panel is manufactured by Honeywell and located in the administration area. Notification to the fire department is by a surface master box located outdoors at the main entrance. Classrooms and toilet rooms do not have ADA horn/strobe units.

Corridors have smoke detectors, horn/strobes and pull stations throughout the building.





Fire Alarm System

Exterior Site Lighting

DEFICIENCIES/RECOMMENDATIONS:

#### Electrical Distribution System:

The existing 600 amp main disconnect switch and fused distribution panel should be replaced. The original older panelboards throughout the building should be replaced. These panels are in poor condition and at

the end of their useful life.

#### Interior Lighting System:

Existing lighting throughout the building is in fair condition. All fixtures throughout the building should be replaced with new efficient LED lighting fixtures and the building equipped with an automated lighting control system.

#### Emergency Lighting System:

All existing exit signs should be replaced with new more efficient LED type. Additional exit signs will be required throughout the building.

A new generator should be used to provide the emergency power needs of the school. Additional emergency self-contained battery units should be provided throughout the building if a generator is not used.

#### Site Lighting System:

New pole mounted fixtures should be provided in parking area to replace the existing fixtures on utility poles. Incandescent fixtures at entrances should be replaced with new more efficient fixtures.

#### Wiring Devices:

Each classroom should have a minimum of (2) duplex receptacles per wall and (2) double duplex receptacles at classroom computer workstations.



Fire Alarm

#### Fire Alarm System:

A new fire alarm system will be required to meet the latest codes. The system will be an automatic addressable system with ADA strobe units, smoke detectors, pull stations and horn/strobe units throughout the building. A LCD annunciator will be located at the main entrance with the fire alarm control panel at the administration area.

#### 7. PLUMBING - GARCIA, GALUSKA, DESOUSA, Inc.

#### EXECUTIVE SUMMARY

Presently, the Plumbing Systems serving the building are cold water, hot water, sanitary, waste and vent system, storm drain piping, LPgas, and natural gas. Municipal water and on-site wastewater treatment system services the Building.

The majority of the plumbing systems are original to the building and its additions. Portions of the system have been updated as part of building renovation and upgrade projects. The plumbing systems, while continuing to function, have served their useful life. The school plumbing systems could continue to be used with maintenance and replacement of failed components; however other non-dependent decisions will likely force the plumbing upgrade. Due to its age, a complete new water piping system is recommended. The copper piping has served its useful life.

The plumbing fixtures are in fair condition. The fixtures do not meet current accessibility codes. In general, the fixtures appear to have served their useful life. Current Access Code requires accessible fixtures wherever plumbing is provided. In terms of the water conservation fixtures, their use is governed by the provisions of the Plumbing and Building Code. The existing plumbing fixtures do not meet current water conservation requirements. Essentially, the code does not require these fixtures to be upgraded, but where new fixtures are installed, as may be required by other codes or concerns, the new fixtures need to be water conserving type fixtures. All new fixtures are recommended.

Cast iron is used for sanitary and storm drainage. Where visible, the cast iron pipe appears to be in fair condition. Smaller pipe sizes appear to be copper. In general, the drainage piping can be reused where adequately sized for the intended new use.



Kindergarten classroom toilet fixture



Urinals with exposed flush valves

#### **FIXTURES**

Water closets are both wall hung and floor mounted vitreous china, flush valve type.

Urinals are wall hung vitreous china, with either fully recessed or exposed manual flush valves.

Lavatories are wall hung vitreous china, with separate hot and cold water faucets. Lavatories in the student gang toilet rooms are molded stone wash fountains, with foot operation.

Janitor's sinks are cast-iron enameled, with stainless steel rim. Faucets in the original building have no vacuum breakers. Faucets on the sinks in the 1959 building addition have vacuum breakers.

Classroom sinks are self rimming with hot and cold water controls.

Drinking fountains are generally wall hung, stainless steel and vitreous china.

#### WATER SYSTEMS

The domestic water service enters the building through the wall of the boiler room. The domestic water service entering the building is 3 in., which then splits into two separate water meters. There is also a 2 inch water line with meter, which is dedicated to the domestic water for the building. There is a 2 inch water meter for outbuildings. There is no backflow preventer on the systems.

Domestic water piping is copper tubing with sweat joints. Majority of water piping is insulated. Piping is located within pipe trenches and crawl spaces, with limited access. The building water system has significant water hammer issues.

The domestic hot water system is generated through a high efficiency gas-fired water heater. Water heater was installed in 2011. The heater has a natural gas input of 199,000 BTUH and storage capacity of 100 gallons of water. The heater is direct vented to the exterior. The hot water systems is recirculated.

Wall hydrants on exterior of building are original and are in poor condition.

#### DRAINAGE SYSTEMS

The sanitary drainage system is piped with cast-iron. The visible sanitary drainage piping is in fair condition. Sanitary system is discharged to the on-site wastewater treatment facility.

The storm water drainage system is comprised of pitched roofs with gutter and downspout systems. The down spouts run down the exterior face of the building and discharge to grade. There is a simplex sump pump in the boiler room which collects all of the indirect waste piping from the equipment in the boiler room. The waste is then pumped up to the gravity drainage system

#### GAS SYSTEMS

The LP gas system is supplied by an exterior above-grade storage tank which is located outside of the kitchen. The LP gas system is dedicated to the kitchen cooking equipment. The piping runs below ground and enters the building from under the kitchen floor and is piped directly to the equipment. There is an emergency shut-off inline for the kitchen equipment that is connected to the fire suppression system in the kitchen hood.

The natural gas systems supplies the heating boilers and domestic water heater. Gas meter is located on the exterior of the building.

Gas piping is black steel with welded or threaded joints depending on pipe size.

#### KITCHEN

The kitchen at this facility is all original and indicates its vintage. All the equipment is in fair to good condition and is working properly.

The two pot sink and the dishwasher are piped above the floor to a recessed grease receptor. The grease trap seems undersized for the load.

The dishwasher is original but is in good condition. There is a pre-rinse station with a hose spray which is also in good condition.

#### RECOMMENDATIONS

Provide new plumbing fixtures throughout. Fixtures should be high efficiency water conserving type.

Provide new domestic water piping throughout the building.

Provide water hammer arresters at all plumbing fixtures with quick closing devices.

Provide natural gas to cooking equipments. Provide manually reset gas valve interlocked with carbon monoxide detectors to confirm hood exhaust as required by current code.

#### 8. FIRE PROTECTION - GARCIA, GALUSKA, DESOUSA, Inc.

#### EXECUTIVE SUMMARY

Portions of the school are protected by automatic sprinkler systems, the building is not fully sprinklered. In general, the original building is fully sprinklered and the 1959 building addition is not. The majority of the equipment and systems is vintage and in fair condition.

Massachusetts General Law requires any existing commercial building which undergoes a major renovation or building addition which results in a gross floor area of greater than 7,500 square feet must be sprinklered throughout. Massachusetts code requires that any new school building greater than 12,000 square feet gross floor area must be sprinklered. Should the existing building undergo a major renovation the building will require upgrades to the existing sprinkler system to provide complete protection of all spaces, existing and new.

#### **EXISTING CONDITIONS**

The original building is protected with an automatic sprinkler system. The 1959 building addition is not protected with automatic sprinklers. The refrigeration addition to Kitchen is not protected with automatic sprinklers.

There is a 6" fire service which enters the main Mechanical Room. The service does not have a backflow prevention device.

The service has a 6 inch OS&Y gate valve and an alarm check valve. The gate valve is not supervised by the fire alarm system.

The main riser has a flow switch connected to the fire alarm system.

Sprinkler piping is black steel with threaded and grooved coupling joints.

The lower level sprinkler system is generally exposed.

Sprinklers in exposed areas are upright type. Sprinklers in ceiling areas are pendent type. Sprinklers are solder type.

Fire department connection is a Siamese type, 2-1/2" x 2-1/2" x 4" connection. There is a water motor gong above the connection.

#### RECOMMENDATIONS

Provide backflow preventer on fire service to meet current codes.

Provide automatic sprinkler system throughout the existing building and any addition.

Replace existing automatic sprinklers with quick response type sprinklers.

Replace existing system in the Original Building.




Fire Service & Alarm Valve

#### 9. FURNITURE & EQUIPMENT - TAVARES DESIGN ASSOCIATES, INC.

General Casework:

Description/Assessment:

- Sink locations are not Handicap Accessible
- Exterior shelving is exposed wood and with panels coming off
- Drawers on cabinets are broken and/or do not slide easily
- Furniture is of older styles with damage.
- Typically the student desk is combination chair/desk unit. This is a smaller work space than typically used in new schools.
- Teacher chairs are not uniform throughout the school. Several different styles are present.
- Metal teacher desks are in older conditions.
- · Literacy area and library are in open spaces.
- Lack of Storage space.
- Nurses area small and old.



Mismatched Furniture

#### Kitchen:

The current configuration of the kitchen is traditional with a straight line configuration. The amount of space creates congestion with too many students trying to get through the line. They must line up and this slows down the line.

The storage is spread out between multiple areas, including the receiving area and general storage area. The Cooler and Freezer storage areas are deep in the kitchen. The shipments must be carried through the prep spaces to get into the Storage.

Description/Assessment:

- Older equipment, including double convection oven.
- · Wood worktables.
- Wood shelving in storage room
- Rusted shelving
- Equipment too big for the population, range





Classroom Sink Cabinet



Kitchen Storage Shelving

#### 10. TECHNOLOGY - EDVANCE

TECHNOLOGY INFRASTRUCTURE

- MDF and one IDF which share space in a storage room
- No environmental control in equipment rooms
- Category 5 and 5e cabling with some in wall and mostly surface mount raceway
- · School is connected to MS via dedicated Fiber
- Spline Ceiling in Office Area, accessibility issues
- There was exposed network cabling in some areas

#### COMMUNICATIONS SYSTEM

- PA system is a Rauland Borg Telecenter, which is in working order and currently maintained by Signet. System could be expanded to support additional speakers
- Older Wall Speakers throughout
- Older Simplex Master Clock System
- Call Buttons in the rooms

#### TELEPHONE

 Older Nortel Telephone System with handsets in classrooms and office spaces and integrated with PA system

#### SECURITY

- Limited security, with one CCTV camera at front door with monitor in main office, and some older motion sensors in the hallways
- Video monitor of front door camera is located in the main office
- · Video intercom system with remote control of electric door latch

#### CLASSROOM INSTRUCTIONAL TECHNOLOGY

- SMART Technology Smart Boards with ultrashort projectors in some rooms and elnstruction boards with short throw NEC projectors in other rooms. Wall mount speakers for sound were also observed. All classroom appear to contain this technology
- HP Desktop Computers for teachers and students
- 4-5 computers in classrooms for students
- Mobile Chromebook carts were observed



Smartboard and Projector



Surface Mounted Cabling

#### NETWORK

- Older and obsolete Procurve HP switch chassis in the closet for networking. Switch equipment is still supported by HP
- Some UPS equipment supporting network switches
- 3-4 Enterasys wireless access points throughout

#### LARGE VENUE AV SYSTEM


• Older speakers and large venue AV system on stage area

RECOMMENDATIONS AS PART OF A RENOVATION PROJECT

- Increase level of security equipment to include surveillance, intrusion and access control
- Update clock system
- Update network cabling and equipment
- Expand wireless coverage and density
- Update telephone system
- Update technology equipment rooms as dedicated spaces that can be secured and conditioned
- Update AV equipment in large venue spaces like Cafeteria and Gym


#### 11. HAZARDOUS MATERIALS - FUSS & O'NEILL

The hazardous materials report is appended to section 3.1.4 within section K.



**Peebles Elementary School** Bourne, Massachusetts

### **Flansburgh** Architects



Peebles Elementary School *Bourne, Massachusetts* 

# **Peebles Elementary** Existing Building Elevations

## Flansburgh Architects

### Existing Conditions Report

Bournedale Elementary School

- A. Executive Summary
- B. Detailed Report
  - 1. Landscape
  - 2. Civil
  - 3. Architectural
  - 4. Structural
  - 5. HVAC
  - 6. Electrical
  - 7. Plumbing
  - 8. Fire Protection
  - 9. Furniture & Equipment
  - 10. Technology
  - 11. Hazardous Materials

### A. Executive Summary: Bournedale Elementary School

Bournedale Elementary School is relatively new construction, completed in 2009, and has been well maintained. With certain exceptions, the spaces are well-suited for programmatic requirements. The building could be enlarged with minimal renovation necessary to the majority of existing spaces.

Upon the selection of a preferred option, additional testing and investigations will be required to evaluate further the existing conditions of the building and site.

The following additional investigations are anticipated:

- Catch basin and drainage structure inspection
- Grease trap inspection
- Hydrant flow test
- Infrared roof scan
- Geotechnical test pits/borings
- Masonry removal to review wall flashings at base of wall to roof intersection

Working in conjunction with the Town of Bourne, Flansburgh Architects has prepared this existing conditions report in the Fall of 2016. This report considers the quality and anticipated life of the physical plant of the school, the building's interior and exterior building components, play fields and site features, structural systems, mechanical/electrical/plumbing systems, and technology infrastructure. The findings of this report will assist in finalizing the scope of the preferred option and assure that systems and materials left in place are sound and appropriate for the school's anticipated life. The process involved a physical survey of the buildings by the following qualified architects and engineers:

- Flansburgh Architects Architectural
- Garcia, Galuksa & DeSousa Mechanical, Plumbing, Electrical
- Boston Building Consultants Structural Engineers
- Nitsch Engineering Site/Civil
- Edvance Technology Consultants
- Waterman Design Landscape
- Tavares Design Equipment and Food Service Consultant
- Fuss & O'Neill Hazardous materials consultant

#### 1. LANDSCAPE/SITE DESIGN

The existing vehicular and pedestrian circulation systems will require redesign to accommodate the new facility's design intent and to reduce existing bus and car traffic congestion.

Exterior lighting, courtyards, site furnishings, site vegetation and play areas need further review and discussion of how they are used and what improvements will be needed.

#### 2. CIVIL

#### Storm Water

The storm water system meets today's standards. Existing structures to remain will need to be inspected and any drain lines should be cleaned.

#### Water

Existing exterior water lines for domestic use may remain, but this needs further review. A new water line for fire protection will be required to service the building.

#### Sewer

The existing shared septic field will require expansion to accommodate increase flow from design options being considered.

#### Natural Gas

The existing gas line into the school will be reviewed further to confirm that the pressure and flow will be adequate to accommodate any new addition. Anticipated loads for the design options being considered have been forwarded to the utility company for review.

#### Permitting Considerations

Any expansion and renovation disturbing more than 1 acre will require a permit by the United States Environmental Protection Agency's National Pollution Discharge Elimination Systems Program.

#### **3. ARCHITECTURAL**

Overall the building systems are in good to very good condition. The requirements to meet current codes will have minimal impact on all spaces and effectively require only minor renovation of the school to achieve compliance.

#### Exterior Wall

The exterior envelope is in good condition. Some minor cracking and spalling of masonry components are evident. Under the current energy standards the exterior wall's R-Value in line with current code and should meet today's standards. Increasing the exterior walls R-Value will reduce the size of the HVAC system and save energy.

#### Windows

Many of the original windows consist of double pane glazing. Steel lintels above the windows are in good condition.

#### Roof

The roof system was installed with a EDPM membrane and high R-value insulation throughout the school. It may be prudent to test the roof with an infrared camera to determine if moisture has infiltrated the roofing system.

#### Interior

The existing finishes have been well maintained throughout. A renovation that may include some upgrades throughout will require the protection of many finishes.

#### 4. STRUCTURAL

Since there will be no change in use, existing floors should be able to remain in use without any problems, unless a specific increase in loading is required.

#### 5. HVAC

The School has received good maintenance on the heating system and equipment over the years. The heating system presently installed is original to the building with a digital control system. Overall equipment is functioning correctly. We recommend the entire heating and ventilation system be evaluated and commissioned to ensure it is running at peak performance.

#### 6. ELECTRICAL

The existing electrical system of this facility meets the needs of a modern day facility. System should be tested and commissioned to ensure adequate performance.

#### 7. PLUMBING

The school plumbing systems can continue to be used with maintenance and replacement of failed components. Commissioning of the existing plumbing system is recommended.

#### 8. FIRE PROTECTION

Currently the building contains an automatic sprinkler system.

In general, Massachusetts General Law M.G.L. c.148, s.26G requires that any existing building over 7,500 square feet that undergoes major alterations or modifications must be sprinklered.

The proposed scope of work is considered a major alteration therefore an automatic combined sprinkler/ standpipe system is required for the building

A hydrant flow test will be required to evaluate water supply capacities.

#### 9. FURNITURE & EQUIPMENT

Generally the school is in very good shape as it was recently built. The school space is close to capacity.

#### **10. TECHNOLOGY**

The technology systems appear adequate for current use. Projecting use for the future requires additional considerations, such as:

- Increasing the size of the technology rooms
- Adding security systems
- Improving the data cable quality and installation
- Provide more power where needed for technology equipment.

#### 11. HAZARDOUS MATERIALS

The hazardous materials report is appended to section 3.1.4 within section K.

#### **B. Detailed Report**

#### 1. LANDSCAPE ARCHITECTURE - WATERMAN DESIGN ASSOCIATES

#### GENERAL

The Bournedale Elementary School is located on Ernest Valeri Road, directly west of the new Department of Public Works building. The site is immediately surrounded by native woodlands in all other directions. Residential properties exist further to the northwest and west, with Route 6 and the Cape Cod Canal further to the southeast. The portion of the site populated by the existing building is relatively flat, with little topographical relief in any direction. An open play field and tot lot at the south of the site sit at an elevation approximately 5' higher than the school building. The site contains the school building, along with the associated vehicular and pedestrian circulation systems and recreation facilities.

#### VEHICULAR ENTRANCES AND CIRCULATION

There exists three primary means of vehicular access and egress for the site from Ernest Valeri Road. The first, easternmost entrance is marked with a building identification sign. This is the main vehicular entrance for buses, passenger vehicles, and deliveries. Buses entering here proceed to the rear (west) of the building to the designated bus drop off/pick up area- a covered entrance at the northwest corner of the building. Upon drop off/pick up, buses exit the site by the third, westernmost curb cut along Ernest Valeri Road, then proceed right (east) back towards Route 6. Passenger vehicles for parent drop off/pick up proceed to the front (east) of the building to the designated student drop off area. Parents then loop around to exit at the same point of ingress, then proceed right (east) back towards Route 6. Faculty, staff and visitors also follow the same circulation loop as the parents. Delivery trucks proceed to the designated loading area at the south of the building, then exit in the same manner as the buses- at the third, westernmost curb cut along Ernest Valeri Road, then proceed right (east) back towards Route 6. The second (middle) entrance services Pre-K parent drop off/pick up and a smaller parking area for Pre-K faculty and visitors. Passenger vehicles for parent drop off/pick up proceed to the designated entrance, then loop around to exit at the same point of ingress, then proceed right (east) back towards Route 6. The predominantly one-way circulation route attempts to minimize traffic conflicts. The pavement condition of the vehicular entrances and interior circulation system can be characterized as good throughout the site.





Parent/Bus Drop-Off

Parking Circulation

#### PARKING LOCATION, ARRANGEMENT AND QUANTITY

Existing parking for faculty, staff and visitors is interspersed throughout the site. The majority of the parking is located at the front (east) of the building, adjacent to the main entrance. Additional parking exists along the edges of the access drives, with a separate lot accessed by the Pre-K entrance. There exist approximately 175 striped spaces throughout the entire site. It is our understanding that the existing quantity of parking

spaces is sufficient for normal school hours and for events involving after school functions or athletic activities. Accessible parking spaces all appear to comply with current MAAB standards (see Section 5 for further detail). The pavement condition of the parking areas mirrors that of the vehicular entrances, and shall also be characterized as good throughout the site.

#### PEDESTRIAN CIRCULATION

Due to the school's remote location, few students walk to school; however, a bituminous concrete walkway exists along Ernest Valeri Road, which connects the school grounds to Heather Hill Road. Once on school property, the bituminous concrete walkway connects to a series of internal walkways leading to different entrances to the school. A Portland cement concrete walk extends along the entire front (east) of the school at the student drop off area, spanning from the Pre-K play area to the main entrance. From the main entrance, a newly constructed bituminous concrete walkway extends along the entire rear (west) side of the school, from the bus drop off to the asphalt play area at the southwest corner of the building. The condition of the pedestrian circulation pavement on the site can be characterized as good throughout.

#### PEDESTRIAN ACCESSIBILITY AND MAAB COMPLIANCE

A total of seven (7) accessible parking spaces were identified within the property. Four (4) accessible parking spaces are located at the faculty/staff and visitor parking directly across from the main building entrance. These accessible spaces lead to the building by a combination bituminous concrete and Portland cement concrete walkways. The parking spaces, signage, access aisle and accessible route all appear to comply with current MAAB standards. However, a drainage issue within the accessible route has caused a significant buildup of sediment. One (1) accessible space is located at the south side of the building, servicing the free-play and tot-lot areas. The parking space, signage, access aisle and accessible route all appear to comply with current MAAB standards. One (1) accessible space is located at the rear (west) side of the building, servicing the rear entrance of the building. The parking space, signage, access aisle and accessible space is located at the Pre-K entrance to the building. The parking space, signage, access aisle and accessible space is located at the Pre-K entrance to the building. The parking space, signage, access aisle and accessible route all appear to comply with current MAAB standards. All of the existing doors leading into the building appear to be MAAB compliant. There are a series of cross walks with accompanying curb cuts and ramps,





Handicap Parking

Handicap Parking

as well as flush curbing conditions throughout the site. All of the curb cuts and crosswalks appear to comply with current MAAB Standards.

#### LOADING DOCKS AND SERVICE AREAS

There is one (1) loading area located at the southernmost end of the school building that services the cafeteria. Loading is handled by a single swing door, and a bay door at ground level. Its overall size appears sufficient for large deliveries.

#### COURTYARDS AND OTHER EXTERIOR STUDENT CONGREGATION AREAS

There exists an exterior courtyard for formal exterior student congregation that is located at the center of the academic wing, accessed only from the interior of the building. This courtyard has no site furnishings, but features a planting area filled with maturing perennials and ornamental grasses. There appears to be drainage issues at one of the entrances to the courtyard, where ponding occurs and water enters the building. There is another small asphalt free play area at the southwest corner of the building with painted pavement activities. The condition of the surfacing in this area appears to be good. A large expanse of lawn along with a tot lot, exist at the southern portion of the site. The tot lot contains modern play structures, and resilient rubber tile surfacing, which appear to be in good condition.

#### SITE LIGHTING FOR BUILDING, VEHICULAR AND PEDESTRIAN AREAS

Exterior wall-mounted or overhead-mounted lighting exists at all entrance doors to the building. The parking areas and vehicular circulation routes are predominantly illuminated by ornamental pole-mounted lighting or spotlight lighting secured to the facade of the building. Pedestrian lighting is handled by wall-mounted lighting.

#### SITE FURNISHINGS

There is a flagpole within a parking island area adjacent to the main building entrance. The flagpole is surrounded by lawn, and does not appear to have an MAAB compliant accessible route. There is a concrete and brick building identification sign at the primary access route along Ernest Valeri Road. Several benches are found along the sidewalk on either side of the main entrance and near the Pre-K playground. Trash receptacles are located throughout the site proximate to building entrances. No bicycle racks exist on the site.

#### SITE VEGETATION

There exists very little existing mature vegetation throughout the site. The site is abutted to the west and south by existing mature vegetation. There are a series of small deciduous and evergreen trees and shrubs interspersed around the building perimeter, which soften the architecture. All are in fair condition.

#### 2. CIVIL ARCHITECTURE - NITSCH ENGINEERING, Inc.

#### EXISTING SITE UTILITIES

The Bournedale Elementary School was built in 2007 and is located on a site with driveways, sidewalks, parking lots, athletic fields and playgrounds. The existing school is slab on grade with two stories and a two story connected wing off the back of the school. Based on record documents and site observations, the summary descriptions below represent the site utility conditions/assumptions as we understand them at this time.

#### STORM DRAINAGE

The existing Bournedale Elementary School building sits at a midpoint elevation on the site and area in front of the building includes the parking lots and driveways and generally slopes west towards the existing building. The topography to the south rises up to the athletic fields. The area to the north slopes to the west and the area behind the school slope to the west towards the wooded area on the west side of the site driveway. The school roof run-off is collected in internal roof drain system and is discharged to the site drainage system at various points around the building. Based on information gathered on the site visits and existing design plans there appears to be an extensive closed drainage system installed around the project site which includes catch basin inlets, drain manholes, water quality treatment structures, water quality swales, and a large retention pond located south east of the school building. Runoff from a large portion of the east side of the site is conveyed to this detention pond where it is stored and infiltrated back to groundwater. The runoff from the portion of the site behind the school building is collected in drywells and overflows via drainage outlets to the west of the site driveway. Visual inspection of the catch basins during the site visit identified that most of the drainage inlets did contain sumps within the basins. It appears that the current drainage system was designed to be in compliance with the Department of Environmental Protection (DEP) Stormwater Regulations in place at the time of the construction. Further investigation would be needed to insure that the drainage collection system would meet Current DEP Stormwater Standards but at first glance it appear that it would.



Storm Drain



Site Lighting

The building appears to be slab on grade, and based on the highly infiltrative nature of the site soils groundwater does not appear to be a substantial concern on this site.

Any addition to the existing building and/or new construction on this site will require updates to the existing stormwater collection system to insure that any new impervious area created would be treated and infiltrated to mitigate the overall rate and volume of stormwater traveling over the site under post development conditions. Any proposed work should include, at a minimum, the cleaning of the drainage system around the school site. However, Nitsch Engineering recommends that all existing catch basins and drainage structures should be inspected to determine if any structures need to be replaced or repaired.

#### WATER

Bournedale Elementary School is connected to the Municipal water system located under the front parking lot of the school. An existing 16" water main runs north/south there and the 8" CLDI loop for the school site connects to this 16" main on the north and south sides of the school building. A 12" water service also originating in the parking lot area in front of the existing school building runs northeast up Ernest Valeri Road where it connects farther east to the municipal system. The existing domestic water service for the school building is a 4-inch diameter CLDI pipe and the existing fire protection service line is an 8" CLDI pipe that both enter the existing building on its south face in the loading dock area and are fed off of the 8" service loop running around the building.

Multiple fire hydrants were observed within 300 feet of the School and appear to be tied into the 8" service loop that runs around the building.

Fire Hydrant flow tests would be recommended to determine if the pressures and volumes of flow in the water lines could support an addition to the existing school footprint.

#### SEWER

Sanitary sewer for the Bournedale Elementary School is serviced by a private onsite Sewerage Disposal System. Two 6-inch service laterals serve the school. The first exists the school near the main entrance and the second exits the school along the south face of the building in the loading dock area. These two services combine at a sewer manhole located just south of the school. A single 8-inch sanitary sewer pipe connects to a septic tank and then to a sewer lift station. The lift station sends flows south through a 6" PVC force main to the 90'X90' sewer disposal area located within the limits of the athletic fields.

A grease trap is also present on the site which collects sewerage from the kitchen areas prior to them entering the septic tank. The grease trap is located in the lawn area just south of the school building.

#### NATURAL GAS

The existing Bournedale School building is serviced by natural gas line of unknown size for the kitchen, water heater, and boiler. The existing gas service enters the site at the northwest end under the rear entrance drive to the site. It runs north/south behind the building under the access driveway and enters the school building on its south face in the area of the loading dock and connecting to the main gas regulator and meter. Gas is then distributed internally to the building.

A gas fired generator is located in the landscape area just south of the existing building. The gas runs to the generator from the south side of the school building.

#### UNDERGROUND/ABOVE GROUND FUEL TANKS

No underground or above ground fuel tanks were observed during Nitsch Engineering's site visit or on existing plans.

#### ELECTRICAL

According to record drawings, underground electric conduit enter the site from Ernest Valeri Road at the north east end of the site. The underground conduit then runs south along the edge of the access driveway to the transformer located in the landscape area just south of the existing school building. The service enters the building north of the transformer.

Site lighting conduit runs throughout the site to serve the multitude of sight lights in the parking areas, driveways and sidewalks. The site lighting is serviced from the existing school building. The location of the

service entry is unknown but likely exists the building in the area where the loading dock is along the south face of the building.

#### **TELEPHONE/COMMUNICATION SERVICES**

Underground Telephone/Cable service is fed to the site from the same general location as the electrical service. However instead of running to the south side of the building the Telecom lines run west and enters the building on the northern edge of its west face.

#### SITE CONDITIONS AND OPERATIONS

#### SOILS

Based on the Natural Resources Conservation Service (NRCS) Web Soil Survey (2011), the majority of the soils on the Bournedale Elementary School site is Merrimac and Barnstable Sandy loam of varying slopes. These soils are classified as a Hydrologic Soil Group (HSG) Type A and is described Soils having a high infiltration rate (low runoff potential) when thoroughly wet. These consist mainly of deep, well drained to excessively drained sands or gravelly sands. These soils have a high rate of water transmission. Further investigation will be needed to determine groundwater elevations and in-situ infiltration capacities to support new stormwater infrastructure.

#### PAVEMENT

The asphalt pavement in the parking lots, service drives, and walkways adjacent to the school were observed to be in good condition. The vertical granite curb is also good condition around the site with some minimal cracking and breaking observed.

#### SNOW REMOVAL

Snow is plowed and stored on site.

#### PRELIMINARY PERMITTING CONSIDERATIONS

#### WETLANDS PROTECTION ACT (310 CMR 10.00)

The Wetlands Protection Act ensures the protection of Massachusetts' inland and coastal wetlands, tidelands, great ponds, rivers, and floodplains. It regulates activities in coastal and wetlands areas, and contributes to the protection of ground and surface water quality, the prevention of flooding and storm damage, and the protection of wildlife and aquatic habitat.

A review of the Massachusetts Department of Environmental Protection (DEP) wetland layers available on the Massachusetts Geographic Information System (MassGIS), dated April 2007, appear to indicate that the Bournedale School site does not contain any wetlands on the property. There is small wetland area located just north of the school site but it is far enough way that it would not affect development on the school site. Nitsch recommends that a wetland scientist be brought on board to confirm that no wetlands are present.

Work performed within resource areas or buffer zones would require a filing of a Notice of Intent (NOI) or a Request for Determination of Applicability (RDA) with the local Conservation Commission and the Massachusetts Department of Environmental Protection.

#### SURFACE WATER SUPPLY PROTECTION (310 CMR 22.20)

The Massachusetts Department of Environmental Protection (DEP) ensures the protection of surface

waters used as sources of drinking water supply from contamination by regulating land use and activities within critical areas of surface water sources and tributaries and associated surface water bodies to these surface water sources.

A review of the Massachusetts DEP resource layers available on the MassGIS indicates the Bournedale School is not located within a Water Supply Protection Zone but is located very close to a medium and high yield aquifer area.

#### NATURAL HERITAGE & ENDANGERED SPECIES PROGRAM

A review of the 13th Edition of the Massachusetts Natural Heritage Atlas prepared by the Natural Heritage and Endangered Species Program (NHESP), dated October 1, 2008, indicates that the Bournedale School site is located within a Priority Habitat of Rare Species or an Estimated Habitat of Rare Wildlife however there are no vernal pools on or adjacent to the site.

#### FLOOD PLAIN

Based on the Flood Insurance Rate Map (FIRM), Community Panel Number 255210 0314J, dated July 16, 2014, it appears that the project site falls within an Unshaded Zone X which is described as an area determined to be outside the 0.2% annual chance (500-year) floodplain.

#### ZONING

According to the Zoning Map, the Bournedale Elementary School site is located in the SDD Zoning Overlay District. According to the Zoning Bylaw any use permitted in the R40 Zoning District is allowed in the SDD Overlay District. Municipal Uses are allowed in R40 Zoning Districts but must be approved by the Planning Board as part of a Site Plan Review.

The Dimensional Requirements for the site under an SDD zoning are as follows:

Minimum Lot Area of the First Dwelling Unit	40,000 square feet
Minimum Continuous Frontage	150 feet
Front Yard Setback	40 feet
Rear Yard Setback	25 feet
Side Yard Setback	25 feet
Building Height	40 feet
Maximum Building Lot Coverage	10%
Minimum Usable Open Space	40%

#### US EPA NPDES

Construction activities that disturb more than one acre are regulated under the United States Environmental Protection Agency's (EPA) National Pollution Discharge Elimination System (NPDES) Program. In Massachusetts, the USEPA issues NPDES permits to operators of regulated construction sites. Regulated projects are required to develop and implement stormwater pollution prevention plans in order to obtain permit coverage.

If the project will disturb more than one (1) acre this permit will be required.

SEWER CONNECTION PERMIT (314 CMR 7.00)

New connections to sanitary sewers, increases in flow to existing sanitary sewers, and discharges from businesses that are not considered to be "industrial wastewater" are subject to state requirements based on their expected discharge volume:

- Discharges ≤15,000 gallons per day (gpd) will need only local approvals (no approvals by MassDEP)
- Discharges >15,000 gpd but ≤50,000 gpd must file a one-time certification statement with MassDEP within 60 days after the connection starts to be used
- Discharges of > 50,000 gpd must obtain a MassDEP permit before construction

#### PERMITTING TABLE TIMELINE

Permit	Permitting Authority	Anticipated Filing Date	Anticipated Approval Date
Request for Determination of Applicability (RDA)	Town of Bourne Conservation Commission	After 100% DD	Approval in 1 to 3 months
Planning Board Site Plan Review	Town of Bourne Planning Board	From SD to DD	On-going - Up to 6 months+
National Pollutant Discharge Elimination System (NPDES) with EPA Notice of Intent (NOI)	Environmental Protection Agency (EPA)	After 100% CD	Once Submitted; Close NOI at end of Construction
Municipal Separate Storm Sewer System (MS4)	Environmental Protection Agency (EPA)	After 100% CD	Once Submitted, ongoing; yearly reports required

#### SUSTAINABLE SITE POSSIBILITIES

A new or reconstructed building provides opportunities to incorporate sustainable features which may help achieve Massachusetts Collaborative for High Performance Schools (MA-CHPS) points for funding.

*Bio-Swales* are grassed channels that capture runoff from parking lot and walkway that remove sediment from stormwater. Bio-swales can be used throughout the site, primarily along parking lot edges and access roads.

*Rain Gardens* use soils, plants, and microbes to treat stormwater before it is infiltrated and or discharged. Rain gardens are shallow depressions filled with sandy soil topped with a thick layer of mulch and planted with dense vegetation. Rain gardens can be utilized in parking islands and within the site to treat pavement run-off.

*Porous Pavement* is a paved surface with a higher than normal percentage of air voids to allow water to pass through it and infiltrate in the subsoil. Porous pavement, like all drainage systems, requires maintenance at least twice per year.

*Subsurface Structures* are underground systems that capture run-off (usually rooftop) and gradually infiltrate it into the groundwater. This method of infiltrating stormwater saves space by placing the system under parking lots or fields.

Based on the Natural Resources Conservation Service (NRCS) Web Soil Survey (2011) and record information, it appears that the site should have no issues providing for stormwater infiltration into the ground.

Opportunities for rainwater reuse are possible at a new or renovated Peebles Elementary School. However, the initial capital required for tanks, pumps and dual plumbing may be prohibitive in providing payback for water reuse.

#### TRAFFIC ASSESSMENT

As part of the Feasibility Study for the Peebles Elementary School project located in Bourne, Massachusetts, Nitsch Engineering worked with Flansburgh Architects (FA) to observe the existing traffic circulation and queue lengths on school campus and adjacent streets during drop-off and pick-up periods at two existing elementary schools in Bourne, and assess the site improvement options to be presented by FA. The 2 schools include:

- Peebles Elementary School, located at 70 Trowbridge Road, and
- Bournedale Elementary School, located at 41 Ernest Valerie Road

We have scheduled to collect Automatic Traffic Recorder (ATR) counts and Turning Movement Counts (TMC) for evaluation of roadway and intersection capacity analyses as part of the traffic study.

Figure 1 within the report is the Locus Map showing the proximity of each school and the surrounding roadway network.


#### TRAFFIC CIRCULATION

Nitsch Engineering conducted a site visit on Wednesday October 21, 2015 to observe the site circulation associated with the weekday morning drop-off, weekday afternoon pick-up and general queue lengths around each school site. The weekday morning drop-off observation occurred during partly cloudy conditions with a temperature of 48 degrees. The weekday afternoon pick-up activity occurred during partly cloudy conditions with a temperature of 58 degrees.

The following section includes figures that graphically depict the activity during the weekday morning and afternoon pick-up periods, and tables that quantify the parent and bus drop-off/pick-up totals for each school.

Туре		Parent		Βι	JS
Time		Drop-Off	Pick-Up	Drop-Off	Pick-Up
8:15 - 8:30		1			
8:30 - 8:45		3		4	
8:45 - 9:00		48		7	
9:00 - 9:15		17		2	
9:15- 9:30					
1:45 – 2:00			2		
2:00 - 2:15					
2:15 - 2:30			1		
2:30 - 2:45			7		
2:45 - 3:00			20		4
3:00 – 3:15			23		9
3:15 - 3:30					
Total		69	53	13	13


#### Table 2 – Bournedale Pick-Up/Drop-Off Quantity




**Figure 7: Bournedale Elementary School Site Circulation** Peebles Elementary School Bourne, Massachusetts



Data Source: MassGIS Nitsch Project #11078



**Figure 8: Bournedale Elementary Parking Utilization** Peebles Elementary School Bourne, Massachusetts





#### 3. ARCHITECTURE - FLANSBURGH ARCHITECTS

#### **GENERAL DESCRIPTION**

#### BUILDING

- a. Organization: The 2009 School is approximately 68,120 square feet. This space currently houses classrooms, a cafeteria, a kitchen, reception area, gymnasium, and offices.
- b. Circulation: The building is a two-story school in a rectangular plan with classrooms along the exterior perimeter, the cafeteria at the southwest corner, gym at the northwest corner, and media center centrally located in the facility.
- c. Program and Space Issues: The Bournedale Elementary School currently serves 435 students grades PreK through 4. The school's maximum class size goal is 24 students per classroom.

Comparisons with current MSBA space standards indicate that classrooms and core academic spaces are undersized.

<u>Room</u>	MSBA Standards	Bournedale Existing
Classrooms	850 - 950 s.f.	850 s.f.
Music	1,200 s.f.	920 s.f.
Cafeteria	3,260 s.f.	2,200 s.f.
Gymnasium	6,000 s.f.	2,980 s.f.

d. Physical Conditions:

#### **EXTERIOR ENVELOPE - WALLS**

2009: 4" exterior brick, air space and 6" metal stud wall.

Representative R-Values (20	09 walls)
4" Brick	0.39
2" Air Space	2.02
Air/Vapor Barrier	0.85
1/2" Gypsum Sheathing	0.45
Insulation	15.00
Vapor Barrier	0.15
Interior Gypsum Board	0.45

TOTAL R-VALUE ----- 19.76

Window: Double Pane R-VALUE = 2.04

Typical Exterior Walls - Current Minimum Requirements

Face Brick Air Space Air/Vapor Barriers 1/2" gypsum sheathing Insulation Vapor Barrier Interior Gypsum Board		0.39 2.02 0.85 0.45 22.00 0.15 0.45
TOTAL R-VALUE Window: Triple Pane R-		26.16
window. The rane R-	VALUE	- 5.00

16

#### EXTERIOR ENVELOPE - EXTERIOR BRICK AND PRECAST PANELS

The school is faced with split face CMU in a running bond pattern with ground face CMU accents. There are minor areas around the perimeter that have some sealant issues. The overall masonry is in good conditions, the sealant control joints are beginning to harden and may need to be replaced in the next few years. The precast sills at the windows are discolored and need to be cleaned and sealed. The roof-to-masonry connection has been problematic with cavity wall flashing creating leaks. Though some repairs have been attempted, leaks continue. We recommend removing the masonry and repairing or replacing the cavity wall flashing. The precast caps around the main entrance should be removed, reset, and resealed.



Cavity Wall Flashing at Roof

#### WALLS AND DOORS

The windows are double paned and are in good condition. The thermal performance of this system is average compared to current standards. The exterior doors are average for current thermal performance.

The doors and windows should undergo general maintenance to ensure they are performing properly. Water infiltration at courtyard doors has damaged the flooring. Exterior door thresholds should be replaced and a suitable threshold to minimize water infiltration should be installed.

#### **EXTERIOR ENVELOPE - ROOF**

Roofing on the building is PVC membrane roofing and rigid insulation, is approximately 7 years old, and is still under warranty.

Existing Flat Roof Construction		Roof Construction - Current Minimum Requirements	
PVC Membrane 4" Rigid Insulation (avg) Structure/Ceiling	0.40 20.00 5.00	Rubber/PVC 4" Polyisocyanurate Structure/Ceiling	0.40 24.00 5.00
TOTAL R-VALUE	25.40	TOTAL R-VALUE	29.40

The original membrane roofing appears in good condition. No active roof leaks were observed. This roof system warranty is still valid and the roofing manufacture should be contacted for a roof inspection prior to any renovation.

The roof is covered with a black substance similar to algae on the surface. Although it does not affect the roof membrane, it is slippery and may contribute to a slip and fall condition.

The roof should be washed to remove the substance.



Algae on Roof

#### INTERIOR

Finishes within the building are well-suited for school use and have been well maintained.

- e. Interior Partitions: In general, all interior partitions appear to be in good condition. The type of interior partitions vary throughout as follows:
  - Concrete masonry walls
  - Painted gypsum board
  - Ceramic tile

Existing gypsum board walls are in good to fair condition; minor denting and scrapes were observed. The wall between the music room and nurse's suite will require additional sound proofing. The corridor walls at the cafeteria need repairs and repainting.

- f. Flooring: In general, all flooring is in good condition. Some lifting of the VCT flooring has occurred at exterior doorways due to water infiltration. The type of flooring that exists is as follows:
  - Vinyl composition tile (12x12)
  - Ceramic tile
  - Rubber flooring
  - Carpeting
  - Wood flooring



Corridor Flooring



Marker Board



Wall Base

- g. Wall Base: The wall base is mostly vinyl in various heights and in good conditions. At ceramic tile areas, the base is ceramic. Ten percent of the base needs replacement due to damage.
- h. Ceilings: In general, the ceiling types are suspended ceilings or drywall soffits. The ceilings

are in good condition and only need replacement due to damage or if new systems above the ceilings are contemplated.

- Painted gypsum board
- Suspended acoustical tile
- Exposed structure
- i. Doors and Frames: Doors and frames vary in size and type, both metal and wood. They are in good condition. Gym door seals need replacement, exterior door thresholds need replacement, and acoustical seals at all music room and vestibule doors should be replaced to improve acoustical separation between music and administrative/nurse suites.

Finish hardware consists of levers, hinges, panic devices, and lock sets keyed to a master keying system. Maintenance of door hardware should be considered to extend its useful life.

- j. Fire Extinguishers: All existing fire extinguishers appear to be operational and certified. It appears that fire extinguishers are located in accordance with NFPA requirements.
- k. Tack Boards and Markers Boards: Both types of boards exist in various sizes and conditions. The recent fire code regulations do not allow for tack boards to be within 5 feet of egress doorways, some of the existing tack boards may need to be moved as a result. Marker boards are in good condition.

#### REGULATIONS

Refer to Code Evaluation appended to section 3.1.4 within Section F.

HANDICAP ACCESSIBILITY

Refer to MAAB/Accessibility Evaluation appended to section 3.1.4 within Section G.

#### 4. STRUCTURAL - BOSTON BUILDING CONSULTANTS, Inc.

#### EXISTING CONDITIONS

This school is a fairly new school, and was dedicated in 2009. The southerly portion is one story, and contains the gym, cafeteria and administrative areas. The northerly portion is two stories, and contains mostly classrooms. There is an open courtyard in the middle of the north wing. The design was based on the Sixth Edition of State Building Code.

The building is constructed of composite structural steel framing, open web steel joists, steel columns and many masonry bearing walls. The building appears in good structural condition.

On the exterior, the veneer is largely concrete masonry units, with some brick masonry. There are some locations 8" architectural recessed units were mortared to the adjacent units. These joints are cracking and acting as control joints. The mortar should be removed and replaced with sealant.





Exterior Masonry

Exterior Masonry

## 5. HVAC - GARCIA, GALUSKA, DESOUSA, Inc.

#### EXECUTIVE SUMMARY

Presently, the HVAC Systems serving the building are: a gas-fired hot water boiler plant serving perimeter fin-tube radiation, fan-coil units, terminal induction units, and terminal unit heaters. Tempered ventilation is provided to all occupied spaces via (3) Rooftop-mounted air-handling units containing gas-fired furnaces and direct expansion cooling sections.

The majority of the HVAC systems are original to the building which was built in 2009. All of the HVAC systems are considered to be in very good condition.

#### **BOILER PLANT**

The building is heated by a gas-fired hot water boiler plant. Hot water pumps with VFD drives, expansion tanks air separator and DDC (direct digital control) boiler plant controls are also installed.

There are (2) Viessmann (Model VD2A-195) gas-fired sectional cast iron hot water boilers. Each boiler has a capacity of 792 MBH input, 673 MBH output and are approximately 85% efficient. The boilers are equipped with Riello gas burners (Model RS45/M) with input capacity of 792 MBH each. Each boiler is vented via an individual steel breeching that terminates above the roof to building exterior.

There are two (2) hot water heating pumps (Bell & Gossett manufacture, 115 GPM, 65 Ft Head, 5 HP). Each pump is equipped with a VFD drive. The hot water pumps operate in a primary, standby fashion and serve the building hot water heating equipment via a hot water steel and copper insulated two-pipe distribution system.

Combustion air is provided for the boiler plant by a ceiling-suspended combustion air fan that is located in the Boiler Room & ducted to the outdoors through the roof. The combustion air fan was manufactured by Tjernlund and has a capacity of 625 CFM. The unit appears to be in good condition.



Boiler & Water Heater Breeching

## CHILLER PLANT

The building is provided with a roof-mounted air-cooled Chiller with a cooling capacity of 15 Tons (180 MBH). Chilled water pumps (Bell & Gossett manufacture, 35GPM, 50 Ft Head, 1.5 HP) with VFD drives, expansion tanks air separator and DDC (direct digital control) Chiller plant controls are also installed.

#### **KITCHEN**

The kitchen and servery are heated and ventilated by a gas-fired rooftop heating and ventilation unit. HV-1 serves the kitchen & servery areas (Greenheck Model IG-112-H30, Capacity of 3,600 CFM). There is also a gas-fired make-up rooftop air handling unit that provides make-up air for the kitchen exhaust hood. The make-up air unit, MAU-1, was manufactured by Greenheck (Model IG-109-H10) with a capacity of 2,000 CFM). The H&V and MUA units appear to be in good condition.

The kitchen hood and dishwasher are provided with exhaust air fan systems. EF-2 serves the kitchen hood; the fan was manufactured by Greenheck (Model CUBE-240HP-20 – 5,000 CFM). EF-4 serves the dishwasher; the fan was manufactured by Greenheck (Model GB-101-4 – 600 CFM).





Dishwasher Ductwork

#### EF-6

## CAFETORIUM

The cafeteria is heated, ventilated and air conditioned by a packaged rooftop gas-fired heating and DX cooling air handling unit, RTU-3. The RTU was manufactured by Trane and has a capacity of 7,000 CFM, and 182 MBH cooling. The unit appears to be in good condition. The RTU is connected to overhead supply air ductwork and diffusers & low wall return ductwork & grilles.

#### GYMNASIUM

The gymnasium is heated and ventilated by a rooftop energy recovery ventilation unit with gas-fired heating. The unit was manufactured by Greenheck (ERH-90H-30). The unit has a capacity of 6,000 CFM Supply air and is equipped with a total energy recovery wheel. The units appears to be in good condition. The ERV unit is connected to overhead supply air ductwork and diffusers and return ductwork that is routed to low wall return grilles.

## RESTROOMS

The majority of restrooms are heated by hot water convectors that appear to be in good condition. The restrooms are typically exhausted by rooftop exhaust air fan systems.

## ADMINISTRATION AREA

The administration, guidance and teaching office areas located throughout the building are typically heated, cooled, and ventilated by ceiling-mounted induction units connected to RTU-1 & RTU-2 by a concealed supply air duct system. Each induction unit also contains chilled water and hot water coils for spatial heating and cooling connected to the Chiller & Boiler plants via (two-pipe) insulated piping systems. Each space also contains a ceiling-mounted return grille connected to the associated RTU via a concealed return air duct system. All induction units, RTU's, and return grilles appear to be in good condition.

## **ENTRYWAYS & CORRIDORS**

All entryways and are heated by hot water cabinet unit heaters, either ceiling or wall-mounted. Corridors are generally provided with code-required ventilation via ceiling supply diffuser grilles connected to an RTU by a supply air ductwork system. This supply air also serves as make-up air for adjacent bathrooms & custodial storage spaces. All of the associated heating equipment appears to be in good condition.

#### CLASSROOMS

All classrooms are served by RTU-1 & RTU-2 with displacement ventilation systems consisting of lowwall displacement (low-velocity) air diffusers & ceiling-mounted return grilles connected to their associated

RTU's by supply & return duct systems. Classrooms also contained hot water fin-tube radiation for heating of the spaces.

#### COMPUTER CLASSROOMS

The Computer Classrooms are typically heated and ventilated by ceiling-mounted Supply & return air grilles connected to either of the RTU's via supply & return duct systems. Computer Classrooms are air conditioned by wall-mounted ductless cooling AC units. There are typically (2) wall mounted AC units installed in each of the Computer Classrooms. The AC units are connected with refrigerant piping to roof mounted air-cooled condensing units. The indoor and rooftop units were manufactured by Sanyo and appear to be in good condition

#### MEDIA CENTER

The media center is heated, cooled, and ventilated by ceiling-mounted induction units & active chilled beams connected to RTU-1 & RTU-2 by a concealed supply air duct system. Each active chilled beam also contains a dual-temperature water coils for spatial heating and cooling connected to the Chiller & Boiler plants via (two-pipe) insulated piping systems. Each space also contains a ceiling-mounted return grille connected to the associated RTU via a concealed return air duct system. All induction units, RTU's, and return grilles appear to be in good condition



Active Chilled Beams



Classroom Temperature Controller



Faculty Space Temperature Controller

## CONTROLS

The building HVAC systems are controlled by a DDC (direct digital control) system that was installed in 2009. A Front-End workstation was provided or interface & control of the DDC control system. It is our understanding that the existing controls system is operating satisfactorily and is in good condition

#### RECOMMENDATIONS

We recommend the following HVAC system repairs and/or renovations:

- The existing hot water heating equipment, including classroom unit ventilators, fan coil units, fin tube radiation, convectors and unit heaters should continue to be maintained per manufacturer's recommendations.
- The existing rooftop air handling equipment including packaged rooftop units, H&V units, ERV

units and exhaust air fans should be maintained per manufacturer's recommendations. RTU with DX cooling should be checked for proper refrigerant charge, compressor and condensing section operation.

- The majority of exhaust air fans should be serviced.
- Terminal heating equipment equipped with fans (i.e. fan coil units, unit ventilators and cabinet unit heaters) should be serviced.
- Split system AC units should be checked for proper refrigerant charge.

#### 6. ELECTRICAL - GARCIA, GALUSKA, DESOUSA, Inc.

#### ELECTRICAL SERVICE

The existing electrical service is in good condition and rated at 1600 Amps, 277/480V, 3 Phase, 4 Wire. The service is underground to the building and there is one secondary meter. There is a pad mounted transformer located outside. The main switchboard was manufactured by Square D. The switchboard is in good condition and has space for expansion.

#### DISTRIBUTION SYSTEM

The electrical distribution system is in good condition. Existing panelboards are adequate and they are located within dedicated electrical/mechanical spaces.

#### INTERIOR LIGHTING

Lighting is in good condition and mainly consists of fluorescent fixtures with electronic ballasts.

#### EXTERIOR LIGHTING

Exterior lighting is in good condition and consists of pole mounted metal halide in the parking/driveway areas and building mounted fluorescent lighting for walkways and surrounding area.

#### EMERGENCY POWER SYSTEM



Classroom with Pendant Lighting

There is an existing 125 KW natural gas Olympian generator. The generator is in good condition and is code compliant. The life safety automatic transfer switch is adequately located in a dedicated emergency electric closet. The generator is adequate for an addition project.

#### FIRE ALARM SYSTEM

The existing fire alarm system is in good condition, however there are system notification devices that are not compliant with current codes. The fire alarm control panel is a GE EST-3.

#### RECOMMENDATIONS

For an addition project we would recommend a new distribution panel to serve the addition and keep the existing main switchboard as it is in good condition. The existing generator could be re-used as it is in good condition. New transfer switches would be required to serve the new addition. We would recommend keeping the existing fire alarm system and adding new current code compliant notification devices throughout.

#### 7. PLUMBING - GARCIA, GALUSKA, DESOUSA, Inc.

#### EXECUTIVE SUMMARY

Presently, the Plumbing Systems serving the building are cold water, hot water, sanitary, waste and vent system, Kitchen waste and vent system, storm drain piping, and natural gas. A septic sewer system and municipal water service the Building.

The Building was constructed in 2008 and the plumbing systems are original to the building. The plumbing systems, in general, have been well maintained and are in good condition. The school plumbing systems could continue to be used with maintenance and replacement of failed components; however other nondependent decisions will likely force the plumbing upgrade. The plumbing systems infrastructure is adequate for a major renovation or addition.

The plumbing fixtures are in good condition. Bathroom fixtures are accessible and compliant per current regulations. Essentially, the code does not require these fixtures to be upgraded, but where new fixtures are installed, as may be required by other codes or concerns, the new fixtures may be low flow, water conserving type fixtures.

Cast iron is used for sanitary, Kitchen waste and storm drainage. The Kitchen waste system is directed to an exterior grease trap, with point of use interceptors at various pieces of Kitchen equipment. Rainwater from roof areas is collected by interior rain leaders which appear to discharge to a below grade site drainage system. Where visible, the cast iron pipe appears to be in good condition. Smaller pipe sizes appear to be copper. In general, the drainage piping can be reused where adequately sized for the intended new use.

Domestic water is copper with soldered fittings and is in good condition. In general, the domestic water piping can be reused where adequately sized for the intended new use. The domestic water heater is in good condition, but any additional hot water load for a major renovation or addition will require recalculation to determine is system is sufficiently sized.



#### **FIXTURES**

The water closets are predominately wall hung vitreous china with manually operated, 1.6 gallon per flush - flush valves. The early childhood fixtures are set at a lower height to accommodate younger children.

Urinals are wall hung vitreous china with manually operated, 1.0 gallon per flush - flush valves.

Lavatories are wall hung vitreous china. The majority of lavatories include sensor faucets with mixing valves. Accessible lavatories are fitted with protective insulation below fixture. There are wash-fountain type lavatories in the core Boys and Girls Toilet Rooms.

Drinking fountains consist of wall hung, stainless steel, accessible, electric water coolers.

Child Toilet

Janitor's sinks are generally floor mounted, 24" X 24" X 12" terrazzo basins. Faucets are equipped with vacuum breakers.

Art Room sinks are stainless steel, drop-in fixtures with gooseneck faucets and wrist blade handles. Each Art Room sink is equipped with a solids interceptor.

Staff Sinks and classroom sinks are stainless steel, drop-in fixtures with gooseneck faucets and wrist

blade handles. The classroom sinks include a bubbler. Nurses Exam Sink includes an eyewash.

Kitchen area fixtures are in good condition. There are a total of two (3) interior grease interceptors. The dishwasher, pot wash sink, and kettle each are directed to an interceptor.

## WATER SYSTEMS

The main domestic water service is located in the Custodial Storage Room. The service is 4" in size and includes a 3" water meter and a 4" reduced pressure backflow preventer. The main domestic cold-water distribution is 4" in size.

The domestic water is in good condition. Piping, where exposed, appears to be insulated copper with sweat joints. Ball valves are utilized for isolation purposes and are tagged and charted.



Classroom Sink

The main domestic hot water for the School is generated through gas fired water heater and storage tank. The hot water systems are recirculated. There is a thermostatic mixing valve on the systems to prevent scalding. An expansion tank is installed on the cold water make-up line. The water heater has a natural gas input of 715,000 BTUH and 250 gallon storage capacity. The kitchen is serviced with 140 degree F. hot water. The domestic hot water system is in good condition.

## DRAINAGE SYSTEMS

Cast iron is used for sanitary, Kitchen waste and storm drainage. Where visible, the cast iron pipe appears to be in good condition. Smaller pipe sizes appear to be copper. The Building sanitary drainage is directed to a site septic system. The Kitchen waste system is directed to an exterior grease trap. The pot wash sink, dishwasher and kettle are each equipped with a local m-ground grease interceptor. The storm system exits to a site storm system at multiple locations.

In general, the cast iron drainage piping can be reused even in a major renovation or addition where adequately sized for the intended new use.

## GAS

An elevated pressure natural gas is supplied to the building. The exterior gas meter is located just outside of the Kitchen Storage Room. The natural gas includes a regulator to serve the building heating system, the domestic hot water heater, and the Kitchen equipment. At the meter there is also a dedicated line with a regulator to serve the emergency generator.

Gas piping is black steel with a combination of screwed and welded joints and fittings depending on the size of the pipe.

Natural gas is provided for kitchen cooking equipment. Kitchen supply is equipped with an automatic shutoff valve.

## RECOMMENDATIONS

In general, the building Plumbing systems are in good condition and appear to be code compliant. The plumbing systems infrastructure is adequate for a major renovation or addition.

We recommend that the plumbing systems continue to receive preventative maintenance.

### 8. FIRE PROTECTION - GARCIA, GALUSKA, DESOUSA, Inc.



Sprinkler Zone Control Valve

#### EXECUTIVE SUMMARY

The entire school is fully protected by an automatic sprinkler system. The Fire Protection system was installed in 2008. The majority of the equipment and systems installed appear to have been well maintained and are generally in good condition.

Should the existing School undergo a major renovation or addition, the building will require upgrades to the existing sprinkler system to provide complete protection of all spaces, but the system infrastructure is adequate to support such an upgrade. In general, the sprinkler piping can be modified to suit new architectural and ceiling layouts.

#### **EXISTING CONDITIONS**

There is an 8" fire water service that enters the building in the Custodial Storage Room. This service includes a 6" Watts double check valve assembly with 4" wet alarm valve, a 4" dry alarm valve and a wall

mounted Fire Department Connection. The sprinkler distribution main is 4" after the alarm valves. The system includes a Sprinkler zone control valve assemblies at the Custodial Storage Room ceiling to isolate the South section of First Floor sprinklers. The North Section of the school is isolated from the Sprinkler zone control valve located in Stair 3. The Second Floor sprinklers are isolated by the Sprinkler zone control valve assembly at the Second Floor of Stair 3. Exposed Sprinkler piping is painted off white.

The existing Stage is equipped with (2) two Fire hose cabinets on either side. Each Stair landing includes a Fire Department valve. The Roof includes a Roof Hydrant with an OS&Y indicating valve operable from the Roof level.

The sprinkler heads throughout rooms without ceilings are upright type sprinkler heads with exposed piping. In rooms with finished ceilings the sprinkler heads are semi recessed pendent type with chrome escutcheons.

#### RECOMMENDATIONS

In general, the building Fire Protection system appears to be in good condition and has been well maintained and can be modified for major renovation or addition.

## 9. FURNITURE & EQUIPMENT - TAVARES DESIGN ASSOCIATES, INC.

Generally the school is in very good shape as it was recently built. The school space is close to capacity.

## GENERAL FURNITURE:

Description/Assessment:

- Cafeteria is at capacity.
- Media center has no more space for additional books.
- Gym climbing wall is in hallway.

#### KITCHEN:

Description/Assessment:

- Extra unused space in dish room.
- Lack of adequate storage.
- No room for expansion of cooking battery in current location.
- Lack of expansion space for serving line in current location.



Cafeteria



Dish room



Media Center



Climbing Wall



Dry Storage

### 10. TECHNOLOGY - EDVANCE TECHNOLOGY DESIGN

#### TECHNOLOGY INFRASTRUCTURE

- Dedicated MDF and one IDF with sufficient power and environmental conditioning;
- Category 6 data cabling;
- Comcast for internet and connectivity
- Drop Ceilings with above ceiling accessibility

#### COMMUNICATIONS SYSTEM

- PA system is a Rauland Borg Telecenter, which is appears to be in good working order and currently maintained by Signet. System could be expanded to support additional speakers and clocks;
- Newer integrated master clock system;
- Newer room and hallway speakers and secondary clocks throughout;
- Digital signage displays were observed

#### TELEPHONE

- Newer Vertical VoIP Telephone System with integrated voicemail server and handsets at teacher's desk in classrooms and office spaces;
- · Integration with PA system is lacking but could be corrected

#### SECURITY

- Modern access control, Intrusion control and video surveillance equipment that is expandable;
- · Cameras were observed in hallways and exterior of building;
- · Video monitor of cameras is located in the main office;
- Video intercom "Alphones" with remote control of door locks. System is expandable

## CLASSROOM INSTRUCTIONAL TECHNOLOGY

- SMART Technology Smart Boards with standard throw projectors mounted in the ceilings. All classrooms appear to contain this technology;
- Small laser printers at the teacher's desk area



Access Control System



Digital Signage



Security Camera Display

- HP Desktop Computers for teachers and 4 computers for students;
- Mobil Chromebook carts were observed;
- One computer lab with multiple student desktop computers and similar AV equipment as the classroom

#### NETWORK

- Newer Procurve HP switch chassis in the closet for networking. Switch equipment is expandable and supported by HP;
- UPS equipment supporting network switches;
- Enterasys wireless access points throughout that can be expanded

## LARGE VENUE AV SYSTEMS

Large venue AV system in Cafeteria (with stage) and Gym

## RECOMMENDATIONS AS PART OF A RENOVATION PROJECT

- Review security plans and expand surveillance as required;
- Expand wireless access as required;
- Update and possibly replace telephone system due to difficulty obtaining replacement parts;
- Upgrade from standard throw projectors in the ceilings to ultrashort throw projectors;
- · Review AV equipment in large venue spaces like Cafeteria and Gym and update as required;
- All building related technology systems appear to be recent and are in good working condition with capability for expansion. These core systems include building communications, clock system, infrastructure cabling, security system (intrusion, access control and surveillance) and large venue AV systems. The possibility exists that the existing core systems could be expanded to accommodate expansion of the school.


## 11. HAZARDOUS MATERIALS - FUSS & O'NEILL

Refer to full Hazardous Materials report appended to section 3.1.4 within section K.



**Bournedale Elementary School** Bourne, Massachusetts

## **Flansburgh** Architects



EAST ELEVATION

**Bournedale Elementary School** Bourne, Massachusetts

## **Bournedale Elementary Existing Building Elevations**

- $|1\rangle$  control joint to be resealed
- - - CONTROL JOINT
- PRECAST SILLS TO BE REPOINTED
- **ROOF FLASHING TO BE REPLACED ROOF/WALL INTERFACE, FURTHER** INVESTIGATION REQUIRED
- STAINING ON BLOCK AND PRECAST SILLS TO BE CLEANED AND SILLS TO BE SEALED. FURTHER INVESTIGATION REQUIRED



## **Flansburgh** Architects



## F. CODE EVALUATION

## Peebles Elementary School

In accordance with the code, an existing building is presumed to have met the codes and regulations in effect at the same time of its construction and is allowed to continue in its use, provided it is maintained per the original code. Current building codes are applicable to any alteration, addition or change in use of the structure, in accordance with 780 CMR. The requirements to meet current codes will impact all spaces and effectively require a full renovation of the school to achieve compliance.

Current codes applicable to the project include the following:

Building: 780 CMR: Massachusetts State Building Code, 8th Edition (2009 International Building Code)
Fire Prevention: 527 CMR: Massachusetts Fire Prevention Regulations (2012 NFPA 1),
M.G.L. C148 §26G – Sprinkler Protection
Mechanical: 2009 International Mechanical Code
Electrical: 527 CMR 12.00: Massachusetts Electrical Code (2014 National Electrical Code)
Plumbing: 248 CMR: Massachusetts Plumbing Code
Energy Conservation: 2012 International Energy Conservation Code

The occupancy of the facility in non-separated mixed use with assembly and educational uses as follows:

Classrooms, School Offices, Media Center	E - Educational
Cafeteria, Gymnasium	A-3 – Accessory Assembly

## CONSTRUCTION CLASSIFICATION

Based upon the definitions in the current code, the minimum classification of the building is as follows:

1953 (Original)	IIB Noncombustible
1959 (Addition)	IIB Noncombustible

A renovation project is governed by 2009 IEBC - International Existing Building Code, incorporated into 780 CMR as Chapter 34. This chapter is "intended to maintain or increase public safety, health, and general welfare, without requiring full compliance with the code for new construction." The scope of work will determine the level of compliance required by code.

- i. Building renovation For continuation of the same use groups the building shall comply with 2009 IEBC.
- ii. New Building Systems Any new building system or portion thereof shall conform to 2009 IEBC for new construction to the fullest extent practical.
- iii. Alterations and Repairs Alterations of repairs to existing buildings, which maintain or improve the performance of the building may be made with like material, unless required otherwise under 2009 IEBC - Structural Requirements for Existing Buildings.
- iv. Number of Means of Egress Egress for the existing facility is sufficient in accordance with the current building code.
- v. Capacity of Exits There is sufficient egress capacity to meet current codes at the doors throughout the facility.
- vi. Length of Access Travel Shall not exceed 200 feet, in building without a sprinkler system. All

areas of the existing building are within 200 feet of an exit.

- vii. Exit Signs and Lights For notes on the existing system, refer to the Electrical Existing Conditions Report.
- viii. Means of Egress Lighting Refer to the Electrical Existing Conditions Report.
- ix. Height and Area Limitations Under 2009 IEBC the building is in conformance with applicable height and area limitations, so long as there is no change in use. Additions may be made to the structure.
- x. Fire Protection Systems Fire protection systems must be provided for existing buildings that are "substantially" altered or "substantially" renovated where required for the specific use group. 30% rule, if 30% of the assessed value is expended then fire protection must be installed.
- xi. Enclosure of Stairways Open egress stairways are prohibited. There shall be no minimum fire resistance rating required for an existing enclosure of a stairway.
- xii. Assembly Use Groups Any alteration within an assembly use group shall comply with the code for new construction. This applies to the cafeteria, auditorium and gymnasium.
- xiii. Accessibility for Persons with Disabilities Accessibility for persons with disabilities shall be provided in accordance with the regulations of the Architectural Access Board.
- xiv. Energy Provisions for Existing Buildings Alterations to components affecting energy conservation performance shall comply with 2009 IECC International Energy Conservation Code.
- xv. Evaluation of Existing Building The structural engineer shall make a structural evaluation of the existing building to determine the adequacy of all structural systems that are affected by alteration or damage to be repaired.
- xvi. Existing Lateral Load Capacity (Refer to Structural Existing Conditions Report for further information) Alterations shall not be made to elements or systems contributing to the lateral load resistance unless the altered lateral load resisting system conforms to 2009 IEBC.
- xvii. Earthquake Loads (Refer to Structural Existing Conditions Report for further information) -For no change in use groups, but alterations exceeding 50% of the assessed valuation of the building, the project is defined as Seismic Hazard Category 2.
- xviii. Earthquake resistance shall comply with the requirements of 2009 IEBC.
- xix. The provisions of NFPA govern Fire Resistant Materials Fire resistant construction systems.

#### Interior Finishes 780 CMR 8

Interior trim and finishes altered as a part of a renovation shall conform to the requirements of the NFPA. Flame spread of Interior Finishes for the E, A-2, and A-3 Use Groups, shall conform to current requirements. Existing finishes are code compliant.

The State Fire Marshall introduced regulations in 2003 restricting display of paper in egress areas. The provisions are as follows:

- i. Paper display in classrooms shall not exceed 20% of the wall area. Measurement of wall area shall include windows and doors.
- ii. Paper display in corridors shall not exceed 10% of the wall area and shall not be placed within 5 feet of an egress door. It shall be applied directly to the wall and shall not be grouped in areas bigger than 6 feet by 12 feet.

Below are listed deficiencies noted during evaluation of the existing buildings.

- 1. LANDSCAPE
- The larger play structure does not appear to meet fall zone height requirements.
- 2. CIVIL
- Current drainage system is not in compliance with the current Department of Environmental Protection (DEP) Stormwater Regulations (2008).

## 3. ARCHITECTURE

- Existing envelope has a low R-value of approximately 8.65. Current energy code requires approx. R-22.
- Existing roof has a low R-value of approximately 11. Current energy code requires at least R-25.
- Egress stair at south end of 1953 building does not discharge to grade.
- Annex building is not protected with a sprinkler system.
- Door width of 2'-4" at individual toilet rooms is insufficient. Clear width at all doors should be minimum 2'-8".
- ADA lift encroaches on the required clear width of stair; minimum of 3'-8" is required.
- Windows near grade at addition are not tempered and are prone to breaking. All glazing within 18" of grade or floor level is required to be tempered, as is fixed glazing within 24" of a doorway with bottom edge less than 60" above floor level.
- Plumbing fixture counts are insufficient to support occupant load.
- 4. STRUCTURAL
- At the time these buildings were constructed, un-reinforced masonry was allowed for load bearing elements, and lateral load analysis for wind was commonly ignored for low rise buildings, assuming that masonry walls and partitions would provide sufficient resistance. Seismic provisions were not a requirement. Existing wall anchorage, and transitions between the concrete and wood floors at the Multipurpose Room (Gym) are not adequate by today's standards.
- The most significant structural item is likely to be alterations to the lateral load-resisting system. We assume that the work area will exceed 50% of the building area. That will require existing unreinforced masonry walls to be tied into the floor and roof diaphragms.
- Lateral bracing is required at tops of interior partitions.
- Anchoring exterior walls to roof and floor diaphragms is necessary.
- 5. HVAC
- Dishwasher must be vented separately from the main kitchen exhaust hood.
- Make-up air for the kitchen hood is provided through openings between the cafeteria and kitchen wall
  as there is no direct supply of make-up air or ventilation for the kitchen. This lack of ventilation within
  the kitchen is not code-compliant.
- The stage area was not provided with any supply or exhaust ventilation air, leaving this area non-code compliant.
- The music room and the teachers' workroom in original locker rooms were provided with convection heat however, they were not provided with any source of ventilation air and based on the size and population of the space would be considered non-code compliant.
- At all classroom unit ventilators, exterior wall louver providing outside ventilation air is undersized to meet the standard ASHRAE II control cycle.

- 6. ELECTRICAL
- Although there have been some upgrades to the lighting and emergency lighting, most of the equipment is not up to current industry standards, nor current energy efficiency or code requirements.
- Lighting levels do not appear to provide sufficient footcandles for egress paths.
- Additional exit signs will be required throughout the building.
- Each classroom should have a minimum of (2) duplex receptacles per wall and (2) double duplex receptacles at classroom computer workstations.
- A new fire alarm system will be required to meet the latest codes.
- 7. PLUMBING
- In terms of water conservation fixtures, their use is governed by the provisions of the Plumbing and Building Code. The existing plumbing fixtures do not meet current water conservation requirements.
- 8. FIRE PROTECTION
- Massachusetts General Law M.G.L. c.148, s.26G requires any existing commercial building which undergoes a major renovation or building addition which results in a gross floor area of greater than 7,500 square feet must be sprinklered throughout. Massachusetts code requires that any new school building greater than 12,000 square feet gross floor area must be sprinklered. Should the existing building undergo a major renovation the building will require upgrades to the existing sprinkler system to provide complete protection of all spaces, existing and new. The proposed scope of work is considered a major alteration; therefore, an automatic combined sprinkler/standpipe system is required for the building
- There is a 6" fire service which enters the main Mechanical Room. The service does not have a backflow prevention device.
- The service has a 6 inch OS&Y gate valve and an alarm check valve. The gate valve is not supervised by the fire alarm system.

## F. CODE EVALUATION

## **Bournedale Elementary School**

The existing facility as a whole is in compliance with the original code. This does not mean that it meets every standard of the current code. In accordance with the code, an existing building is presumed to have met the codes and regulations in effect at the same time of its construction and is allowed to continue in its use, provided it is maintained per the original code. Current building codes are applicable to any alteration, addition or change in use of the structure, in accordance with 780 CMR.

Current codes applicable to the project include the following:

Building: 780 CMR: Massachusetts State Building Code, 8th Edition (2009 International Building Code)
Fire Prevention: 527 CMR: Massachusetts Fire Prevention Regulations (2012 NFPA 1),
M.G.L. C148 §26G – Sprinkler Protection
Mechanical: 2009 International Mechanical Code
Electrical: 527 CMR 12.00: Massachusetts Electrical Code (2014 National Electrical Code)
Plumbing: 248 CMR: Massachusetts Plumbing Code
Energy Conservation: 2012 International Energy Conservation Code

The occupancy of the facility in non-separated mixed use with assembly and educational uses as follows:

Classrooms, School Offices	E - Educational
Cafeteria, Gymnasium, Media Center	A-3 – Accessory Assembly

## CONSTRUCTION CLASSIFICATION

Based upon the definitions in the current code, the minimum classification of the building is as follows:

2009 building

**IIB Noncombustible** 

A renovation project is governed by 2009 IEBC - International Existing Building Code. This chapter is "intended to maintain or increase public safety, health, and general welfare, without requiring full compliance with the code for new construction."

- i. Building renovation For continuation of the same use groups the building shall comply with 2009 IEBC.
- ii. New Building Systems Any new building system or portion thereof shall conform to 2009 IEBC for new construction to the fullest extent practical.
- iii. Alterations and Repairs Alterations of repairs to existing buildings, which maintain or improve the performance of the building may be made with like material, unless required otherwise under 2009 IEBC - Structural Requirements for Existing Buildings.
- iv. Number of Means of Egress Egress for the existing facility is sufficient in accordance with the current building code.
- v. Capacity of Exits There is sufficient egress capacity to meet current codes at the doors throughout the facility.
- vi. Length of Access Travel Shall not exceed 200 feet, in building without a sprinkler system. All areas of the existing building are within 200 feet of an exit.

- vii. Exit Signs and Lights For notes on the existing system, refer to the Electrical Existing Conditions Report.
- viii. Means of Egress Lighting Refer to the Electrical Existing Conditions Report.
- ix. Height and Area Limitations Under 2009 IEBC the building is in conformance with applicable height and area limitations, so long as there is no change in use. Additions may be made to the structure.
- x. Fire Protection Systems Fire protection systems must be provided for existing buildings that are "substantially" altered or "substantially" renovated where required for the specific use group. 30% rule, if 30% of the assessed value is expended then fire protection must be installed.
- xi. Enclosure of Stairways Open egress stairways are prohibited. There shall be no minimum fire resistance rating required for an existing enclosure of a stairway.
- xii. Assembly Use Groups Any alteration within an assembly use group shall comply with the code for new construction. This applies to the cafeteria, auditorium and gymnasium.
- xiii. Accessibility for Persons with Disabilities Accessibility for persons with disabilities shall be provided in accordance with the regulations of the Architectural Access Board.
- xiv. Energy Provisions for Existing Buildings Alterations to components affecting energy Conservation performance shall comply with 2009 IECC - International Energy Conservation Code.
- xv. Evaluation of Existing Building The structural engineer shall make a structural evaluation of the existing building to determine the adequacy of all structural systems that are affected by alteration or damage to be repaired.
- xvi. Existing Lateral Load Capacity (Refer to Structural Existing Conditions Report for further Information) Alterations shall not be made to elements or systems contributing to the lateral load resistance unless the altered lateral load resisting system conforms to 2009 IEBC.
- xvii. Earthquake Loads (Refer to Structural Existing Conditions Report for further information) -For no change in use groups, but alterations exceeding 50% of the assessed valuation of the building, the project is defined as Seismic Hazard Category 2.
- xviii. Earthquake resistance shall comply with the requirements of 2009 IEBC.
- xix. The provisions of NFPA govern Fire Resistant Materials Fire resistant construction systems.

#### Interior Finishes 780 CMR 8

Interior trim and finishes altered as a part of a renovation shall conform to the requirements of the NFPA. Flame spread of Interior Finishes for the E and A-3 Use Groups shall conform to current requirements. Existing finishes are code compliant.

The State Fire Marshall introduced regulations in 2003 restricting display of paper in egress areas. The provisions are as follows:

i. Paper display in classrooms shall not exceed 20% of the wall area. Measurement of wall

area shall include windows and doors.

ii. Paper display in corridors shall not exceed 10% of the wall area and shall not be placed within 5 feet of an egress door. It shall be applied directly to the wall and shall not be grouped in areas bigger than 6 feet by 12 feet



Display Areas in Corridor

Below are listed deficiencies noted during evaluation of the existing building.

- 6. ELECTRICAL
- The existing fire alarm system is in good condition, however there are system notification devices that are not compliant with current codes.

G. MAAB/ADA Evaluation


## G. MAAB/ADA EVALUATION

## **Peebles Elementary School**

The building should comply with the 2006 version of the Massachusetts Architectural Access Board (MAAB) regulations. Although there have been some upgrades such as installation of lifts, most of the building is not up to current accessibility code. The regulations require that any building undergoing a renovation where the costs exceed 30% of its assessed value must comply with the requirements of the MAAB.

Accessibility Code: 521 CMR: Massachusetts Architectural Access Board Regulations (2006)

Below are listed deficiencies noted during evaluation of the existing buildings.



Gymnasium Handicap Lift

#### 1. LANDSCAPE

- Number of accessible parking spaces is insufficient: two provided; three required. The parking spaces, signage, access aisle, and accessible route to the accessible building entrance all do not appear to comply with current MAAB standards.
- None of the existing doors leading into the building appear to be MAAB compliant.
- Crosswalk at Trowbridge Road does not include a curb cut ramp, and does not comply with current MAAB Standards. No accessible route from Trowbridge Rd exists.
- The accessible route to the tot lot does not meet current MAAB universal accessibility standards.
- The tot lot does not appear to comply with current MAAB universal accessibility standards.

## 3. ARCHITECTURAL

- Main school entry is not accessible due to six-inch step into entry vestibule. Out-swinging doors must have flat surface beyond swing of door. No wheelchair access to main entrance is provided.
- Finish hardware consists of a mix of knobs and levers, hinges, panic devices, and locksets. The current door hardware knobs do not meet handicap accessibility code regulations and need to be replaced with levers. Doors at classroom storage do not include accessible door pulls.
- Guardrails, railing heights, mix of materials, handrail profile vary throughout the project and are noncompliant. Requirements for height, handrail profile are as follows:
- Minimum guardrail height should be 42"; handrail height should be 34" above stair nosing.
- Handrail at stairs is not continuous and extensions are not provided.
- Handrail profile is 2" round and should not exceed 11/2".
- Required distance of 1<sup>1</sup>/<sub>2</sub>" clear between handrail and wall or guardrail is not continuously maintained.
- Second means of egress from gymnasium is metal fire escape with non-compliant guardrail. Vertical spacing of pickets exceeds permissible dimension.
- Railing at exterior areaway is too low.
- Drinking fountains are not accessible; fixtures protrude into knee space.
- Toilet partitions do not include accessible stalls.
- · Individual toilets between classrooms do not include adequate clearances for accessibility.
- Classroom sinks do not provide accessible knee space.
- Fixture controls are not accessible.
- From most remote point of upper level, a student in a wheelchair must travel 400 feet to reach the cafeteria and must utilize two chair lifts and one vertical lift.
- Required push/pull clearances at doorways are not provided.

### 6. ELECTRICAL

- The fire alarm system is addressable, but does not meet ADA requirements and is lacking coverage in some areas.
- Existing strobes do not meet ADA for intensity; classrooms and toilet rooms do not have ADA horn/ strobe units.
- 7. PLUMBING
- The plumbing fixtures are in fair condition. The fixtures do not meet current accessibility codes. In general, the fixtures appear to have served their useful life. Current Access Code requires accessible fixtures wherever plumbing is provided.
- Lavatories in the student gang toilet rooms are molded stone wash fountains, with foot operation, not permitted under current accessibility code.
- 9. FURNITURE & EQUIPMENT
- Classroom sinks do not provide accessible knee space.

## G. MAAB/ADA EVALUATION


## **Bournedale Elementary School**

The building should comply with the 2006 version of the Massachusetts Architectural Access Board (MAAB) regulations. Designed under the 1996 version of MAAB regulations, for the most part, the building is in compliance with the current accessibility code. The regulations require that any building undergoing a renovation where the costs exceed 30% of its assessed value must comply with the requirements of MAAB.

Accessibility Code: 521 CMR: Massachusetts Architectural Access Board Regulations (2006)

Below are listed deficiencies noted during evaluation of the existing building.

- 1. LANDSCAPE
- The flagpole is surrounded by lawn and does not appear to have an MAAB compliant accessible route.
- 6. ELECTRICAL
- Existing fire alarm strobes do not meet ADA for intensity.



## H. PROPOSED SOILS EXPLORATION AND GEOTECHNICAL EVALUATIONS

Geotechnical Services Inc. performed geotechnical engineering services associated with the Peebles and Bournedale Elementary School sites in Bourne.

#### PURPOSE:

The purpose of the work is provide information on the subsurface soil conditions to determine bearing capacity, foundation design, and other subsurface related information to aid in the future design of a potential addition or new construction option on these sites.

## PEEBLES ELEMENTARY SCHOOL SITE

#### TASKS PERFORMED:

- A total of four test borings were drilled on site and identified as borings B-1 to B-4. The borings were drilled to depths ranging from approximately 18.5-ft to 22-ft below the existing grade.
- Standard Penetration Tests (SPTs) were performed and split-spoon soil samples were retrieved generally at the ground surface and subsequently at 5-ft intervals.
- The finalized logs for the test borings were compiled.

#### FINDINGS:

- Topsoil was encountered in all the test borings except boring B-4. The thickness of the topsoil encountered varies from about 3-in. to 8-in.
- The naturally deposited Sand Deposits were encountered in all the borings. The Sand Deposits generally consist of medium dense to dense, brown, fine to medium SAND with varying amounts of gravel, coarse sand and silt.
- Very large boulders were observed in the vicinity of boring B-3 and along the hillside in an area just south of the paved area behind the existing school.
- Groundwater levels were measured within each borehole which varied from about 7 to 8-ft below grade at the time the borings were completed.

## CONCLUSION / RECOMMENDATIONS:

- 1. It is anticipated that the foundations for any new construction will bear upon the Sand Deposits. The naturally deposited Sand Deposits are suitable foundation bearing material (referred to herein as the "bearing strata"). Boulders and bedrock may be encountered and may require rock excavation via drilling and blasting.
- 2. Building walls, columns and other structural elements be supported by reinforced concrete spread or strip footings bearing directly on the bearing strata.
- 3. Bottoms of exterior footings bearing on compacted Structural Fill, Crushed Stone or on the undisturbed (prepared) bearing strata should be positioned at least 4-ft below the lowest adjacent ground (finished grade) exposed to freezing temperatures.
- 4. A permanent foundation perimeter drainage should be provided to collect and drain any infiltrating surface or seepage water which might otherwise become trapped against below-grade walls and seep into the building or exert hydro-static pressures on the walls.
- 5. Other construction related recommendations, i.e., excavation, compacted, drainage, protection, structural and common fill material, etc. are standard measures the design team will consider in the design of the project.

## BOURNEDALE ELEMENTARY SCHOOL SITE

#### TASKS PERFORMED:

- A total of five test borings were drilled on site identified as borings B-1 to B-5. The borings were drilled to depths ranging from approximately 7-ft (Boring B-3) to 22-ft (Boring B-4) below the existing grade.
- Standard Penetration Tests (SPTs) were performed and split-spoon soil samples were retrieved

generally at the ground surface and subsequently at 5-ft intervals.

• The finalized logs for the test borings were compiled.

## FINDINGS:

- Topsoil was encountered in all the test borings. The thickness of the topsoil encountered varies from about 7-in. to 8-in.
- The naturally deposited Sand Deposits were encountered in all the borings. The Sand Deposits generally consist of medium dense to very dense, brown, fine to medium SAND with varying amounts of gravel, coarse sand and silt.
- Refusal was encountered in all the test boring expect boring B-4 at depths ranging from 7-ft (boring B-3) to 17-ft (boring B-5). The refusal is likely due to cobbles, boulders or bedrock.

Groundwater levels were measured within each borehole varied from about 8 to 12-ft below grade at the time the borings were completed.

## CONCLUSION:

- 1. It is anticipated that the foundations for any new construction will bear upon the Sand Deposits. The naturally deposited Sand Deposits are suitable foundation bearing material (referred to herein as the "bearing strata"). Boulders and bedrock may be encountered and may require rock excavation via drilling and blasting.
- 2. Building walls, columns and other structural elements be supported by reinforced concrete spread or strip footings bearing directly on the bearing strata.
- 3. Bottoms of exterior footings bearing on compacted Structural Fill, Crushed Stone or on the undisturbed (prepared) bearing strata should be positioned at least 4-ft below the lowest adjacent ground (finished grade) exposed to freezing temperatures.
- 4. A permanent foundation perimeter drainage should be provided to collect and drain any infiltrating surface or seepage water which might otherwise become trapped against below-grade walls and seep into the building or exert hydro-static pressures on the walls.
- 5. Other construction related recommendations, i.e., excavation, compacted, drainage, protection, structural and common fill material, etc. are standard measures the design team will consider in the design of the project.

The full geotechnical report follows.

# **GEOTECHNICAL REPORT**

## PEEBLES ELEMENTARY SCHOOL 70 TROWBRIDGE ROAD BUZZARDS BAY, MASSACHUSETTS

November 18, 2015 (Revised December 17, 2015)

GSI Project No. 215256

Prepared for:

Mr. Kent Kovacs Flansburgh Architects, Inc. 77 North Washington Street Boston, Massachusetts 02114-1910

Prepared by:

Geotechnical Services, Inc. 55 North Stark Highway Weare, NH 03281





November 18, 2015 (Revised December 17, 2015)

Mr. Kent Kovacs Flansburgh Architects, Inc. 77 North Washington Street Boston, Massachusetts 02114-1910

Advanced copy via email: kkovacs@flansburgh.com

#### Re: Geotechnical Investigation Report Peebles Elementary School Buzzards Bay, MA GSI Project No. 215256

Dear Mr. Kovacs:

Geotechnical Services, Inc. (GSI) is pleased to submit this geotechnical report on the above referenced project. The report includes the subsurface data obtained through an exploration program, a geotechnical engineering evaluation of the subsurface data and the observed surface geology in relation to foundation design for the proposed development. The work was undertaken in accordance with the scope of work stated in our proposal dated September 29, 2015 and your subsequent authorization. The content of this report is subject to the attached **Limitations** (Appendix A).

#### **PROJECT UNDERSTANDING**

The project site is located at the Peebles Elementary School at 70 Trowbridge Road in Buzzards Bay, MA (See Figure 1, Project Locus. The geotechnical evaluation presented in this report is part of a feasibility study to either renovate of replace the existing school building. Several test borings were made around the existing building to investigation the subsurface soil and groundwater conditions as part of this study.

## SUBSURFACE INVESTIGATION

Four test borings, identified as borings B-1 to B-4, were drilled at the site on November 5, 2015 by New England Boring Contractors located in Brockton, Massachusetts under full-time supervision by a GSI engineer. The borings were drilled using a truck-mounted drill rig (Diedrich D-50) 4-in. I.D. flush-mounted casing with a rollerbit and water to advance the boreholes. The borings were drilled to depths ranging from approximately 18.5-ft to 22-ft below the existing grade. The locations of the test borings are shown on Figure 2, Exploration Location Plan.

Standard Penetration Tests (SPTs) were performed and split-spoon soil samples were retrieved (ASTM D 1586) generally at the ground surface and subsequently at 5-ft intervals. Each soil sample, upon recovery, was observed by the GSI engineer and classified in accordance with the Burmister Classification system. Representative portions of each sample retrieved were saved in glass jars with identification, and delivered to the GSI Soils Laboratory. The samples were re-examined and field classifications were reviewed. The finalized logs for the test borings are included in Appendix B. The soil samples will be stored at the GSI laboratory during the course of the project design-development, and will be shipped to your designated address or discarded upon your notification.

#### SUBSURFACE CONDITIONS

The subsurface conditions encountered in the investigation indicate that the site is underlain by the following soil units/deposits, described in order of increasing depth:

**Topsoil (Surface Deposits):** Topsoil was encountered in all the test borings except boring B-4. The thickness of the topsoil encountered varies from about 3-in. to 8-in.

Sand Deposits: The naturally deposited Sand Deposits were encountered in all the borings. The Sand Deposits generally consist of medium dense to dense, brown, fine to medium SAND with varying amounts of gravel, coarse



sand and silt. The drill action during borehole advancement indicated nested **cobbles** within the Sand Deposit Layer. In addition, very **large boulders** were observed in the vicinity of boring B-3 and along the hillside in an area just south of the paved area behind the existing school. The Sand Deposits were encountered to the termination depths of the test borings ranging from 18.5 to 22-ft below the existing grade.

#### **Groundwater Conditions**

Groundwater levels were measured within each borehole which varied from about 7 to 8-ft below grade at the time the borings were completed.

#### PRELIMINARY GEOTECHNICAL DESIGN RECOMMENDATIONS

#### General

As a general guideline, foundation design and construction must conform to the applicable provisions of the Massachusetts Building Code, 8<sup>th</sup> Edition (Building Code). At this early phase in the design, it is assumed that no basements are planned and that the lowest floor elevation for any new structures will be slab-on-grade.

#### Foundations

It is anticipated that the foundations for any new construction will bear upon the Sand Deposits. Pavement, Topsoil, and any fill soils that may be encountered during construction are unsuitable for building foundation support and should be excavated and replaced, if necessary. The naturally deposited Sand Deposits are suitable foundation bearing material (referred to herein as the "**bearing strata**").

We recommend that building walls, columns and other structural elements be supported by reinforced concrete spread or strip footings bearing directly on the bearing strata or compacted Structural Fill or Crushed Stone (wrapped in a geotextile filter fabric, such as, Mirafi 160N, or equal) placed above the natural bearing strata after removal of the unsuitable materials.

Specific building foundation design recommendations are provided below:

- Footings with a least lateral dimension (width) of 3-ft may be designed using a design bearing pressures of 4.0 ksf.
- For footings with a lateral dimension less than 3-ft, the maximum allowable bearing pressure should be reduced to a value equal to one-third of the maximum allowable bearing pressure given above multiplied by the least lateral dimension of the footing, measured in feet. For example, a 1.5-ft wide footing should be designed using a reduced allowable bearing pressure equal to 1.5-ft x 1/3 x 4 ksf = 2.0-ksf.
- Wall (Strip) Footings should have a least lateral dimension of 18-in.
- Bottoms of exterior footings bearing on compacted Structural Fill, Crushed Stone or on the undisturbed (prepared) bearing strata should be positioned at least 4-ft below the lowest adjacent ground (finished grade) exposed to freezing temperatures. Footings at heated interior locations should bear at least 18-in. below the adjacent slab surface.

#### **Ground Floor Slab**

We recommend that the ground floor be constructed as an earth-supported slab-on-grade, after removal of any Pavement, Topsoil, or any other unsuitable material, and backfilling with Compacted Structural Fill and Slab Base Course. A 6-in. minimum thickness of Compacted Slab Base Course should be provided directly beneath the slab. For slab design, GSI recommends a modulus of subgrade reaction equal to 175 pounds per cubic feet (pci).

#### **Foundation Settlements**

At the recommended allowable bearing pressures, we anticipate that the settlement of individual footings under the anticipated design loading conditions and constructed as recommended herein, will not exceed about 3/4-in., with differential settlements between adjacent footings not exceeding about 3/4-in. Most of the settlement will likely occur during construction as structure dead loads are placed on the foundations.



#### Seismic Design Input

Seismic design parameters for the project site have been obtained from Commonwealth of Massachusetts, State Building Code, Eighth Edition, 2010. Ground motion parameters at the project site (i.e., the design earthquake for the subject facility) are represented by  $S_s$ , 0.2 sec. (short period) Spectral Acceleration, and  $S_1$ , 1.0-second period Spectral Acceleration. These parameters have been obtained as:

 $S_s = 0.210 \text{ g}$ 

 $S_1 = 0.056 \text{ g}$ 

Site Class for the project site has been established as "Stiff Soil Profile" with the designation **Site Class D**. Site Coefficient for the Short Period has been established as  $F_a$ = 1.6, and Site Coefficient for the 1-sec Period has been established as  $F_v$  = 2.4. Parameters  $F_a$ , and  $F_v$  relate to the potential amplification of the earthquake induced shear stress waves traveling upward through the soil-rock profile underlying the project site. The soils within the project site are not considered liquefaction susceptible.

#### **Lateral Earth Pressures**

The following design criteria for yielding and non-yielding walls are recommended based on the assumption that adequate drainage shall be installed adjacent to and along the below grade structures and behind retaining walls, to eliminate any hydrostatic forces acting on the walls:

	Yielding	Non-yielding
Static Lateral Earth Pressure: (Native soil or lightly compacted structural fill as an equivalent fluid unit weight)	40 pcf (drained)	60 pcf
<u>Traffic Surcharge:</u> (Distributed uniformly over the height of the wall)	80 psf	120 psf

#### Seismic Lateral Earth Pressures

Per Section 1610.2 of the Building Code, exterior foundation walls and retaining walls shall be designed to resist an earthquake force,  $F_w$ , for horizontal backfill surface equal to:

 $F_w = 0.100(S_s)(F_a)(\gamma_t)(H)^2$ 

where:  $S_s$  is the 0.2 sec. (short period) Spectral Acceleration,

- F<sub>a</sub> is the site coefficient for the Short Period,
- $\gamma_t$  is the total unit weight of the soil (backfill), and
- H is the height of the wall measured as the difference in elevation of the finished ground surface or floor in front of and behind the wall.

For design, a soil unit weight ( $\gamma_t$ ) of 125 pounds per cubic feet (pcf) may be used.

#### Foundation and Floor Drainage

GSI recommends that permanent foundation perimeter drainage be provided to collect and drain any infiltrating surface or seepage water which might otherwise become trapped against below-grade walls and seep into the building or exert hydro-static pressures on the walls. We recommend that drainage be provided at all below-grade foundation walls where the adjacent floor slab is **2-ft or deeper** below adjacent exterior finished grade. Such systems should be provided at exterior walls and walls between differing floor levels beneath the building.

The perimeter foundation drainage should consist of a free-draining material against the wall and a drainage "pipe" at the wall base to collect and transmit the water. For installation convenience and cost-efficiency, we recommend



that a prefabricated drainage board product, such as Amerdrain 200 by the American Wick Drain Company (AWDC), or equivalent, be applied to the exterior walls from the level 2-ft below ground surface down to the drainage "pipe". The drainage board should connect at its base to a "high-profile sheet drain section" (such as Amerdrain Total-Drain System by AWDC) or to a 4-in. diameter continuous perforated PVC or corrugated HDPE drainpipe.

If a drain pipe is used for the perimeter drainage, it should be completely surrounded by a 6-in. (min.) thick zone of drainage fill (1/2-in to 3/4-in. sized crushed stone) which in turn is completely surrounded by a non-woven filter fabric to avoid potential clogging due to migration of fine soils into the drainage system. The crushed stone should be placed in contact with the drainage board against the wall in accordance with manufacturer's details. Drainpipe inverts should be between the bottom of footing and 6-in. beneath the elevation of the adjacent building floor. Pipes should be pitched nominally toward the system discharge points (slope 0.25 to 0.10 percent). Perforations in the drainpipe should be positioned downward.

Below-grade walls and floors should be dampproofed and insulated in according with the Building Code. Elevator pits and other small depressions below the lowest floors should be water proofed and designed to resist hydrostatic pressures corresponding to the full vertical depth of the structural depression below the floor slab. Vapor barriers should be installed beneath the floor slab per the Code. Use of vapor barriers should be coordinated with the slab design and construction.

To limit the water infiltration around the structures, it is recommended that the upper twelve inches of backfill within approximately 10-ft of the building in unpaved areas should consist of silty topsoil or other soils having relatively low permeability. In general, the ground surface immediately around the buildings should be sloped downward and away from the structures to direct surface runoff.

#### CONSTRUCTION CONSIDERATIONS

#### General

In general, all excavation work, dewatering, and other construction activities should conform to the requirements of OSHA and all other applicable regulations. The site soils would typically be classified as Type C based on OSHA 29 CFR 1926.

#### Excavation

Building foundation and the lowest floor slab construction will involve clearing and grubbing, stripping off the topsoil, subsoil, pavements, fill soils, as well as naturally deposited Alluvial soils, and then backfilling and filling to design footing and slab bearing levels. All unsuitable materials above the undisturbed bearing strata and floor slab must be removed within the zone of influence of new footings. The zone of influence for the footings is defined as the zone beneath the footing bottoms down to the top of the natural, undisturbed bearing strata, and within the zone beneath imaginary lines extending from points 1-ft laterally beyond the footing outer bottom edges and down on a 1H:1V slope to the top of undisturbed glacial deposit or bedrock.

We anticipate that the excavations in soil for the building construction and site grading can be accomplished with conventional earth-moving equipment.

Temporary cut soil slopes should, typically, be stable if constructed no steeper than about 1.5H:1V. Some sloughing and raveling should be anticipated in temporary earth slopes.

#### **Construction Dewatering**

Based on the available subsurface data it is anticipated that during the general site work, no significant dewatering measures will be necessary to conduct the construction "in-the-dry." Groundwater and surface water must be controlled as necessary to enable all final excavation and foundation construction to be conducted in-the-dry.

The Contractor should take measures to prevent storm water to enter into excavated areas, and be prepared to remove ponded surface water by means of localized sumps and pumps. The Contractor should select whichever dewatering procedures may be effective to maintain dry, stable excavation bottoms. Dewatering, including its discharge, should be performed in accordance with all local, state, and federal regulations.



#### **Existing Utilities and Foundations of Former Structures**

Unknown and/or undocumented subsurface features, structures, and utilities may be present within the project site. Foundations and utilities from buildings, and associated construction debris should be anticipated during excavation work, especially within the existing "Big Room" area, and will need to be carefully removed to limit disturbance to underlying natural soil deposits. Remnants of prior structures should be removed within the zone of influence beneath new foundations.

#### **Preparation and Protection of Bearing Surfaces**

Final excavation should be conducted in a manner that minimizes disturbance to the natural soils when excavating for footing or slab bearing surfaces. All final excavation and footing construction should be conducted in-the-dry. We recommend that the exposed subgrade soils be observed in the field by a geotechnical engineer to confirm the projected foundation bearing conditions. It may be necessary to over-excavate and replace weak, disturbed or otherwise unacceptable foundation bearing materials.

Following excavation to slab or footing bearing grades, exposed naturally deposited soil surfaces should be recompacted (proofrolled) prior to placing Compacted Structural Fill or constructing foundations, with a minimum of two passes with a heavy vibratory roller or other heavy vibratory compaction equipment.

If subgrade protection difficulties are encountered due to surface or groundwater, various methods can be utilized:

- Leave subgrades high until immediately before forming and concreting to minimize the time the subgrade is exposed.
- Place a lean concrete mud mat on the exposed soil surface at footing locations after the subgrade has been prepared.
- Over excavate footings by 6 to 8 in. using a smooth edged bucket, place non-woven filter fabric on the exposed stable soil subgrade, and backfill to the design bearing elevation using crushed stone. The exposed top of the crushed stone beneath the constructed footing should also be covered with non-woven filter fabric to prevent migration of fines from the backfill placed above.

Each such encounter is probably best resolved individually in the field upon observation of the subgrade conditions.

In the event that a boulder becomes partially exposed at subgrade level or at footing bearing level, one of the following options should be utilized:

- Remove the boulder, and fill the void with crushed stone, compacted structural fill or lean concrete, or
- Remove a portion of the boulder sufficient to provide placement of 6 in. of crushed stone (with filter fabric) beneath the slab or footing over the boulder. Each such encounter is probably best resolved individually in the field.

#### **Protection From Freezing**

Soil bearing surfaces below completed foundations and slabs must be protected against freezing, before and after foundation construction. If construction is performed during freezing weather, footings bearing on the Glacial deposits or compacted Structural Fill should be covered to a sufficient depth (up to 4-ft) as soon as possible after they are constructed. Alternatively, insulating blankets, lowering of footings, providing heaters, or other means may be used for protection against freezing.

#### Compaction

Minimum compaction requirements refer to percentages of the maximum dry density determined in accordance with ASTM D1557. Recommended compaction requirements are as follows:

Location	Minimum Compaction Requirements
Beneath and around footings, beneath slabs	95 %
Parking, roadways	92 % up to 3 ft below finished grade
and sidewalks	95 % in the upper 3 ft
Landscaped areas	90 % nominal compaction

#### **Filling and Backfilling**

Filling and backfilling will be required within the proposed building limits to reach footing and slab bearing levels. We recommend that Compacted Structural Fill or Slab Base Coarse be used as fill and backfill beneath footings and slabs to the limits described below. A minimum of 6-in. of Compacted Slab Base Coarse, or 12-in. of Crushed Stone for the planned basement, should be provided directly beneath the floor slabs.

Where Compacted Structural Fill is required beneath foundations, it should be placed beneath the footings and within the zone beneath imaginary lines extending from points 1-ft laterally beyond the footing outer bottom edge and down on a 1H:1V slope, down to the top of natural bearing strata (zone of influence).

Except for zones requiring special backfill such as directly beneath pavements or exterior slabs, the exterior of foundation walls may be backfilled with Common Fill.

Placement of compacted soil fills should not be conducted when air temperatures are low enough (approximately 30 degrees F, or below) to cause freezing of the moisture in the fill during or before placement. Fill materials should not be placed on snow, ice or uncompacted frozen soil. Compacted fill should not be placed on frozen soil. No fill should be allowed to freeze prior to compaction. At the end of each day's operations, the last lift of fill, after compaction, should be rolled by a smooth-wheeled roller to eliminate ridges of uncompacted soil.

#### **Structural Fill**

Structural Fill beneath footings and building slabs should consist of bank-run sand and gravel, free of organic material, snow, ice, or other unsuitable materials and should be well-graded within the following limits:

Sieve Size	Percent Finer by Weight
3 in.	100
No. 4	30 - 80
No. 40	10 - 50
No. 200	0 – 10

Other materials could be acceptable for compacted Structural Fill, and should be evaluated by the Geotechnical Engineer on a case-by-case basis if proposed by the Contractor.

Structural Fill should be placed in lift thicknesses not exceeding 12 in. loose measure. In confined areas, handguided equipment such as a vibratory plate compactor should be used and the loose lift thickness should not exceed 6 in.

A minimum of four systematic passes of the compaction equipment should be used to compact each lift.

#### **Common Fill**

Common fill should consist of mineral sandy soil, free from organic matter, plastic, metal, wood, ice, snow or other deleterious material and should have the characteristic that it can be readily placed and compacted. Common fill imported to the site should have a maximum of 80 percent passing the No. 40 sieve and a maximum of 30 percent finer than the No. 200 sieve. The largest particle size for common fill should not exceed 2/3 of the lift thickness.



Silty common fill soils may require moisture control during placement and compaction. Common Fill should be placed and compacted in the manner described in "Filling and Backfilling."

#### **Crushed Stone**

Crushed Stone should consist of durable crushed rock or crushed gravel stone obtained by breaking and crushing rock, or boulders, and it is free from a detrimental quantity of thin, flat, elongated or other objectionable pieces.

The <sup>1</sup>/<sub>2</sub>-inch crushed stone should have the following gradation:

Sieve Size	Percent Finer by Weight
5/8 inch	100
<sup>1</sup> / <sub>2</sub> inch	85-100
3/8 inch	15-45
No. 4	0-15
No. 8	0-5

#### **Slab Base Course**

Slab Base Course beneath building slabs should consist of bank-run sand and gravel, free of organic material, snow, ice, or other unsuitable materials and should be well-graded within the following limits:

Sieve Size	Percent Finer by Weight
2 in.	100
No. 4	40 - 70
No. 40	25 - 45
No. 200	0-10

Other materials could be acceptable for compacted Slab Base Course, and should be evaluated by the Geotechnical Engineer on a case-by-case basis if proposed by the Contractor.

Slab Base Course should be placed in lift thicknesses not exceeding 8-in. loose measure. In confined areas, handguided equipment such as a vibratory plate compactor should be used and the loose lift thickness should not exceed 6 in.

A minimum of four systematic passes of the compaction equipment should be used to compact each lift.

#### PLAN REVIEW

It is recommended that GSI be provided the opportunity to review the final plans in order to confirm that the recommendations made in this report were interpreted and implemented as intended.

#### CLOSURE

GSI appreciates the opportunity for participating in this early phase of the project, and looks forward to our continuing association during its subsequent phases towards its successful completion. In the mean time, please do not hesitate to contact us, if you have any questions on the content of this report.

Very truly yours,

GEQTECHNICAL SERVICES, INC.

Glen V. Zoladz, P.E.

Project Engineer

Harry K. Wetherbee, P.E. *Principal Engineer* 

Figure 1Project LocusFigure 2Exploration Location Plan

Appendix ALimitationsAppendix BTest Boring Logs







FIGURE 1-PROJECT LOCUS



PEEBLES ELEMENTARY SCHOOL BUZZARDS BAY, MA GSI PROJECT NO. 215256



NOT TO SCALE

LEGEND:



TEST BORING I.D. AND APPROXIMATE LOCATION



FIGURE 2-EXPLORATION LOCATION PLAN

PEEBLES ELEMENTARY SCHOOL BUZZARDS BAY, MA GSI PROJECT NO. 215256 APPENDIX A

LIMITATIONS



#### LIMITATIONS

#### Explorations

- 1. The analyses, recommendations and designs submitted in this report are based in part upon the data obtained from preliminary subsurface explorations. The nature and extent of variations between these explorations may not become evident until construction. If variations then appear evident, it will be necessary to re-evaluate the recommendations of this report.
- 2. The generalized soil profile described in the text is intended to convey trends in subsurface conditions. The boundaries between strata are approximate and idealized and have been developed by interpretation of widely spaced explorations and samples; actual soil transitions are probably more gradual. For specific information, refer to the individual test pit and/or boring logs.
- 3. Water level readings have been made in the test pits and/or test borings under conditions stated on the logs. These data have been reviewed and interpretations have been made in the text of this report. However, it must be noted that fluctuations in the level of the groundwater may occur due to variations in rainfall, temperature, and other factors differing from the time the measurements were made.

#### Review

- 4. It is recommended that this firm be given the opportunity to review final design drawings and specifications to evaluate the appropriate implementation of the recommendations provided herein.
- 5. In the event that any changes in the nature, design, or location of the proposed areas are planned, the conclusions and recommendations contained in this report shall not be considered valid unless the changes are reviewed and conclusions of the report modified or verified in writing by Geotechnical Services, Inc.

#### Construction

6. It is recommended that this firm be retained to provide geotechnical engineering services during the earthwork phases of the work. This is to observe compliance with the design concepts, specifications, and recommendations and to allow design changes in the event that subsurface conditions differ from those anticipated prior to the start of construction.

#### Use of Report

- 7. This report has been prepared for the exclusive use of Flansburgh Architects, Inc. in accordance with generally accepted soil and foundation engineering practices. No other warranty, expressed or implied, is made.
- 8. This report has been prepared for this project by Geotechnical Services, Inc. This report was completed for preliminary design purposes and may be limited in its scope to complete an accurate bid. Contractors wishing a copy of the report may secure it with the understanding that its scope is limited to evaluation considerations only.



### **APPENDIX B**

**TEST BORING LOGS** 



G	-
	]

## 

Boring No.

		>					I E	51	ROF	RING	i LOC	Ā					B-	1	
4																Pa	ge 1	of	
Pro	ject			Peebles	School			Proj	ject No		2152	56		E	levation			N/A	
Loc	ation			Bourne, N	ЛА				, bector		G. Zo	oladz		D	atum		I	N/A	
Clie	ent			Flansbur	gh Archite	ects		Proj	ject Ma	nager	G. Zo	oladz		S	start		11/	5/201	
Co	ntractor			NEBC				Che	ecked E	By				F	inish		11/	5/201	
Dri	ler			P. Donoh	oe			Drill	l Rig		Diedrich			N	lodel		D-50	)	
Iter	n:			Auger	Casin	g S	Sample	er (	Core Ba	rrel 🗸	Truck Skid				ŀ	lamr	ner Typ	ce:	
Тур	be			-	HW		S		-	$\neg$	Track	Γ	ATV		~	Safety Hamr			
Ins	ide Dian	neter (in	.)	-	4		1.375	5	-		Bomb.		 Geopho	ne		-	Doughnut		
Ha	mmer W	'eight (lb	)	-	300		140				Tripod Other Automat								
Ha	mmer Fa	all (in.)		-	24		30										Cuttin	a Hea	
				S	ample D	ata												9.100	
(ft)	ing 's/ft				SPT	Rock	PI	D St	tratum		Soil-F				tion and D	escr	iption		
Depth (	Casing (Blows/ft)	No.	Depth		(Blows/	RQD	Rd		hange		/1				r System)	(otoo	-)		
ă	СB		(ft)	(in.)	6-in.)	(%)	(pp	-	(ft)		()		J.S. Corp	s ur ⊨r	ngineers Sy	sien	1)		
0 -		S1	0-2	8	3		1			Topsoil									
			02		11		1		~8	. 50501									
					10 6		1												
-					Ũ														
-							1			Note: d	rill action	n Indicai	es nested	a coppi	les				
_																			
_																			
5 -		S2	5-7	12	6					M. dens	se, browr	n, f/m S	AND, little	e grave	el, c-sand, t	tr. sil	t		
-					6 5 7														
					6														
-																			
-																			
10																			
10 -		S3	10-12	8	8 9					Dense, brown, f/m SAND, little c-sand									
-					9 21														
_					17														
										Note: d	rill action	n indicat	es nested	d cobbl	les				
-																			
15 -																			
		S4	15-17	3	6 9					M. dens	se, browr	n, f/m S	AND, little	e c-sar	nd, tr. grave	el			
-					11		1												
-					14		1												
							1												
							1	$\vdash$											
1											efusal at								
20 -							1			Bottom	of exploi	ration a	t 18.5-ft.						
							1												
1																			
-							1												
_							1												
-																			
25 -								Ĺ								-			
			Water L	evel Data					-	entificatio			<u>e Soils N</u>				Soils N		
Dat		Time	Pott		oth (ft) to:					en Endeo			2: Very S to 4: Soft				Very Lo 0: Loo		
Dat		IIIIE	Bott. Casi		Bott. of Hole	Wate	ər			isturbed t Spoon			Medium				ledium		
5-N	ov	-	- Jas		-	~8			= Spin = Roc				o 15: Stif				50: Der		
			L							= Geoprobe 15 to 30 Very Stiff Over 50: V									
										-			er 30: Har	ď					
			Traco	e (0 to 5%	)   ittl	e (10 to	20%	). <u>S</u>	Some (2	20 to 35%	%) <u>A</u>	nd (35 t	0.50%)				E		

G	
$\rightarrow$ S	
	T

		$\supset$	5_						TE	S1	Г BOF	RINC	βL	.OG						B	-2	
α	2																	F	ag	<b>e</b> 1	1 of 1	
430	Pro	ject		1	Peek	oles S	School			F	Project No			215256			Elevat	ion	Т		N/A	
61/.455.4248 Fax. 61/./45.4308		ation				ne, N				-	nspector	-	-	G. Zoladz			Datum		+		N/A	
/./	Clie	ent					h Archite	ects		-	Project Ma	inager	-	G. Zoladz			Start				/5/2015	
6	Co	ntractor	-		NEB	C				-	Checked E	-					Finish		11/5/2015			
-ax	Dri	ler			P. D	onoh	oe			-	Drill Rig			Diedrich			Model		D-50			
- <del>β</del>	Iter	n:			Aug	er	Casin	g	Samp	ler							Hai	Hammer Type:				
47	Тур	e			-		HW		S		-		Tra								immer	
455	Ins	de Dian	neter (in.	.)	-		4		1.37	5	-			mb.		phone				ghnut		
17.	Ha	nmer W	/eight (lb	))	-		300		140	)			_	ipod	Oth	•				matic		
<u>9</u> .	Ha	nmer Fa	all (in.)		-		24		30		1		Wi	nch 🔽 C	Cat Head	I L	Rolle	r Bit	√ (	Cuttir	ng Head	
 9	t)	ţ;				S	ample Da	ata														
Boston, MA 02116 1el.	Depth (ft)	Casing (Blows/ft)	No.	Dep (ft		lec. in.)	SPT (Blows/ 6-in.)	Rock RQE (%)	R	lD dg. pm)	Stratum Change (ft)		5	Soil-Rock \ (Rock -	(Soils -	Burmis	ter Syst		-		I	
soston	0		S1	0-	2	16	6 10				~8	Topso	il									
							10 13					M. der	nse, k	or., silty f/c	SAND,	little gra	avel					
30 Newbury Street,	5 -		S2	5-	7	14	6 12 18					Note: drill action indicates nested cobbles Dense, brown, f/m SAND, little gravel, c-sand										
603.529.7080	 						24															
603.529.7766 Fax. (	· •		S3	10-	12	16	14 21 27 21							wn, f/m SA action indic		-		d, tr. siit				
lei.	- 15 -		S4	15-	17	16	14 10 14 15					M. der	nse, t	brown, f/m	SAND,	little gra	vel, c-s	and				
	20 -		S5	20-	22	8	24 20 21 21					<i>Note: drill action indicates nested cobbles</i> Dense, brown, f/m SAND, little gravel, c-sand, tr. silt										
ll Services, Inc.	. 25											Bottom of exploration at 22-ft.										
nica			V	Wate	r Level					<u>S</u>	ample Ide					s N-Valu	le				<u>I- Value</u>	
Geotechnical	Det		Time		o# -f	-	oth (ft) to:			4	O = Ope				o 2: Ver 2 to 4: \$			0 to 4		ery L ): Loc		
eote	Dat	e e	Time		ott. of asing		ott. of Hole	Wa	ater	U = Undisturbed S = Split Spoon						um Stiff					n Dense	
Ī	5-N	vc	-		-		-	^	7	1	C = Cpm C = Roc		•	8	8 to 15:	Stiff		31 t	o 5	0: De	ense	
ļ						1					G = Geo	probe			o 30 Ve			Over 5	50: <b>\</b>	/ery	Dense	
ŀ				Tro	ace (0 te	0 5º/	) [ ;++1.	e (10 t	0 200/		Some (2	20 to 25	<u>%</u> )	And (35	ver 30:							
ŀ	Note	es:		119	100 (U [	0 0 %	/, ∟!([0		U 20%	o),	Some (2	-0 10 35	, /0),	And (35	10 30%	9)					B-2	

G	
$\Rightarrow s$	
	I

## TEST BORING LOG

		$\Rightarrow$	S_				•	TE	ST	<b>BOF</b>	RING	i L(	OG					B-3	
8	4																Pa	ge 1 of 1	
.430	Pro	ject			Peeble	s School			Р	roject No		2	15256			Elevation		N/A	
/45	Loc	ation			Bourne				lr	nspector		Ģ	a. Zoladz			Datum	N/A		
17.	Clie	ent				urgh Archite	ects		Р	roject Ma	nager	Ģ	a. Zoladz			Start	11/5/201		
×.		ntractor			NEBC					hecked E	By					Finish		11/5/2015	
гa	Dri	ler			P. Done	ohoe	-		D	rill Rig		D	liedrich			Model		D-50	
248	Iter				Auger	Casin	g S	ample	ər	Core Barrel  Truck Skid				<u> </u>	Hamr	<u>ner Type:</u>			
5.4	Тур				-	HW		S	_	-		Trac		ATV		~	_	ety Hammer	
7.45			neter (in.	,	-	4		1.375	5	-		Bomb. Geophone				ughnut			
6			eight (lb	)	-	300		140				Tri		Other				omatic	
e.	Ha	mmer Fa	all (in.)		-	24		30				Win	ch _√ C	at Head		Roller Bit	$\checkmark$	Cutting Head	
16	(tt)	g ∰				Sample Da			_	_		S	oil-Rock \	/isual Cla	ssific	ation and D	)escr	ription	
30 Newbury Street, Boston, MA 02116 1el. 61/.455.4248 Fax. 61/./45.4308	Depth	Casing (Blows/ft)	No.	Deptl (ft)	h Rec (in.)	(Blows/	Rock RQD (%)	PI Rd (pp	g.	Stratum Change (ft)				(Soils - B	urmist	er System) Engineers S			
on,	- 0 -		S1	0-2	20	3				~0.3	Topsoil								
sost			01	02	20	5				0.0							•••••		
et, E						13 14					w. dens	se, s	ilty, f/m SA	and, tr. gi	ravei				
itre																			
5																			
ngv											Note: d	irili ad	ction indic	ates neste	ed cob	bles			
Ne	- 5 -		S2	5-7	18	15					M done	no h	rown f/m		lo ara	vel, c-sand			
30			52	5-7	10	16					w. den	se, D	10wn, 1/m	SAND, III	le grav	vei, c-sanu			
						11 15													
80						10													
.70																			
529																			
603.529.7766 Fax. 603.529.7080	- 10 -																		
×.	- 10 -		S3	10-12	2 12	12 12					M. dense, brown, f/m SAND, little gravel, c-sand, tr. silt							t	
с Га						13													
/66						18													
29./											Note: d	Irill a	ction indic	ates neste	ed cob	bles			
3.52																			
60	]																		
<u>e</u> .	- 15 -		S4	15-17	7 12	14					Dense,	brov	vn, f/m SA	ND, little	gravel,	, c-sand			
'ay						19 19													
ghw						22													
55 North Stark Highway I																			
star											Note: d	irill a	ction indic	ates neste	ed cob	DIES			
1 L	- 1																		
Nor	- 20 -		S5	20-22	2 16	20 23					Dense,	brov	vn, f/m SA	ND, little	gravel,	, c-sand, tr.	silt		
<b>çç</b>						23 24										-			
ci l						34													
Ĕ.																			
ces	- 1										Bottom	of e	xploration	at 22-ft.					
Geotechnical Services, Inc.																			
a S	- 25 -							L,	_										
JIIC			١	vvater l	Level Da	ata epth (ft) to:		$\neg$	<u>s</u>	ample Ide O = Ope				i <u>ve Soils N</u> 5 2: Very \$				<u>Soils N- Value</u> Very Loose	
tecr	Dat	e	Time	Bot	t. of	Bott. of	Wate	)r			ndisturbed 2 to 4: Soft						4 to 1	10: Loose	
2 eo				Cas		Hole		71		S = Split				8: Medium			11 to 30: Medium Dense		
	5-N	V	-		-	-	~8			C = Roc G = Geo				8 to 15: St o 30 Very				50: Dense Very Dense	
											-		0	ver 30: Ha					
	N1-7			Trac	e (0 to 5	%), Littl	e (10 to	20%)	),	Some (2	20 to 359	%),	And (35	to 50%)				B-3	
	Note	es:																	

G	
$\Rightarrow$	5_

" 30 Newbury Street, Boston, MA 02116 Tel. 617.455.4248 Fax. 617.745.4308

Geotechnical Services, Inc. "55 North Stark Highway Tel. 603.529.7766 Fax. 603.529.7080

Boring No.

	$\square$	<b>S</b> _					TE	S1	r Bof	RIN	G	LOC	3						В	-4	
4		I															F	ag	е .	1 of	f 1
Pro	ject			Peebles	School			Р	roject No	).		2152	56			Eleva	tion			N/A	
Loc	ation			Bourne,	MA				nspector			G. Zo	oladz			Datun	n			N/A	
Clie	ent			Flansbu	rgh Archite	ects		Р	Project Ma	anagei	ſ	G. Zo	a. Zoladz Start						11,	/5/201	15
Co	ntractor			NEBC				С	Checked E	Зу						Finish	า	11/5/201			
Dri	ler			P. Dono	hoe			D	Drill Rig			Diedr	rich			Mode			D-5	0	
Iter	n:			Auger	Casin	g :	Sample	er	Core Ba	rrel [	rel 🗸 Truck 🗌 Skid				<u>Ha</u>	Hammer Type:					
Тур	be			-	HW		S		-	[								afet	ty Ha	mme	er
Ins	ide Diar	meter (in	.)	-	4		1.375	5	-	[		Bomb.		Geop	ohone			Doug	oughnut		
Ha	mmer V	Veight (Ib	o)	-	300		140			l		Tripod		_ Othe	r		A	luto	matio	2	
Ha	mmer F	all (in.)		-	24		30			[		Winch	√ Ca	it Head		Rolle	er Bit	√ (	Cuttir	ng He	ad
£	n Î				Sample D	ata						Soil B	Pook Vi		loooifio	otion	and Des	orin	stion		
th (I	sing vs/1		Dept	th Rec.	SPT	Rock	PI		Stratum			30II-H			Burmist			scrip	Juon	I	
Depth (ft)	Casing (Blows/ft)	No.	(ft)		(Blows/	RQD	Rd	•	Change			(F					ers Syst	em)			
	)		、	```	6-in.)	(%)	(pp	m)	(ft)			•					-				
- 0 -		S1	0-2	5	15					V. de	ense	e, br., f/c	SANE	), some	e gravel,	, tr. silt	t				
					24 50/3"																
L																					
- 5 -		S2	5-7	10	7					Loos	e. k	orown, f/	m SAN	ID. little	c-sand	l, tr. sil	lt				
				-	7 5 3						-,	,	-	,		,	-				
					2																
- 10 -		S3	10-1	2 12	00					Mak		o brown	. f/m C		:++ 0 0 0	and tr	ailt				
		- 53	10-1	2 12	28 8					IVI. GE	ens	e, browr	1, 1/11 3	AND, I	illie c-sa	anu, tr	. SIII				
					9 42																
					72						,		. ,.								
										Note	: dr	rill action	Indica	tes nes	sted cob	bles					
- 15 -																					
- 13 -		S4	15-1	7 11	25					Loos	e, t	orown, f/	m SAN	ID, little	c-sand	l, tr. sil	lt				
					5 4																
					3																
										Nata	. d.	rill action	indiaa	+	tad aab	blac					
										Note	. ar	ni action	i indica	les nes	ieu cop	bies					
- 20 -		S5	20-2	2 10	9					M. de	ens	e, browr	n, f/m S	AND, I	ittle c-sa	and, tr	. silt				
					9 8 9																
					12																
			1																		
[ ]			1							Bottom of exploration at 22-ft.											
- 1			1																		
- 25 -			<u> </u>	<u> </u>							.,	_					_	~			
			Water	Level Dat			]	<u>S</u>	ample Ide					<u>re Soils</u> 2: Very	<u>N-Valu</u>	e	Granula 0 to /			<u>I- Val</u> .oose	
Dat	e	Time	Bot	1	epth (ft) to: Bott. of				O = Ope U = Und					2: very to 4: S					ery L ): Loo		
				sing	Hole	Wat	-		S = Split				4 to 8	: Mediu	ım Stiff		11 to 30	: Me	ediun	n Der	nse
5-N	vo	-		-	-	~8	3			= Rock Core8 to 15: Stiff31 to 50: Dense= Geoprobe15 to 30 Very StiffOver 50: Very Den											
									G = Geo	probe	)			30 Vei er 30: H			Over 5	٥U: ۱	very	Dens	e
			Trac	ce (0 to 59	%), Littl	e (10 to	20%	),	Some (2	20 to 3	35%	%), Ar		to 50%		I					
Note	es:			, ,	,. ,.	,			- \-			,	\ - ·							B-4	

# **GEOTECHNICAL REPORT**

## BOURNEDALE ELEMENTARY SCHOOL 41 ERNEST VALERI ROAD BOURNE, MASSACHUSETTS

November 19, 2015 (Revised: December 17, 2015)

GSI Project No. 215257

Prepared for:

Mr. Kent Kovacs Flansburgh Architects, Inc. 77 North Washington Street Boston, Massachusetts 02114-1910

Prepared by:

Geotechnical Services, Inc. 55 North Stark Highway Weare, NH 03281





November 19, 2015

(Revised: December 17, 2015)

Mr. Kent Kovacs Flansburgh Architects, Inc. 77 North Washington Street Boston, Massachusetts 02114-1910

Advanced copy via email: <u>kkovacs@flansburgh.com</u>

#### Re: Geotechnical Investigation Report Bournedale Elementary School Bourne, MA GSI Project No. 215257

Dear Mr. Kovacs:

Geotechnical Services, Inc. (GSI) is pleased to submit this geotechnical report on the above referenced project. The report includes the subsurface data obtained through an exploration program, a geotechnical engineering evaluation of the subsurface data and the observed surface geology in relation to foundation design for the proposed development. The work was undertaken in accordance with the scope of work stated in our proposal dated September 29, 2015 and your subsequent authorization. The content of this report is subject to the attached **Limitations** (Appendix A).

#### **PROJECT UNDERSTANDING**

The project site is located at the Bournedale Elementary School at 41 Ernest Valeri Road in Bourne, MA (See Figure 1, Project Locus. The geotechnical evaluation presented in this report is part of a feasibility study to either renovate of replace the Peebles Elementary School currently located at 70 Trowbridge Road in Buzzards Bay, MA. Several test borings were made around the existing building to investigation the subsurface soil and groundwater conditions as part of this study.

#### SUBSURFACE INVESTIGATION

Five test borings, identified as borings B-1 to B-5, were drilled at the site on November 4, 2015 by New England Boring Contractors located in Brockton, Massachusetts under full-time supervision by a GSI engineer. The borings were drilled using a truck-mounted drill rig (Diedrich D-50) and 4-in. I.D. flush-mounted casing with a rollerbit and water to advance the boreholes. The borings were drilled to depths ranging from approximately 7-ft (Boring B-3) to 22-ft (Boring B-4) below the existing grade. The locations of the test borings are shown on Figure 2, Exploration Location Plan.

Standard Penetration Tests (SPTs) were performed and split-spoon soil samples were retrieved (ASTM D 1586) generally at the ground surface and subsequently at 5-ft intervals. Each soil sample, upon recovery, was observed by the GSI engineer and classified in accordance with the Burmister Classification system. Representative portions of each sample retrieved were saved in glass jars with identification, and delivered to the GSI Soils Laboratory. The samples were re-examined and field classifications were reviewed. The finalized logs for the test borings are included in Appendix B. The soil samples will be stored at the GSI laboratory during the course of the project design-development, and will be shipped to your designated address or discarded upon your notification.

#### SUBSURFACE CONDITIONS

The subsurface conditions encountered in the investigation indicate that the site is underlain by the following soil units/deposits, described in order of increasing depth:

**Topsoil (Surface Deposits):** Topsoil was encountered in all the test borings. The thickness of the topsoil encountered varies from about 7-in. to 8-in.

55 N. Stark Highway, Weare, NH 03281
 603/529/7766
 FAX 603/529/7080
 30 Newbury Street, Boston, MA 02116
 617/861/2617

**Sand Deposits:** The naturally deposited Sand Deposits were encountered in all the borings. The Sand Deposits generally consist of medium dense to very dense, brown, fine to medium **SAND** with varying amounts of gravel, coarse sand and silt. The Sand Deposits were encountered to the termination depths of the test borings ranging from 7 to 22-ft below the existing grade.

**Refusal:** Refusal was encountered in all the test boring expect boring B-4 at depths ranging from 7-ft (boring B-3) to 17-ft (boring B-5). The refusal is likely due to cobbles, boulders or bedrock.

#### **Groundwater Conditions**

Groundwater levels were measured within each borehole varied from about 8 to 12-ft below grade at the time the borings were completed. Groundwater levels should be expected to vary with season, precipitation, snowmelt, construction activities, and other factors. As a result, groundwater levels encountered during construction may differ from those encountered during the explorations.

#### PRELIMINARY GEOTECHNICAL DESIGN RECOMMENDATIONS

#### General

As a general guideline, foundation design and construction must conform to the applicable provisions of the Massachusetts Building Code, 8<sup>th</sup> Edition (Building Code). At this early phase in the design, it is assumed that no basements are planned and that the lowest floor elevation for any new structures will be slab-on-grade.

#### Foundations

It is anticipated that the foundations for any new construction will bear upon the Sand Deposits. Pavement, Topsoil, and any fill soils that may be encountered during construction are unsuitable for building foundation support and should be excavated and replaced, if necessary. The naturally deposited Sand Deposits are suitable foundation bearing material (referred to herein as the "**bearing strata**"). Some cobbles, boulders and possiblly bedrock may be encountered based on the refusals encountered in the test borings at depth ranging from 7 to 17-ft.

We recommend that building walls, columns and other structural elements be supported by reinforced concrete spread or strip footings bearing directly on the bearing strata or compacted Structural Fill or Crushed Stone (wrapped in a geotextile filter fabric, such as, Mirafi 160N, or equal) placed above the natural bearing strata after removal of the unsuitable materials.

Specific building foundation design recommendations are provided below:

- Footings with a least lateral dimension (width) of 3-ft may be designed using a design bearing pressures of 4.0 ksf.
- For footings with a lateral dimension less than 3-ft, the maximum allowable bearing pressure should be reduced to a value equal to one-third of the maximum allowable bearing pressure given above multiplied by the least lateral dimension of the footing, measured in feet. For example, a 1.5-ft wide footing should be designed using a reduced allowable bearing pressure equal to 1.5-ft x 1/3 x 4 ksf = 2.0-ksf.
- Wall (Strip) Footings should have a least lateral dimension of 18-in.
- Bottoms of exterior footings bearing on compacted Structural Fill, Crushed Stone or on the undisturbed (prepared) bearing strata should be positioned at least 4-ft below the lowest adjacent ground (finished grade) exposed to freezing temperatures. Footings at heated interior locations should bear at least 18-in. below the adjacent slab surface.

#### **Ground Floor Slab**

We recommend that the ground floor be constructed as an earth-supported slab-on-grade, after removal of any Pavement, Topsoil, or any other unsuitable material, and backfilling with Compacted Structural Fill and Slab Base Course. A 6-in. minimum thickness of Compacted Slab Base Course should be provided directly beneath the slab. For slab design, GSI recommends a modulus of subgrade reaction equal to 175 pounds per cubic feet (pci).



#### **Foundation Settlements**

At the recommended allowable bearing pressures, we anticipate that the settlement of individual footings under the anticipated design loading conditions and constructed as recommended herein, will not exceed about 3/4-in., with differential settlements between adjacent footings not exceeding about 3/4-in. Most of the settlement will likely occur during construction as structure dead loads are placed on the foundations.

#### Seismic Design Input

Seismic design parameters for the project site have been obtained from Commonwealth of Massachusetts, State Building Code, Eighth Edition, 2010. Ground motion parameters at the project site (i.e., the design earthquake for the subject facility) are represented by  $S_s$ , 0.2 sec. (short period) Spectral Acceleration, and  $S_1$ , 1.0-second period Spectral Acceleration. These parameters have been obtained as:

 $S_s = 0.210 \text{ g}$ 

 $S_1 = 0.056 \text{ g}$ 

Site Class for the project site has been established as "Very dense soil and soft rock" with the designation **Site Class** C. Site Coefficient for the Short Period has been established as  $F_a$ = 1.2, and Site Coefficient for the 1-sec Period has been established as  $F_v$  = 1.7. Parameters  $F_a$ , and  $F_v$  relate to the potential amplification of the earthquake induced shear stress waves traveling upward through the soil-rock profile underlying the project site. The soils within the project site are not considered liquefaction susceptible.

#### **Lateral Earth Pressures**

The following design criteria for yielding and non-yielding walls are recommended based on the assumption that adequate drainage shall be installed adjacent to and along the below grade structures and behind retaining walls, to eliminate any hydrostatic forces acting on the walls:

	Yielding	Non-yielding
<u>Static Lateral Earth Pressure:</u> (Native soil or lightly compacted structural fill as an equivalent fluid unit weight)	40 pcf (drained)	60 pcf
<u>Traffic Surcharge:</u> (Distributed uniformly over the height of the wall)	80 psf	120 psf

#### Seismic Lateral Earth Pressures

Per Section 1610.2 of the Building Code, exterior foundation walls and retaining walls shall be designed to resist an earthquake force,  $F_w$ , for horizontal backfill surface equal to:

$$F_w = 0.100(S_s)(F_a)(\gamma_t)(H)^2$$

where:  $S_s$  is the 0.2 sec. (short period) Spectral Acceleration,

- F<sub>a</sub> is the site coefficient for the Short Period,
- $\gamma_t$  is the total unit weight of the soil (backfill), and
- H is the height of the wall measured as the difference in elevation of the finished ground surface or floor in front of and behind the wall.

For design, a soil unit weight ( $\gamma_t$ ) of 125 pounds per cubic feet (pcf) may be used.

#### Foundation and Floor Drainage

GSI recommends that permanent foundation perimeter drainage be provided to collect and drain any infiltrating surface or seepage water which might otherwise become trapped against below-grade walls and seep into the



building or exert hydro-static pressures on the walls. We recommend that drainage be provided at all below-grade foundation walls where the adjacent floor slab is **2-ft or deeper** below adjacent exterior finished grade. Such systems should be provided at exterior walls and walls between differing floor levels beneath the building.

The perimeter foundation drainage should consist of a free-draining material against the wall and a drainage "pipe" at the wall base to collect and transmit the water. For installation convenience and cost-efficiency, we recommend that a prefabricated drainage board product, such as Amerdrain 200 by the American Wick Drain Company (AWDC), or equivalent, be applied to the exterior walls from the level 2-ft below ground surface down to the drainage "pipe". The drainage board should connect at its base to a "high-profile sheet drain section" (such as Amerdrain Total-Drain System by AWDC) or to a 4-in. diameter continuous perforated PVC or corrugated HDPE drainpipe.

If a drain pipe is used for the perimeter drainage, it should be completely surrounded by a 6-in. (min.) thick zone of drainage fill (1/2-in to 3/4-in. sized crushed stone) which in turn is completely surrounded by a non-woven filter fabric to avoid potential clogging due to migration of fine soils into the drainage system. The crushed stone should be placed in contact with the drainage board against the wall in accordance with manufacturer's details. Drainpipe inverts should be between the bottom of footing and 6-in. beneath the elevation of the adjacent building floor. Pipes should be pitched nominally toward the system discharge points (slope 0.25 to 0.10 percent). Perforations in the drainpipe should be positioned downward.

Below-grade walls and floors should be dampproofed and insulated in according with the Building Code. Elevator pits and other small depressions below the lowest floors should be water proofed and designed to resist hydrostatic pressures corresponding to the full vertical depth of the structural depression below the floor slab. Vapor barriers should be installed beneath the floor slab per the Code. Use of vapor barriers should be coordinated with the slab design and construction.

To limit the water infiltration around the structures, it is recommended that the upper twelve inches of backfill within approximately 10-ft of the building in unpaved areas should consist of silty topsoil or other soils having relatively low permeability. In general, the ground surface immediately around the buildings should be sloped downward and away from the structures to direct surface runoff.

#### CONSTRUCTION CONSIDERATIONS

#### General

In general, all excavation work, dewatering, and other construction activities should conform to the requirements of OSHA and all other applicable regulations. The site soils would typically be classified as Type C based on OSHA 29 CFR 1926.

#### Excavation

Building foundation and the lowest floor slab construction will involve clearing and grubbing, stripping off the topsoil, subsoil, pavements, fill soils, as well as naturally deposited Alluvial soils, and then backfilling and filling to design footing and slab bearing levels. All unsuitable materials above the undisturbed bearing strata and floor slab must be removed within the zone of influence of new footings. The zone of influence for the footings is defined as the zone beneath the footing bottoms down to the top of the natural, undisturbed bearing strata, and within the zone beneath imaginary lines extending from points 1-ft laterally beyond the footing outer bottom edges and down on a 1H:1V slope to the top of undisturbed Sand Deposits.

We anticipate that the excavations in soil for the building construction and site grading can be accomplished with conventional earth-moving equipment.

Temporary cut soil slopes should, typically, be stable if constructed no steeper than about 1.5H:1V. Some sloughing and raveling should be anticipated in temporary earth slopes.

#### **Construction Dewatering**

Based on the available subsurface data it is anticipated that during the general site work, no significant dewatering measures will be necessary to conduct the construction "in-the-dry." Groundwater and surface water must be controlled as necessary to enable all final excavation and foundation construction to be conducted in-the-dry.

The Contractor should take measures to prevent storm water to enter into excavated areas, and be prepared to remove ponded surface water by means of localized sumps and pumps. The Contractor should select whichever



dewatering procedures may be effective to maintain dry, stable excavation bottoms. Dewatering, including its discharge, should be performed in accordance with all local, state, and federal regulations.

#### **Existing Utilities and Foundations of Former Structures**

Unknown and/or undocumented subsurface features, structures, and utilities may be present within the project site. Foundations and utilities from buildings, and associated construction debris should be anticipated during excavation work, especially within the existing "Big Room" area, and will need to be carefully removed to limit disturbance to underlying natural soil deposits. Remnants of prior structures should be removed within the zone of influence beneath new foundations.

#### **Preparation and Protection of Bearing Surfaces**

Final excavation should be conducted in a manner that minimizes disturbance to the natural soils when excavating for footing or slab bearing surfaces. All final excavation and footing construction should be conducted in-the-dry. We recommend that the exposed subgrade soils be observed in the field by a geotechnical engineer to confirm the projected foundation bearing conditions. It may be necessary to over-excavate and replace weak, disturbed or otherwise unacceptable foundation bearing materials.

Following excavation to slab or footing bearing grades, exposed naturally deposited soil surfaces should be recompacted (proofrolled) prior to placing Compacted Structural Fill or constructing foundations, with a minimum of two passes with a heavy vibratory roller or other heavy vibratory compaction equipment.

If subgrade protection difficulties are encountered due to surface or groundwater, various methods can be utilized:

- Leave subgrades high until immediately before forming and concreting to minimize the time the subgrade is exposed.
- Place a lean concrete mud mat on the exposed soil surface at footing locations after the subgrade has been prepared.
- Over excavate footings by 6 to 8 in. using a smooth edged bucket, place non-woven filter fabric on the exposed stable soil subgrade, and backfill to the design bearing elevation using crushed stone. The exposed top of the crushed stone beneath the constructed footing should also be covered with non-woven filter fabric to prevent migration of fines from the backfill placed above.

Each such encounter is probably best resolved individually in the field upon observation of the subgrade conditions.

In the event that a boulder or bedrock becomes partially exposed at subgrade level or at footing bearing level, one of the following options should be utilized:

- Remove the boulder, and fill the void with crushed stone, compacted structural fill or lean concrete, or
- Remove a portion of the boulder or bedrock sufficient to provide placement of 6 in. of crushed stone (with filter fabric) beneath the slab or footing over the boulder. Each such encounter is probably best resolved individually in the field.

#### **Protection From Freezing**

Soil bearing surfaces below completed foundations and slabs must be protected against freezing, before and after foundation construction. If construction is performed during freezing weather, footings bearing on the Glacial deposits or compacted Structural Fill should be covered to a sufficient depth (up to 4-ft) as soon as possible after they are constructed. Alternatively, insulating blankets, lowering of footings, providing heaters, or other means may be used for protection against freezing.



#### Compaction

Minimum compaction requirements refer to percentages of the maximum dry density determined in accordance with ASTM D1557. Recommended compaction requirements are as follows:

Location	Minimum Compaction Requirements
Beneath and around footings, beneath slabs	95 %
Parking, roadways and sidewalks	92 % up to 3 ft below finished grade 95 % in the upper 3 ft
Landscaped areas	90 % nominal compaction

#### Filling and Backfilling

Filling and backfilling will be required within the proposed building limits to reach footing and slab bearing levels. We recommend that Compacted Structural Fill or Slab Base Coarse be used as fill and backfill beneath footings and slabs to the limits described below. A minimum of 6-in. of Compacted Slab Base Coarse, or 12-in. of Crushed Stone for the planned basement, should be provided directly beneath the floor slabs.

Where Compacted Structural Fill is required beneath foundations, it should be placed beneath the footings and within the zone beneath imaginary lines extending from points 1-ft laterally beyond the footing outer bottom edge and down on a 1H:1V slope, down to the top of natural bearing strata (zone of influence).

Except for zones requiring special backfill such as directly beneath pavements or exterior slabs, the exterior of foundation walls may be backfilled with Common Fill.

Placement of compacted soil fills should not be conducted when air temperatures are low enough (approximately 30 degrees F, or below) to cause freezing of the moisture in the fill during or before placement. Fill materials should not be placed on snow, ice or uncompacted frozen soil. Compacted fill should not be placed on frozen soil. No fill should be allowed to freeze prior to compaction. At the end of each day's operations, the last lift of fill, after compaction, should be rolled by a smooth-wheeled roller to eliminate ridges of uncompacted soil.

#### **Structural Fill**

Structural Fill beneath footings and building slabs should consist of bank-run sand and gravel, free of organic material, snow, ice, or other unsuitable materials and should be well-graded within the following limits:

Sieve Size	Percent Finer by Weight
3 in.	100
No. 4	30 - 80
No. 40	10 - 50
No. 200	0 – 10

Other materials could be acceptable for compacted Structural Fill, and should be evaluated by the Geotechnical Engineer on a case-by-case basis if proposed by the Contractor.

Structural Fill should be placed in lift thicknesses not exceeding 12 in. loose measure. In confined areas, handguided equipment such as a vibratory plate compactor should be used and the loose lift thickness should not exceed 6 in.

A minimum of four systematic passes of the compaction equipment should be used to compact each lift.

#### **Common Fill**

Common fill should consist of mineral sandy soil, free from organic matter, plastic, metal, wood, ice, snow or other deleterious material and should have the characteristic that it can be readily placed and compacted. Common fill imported to the site should have a maximum of 80 percent passing the No. 40 sieve and a maximum of 30 percent



finer than the No. 200 sieve. The largest particle size for common fill should not exceed 2/3 of the lift thickness. Silty common fill soils may require moisture control during placement and compaction. Common Fill should be placed and compacted in the manner described in "Filling and Backfilling."

#### **Crushed Stone**

Crushed Stone should consist of durable crushed rock or crushed gravel stone obtained by breaking and crushing rock, or boulders, and it is free from a detrimental quantity of thin, flat, elongated or other objectionable pieces.

The <sup>1</sup>/<sub>2</sub>-inch crushed stone should have the following gradation:

Sieve Size	Percent Finer by Weight
5/8 inch	100
<sup>1</sup> / <sub>2</sub> inch	85-100
3/8 inch	15-45
No. 4	0-15
No. 8	0-5

#### Slab Base Course

Slab Base Course beneath building slabs should consist of bank-run sand and gravel, free of organic material, snow, ice, or other unsuitable materials and should be well-graded within the following limits:

Sieve Size	Percent Finer by Weight
2 in.	100
No. 4	40 - 70
No. 40	25 - 45
No. 200	0-10

Other materials could be acceptable for compacted Slab Base Course, and should be evaluated by the Geotechnical Engineer on a case-by-case basis if proposed by the Contractor.

Slab Base Course should be placed in lift thicknesses not exceeding 8-in. loose measure. In confined areas, handguided equipment such as a vibratory plate compactor should be used and the loose lift thickness should not exceed 6 in.

A minimum of four systematic passes of the compaction equipment should be used to compact each lift.

#### PLAN REVIEW

It is recommended that GSI be provided the opportunity to review the final plans in order to confirm that the recommendations made in this report were interpreted and implemented as intended.

#### CLOSURE

GSI appreciates the opportunity for participating in this early phase of the project, and looks forward to our continuing association during its subsequent phases towards its successful completion. In the mean time, please do not hesitate to contact us, if you have any questions on the content of this report.

Very truly yours,

#### GEQTECHNICAL SERVICES, INC.

Glen V. Zoladz, P.E.


Project Engineer


Harry K. Wetherbee, P.E. *Principal Engineer* 



Figure 1	Project Locus
Figure 2	Exploration Location Plan
Appendix A	Limitations

Appendix ALimitationsAppendix BTest Boring Logs





#### LEGEND:

**B-1** 

TEST BORING I.D.AND APPROXIMATE LOCATION



FIGURE 2-EXPLORATION LOCATION PLAN

**BOURNEDALE ELEMENTARY SCHOOL** BOURNE, MA GSI PROJECT NO. 215257

APPENDIX A

LIMITATIONS



#### LIMITATIONS

#### Explorations

- 1. The analyses, recommendations and designs submitted in this report are based in part upon the data obtained from preliminary subsurface explorations. The nature and extent of variations between these explorations may not become evident until construction. If variations then appear evident, it will be necessary to re-evaluate the recommendations of this report.
- 2. The generalized soil profile described in the text is intended to convey trends in subsurface conditions. The boundaries between strata are approximate and idealized and have been developed by interpretation of widely spaced explorations and samples; actual soil transitions are probably more gradual. For specific information, refer to the individual test pit and/or boring logs.
- 3. Water level readings have been made in the test pits and/or test borings under conditions stated on the logs. These data have been reviewed and interpretations have been made in the text of this report. However, it must be noted that fluctuations in the level of the groundwater may occur due to variations in rainfall, temperature, and other factors differing from the time the measurements were made.

#### Review

- 4. It is recommended that this firm be given the opportunity to review final design drawings and specifications to evaluate the appropriate implementation of the recommendations provided herein.
- 5. In the event that any changes in the nature, design, or location of the proposed areas are planned, the conclusions and recommendations contained in this report shall not be considered valid unless the changes are reviewed and conclusions of the report modified or verified in writing by Geotechnical Services, Inc.

#### Construction

6. It is recommended that this firm be retained to provide geotechnical engineering services during the earthwork phases of the work. This is to observe compliance with the design concepts, specifications, and recommendations and to allow design changes in the event that subsurface conditions differ from those anticipated prior to the start of construction.

#### Use of Report

- 7. This report has been prepared for the exclusive use of Flansburgh Architects, Inc. in accordance with generally accepted soil and foundation engineering practices. No other warranty, expressed or implied, is made.
- 8. This report has been prepared for this project by Geotechnical Services, Inc. This report was completed for preliminary design purposes and may be limited in its scope to complete an accurate bid. Contractors wishing a copy of the report may secure it with the understanding that its scope is limited to evaluation considerations only.



### **APPENDIX B**

**TEST BORING LOGS** 



		<b>\G</b>	ř												Bor	ing No.	
		$\Rightarrow$	S_					TES	Г ВОР	RING	LOG				I	B-1	
8	2													P	age	1 of	1
617.745.4308	Pro	oject			Bourned	ale Schoo	ol	F	Project No	).	215257		Elev	ation		N/A	
45.		cation			Bourne,	MA			nspector		G. Zolac	lz	Datu	ım		N/A	_
7.7	Cli	ent			Flansbur	gh Archite	ects		Project Ma	anager	G. Zolac	Iz	Star	t	1	1/4/201	5
. 61	Co	ntractor			NEBC	-			, Checked E				Finis		-	1/4/201	
ax.	Dri	ller			P. Donoł	noe			Drill Rig	,	Diedrich		Mod		-	-50	-
8	Iter	m:			Auger	Casin	a	Sampler	Core Ba	ırrel 🗸	Truck	Skid		Ham	mor	Type:	
424	Ty					HW	-	S	-		Track			_			
55.		ide Dian	notor (in	)	-	4		1.375	-		Bomb.	Geopho	<b>no</b>			lammer	
617.455.4248 Fax.		mmer W			-	300		140			Tripod	Other	ne		oughn Itoma		
. 61				,,					4						_		
Tel	на	mmer Fa	all (In.)		-	24 Comple D	ata	30			Winch _	Cat Head	Ro	ller Bit	Cut	ting Hea	ıd
16	(ft)	a (‡		<u> </u>		Sample D			1_	-	Soil-Roc	k Visual Clas	sification	n and Desc	riptio	on	
Boston, MA 02116 Tel.	Depth (ft)	Casing (Blows/ft)	No.	Dept (ft)	h Rec. (in.)	SPT (Blows/ 6-in.)	Rock RQD (%)		Stratum Change (ft)			(Soils - Bu ck - U.S. Corp	rmister Sy	ystem)	•		
ston	0		S1 0-2 20 5 Topsoil														
Bo						12 24			~0.6	<b>.</b>			•••••				
30 Newbury Street,						24 33				Dense,	brown, silty	f/m SAND, tr.	. gravel, c	-sand			
Stre																	
h																	
wbı																	
Ne	- 5 -		S2	5-7	14	10				Donco	brown, f/m	SAND					
30			32	5-7	14	12 17				Dense,		SAND					
•						20 23											
õ						23											
706																	
29.																	
603.529.7080																	
. 60	- 10 -		S3	10-1	2 14	19				V. dens	e, brown, fii	ne SAND, with	n 2-in. sea	am of br., f/	SAN	ID,	
Fax						19 27 29 33				tr. grav							
96 I						33											
.77																	
529																	
603.529.7766 Fax.										Note: g	rinding on ro	ock at 14-ft. F	Rollerbit re	efusal at 14	7-ft.		
el. 6	- 15 -									Refusa	at 14.6-ft.						
" 55 North Stark Highway Tel.										Bottom	of exploration	on at 14.6-ft.					
Iwa																	
High																	
urk ł																	
Sta																	
orth	20																
NC	- 20 -																
. 55																	
h L																	
ces				1													
ervi				1													
Geotechnical Services, Inc.	_ 25 _																
nica				Water	Level Data			<u> </u>	Sample Ide			esive Soils N-		Granular			le
schı	De	to I	Timo			oth (ft) to:			O = Ope			0 to 2: Very So 2 to 4: Soft			Very 10: L	Loose	
∋ote	Da	le	Time		tt. of I sing	Bott. of Hole	Wa	ter	U = Und S = Spli		4	2 to 4: Soft to 8: Medium		4 to 11 to 30:			se
Ğ	4-N	ov		Ca	SILIQ	BIOLE	~	8	S = SpirC = Roc		-	8 to 15: Stiff				Dense	
					1				G = Geo		1	5 to 30 Very S	Stiff	Over 50			;
										-		Over 30: Har	d		-		
	Not			Trac	e (0 to 5%	b), Littl	e (10 to	o 20%),	Some (2	20 to 359	%), And	(35 to 50%)			4	B-1	
	Note	<i>σ</i> δ.													1		

[		G	ř															Bori	ng No.	
		Þ	S					TE	S1	r Bof	RIN	IG	LOG						3-2	_
617.745.4308		⊐ oject	-		Bourned	lale Schoo	ol		F	Project No			215257		Ele	evation	Pag	je	1 of 1 N/A	_
745	Loc	cation			Bourne,	MA			h	nspector			G. Zoladz		Da	tum			N/A	
17	Clie	ent			Flansbu	rgh Archit	ects		F	Project Ma	inage	er	G. Zoladz		Sta	art		11	1/4/2015	
	Co	ntractor			NEBC				C	Checked E	By				Fir	nish		11	1/4/2015	
Fax.	Dri	ler			P. Dono	hoe			С	Drill Rig	-		Diedrich		Mc	odel		D-	50	
ᅇ	lter	n:			Auger	Casir	na	Samp		Core Ba	rrel		Truck	Skid	I	F	lamm		ype:	-
424	Тур				-	HW	•	S	-											
55.			neter (in.	`	-	4		1.37	5				Track						ammer	
7.4				,		_				-		Н	Bomb.	Geophor	ne		Dou			
61			eight (lb	)	-	300	)	14(		-	-		Tripod	Other			Auto			
ē.	Ha	mmer Fa	all (in.)		-	24		30			-		Winch 🗸	Cat Head	F	Roller Bit	$\checkmark$	Cutt	ing Head	_
6	(f	_ <del>,</del> <del>,</del>		T		Sample D	ata												-	
30 Newbury Street, Boston, MA 02116 Tel. 617.455.4248	Depth (ft)	Casing (Blows/ft)	No.	Dep (ft)		SPT (Blows/ 6-in.)	Ro RC (%	D R	ID dg. om)	Stratum Change (ft)				Visual Class (Soils - Bur - U.S. Corps	mister	System)		-	n	
ton	- 0 -		S1	0-2	2 12	4					Тор	soil								
30S						4 7 7				~0.6	·									
et, E						5					M. d	lens	e, brown, silty	y fine SAND.	tr. m/c	sand				
itre													-							
5																				
inq,																				
lev	- 5 -																			
20 2	- 5 -		S2	5-7	7 5	4 8					M. d	lens	e, brown, f/m	SAND, little	c-sand	l, tr. silt				
:						6														
						6														
080																				
9.7(																				
22																				
55 North Stark Highway Tel. 603.529.7766 Fax. 603.529.7080	- 10 -																			
× 0	10		S3	10-10	0.6 5	82 50/0"					V. d	ens	e, brown, f/c S	SAND, tr. silt	t (rick ir	i spoon tip	)			
ц						50/0														-
200													it to 11-ft. at 11-ft.							
9.7	_												of exploration	n at 11-ft.						
523																				
803																				
9. O	- 15 -																			
, T€																				
va)																				
igh																				
Т																				
tarl																				
s u																				
lort	- 20 -																			
2 2																				
<u>ں</u>																				
2 2																				
s, Ir																				
ice																				
erv																				
S I	- 25 -																			
Geotechnical Services, Inc.				Nater	Level Dat				S	ample Ide				sive Soils N-					N- Value	
chr	<u> </u>			<u> </u>		epth (ft) to	:		4	O = Ope				to 2: Very Sc	oft				Loose	
ote	Dat	e	Time		tt. of	Bott. of	V	Vater	1	U = Und				2 to 4: Soft 8: Medium §	Stiff		to 1		n Dense	
Ge	4-N	ov		Ca	ising	Hole	├──	~8	1	S = Split C = Roc				8: Medium 3 8 to 15: Stiff	ווו				m Dense ense	
ŀ	- <b>T</b> 'I N	~ •					-	5	1	G = Gec				to 30 Very S	tiff				Dense	
ŀ									1				C	Over 30: Hard						
[				Trac	ce (0 to 5%	%), Litt	le (10	) to 20%	<i>(</i> ,),	Some (2	20 to	35%	%), And (3	5 to 50%)					B-2	

Notes:

B-2

G	
₽₽	5_

#### \_

Boring I	No.
----------	-----

			<b>&gt;</b>						ΤE	S1	r Bof	RING	i L(	OG						B-3
0	2																		Pa	ge 1 of 1
ງ ບິ	Pro	ject		<u> </u>	Bourr	nedal	le Schoo	l		P	Project No		2	15257			El	evation		N/A
40.		ation			Bourr						nspector			a. Zoladz				atum		N/A
Fax. 61/./45.4308	Clie	ent			Flans	burg	h Archite	ects			roject Ma	nager	-	a. Zoladz				art		11/4/2015
0 ;	Co	ntractor			NEBC	)				C	Checked E	By					Fir	nish		11/4/2015
Га	Dri	ler			P. Do	noho	be			D	Drill Rig		C	iedrich			Mo	odel		D-50
44	Iter	n:			Auge	r	Casin	g S	Sampl	er	Core Ba	rrel 🗸	] Truo	ck	🗌 Sk	id		Ŀ	lamr	<u>ner Type:</u>
5.4 1	Тур				-		HW		S		-		Trad	:k	AT			$\checkmark$	] Saf	ety Hammer
- - -		ide Diarr	,	,	-		4		1.37		-		Bon			ophone	9			ıghnut
<u> </u>		mmer W	• •	)	-		300		140				] Tri			her			_	omatic
e.	Ha	mmer Fa	all (in.)		-		24		30				Win	ch 🗸	Cat He	ad	F	Roller Bit	$\checkmark$	Cutting Head
<u>0</u>	(tt)	g /ft)		T		Sa	ample Da		<u> </u>				S	oil-Rock	Visual	Class	ificati	on and D	escr	iption
	oth	Casing (Blows/ft)	No	Dep	th Re	ec.	SPT (Diawa)	Rock	PI		Stratum				(Soils	s - Burn	nister	System)		-
ΑN	Depth	ů (Blo	No.	(ft)	) (ir	า.)	(Blows/ 6-in.)	RQD (%)	Ro (pp	-	Change (ft)			(Rock	- U.S.	Corps	of Eng	gineers Sy	vsten	ו)
, L	0 -				_		,	(70)	(PP	,,,,,	(11)									
BOSTON, IMA UZ I 16 161. 617.455.4248	U		S1	0-2	2   6	6	11 14				~0.6	Topsoi	I							
<u>،</u>	- 1						14 13				[	M don	ca h	rown, f/m		······				
olreel,	• •						10						JC, D	J WIT, 1/11	ONINE					
'nnu																				
30 Newpury	- 5 -						_													
30	U		S2	5-7	7   1	4	5 17					V. dens	se, bi	rown, f/c	SAND,	tr. silt				
ľ							100/6"													
ž														7-ft. Sec	ond att	empt-re	efusal	at 7-ft.		
0.												Refusa Bottom		1-ft. xploratior	n at 7-ft	t.				
003.529.7080																				
03.	10 -											NO GIO	unaw	ater dete	cieu.					
rax. o	10																			
с о																				
0//																				
N.																				
003.229.770																				
	- 15 -																			
-	- 13 -																			
vay.																				
- Ign																				
L Y																				
otal																				
E																				
55 NORTH STARK HIGHWAY	- 20 -								1											
20									1											
<u>p</u>									1											
s, ⊨																				
/Ice																				
Geotecnnical Services, Inc.									1											
cal ;	. 25 -		· · · ·	Nator	Level [	)ata			<u> </u>	<u>م</u>	ample Ide	entificati	ion	Cohe	sive Sr	oils N-V	alue	Gran	ular	Soils N- Value
				aiei			th (ft) to:			<u> </u>	O = Ope					ery Sof				Very Loose
Dec	Dat	e	Time		ott. of	B	ott. of	Wate	ər		U = Und	isturbed	ł		2 to 4:	Soft		2	4 to 1	0: Loose
б С	4-N	ov		Ca	asing		Hole	N/A			S = Split C = Roc				8: Me 8 to 15	dium St Stiff	titt			ledium Dense 50: Dense
ł	4-IN							IN/ <i>F</i>	1		C = Roc G = Gec					/ery Sti	ff			Very Dense
ļ				İ_				/ · - ·		Ļ			- / )	C	Over 30	): Hard				-
ŀ	Note	es:		Tra	ce (0 to	5%)	, Little	e (10 to	20%	),	Some (2	20 to 35	%),	And (3	5 to 50	%)				B-3

	G	S,					TE	ST	r Bof	RINC	G LOG				Boring <b>B-</b>	-	
$\angle$	]													Pag	je 1	of	
Proj	ect			Bourne	dale Schoo	ol		P	roject No		215257		Elevation		I	N/A	-
Loca	ation			Bourne	MA				nspector		G. Zoladz		Datum		I	N/A	_
Clie	nt			Flansbu	irgh Archit	ects			roject Ma	nader	G. Zoladz		Start			4/201	5
Con	tractor			NEBC	0				hecked E	-			Finish			4/201	-
Drill				P. Dono	hoe				rill Rig	<i>,</i> y	Diedrich		Model		D-50		_
							0	L									
Item				Auger	Casir	-	Samp	ler	Core Ba	rrei	Truck	Skid		_	ner Typ		
Тур				-	HW		S		-		Track	ATV	~	Safe	ty Har	nmer	
	de Diam			-	4		1.37	5	-		Bomb.	Geophone			ghnut		
Han	nmer We	eight (lb	)	-	300	)	140	)			Tripod	Other		Auto	omatic		
Han	nmer Fa	ll (in.)		-	24		30				Winch 🔽 Ca	at Head	Roller Bit	$\checkmark$	Cuttin	a Hea	d
		, ,			Sample D	ata									Cuttin	91100	u
Depth (ft)	Casing (Blows/ft)	No.	Deptl (ft)		(Blows/	Ro RC (%	D R	ID dg. om)	Stratum Change (ft)			isual Classific (Soils - Burmist U.S. Corps of E	er System)				
0		S1	0-2	14	6					Topso	il						
			-		12	1			~8								
					8 6					M. der	nse, br., f/m SAN	ID, tr. silt					
- 5 - - -		S2	5-7	6	5 3 2 3					Loose	, br., f/m SAND						
10 -		S3	10-12	2 8	8 10 14 17					M. der	nse, br., f/m SAN	ID, tr. silt					
15 -		S4	15-13	7 16	7 11 18 32					M. der	nse, br., f/m SAN	ID					
20		S5	20-22	2 14	20 21 24 62					V. den	se, br., fine SAN	ID, tr. m-sand					
										Botton	n of exploration a	at 22-ft.					
25			Nator		ta	1		<u>ر</u>	ample Id	antificat		A Soile N Valu	e Gran	ular S			
Date 4-No		ïme	Boti Cas	tt. of sing	epth (ft) to Bott. of Hole	V	Vater ~12	-	$\frac{\text{ample Ide}}{O = Ope}$ $U = Und$ $S = Split\\C = Roc$ $G = Gec$	en Ende isturbe t Spoor k Core probe	ed 0 to d 2 n 4 to 8 15 to Ov	ve Soils N-Valu 2: Very Soft 2 to 4: Soft 3: Medium Stiff to 15: Stiff o 30 Very Stiff ver 30: Hard	0 t 2 11 to 3 3	o 4: V 4 to 10 30: M 1 to 5	oils N /ery Loo: ledium 0: Der Very [	bose se I Dens nse	se
			Trac	e (0 to 5	%), Litt	le (10	) to 20%	s),	Some (2	20 to 35					r	B-4	-
Notes	s.															J-4	

	<b>G</b>	-																В	oring	g No.
		S_					ΤE	S	r Bof	RIN	G	LOG							B-	5
																	ſ	Page	1	of
Pro	ject			Bourneda		bl		P	roject No			215257				Elevati	ion		١	N/A
	ation			Bourne, N					nspector			G. Zola				Datum				N/A
Clie	ent ntractor			Flansburg NEBC	gh Archite	ects			Project Ma	<u> </u>	r	G. Zola	dz			Start				1/201
Drill				P. Donoh	00				hecked E Fill Rig	бу	_	Diedrich	n			Finish Model			D-50	1/201 1
Iten				Auger	Casin	q	Samp		Core Ba	rrel	<u>_</u>	Fruck		Skid		modor	H	amme		
Тур	be			-	HW	-	S		-			Frack						Safety		
Insi	ide Diam	eter (in.	)	-	4		1.37	5	-	ĺ		Bomb.		Geoph	one			Doug		
	mmer W	•	)	-	300	)	140	)				Tripod		Other				Auton	natic	
Har	mmer Fa	all (in.)		-	24		30			[	١	Ninch 🔤	√ Ca	t Head		Rolle	r Bit	√ C	utting	g He
(Ĵ	g (Ħ		<u> </u>	S	ample D	T	<u> </u>					Soil-Roo	ck Vi	sual Cla	ssific	ation	and De	escrin	tion	
Depth (ft)	Casing (Blows/ft)	No.	Depth (ft)	Rec. (in.)	SPT (Blows/ 6-in.)	Roc RQ (%	D Ro	ID dg. om)	Stratum Change (ft)				(5	Soils - Bi J.S. Corj	urmist	er Syst	tem)	-		
0		S1	0-2	20	12 21 17				~7	Tops	oil									
					8					Dens	se, b	or., silty f/n	n SAI	ND						
 - 5 -  		S2	5-7	12	7 14 21 24					Dens	se, t	or., f/m SA	ND							
- 10 -		S3	10-12	12	11 19 21 29					Dens	se, b	or., fine SA	AND,	tr. silt						
- 15 - 		S4	15-17		30 38 45 51					V. de	ense	e, br., f/m \$	SANE	D, tr. silt						
 - 20 -										Aiger Botto	r ref om c	usal at 17 of explorat	-ft. ion at	t 17-ft.						
 - 25 - Date 4-No		۱ Гime	Water Le Bott. Casi	of E	bth (ft) to: Bott. of Hole	W	ater 10	<u>S</u>	ample Ide O = Ope U = Und S = Split C = Roc	en End listurb t Spoo k Core	ded ed on e	4	0 to 2 2 to 8: 8 t	<u>e Soils N</u> 2: Very S to 4: Sof Medium o 15: Sti 30 Very	Soft t 1 Stiff ff		4 11 to 3 31	4: Ve to 10:	ery Lo Loos dium : Den	iose se Den ise
	es:		Trace	(0 to 5%	), Littl	e (10	to 20%	s),	G = Geo Some (2	-			Ove	er 30: Ha o 50%)			0.00		-	3-5

I. Traffic Impact Study

#### 3.1.4 Evaluation of Existing Conditions

#### I. TRAFFIC IMPACT STUDY

Nitsch Engineering conducted traffic analysis at work at the Peebles and Bournedale Elementary School sites in Bourne.

PURPOSE: To prepare a qualitative assessment of safety, traffic circulation, and traffic access/egress, associated with the feasibility study. Nitsch Engineering also conducted parental pick-up and drop-off counts as part of their site observation.

The proposed design alternatives were evaluated as part of this study to gain understanding on the potential traffic issues unique to the sites being considered.

Traffic counts were taken at the following two major intersections:

- Route 6 at Nightingale Road
- Route 6 at Edge Hill Road

In addition, Automatic Traffic Recorder (ATR) counts were taken at Trowbridge Road and Ernest Valeri Road.

#### FINDINGS

(PEEBLES):

- A total of eight buses drop off students at the school
- A total of 93 parental drop-off vehicles were observed
- A total of a 106 vehicles enter the site between 8:30am and 9:30am. 59 vehicles entering the site were traveling eastbound on Trowbridge Road while 47 vehicles were traveling westbound.
- A total of 73 parental pick-up vehicles were observed during afternoon dismissal between 2:00pm and 3:30pm. 47 vehicles entering the site were travelling eastbound on Trowbridge Road while 18 vehicles were traveling westbound.
- There were a total of 66 parking spaces counted with an overall utilization of 78% at the time observed


#### (BOURNEDALE):

- A total of thirteen buses drop off students at the school
- A total of 69 parental drop-offs were observed during the morning.
- A total of a 128 vehicles enter the site between 8:15 AM through 9:30 AM. 128 vehicles entering the site were traveling westbound on Ernest Valerie Road while 4 vehicles were traveling eastbound.
- 60 vehicles entering the site between 2:30pm and 3:30pm. 59 vehicles entering were traveling westbound on Ernest Valerie Road while 4 vehicles were traveling eastbound.
- A total of 53 parental pick-up vehicles were observed during afternoon dismissal.
- There were a total of 137 parking spaces counted with an overall utilization of 58% at the time observed
- Design Option 3 (PK-5) established a total of 177 vehicles at drop-off and 113 vehicles at pick-up

#### CONCLUSION:

- 1. The Design options at the Peebles School site (Options 1 and 4) will have very little or no impact on Trowbridge Road traffic.
- 2. Design Option 3 (PK-5) established 258 additional entering/exits trips during the morning and 202 entering/exits trips during the afternoon
- 3. Design Option 3 (PK-5) established a total of 177 vehicles at drop-off and 113 vehicles at pick-up
- 4. The intersection of Route 6 at Nightingale will see a minor increase in traffic volume.
- 5. The intersection of Route 6 at Edge Hill Road will see a minor increase in traffic volume.

The full Traffic Impact Study report follows.



## Peebles Elementary School Bourne, MA

Transportation Feasibility Study

December 17, 2015

Prepared for:

Flansburgh Architects 77 North Washington Street Boston, MA 02114

Submitted by:

Nitsch Engineering 2 Center Plaza, Suite 430 Boston, MA 02108

Nitsch Project #11078.0

Building better communities with you.

1	INTR	ODUCTION	4	
2	EXISTING CONDITIONS			
	2.1	Study Area Roadways	8	
	2.2	Study Area Intersections		
	2.3	Peebles Elementary School Site Visit		
	2.4	Peebles Elementary School Site Access and Egress		
	2.5	Peebles Elementary School Traffic Circulation and Pick-up/Drop-off		
	2.6	Peebles Elementary School Parking Supply and Demand		
	2.7	Bournedale Elementary School Site Visit		
	2.8	Bournedale Elementary School Site Access and Egress		
	2.9	Bournedal Elementary School Traffic Circulation and Pick-up/Drop-off		
	2.10	Bournedale Elementary School Parking Supply and Demand		
3	SAFETY ANALYSIS			
	24	Creach Data	20	
	3.1	Crash Data	22	
4	EXISTING TRAFFIC CONDITIONS23			
	4.1	2015 Traffic Count Data	23	
	4.2	Seasonal Adjustment	26	
5	FUTURE NO-BUILD TRAFFIC CONDITIONS			
	5.1	Background Growth	26	
	5.2	No-Build Traffic Volumes		
6	FUTURE CONDITIONS			
	6.1	Proposed Trip Generation	28	
	6.2	Proposed Option 3 – Consolidated Peebles and Bournedale Elementary Schools		
7	OPE	RATIONS ANALYSIS		
	7.1	Level of Service Criteria		
	7.2	Capacity Analysis		
	7.3	2015 Existing Capacity Analysis		
	7.4	2020 No-Build Capacity Analysis		
	7.5	2020 Build Capacity Analysis		
	7.6	Traffic Signal Warrant Methodology		
	7.7	Traffic Signal Warrant		
	7.8	Travel Time Study		
8	CONCLUSIONS AND RECOMMENDATIONS			
	8.1	Conclusions		
	8.2	Recommendations		

#### TABLE OF CONTENTS

#### LIST OF TABLES

Table 3 - Crash Summary	22
Table 4 - Automatic Traffic Recorder (ATR) Summary	23
Table 5 - Vehicle Travel Speeds	
Table 6 - Existing and Proposed Trip Generation	
Table 7 - Level of Service Criteria	35
Table 8 – Level of Service Summary - 2015 Existing Conditions	36
Table 9 – Level of Service Summary - 2020 No-Build Conditions	37
Table 10 – Level of Service Summary - 2020 Build Conditions	38
Table 11 – Results of Travel Time Study	40

#### LIST OF FIGURES


Figure 1 – Locus Map	5
Figure 2 – Peebles Elementary School	6
Figure 3 – Bourndale Elementary School	7
Figure 4 – Intersection Locations	11
Figure 5 – Peebles Elementary School Site Circulation	14
Figure 6 – Peebles Elementary Parking Utilization	15
Figure 7 – Bournedale Elementary School Site Circulation	19
Figure 8 – Bournedale Elementary Parking Utilization	20
Figure 9 – 2015 Existing Traffic Volumes	25
Figure 10 – 2020 No-Build Traffic Volumes	27
Figure 11 – Regional Trip Distribution	29
Figure 12 – Trip Distribution	
Figure 13 – Trip Assignment	
Figure 14 – 2020 Future Build Traffic Volumes	

#### 1 INTRODUCTION

Nitsch Engineering has been retained by Flansburgh Architects (FA) to prepare a qualitative assessment of safety, traffic circulation, and traffic access/egress, associated with the feasibility study and schematic design for the Peebles Elementary School project in Bourne, Massachusetts. Two options are considered for the reconstruction. The first option would be renovate and expand the existing Peebles Elementary School building and grounds on the site of the existing school, located 70 Trowbridge Road in Bourne, Massachusetts. The second option would be to renovate and expand existing Bournedale Elementary School, located at 41 Ernest Valerie Road, approximately 2 miles northeast of the existing school site to include the relocated Peebles Elementary School.

This report will outline the existing and proposed traffic volumes, operations, and safety of the adjacent surrounding roadways and intersections; traffic patterns of the existing Peebles Elementary School and the existing Bournedale Elementary School, including site access/egress, parent and bus pick-up/drop-off, traffic circulation, and parking supply/demand. The report will use this information to project future conditions for both the Peebles Elementary School option and the Bournedale Elementary School option.

The Locus Map of the study area is shown in Figure 1, a map of the existing Peebles Elementary School site is shown in Figure 2, and a map of the existing Bournedale Elementary School Site is shown in Figure 3.



**Figure 1: Locus Map** Peebles Elementary School Bourne, Massachusetts

Nitsch Engineering



# **Figure 2: Peebles Elementary School** Peebles Elementary School Bourne, Massachusetts





**Figure 3: Bournedale Elementary School** Peebles Elementary School Bourne, Massachusetts



# 2 EXISTING CONDITIONS

# 2.1 Study Area Roadways

To examine the existing conditions, we studied and collected data at the following roadways:

- 1. Trowbridge Road
- 2. Ernest Valeri Road; and
- 3. Scenic Highway (Route 6)

# Trowbridge Road

Trowbridge Road is classified by the Massachusetts Department of Transportation (MassDOT) as a Rural Major Collector or Urban Minor Arterial and runs in the west-northeast directions between Bourne Rotary and Sandwich Road in Bourne. The posted speed limit along the roadway is 20 miles per hour. The land use along Trowbridge Road is primarily residential. The roadway is within the jurisdiction of the Town of Bourne.

# Ernest Valeri Road

Ernest Valeri Road is classified by the Massachusetts Department of Transportation (MassDOT) as a local road and runs in the east-northwest directions between Edge Hill Road and High Ridge Drive in Bourne. The posted speed limit along the roadway is 20 miles per hour. The land use along Ernest Valeri Road is primarily recreational. The roadway is within the jurisdiction of the Town of Bourne.

# Scenic Highway (Route 6)

Scenic Highway (Route 6) is classified by MassDOT as a Principal Arterial and runs in the northeastsouthwest directions. Scenic Highway (Route 6) is present between Route 3/Sagamore Bridge over Cape Code Canal in Bourne at its northwest terminus and Main Street/Bourne Bridge over the Cape Cod Canal at its southeast terminus. The posted speed limit along the roadway is 50 miles per hour. The land use along Central Avenue is primarily open space. The roadway is within the jurisdiction of the Massachusetts Department of Transportation (MassDOT).

# 2.2 Study Area Intersections

To examine the existing conditions, we included the following intersections in the study area. The intersection locations are shown in Figure 4.

- 1. Scenic Highway (Route 6) at Nightingale Farm Road; and
- 2. Scenic Highway (Route 6) at Edge Hill Road.

# Scenic Highway (Route 6) at Nightingale Farm Road

Scenic Highway (Route 6), Nightingale Farm Road and Andy Olivia intersect as a four-way signalized intersection, with Scenic Highway (Route 6) approaching from the east and west, Nightingale Farm Road approaching from the north, and Andy Olivia approaching from the south. A crosswalks is present at the eastbound approach.

From the west, Scenic Highway (Route 6) is a two-way roadway with two lanes in each direction, separated by a 6 feet wide raised concrete median. The approach to the intersection consists of two lanes. The left lane permits a through movement and a left turn movement that transitions to the north on Nightingale Farm Road, and the right lane permits a through movement and a right turn that transitions to the south onto Andy Olivia. Scenic Highway (Route 6) is approximately 56 feet wide at the intersection. Bituminous concrete sidewalks are present on both sides of Scenic Highway (Route 6).

From the east, Scenic Highway (Route 6) is a two-way roadway with two lanes in each direction, separated by a 6 feet wide pavement marking. The approach to the intersection consists of two lanes. The left lane permits a through movement and a left turn movement that transitions to the south onto Andy Olivia, and the right lane permits a through movement and a right turn that transitions to the north on Nightingale Farm Road. Scenic Highway (Route 6) is approximately 56 feet wide at the intersection. There is no sidewalk present on either side of Scenic Highway (Route 6).

From the south, Andy Olivia is a two-way roadway with one lane in each direction, separated by a double yellow centerline. The approach to the intersection consists of one lane to permit through, left, and right movements that transition to the north on Nightingale Road and east and west on Scenic Highway (Route 6). Andy Olivia is approximately 50 feet wide at the intersection. There is no sidewalk present on either side of Andy Olivia.

From the north, Nightingale Road is a two-way roadway separated by a double yellow centerline. The approach to the intersection consists of two lanes. The left lane permits a through movement and a left turn movement that transitions to the east on Scenic Highway (Route 6), and the right lane is a right turn only that transitions to the west on Scenic Highway (Route 6). Nightingale Road is approximately 40 feet wide at the intersection. A bituminous concrete sidewalks is present on the west side of Nightingale Road.

The fully actuated traffic signal operates in three phases. The following movements are permitted or protected, as noted, during each of the phases.

# First phase:

- Scenic Highway (Route 6) westbound; and
- Scenic Highway (Route 6) eastbound.

# Second phase (if actuated):

• Exclusive pedestrian phase for crossing Scenic Highway (Route 6) eastbound.

# Third phase:

- Nightingale Road southbound; and
- Andy Olivia northbound.

Scenic Highway (Route 6) at Edge Hill Road

Scenic Highway (Route 6) and Edge Hill Road intersect as a three-way signalized intersection, with Scenic Highway (Route 6) approaching from the east and west, and Edge Hill Road approaching from the north. There are no crosswalks present at the intersection.

From the west, Scenic Highway (Route 6) is a two-way roadway separated by a 6 feet wide raised concrete median. The approach to the intersection consists of three lanes. The left lane is an exclusive left turn lane that transitions to the north on Edge Hill Road, and the right two lanes permit through movement east on Scenic Highway (Route 6). Scenic Highway (Route 6) is approximately 80 feet wide at the intersection. There is no sidewalk present on either sides of Scenic Highway (Route 6).

From the east, Scenic Highway (Route 6) is a two-way roadway with two lanes in each direction, separated by a 12 feet wide raised concrete median. The approach to the intersection consists of two lanes. The left lane permits a through movement, and the right lane permits a through movement and a right turn that transitions to the north on Edge Hill Road. Scenic Highway (Route 6) is approximately 80 feet wide at the intersection. There is no sidewalk present on either side of Scenic Highway (Route 6).

From the north, Edge Hill Road is a two-way roadway separated by a raised grass median. The approach to the intersection consists of two lanes. The left lane is an exclusive left turn movement lane that transitions to the east on Scenic Highway (Route 6), and the right lane is an exclusive right turn movement lane that transitions to the west on Scenic Highway (Route 6). Edge Hill Road is approximately 60 feet wide at the intersection. There is no sidewalk present on either side of Edge Hill Road.

The fully actuated traffic signal operates in three phases. The following movements are permitted or protected, as noted, during each of the phases.

# First phase:


- Scenic Highway (Route 6) westbound left; and
- Scenic Highway (Route 6) westbound Through.

# Second phase (if actuated):

- Scenic Highway (Route 6) westbound; and
- Scenic Highway (Route 6) eastbound.

# Third phase:

• Edge Hill Road southbound.



# **Figure 4: Intersection Locations** Peebles Elementary School Bourne, Massachusetts



# 2.3 Peebles Elementary School Site Visit

Nitsch Engineering conducted a site visit on Wednesday October 21, 2015 to observe the site circulation associated with the weekday morning drop-off, weekday afternoon pick-up and general queue lengths around the Peebles Elementary School site. The weekday morning drop-off observation occurred during partly cloudy conditions with a temperature of 48 degrees. The weekday afternoon pick-up activity occurred during partly cloudy conditions with a temperature of 58 degrees.

# 2.4 Peebles Elementary School Site Access and Egress

Peebles Elementary School is located to the south of 70 Trowbridge Road. The single access and egress driveway to Peebles Elementary School exists north of the school at Trowbridge Road. The driveway is approximately 320 feet long and 35 feet wide. A 6-foot sidewalk is present at the westerly side of the driveway, which connect to the sidewalks along Trowbridge Road to the parking lot at Peebles Elementary School. There is no crosswalk at the school driveway at the intersection with Trowbridge Road.

# 2.5 Peebles Elementary School Traffic Circulation and Pick-up/Drop-off

# Existing Morning Drop-off Circulation

Buses and vehicles drop off students via the driveway at Trowbridge Road. The Peebles Elementary School traffic arrives at Trowbridge Road from 8:30 AM through 9:30 AM. We observed that parents arrive and park along driveway and the designated pick-up/drop-off area and walk their children to the school. A total of 93 parental drop-offs were observed during the morning. Buses enter and exit the site from Trowbridge Road. A total of eight buses drop off students at the school. At the time of the site visit we didn't observe any students walkers or bicyclists. 59 vehicles entering the site were travelling eastbound on Trowbridge Road while 47 vehicles were traveling westbound.

# Existing Afternoon Pick-up Circulation

The afternoon pick-up period occurs approximately from 2:00 PM to 3:30 PM. Parents start arriving around 2:00 PM and queue up at the school driveway and the pick-up/drop-off area in the parking lot to wait for their children. Once they have collected their children they leave via Trowbridge Road, and normal traffic returns around 3:30 PM. A total of 73 parental pick-up vehicles were observed during afternoon dismissal. Buses enter and exit the site from Trowbridge Road. A total of eight buses pick up students at the school. At the time of the site visit we didn't observe any students walkers or bicyclists. 47 vehicles entering the site were travelling eastbound on Trowbridge Road while 18 vehicles were traveling westbound.


Table 1 quantifies the parent and bus drop-off/pick-up totals for the school.

Туре	Par	ent	Βι	IS				
Time	Drop-Off	Pick-Up	Drop-Off	Pick-Up				
8:30 - 8:45	13							
8:45 - 9:00	63		8					
9:00 - 9:15	12							
9:15- 9:30	5							
2:00 - 2:15		2						
2:15 - 2:30		6						
2:30 - 2:45		16						
2:45 - 3:00		29		8				
3:00 - 3:15		17						
3:15 - 3:30		3						
Total	93	73	8	8				

### Table 1 – Peebles Pick-Up/Drop-Off Quantity

### 2.6 Peebles Elementary School Parking Supply and Demand

Nitsch Engineering performed a parking supply and demand count on October 21, 2015. The utilization of the lot was taken at 10:00 AM. Figure 6 shows an overview of the Peebles Elementary School parking lot, the total parking spaces, parking space type, and lot utilization.



# Figure 5: Peebles Elementary School Site Circulation

Peebles Elementary School Bourne, Massachusetts





# Figure 6: Peebles Elementary Parking Utilization Peebles Elementary School

Bourne, Massachusetts



As can be seen from Figure 6, a total of 66 parking spaces were counted within the Peebles Elementary School, including two of which being accessible spaces. This meets the Architectural Access Board (AAB) Code of Massachusetts Regulations (521 CMR) for the required number of handicapped parking spaces. The two accessible spaces were not utilized at the time of observation. The overall lot utilization was 78%.

# 2.7 Bournedale Elementary School Site Visit

Nitsch Engineering conducted a site visit on Wednesday October 21, 2015 to observe the site circulation associated with the weekday morning drop-off, weekday afternoon pick-up and general queue lengths around the Bournedale Elementary School site. The weekday morning drop-off observation occurred during partly cloudy conditions with a temperature of 48 degrees. The weekday afternoon pick-up activity occurred during partly cloudy conditions with a temperature of 58 degrees.

# 2.8 Bournedale Elementary School Site Access and Egress

Bournedale Elementary School is located at 41 Ernest Valerie Road to the south of Ernest Valerie Road, and is served by three access and egress driveways at Ernest Valerie Road. The southerly most driveway is the man driveway to the school. The northerly most driveway is signed DO NOT ENTER, and is generally used for teacher/staff and school bus egress. The middle driveway provides access to the Pre School parking and its pick-off and drop-off area. A 6-foot sidewalk is present at the easterly side of the main driveway, which connects the sidewalk along Ernest Valerie Road to the parking lot at Bournedale Elementary School. There is no crosswalk at the school driveways at their intersection with Ernest Valerie Road.

# 2.9 Bournedal Elementary School Traffic Circulation and Pick-up/Drop-off

# Existing Morning Drop-off Circulation

Buses and vehicles drop off students via the main driveway at Ernest Valerie Road. The Bournedale Elementary School traffic arrives at Ernest Valerie Road from 8:15 AM through 9:30 AM. We observed that parents arrive and drop off their children at the front where school staff greet the children. A total of 69 parental drop-offs were observed during the morning. Buses enter the site from Ernest Valerie Road using the main driveway, and exit the site to Ernest Valerie Road using the northerly most driveway. A total of thirteen buses drop off students at the school. At the time of the site visit we didn't observe any students walkers or bicyclists. 128 vehicles entering the site were travelling westbound on Ernest Valerie Road while 4 vehicles were traveling eastbound.

# Existing Afternoon Pick-up Circulation

The afternoon pick-up period occurs approximately from 2:30 PM to 3:30 PM. Parents start arriving around 2:30 PM and queue up at the school driveway and the pick-up/drop-off area in the parking lot to wait for their children. Once they have collected their children they leave via the main driveway to Ernest Valerie Road, and normal traffic returns around 3:30 PM. A total of 53 parental pick-up vehicles were observed during afternoon dismissal. Buses enter the site from Ernest Valerie Road using the main driveway, and exit the site to Ernest Valerie Road using the northerly most driveway. A total of thirteen buses drop off students at the school. At the time of the site visit we didn't observe any students walkers or bicyclists. 60 vehicles entering the site were travelling westbound on Ernest Valerie Road while 4 vehicles were traveling eastbound.


Table 2 quantifies the parent and bus drop-off/pick-up totals for the school.

Туре	Pare	nt	Βι	IS
Time	Drop-Off	Pick-Up	Drop-Off	Pick-Up
8:15 - 8:30	1			
8:30 - 8:45	3		4	
8:45 - 9:00	48		7	
9:00 - 9:15	17		2	
9:15- 9:30				
1:45 – 2:00		2		
2:00 - 2:15				
2:15 - 2:30		1		
2:30 - 2:45		7		
2:45 - 3:00		20		4
3:00 – 3:15		23		9
3:15 - 3:30				
Total	69	53	13	13

#### Table 2 – Bournedale Pick-Up/Drop-Off Quantity


# 2.10 Bournedale Elementary School Parking Supply and Demand

Nitsch Engineering performed a parking supply and demand count on October 21, 2015. The utilization of the lot was taken at 10:00 AM. Figure 7 shows an overview of the Bournedale Elementary School parking lot, the total parking spaces, parking space type, and lot utilization.



**Figure 7: Bournedale Elementary School Site Circulation** Peebles Elementary School Bourne, Massachusetts





**Figure 8: Bournedale Elementary Parking Utilization** Peebles Elementary School Bourne, Massachusetts



As can be seen from Figure 7, a total of 137 parking spaces were counted within the Bournedale Elementary School, including six of which being accessible spaces. This meets the Architectural Access Board (AAB) Code of Massachusetts Regulations (521 CMR) for the required number of handicapped parking spaces. The accessible spaces were not utilized at the time of observation. The overall lot utilization was 58%.

# 3 SAFETY ANALYSIS

### 3.1 Crash Data

Nitsch Engineering reviewed the crash data available from MassDOT for the three most recent years available -2011 to 2013 – for the study intersections. A summary of the crashes, including the severity, and the manner of collision are shown in Table 3.

	Nu	mber of Cr	ashes		Seve	erity			Mar	nner of	Collision		Percent During	
Location	Year	Total Crashes	Average	PDª	PI⁵	NR°	Fª	Ae	RE <sup>f</sup>	HO <sup>a</sup>	Other <sup>h</sup>	Incl. Ped- Bike <sup>j</sup>	Peak Hours <sup>k</sup>	Wet/Icy Conditions
Scenic Highway	2011	5		4	1	0	0	1	2	0	2	0	40%	0%
(Route 6)	2012	12	8.3	12	0	0	0	0	5	0	7	1	25%	33%
at Nightingale Pond Road	2013	8		7	1	0	0	0	7	0	1	0	25%	13%
Scenic Highway	2011	1		1	0	0	0	0	1	0	0	0	0%	0%
(Route 6)	2012	1	1.3	1	0	0	0	1	0	0	0	0	0%	0%
at Edge Hill Road	2013	2		2	0	0	0	1	0	0	1	0	50%	50%
Total	ALL	29	4.8	27	2	0	0	3	15	0	11	1	28%	21%
<sup>a</sup> Property Dama direction; sidesw 9am or 4-6pm														

Table 3 - Crash Summary	Table	d - Cra	ash Sum	mary
-------------------------	-------	---------	---------	------

A total of twenty nine crashes were reported within the study areas for the two locations from 2011 to 2013. In terms of severity, twenty seven of the crashes involved property damage and two reported personal injury. In terms of manner of collision, three of the crashes were angle collisions, fifteen were rear-end, and eleven was of other type. One of the crashes involved a pedestrian/bicyclist. Approximately 28% of the crashes occurred during the peak hours of 7:00 to 9:00 AM or 4:00 to 6:00 PM and 21% occurred during wet/icy conditions. Analyzing the crash data, as most crashes were of angle or rear-end type, the crashes were most likely caused by driver carelessness or inattentiveness.

# 4 EXISTING TRAFFIC CONDITIONS

# 4.1 2015 Traffic Count Data

# Automatic Traffic Recorder (ATR) Data

Nitsch Engineering retained Precision Data Industries, LLC (PDI) of Berlin, Massachusetts to conduct 48hour Automatic Traffic Recorder (ATR) vehicle traffic counts throughout the study area, on Wednesday, September 9, 2015. Table 3 summarizes the ATR data. A copy of the raw traffic count data is included in Appendix A-1.

			ADT <sup>a</sup>		P	EAK HOUR T	RAFFIC		
LOCATION	PERIOD	VOLUMES (vpd) <sup>b</sup>	DIRECT DISTRI	TIONAL BUTION	PERIOD	VOLUMES (vph)°	DIRECT DISTRIE		K factor <sup>d</sup>
Ernest Valeri Road east of Bournedale Elementary School entrance	Weekday	841	50%	WB	Morning Evening	198 209	66% 50%	WB WB	0.24 0.25
Trowbridge Road east of Peebles Elementary School entrance	Weekday	6,730	57%	EB	Morning Evening	556 647	51% 61%	EB EB	0.08 0.10

# Table 4 - Automatic Traffic Recorder (ATR) Summary

<sup>a</sup> Average Daily Traffic; <sup>b</sup> Vehicles per day; <sup>c</sup> Vehicles per hour; <sup>d</sup> Percent of daily traffic

# Turning Movement Count (TMC) Data

PDI collected Turning Movement Counts (TMC) data at the following signalized intersections on Wednesday, November 18, 2015 from 7:30 AM to 9:30 AM and 1:30 PM to 3:30 PM to capture both the school morning and afternoon peak periods.

- Scenic Highway (Route 6) at Nightingale Pond Road
- Scenic Highway (Route 6) at Edge Hill Road

Nitsch Engineering conducted TMC data at the school access and egress points during the Site Visits. We collected weekday morning and afternoon data on October 21, 2015. Nitsch Engineering did not collect bicycle and pedestrian access and egress data at either of the elementary schools.


The peak hours within the study area were established as 7:35 AM to 8:35 AM during the weekday morning period and 2:30 PM to 3:30 PM during the afternoon period. The 2015 existing traffic volumes are shown in Figure 8.

# Vehicle Travel Speeds

PDI measured vehicle travel speeds at the ATR locations at the time of the traffic count. The 85th percentile speed, meaning the speed at which 85% of the vehicles are at or below, is noted because of its importance in determining appropriate roadway speed limits and for calculating required sight distance. The speed data is shown in Table 4.

INTERSECTION	POSTED SPEED (MPHª)	85th PERCENTILE SPEED (MPH <sup>a</sup> )
Ernest Valeri Road east of Bournedale Elementary School entrance		
Eastbound	Not Posted	28
Westbound	20	28
Trowbridge Road east of Peebles Elementary School entrance		
Eastbound	20	38
Westbound	20	38
a = Miles per hour Note: 85th Percentile Speeds were averaged between the full two days of da	ata collected	

# Table 5 - Vehicle Travel Speeds



# Figure 9: 2015 Existing Traffic Volumes Peebles Elementary School

Bourne, Massachusetts



# 4.2 Seasonal Adjustment

Nitsch Engineering researched data from MassDOT to establish if any seasonal adjustment to the traffic counts was necessary. We researched and used the MassDOT's 2007 Weekday Seasonal Adjustment Factors, which is the latest data set available. The data compares monthly traffic volumes from different types of roadways across the Commonwealth to compare the traffic volumes from each individual month to the annual average. During the month of October on Cape Cod Recreational roadways, traffic volumes are approximately 1% higher than an average month. Additionally, the counts were performed while school was in full session, so the traffic counts represent the average condition with respect to traffic within the study area. Therefore, we made no adjustment to the collected volumes. The Weekday Seasonal Adjustment Factors are included in Appendix A-2.


# 5 FUTURE NO-BUILD TRAFFIC CONDITIONS

# 5.1 Background Growth

Consistent with recent MassDOT projects in eastern Massachusetts, we used an annual background traffic growth factor of 0.5%.

# 5.2 No-Build Traffic Volumes

The 2020 No-Build Traffic Volumes are shown in Figure 8 and are derived by applying the traffic growth rate of 0.5% per year over the five-year design horizon to project the 2020 traffic counts.



# Figure 10: 2020 No-Build Traffic Volumes

Peebles Elementary School Bourne, Massachusetts



# 6 FUTURE CONDITIONS

The following four options are being reviewed as part of the study scope:

- Option 1 Construct a new or renovated Peebles Elementary School building and grounds on the existing site.
- Option 2 Renovate Bournedale School to consolidate Peebles Elementary School (K-4);
- Option 3 Renovate Bournedale School to consolidate Peebles Elementary School (K-4) as well as the 5<sup>th</sup> grade students; and
- Option 4 Construct a new or renovated Peebles Elementary School building and grounds on the existing site, and consolidate 5<sup>th</sup> grade.

The operational conditions for Options 1 will be the same as the existing conditions, this option will have no impact on the traffic network surrounding the school sites.

The operational conditions for Options 4 will also be the same as the existing conditions, except for the consolidated 5<sup>th</sup> grade, which will result in an increase in traffic volumes at the intersection of Trowbridge and the School Driveway during the morning drop-off and the afternoon pick-up periods. We analyzed the traffic operations at the intersection of Peebles School Driveway at Trowbridge Road for Existing and Build conditions. The analysis indicate that this option will have no impact on the traffic network surrounding the school sites. The analysis worksheets are provided in Appendix A-6.

To be conservative, we examined the proposed future conditions with respect to Option 3 (which is identical to Option 2 with the addition of the 5<sup>th</sup> grade).


# 6.1 **Proposed Trip Generation**

The increase in traffic volumes at Ernest Valeri Road due to the new site for the school during the weekday morning drop-off and weekday afternoon pick-up, are outlined in Table 6.

TRIP DIRECTION/TYPE	Weekday Morning Peak <sup>b</sup>	Weekday Evening Peak <sup>b</sup>
Entering	AM	РМ
Ernest Valeri Road	129	101
Exiting	AM	РМ
Ernest Valeri Road	129	101
Total Future	258	202
<sup>a</sup> Morning Peak Hour, 7:30 - 8:30 AM; <sup>b</sup> Aft	ternoon Peak Hour, 2:30-	3:30 PM

Table 6 - Existing and Proposed Trip Generation

As shown in Table 6, the proposed consolidated Peebles and Bournedale elementary schools with the 5<sup>th</sup> grade at Ernest Valeri Road site would result in approximately 258 additional entering and exiting trips during the weekday morning drop-off and approximately 202 additional entering and exiting trips during the weekday afternoon pick-up. The increase also accounts for vehicular traffic associated with teachers and staff at the new school.



# **Figure 11: Regional Trip Distribution** Peebles Elementary School Bourne, Massachusetts



# 6.2 Proposed Option 3 – Consolidated Peebles and Bournedale Elementary Schools

A sketch plan of the Consolidated Peebles and Bournedale Elementary Schools on the Bournedale School Site is shown in Appendix A-4. The sketch plan shows the proposed driveway locations of the school with the site location and outline.

# Site Layout

For the construction of the Consolidated Peebles and Bournedale Elementary Schools building and grounds on Bournedale School site, the new school addition building would be constructed east of the existing school.

# Parking

Parking would be provided onsite surrounding the proposed school building. In all, 271 parking spaces are proposed.

# Vehicle Access/Egress, Circulation, Bus and Parent Pick-Up/Drop-Off

Vehicle access and egress will continue to be provided by the existing three driveways.

- The main driveway will provide direct access to the school parking lots. School buses will also use this driveway. The bus pick-up/drop-off will occur at the designated bus loop located west of the school.
- The PK driveway will be reconstructed to provide a one-way counter-clockwise parent pick-up/dropoff loop around a new reconstructed parking to the east of the school building.
- The most northerly driveway will continue to remain a one-way egress to Ernest Valeri Road.

# Trip Distribution, Diversion, and Assignment


The trips to/from the Bournedale Elementary School Site will be distributed and assigned based on the exiting travel patterns and logical travel routes, which are based on the existing roadway network both within the Town of Bourne and the surrounding region.

In order to properly assess the effect of trips to the Bournedale Elementary School Site, drop-off and pickup trips at the existing Peebles Elementary School must be assigned to the Bournedale Elementary School Site. The Trip Distribution Percentages specific to the Bournedale Elementary School Site are shown in Figure 12.

The resultant trip assignment volumes for both the weekday morning and weekday afternoon peak hours were calculated by multiplying the trip distribution by the trip generation from Table 6, and are shown in Figure 13 for the weekday morning and the weekday afternoon peak hours.


# Proposed 2020 Build Volumes

For the Bournedale Elementary School Site, the corresponding trip assignment volumes were added to the 2020 No-Build Volumes to yield the 2020 Build Volumes. The 2020 Build Volumes for the Bournedale Elementary School Site are shown in Figure 14.



# Figure 12: Trip Distribution


Peebles Elementary School Bourne, Massachusetts



# Figure 13: Trip Assignment Peebles Elementary School

Bourne, Massachusetts





# Figure 14: 2020 Future Build Traffic Volumes

Peebles Elementary School Bourne, Massachusetts



# 7 OPERATIONS ANALYSIS

# 7.1 Level of Service Criteria

Level of Service (LOS) is a qualitative measure describing operational conditions within a traffic stream. Six LOS criteria are used to describe the quality of traffic flow for any type of facility controls. LOS A represents the best operating conditions and LOS-F represents the worst operating conditions. Nitsch Engineering analyzed the levels of service for the intersections using Synchro 8 software, which is based on the traffic operational analysis methodology of the Highway Capacity Manual<sup>1</sup> (HCM). The methodology for signalized intersections assesses the effects of signal type, timing, phasing, progression, vehicle mix, and geometrics on control delay. Control delay includes initial deceleration delay, queue move-up time, stopped delay, and final acceleration delay. Table 8 summarizes the relationship between LOS and average control delay for signalized and unsignalized intersections.

SIGNA	LIZED INTERSECTIONS	UNSIGNALIZED INTERSECTIONS						
Level of Service	Control Delay (seconds/vehicle)	Volume-to	Service by D-Capacity Ratio	Control Delay (seconds/vehic				
		v/c ≤ 1.0	v/c > 1.0					
А	0 to 10	А	F	0 to 10				
В	>10 to 20	В	F	>10 to 15				
С	>20 to 35	С	F	>15 to 25				
D	>35 to 55	D	F	>25 to 35				
E	>55 to 80	E	F	>35 to 50				
F	>80	F	F	>50				

 Table 7 - Level of Service Criteria

# 7.2 Capacity Analysis

Nitsch Engineering performed traffic analyses to evaluate traffic operations for the 2015 Existing Conditions, 2020 No-Build Conditions, and 2020 Build Conditions – Consolidated Peebles and Bournedale Elementary Schools on the Bournedale School site during the weekday morning and weekday afternoon peak hours at the study intersections. The analyses depict the volume-to-capacity (v/c) ratio, vehicle delay, LOS, and the 50th/95th percentile vehicle queues.

<sup>&</sup>lt;sup>1</sup> Highway Capacity Manual, 2010 Edition, Transportation Research Board (TRB), Washington, D.C.

#### 2015 Existing Capacity Analysis 7.3

Nitsch Engineering analyzed the 2015 Existing Conditions traffic operations at the study intersections based on the existing traffic counts performed by PDI and Nitsch Engineering in October 2015. The Level of Service Summary is shown in Table 8. The analysis worksheets are provided in Appendix A-6.

		WEE		RNING F	PEAK H	IOUR	WEEKDAY EVENING PEAK HOUR						
INTERSECTION	MOVEMENT	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	<mark>50th</mark> Q⁴	95th Q⁵	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	<mark>50th</mark> Q⁴	95th Q⁵		
	Scenic Hgwy EB - TL	0.79	24.3	С	254	336	0.83	27.1	С	233	320		
	Scenic Hgwy WB - TR	0.76	22.2	С	303	382	0.68	20.1	С	254	323		
Scenic Highway	Andy Olivia NB - LTR	0.01	38.0	D	1	6	0.02	38.7	D	2	10		
(Route 6) at Nightingale Road	Nightingale Rd SB-LT	0.08	39.61	D	7	25	0.06	39.3	D	5	22		
	Nightingale Rd SB-R	0.25	7.0	A	0	23	0.18	3.0	A	0	7		
	Overall	0.79	22.8	С			0.83	22.9	С				
	Scenic Hgwy EB - L	0.46	50.	D	51	95	0.45	50.0	D	49	92		
	Scenic Hgwy EB - T	0.29	2.7	А	54	84	0.27	2.8	А	52	81		
Scenic Highway	Scenic Hgwy WB - TR	0.49	9.3	А	187	292	0.45	9.3	А	166	261		
(Route 6) at Edge Hill Road	Edge Hill Rd SB-L	0.26	47.4	D	23	53	0.32	48.3	D	29	64		
	Edge Hill Rd SB-R	0.26	6.7	A	0	16	0.29	7.9	A	0	22		
	Overall	0.49	8.9	А			0.45	9.1	А				
<sup>1</sup> Volume to Capacity R feet) based upon 22 fee metered by upstream s	et per vehicle; * = De	facto Left L	ane; # = volur	ne exceed	s capacity	y, queue n							

#### 7.4 2020 No-Build Capacity Analysis

Nitsch Engineering analyzed the 2020 No-Build Conditions traffic operations at the study intersections. The 2020 No-Build Condition represents the 2015 Existing Conditions and projects a traffic increase at the rate of 0.5% per year between 2015 and 2020. The Level of Service Summary is shown in Table 9. The analysis worksheets are provided in Appendix A-6.

		WEE		RNING F	EAK H	IOUR	WEEKDAY EVENING PEAK HOUR					
INTERSECTION	MOVEMENT	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	50th Q⁴	95th Q⁵	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	<mark>50th</mark> Q⁴	95th Q⁵	
	Scenic Hgwy EB - TL	0.81	25.4	С	267	355	0.84	28.2	С	245	337	
	Scenic Hgwy WB - TR	0.77	22.5	С	315	397	0.68	20.1	С	264	335	
Scenic Highway	Andy Olivia NB - LTR	0.01	39.0	D	1	6	0.02	39.0	D	2	10	
(Route 6) at Nightingale Road	Nightingale Rd SB-LT	0.08	40.1	D	7	25	0.07	40.0	D	5	22	
	Nightingale Rd SB-R	0.26	7.2	A	0	24	0.19	3.4	А	0	8	
	Overall	0.81	23.5	С			0.84	23.4	С			
	Scenic Hgwy EB - L	0.47	50.2	D	52	96	0.46	50.0	D	51	95	
	Scenic Hgwy EB - T	0.29	2.7	А	56	87	0.28	2.8	А	54	85	
Scenic Highway	Scenic Hgwy WB - TR	0.50	9.5	A	196	304	0.46	9.3	А	175	275	
(Route 6) at Edge Hill Road	Edge Hill Rd SB-L	0.26	47.4	D	23	53	0.33	48.4	D	31	66	
	Edge Hill Rd SB-R	0.26	6.7	A	0	16	0.29	8.1	А	0	23	
	Overall	0.50	9.0	А			0.46	9.3	А			
<sup>1</sup> Volume to Capacity R feet) based upon 22 fee	et per vehicle; * = De	facto Left L	ane; # = volur	ne exceed	s capacit	y, queue n					ue (in	

#### Table 9 – Level of Service Summary - 2020 No-Build Conditions

metered by upstream signal; ~ = Volume exceeds capacity, queue is theoretically infinite

# 7.5 2020 Build Capacity Analysis

Nitsch Engineering analyzed the 2020 Build Conditions traffic operations at the study intersections for the consolidated Peebles and Bournedale Elementary Schools on the Bournedale School Site. The 2020 Build Conditions represents the 2020 No-Build Conditions traffic volumes with added Trip Assignment Volumes for the consolidated Peebles Elementary School on the Bournedale Elementary School Site. The Level of Service Summary is shown in Table 10. The analysis worksheets are provided in Appendix A-6.

		WEEK		NING F	EAK H	OUR	WEEKDAY EVENING PEAK HOUR					
INTERSECTION	MOVEMENT	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	50th Q⁴	95th Q⁵	V/C <sup>1</sup>	DELAY <sup>2</sup>	LOS <sup>3</sup>	Soth Q <sup>4</sup> Soth 304           304         303           2         6           0         116           54         214           31         0	95th Q⁵	
	Scenic Hgwy EB - TL	0.89	30.8	С	338	#497	0.93	373	D	304	#459	
	Scenic Hgwy WB - TR	0.80	23.4	С	372	468	0.72	20.8	С	303	382	
Scenic Highway (Route 6) at Nightingale Road	Andy Olivia NB - LTR	0.01	39.0	D	1	6	0.02	39.3	D	2	10	
	Nightingale Rd SB-LT	0.09	40.8	D	7	25	0.07	40.3	D	6	22	
	Nightingale Rd SB-R	0.27	7.4	А	0	24	0.19	3.5	А	0	8	
	Overall	0.89	26.4	С			0.93	27.9	С			
	Scenic Hgwy EB - L	0.71	51.8	D	134	#218	0.67	50.3	D	116	179	
	Scenic Hgwy EB - T	0.29	2.7	А	56	87	0.28	2.8	А	54	85	
Scenic Highway	Scenic Hgwy WB - TR	0.59	14.8	В	260	348	0.53	13.7	В	214	336	
(Route 6) at Edge Hill Road	Edge Hill Rd SB-L	0.26	47.4	D	23	53	0.33	48.4	D	31	66	
	Edge Hill Rd SB-R	0.26	6.7	А	0	16	0.29	8.1	А	0	23	
	Overall	0.71	14.2	В			0.67	9.3	В			

<sup>1</sup> Volume to Capacity Ratio; <sup>2</sup> Vehicle Delay, measured in seconds; <sup>3</sup> Level Of Service; <sup>4</sup> 50<sup>th</sup> Percentile Queue (in feet); <sup>5</sup> 95th Percentile Queue (in feet) based upon 22 feet per vehicle; \* = Defacto Left Lane; # = volume exceeds capacity, queue may be longer; m = 95th percentile queue is metered by upstream signal; ~ = Volume exceeds capacity, queue is theoretically infinite

# 7.6 Traffic Signal Warrant Methodology

To quantify if additional mitigation would be necessary at the consolidated Peebles and Bournedale Elementary Schools on the Bournedale School Site, based on the expanded student population, or at the access and egress points to the Bournedale Elementary School Site, we performed a Traffic Signal Warrant Analyses.

We performed the warrants based on the procedures outlined in the *Manual on Uniform Traffic Control Devices*<sup>2</sup> (MUTCD), 2009 edition. The MUTCD indicates nine separate conditions under which a traffic signal warrant can be met, and they are shown below.

- 1. Warrant 1: Eight-Hour Vehicular Volume;
- 2. Warrant 2: Four-Hour Vehicular Volume;
- 3. Warrant 3: Peak Hour;
- 4. Warrant 4: Pedestrian Volume;
- 5. Warrant 5: School Crossing;
- 6. Warrant 6: Coordinated Signal System;
- 7. Warrant 7: Crash Experience;
- 8. Warrant 8: Roadway Network; and
- 9. Warrant 9: Intersection Near A Grade Crossing.

# 7.7 Traffic Signal Warrant

We performed the Signal Warrant Analysis for Ernest Valeri Road at the Bournedale Elementary School Driveway.

Given the criteria set forth in the MUTCD and the assumptions above, no traffic signal warrant was met for this location. The Traffic Signal Warrant Analysis is included in Appendix A-5.

<sup>&</sup>lt;sup>2</sup> Manual on Uniform Traffic Control Devices for Streets and Highways, 2009 Edition, Federal Highway Administration

### 7.8 Travel Time Study

To quantify the additional time expected for students to travel to the consolidated Peebles and Bournedale Elementary Schools on the Bournedale School Site, we conducted a travel study using the Test Car Technique. The distance between the Existing Peebles Elementary School and Bournedale Elementary School was driven 10 times to record the average travel time.

Test Run (4.8 Miles)	Travel Time (Min)	Average Travel Speed (MPH)
1	11.5	50
2	12	48
3	11.5	49
4	11.5	50
5	13	48
6	12	46
7	12.25	45
8	13	47
9	11	50
10	11.75	49

# Table 11 – Results of Travel Time Study

Based on the test runs average it will take approximately 12 minutes to travel from existing Peebles Elementary School, located 70 Trowbridge Road to Bournedale Elementary School at 41 Ernest Valerie Road.

### 8 CONCLUSIONS AND RECOMMENDATIONS

### 8.1 Conclusions

Nitsch Engineering has been retained by Flansburgh Architects (FA) to prepare a qualitative assessment of safety, traffic circulation, and traffic access/egress, associated with the feasibility study and schematic design for the Peebles Elementary School project in Bourne, Massachusetts. Four options are considered for the reconstruction.

- Option I. Build new or renovate the existing Peebles Elementary School building and grounds on the site of the existing school, located 70 Trowbridge Road in Bourne, Massachusetts.
- Option II. Renovate and expand existing Bournedale Elementary School, located at 41 Ernest Valerie Road, approximately 2 miles northeast of the existing school site to include the relocated Peebles Elementary School.

Option III. This would be Option 2 with the consolidating the 5<sup>th</sup> Grade presently at the Middle School; and Option IV. This would be Option 1 with the consolidating the 5<sup>th</sup> Grade presently at the Middle School

The operational conditions for Options 1 will be the same as the existing conditions, this option will have no impact on the traffic network surrounding the school sites.

The operational conditions for Options 4 will also be the same as the existing conditions, except for the consolidated 5<sup>th</sup> grade, which will result in an increase in traffic volumes at the intersection of Trowbridge and the School Driveway during the morning drop-off and the afternoon pick-up periods. We analyzed the traffic operations at the intersection of Peebles School Driveway at Trowbridge Road for Existing and Build conditions. The analysis indicate that this option will have no impact on the traffic network surrounding the school sites. The analysis worksheets are provided in Appendix A-6.

We examined the future conditions, as well as site circulation with respect to the projected student drop-off and pick-up for Option -3, since it presents the worst case scenario. This would result in an increase in traffic volumes within the study area during the weekday morning drop-off and weekday afternoon pick-up, totaling approximately 258 additional trips (entering and exiting) during the weekday morning drop-off, and approximately 202 additional trips (entering and exiting) during the weekday afternoon pick-up. The parking lot will contain 271 spaces, and the curb at the car loop can accommodate approximately 25 vehicles.

We anticipate that the following summarizes the vehicular circulation at the New Bournedale Elementary School site during morning drop-off and afternoon pick-up periods:

- During the morning drop-off, the parents (approximately 177 vehicles) will arrive at the new driveway exclusively for pick-up and drop-off between 8:30 and 9:30 AM. They will drop-off their children at the new car loop and exit the school via the main driveway. Our analysis indicate that during the morning drop-off, the 95th Percentile Queue length on the School driveway for the right turns to Ernest Valeri Road will be 12 feet (approximately one vehicle).
- During the afternoon pick-up, the parents (approximately 113) will start arriving between 2:30 and 3:30 PM. The new pick-up and drop-off loop can accommodate approximately 25 vehicles to park along the car loop curb line without spilling out of the car loop and blocking the driveway. Additional spaces are available at the new parking lot, which can accommodate 127 vehicles. Once the parents have picked up their children, they will proceed to exit the parking lot and the school via the main driveway. 95th Percentile Queue length on the School driveway for the right turns to Ernest Valeri Road will be 12 feet (approximately one vehicle).

The existing roadway network at Scenic Highway (Route 6) contains moderate traffic volumes and some delays during the weekday morning peak hours, as the Bournedale Elementary School drop-off traffic overlaps slightly with the peak hour of the commuter traffic, relocating the Peebles Elementary School to the Bournedale Elementary School site location may add minor impacts to the off-site intersections. However, our analysis show the impacts very minor, and may not require mitigation.

### 8.2 Recommendations

Based on the proposed Combined Peebles and Bournedale Elementary Schools at Bournedale Elementary School Site, Nitsch Engineering offers the following recommendations:

- Continue the designation of the area as a School Zone under State and local statute, and install new appropriate School Zone signs equipped with flashing lights at Ernest Valeri Road, which can also act as traffic calming devices.
- Reach out to parents via social media to increase safety awareness.



### 3.1.4 Evaluation of Existing Conditions

#### J. PHASE I ENVIRONMENTAL SITE ASSESSMENT

Fuss & O'Neil Inc. conducted the Phase I Environmental Site Assessment associated with the Peebles and Bournedale Elementary School sites in Bourne.

*Purpose*: To identify recognized environmental conditions (RECs) present at the site with a focus on hazardous substances and/or petroleum products.

*Tasks Performed*: The following areas of focus were evaluated and reviewed as part of this study: Site history in regards to previous use and development, various area maps, town records from various departments, interviews and site walkthroughs with school facilities department, owner's site questionnaire, and general hydrological information

#### FINDINGS (PEEBLES):

- There is a 10,000-gallon fuel underground storage tank (UST) serving the back-up boiler
- There were documents related to an oil spill in 1995 in connection with the underground tank system. Additional documents, which were requested from the Fire Department, but have not been delivered, may complete the review on this item.
- A spill of 17 gallons of diesel fuel occurred when refueling a bus on site and a solution was achieved
- The nearby Camp Edwards is on the USEPANational Priorities list identifying groundwater contamination. The impact area was studied on the maps and none of the impact area plumes migrated toward the site.
- Nearby businesses, i.e. gas stations, did have incidents and solutions were achieved

#### CONCLUSION:

- 1. There is one identified recognized environmental condition (REC) associated with the subject site. The REC is the currently unresolved history of spills associated with the UST system. This REC item may be re-designated as a "historical REC" (i.e. a closed case addressed to the satisfaction of state environmental standards) in this evaluation at a later date pending review of Fire Dept. documentation.
- 2. There are no offsite concerns based on records addressing nearby businesses, i.e. gas stations, Camp Edwards distance from the site, and local hydrological conditions. These conditions should not have a negative impact on the site.


FINDINGS (BOURNEDALE):

- The 2009 Bournedale Elementary School project was greenfield construction
- There are no target sites nearby that would negatively impact the school site
- The eastern portion of the site is located within and adjacent to a medium-yield aquifer. The aquifer map is along the property line and outside proposed project limits.

#### CONCLUSION:

- 1. There are no identified recognized environmental conditions (REC) associated with the subject site.
- 2. There are no offsite concerns based on distance from the site and local hydrological conditions that would have a negative impact on the site.

The full Phase I ESA report follows.



### 3.1.4 Evaluation of Existing Conditions

#### K. HAZARDOUS MATERIAL ASSESSMENT

Fuss & O'Neill EnviroScience, LLC. conducted a Limited Hazardous Building Materials Inspection at the Peebles Elementary School located at 70 Trowbridge Road in Bourne, Massachusetts (the "Site").

PURPOSE: To perform a lead-based paint (LBP) screening, an inventory of fluorescent light ballasts and mercury-containing equipment, a quantification of presumed polychlorinated biphenyl (PCB)–containing source building materials, and a limited asbestos inspection as part of a feasibility study that anticipates demolishing the Site building.

TASKS PERFORMED: The following areas of focus were evaluated and reviewed as part of this inspection: Review of previously performed Limited Hazardous Building Material Inspection Reports, LBP Screening, Inventory of Fluorescent Light Ballasts and Mercury-Containing Equipment, Quantification of Presumed PCB-Containing Source Building Materials, Asbestos Inspection (mostly visual). Destructive investigative techniques were conducted at the Site building to access materials associated with the brick veneer and ceramic tiles only.

#### FINDINGS - PEEBLES SCHOOL:

- LBP was found associated with Window Supports and Ceramic Wall Tiles.
- Several materials are presumed to contain PCBs including: Window Caulking and Glazing Compound.
- Fluorescent Light Ballasts and Mercury-Containing Equipment were quantified in a previous report.
- Multiple samples were determined to be asbestos-containing materials (ACM) including: Caulking, Glazing Compound, Dampproofing, Plaster Skim Coat, Insulations, Floor Tiles, Boiler Components, Duct Vibration Isolators, Cement Panels, and Soil.

#### CONCLUSION:

If disturbed by demolition activities, LBP-coated building components should be segregated from the general demolition waste stream, and be analyzed to determine proper off-site disposal.

Identified PCB-containing materials should be presumed to contain regulated concentrations of PCBs until analysis indicates otherwise. These materials should be removed and disposed at an EPA-approved facility.

DEHP-containing fluorescent light ballasts must be segregated for proper packaging, transporting and disposal. While mercury-containing equipment and fluorescent lamps must be recycled, reclaimed, or disposed as hazardous waste prior to disturbance.

Prior to disturbance ACM that would likely be impacted by the proposed demolition activities must first be abated by a Commonwealth of Massachusetts Department of Labor Standards (MADLS)-licensed Asbestos Abatement Contractor. This is a requirement of MADLS, Commonwealth of Massachusetts Department of Environmental Protection (MassDEP), and the United States Environmental Protection Agency (EPA) National Emission Standards for Hazardous Air Pollutants (NESHAP) regulations governing asbestos abatement.

Due to the date of construction, the Bournedale Elementary School possesses a letter from the architect (Kaestle Boos Associates, Inc.) dated August 11, 2011 stating that "no asbestos-containing building materials were specified for use in, nor to the best of our knowledge installed in, the construction of the Bournedale Elementary School." This letter satisfies the EPA Asbestos Hazard Emergency Response Act (AHERA) regulations governing asbestos in schools; however, prior to renovation or demolition, EPA NESHAP regulations still apply. This regulation requires a thorough asbestos inspection of all areas that will be impacted during renovation or demolition. Once a scope of work is defined, a supplemental inspection should be performed to ensure NESHAP requirements are met.

The full Hazardous Material Assessment report follows.

## Limited Hazardous Building Materials Inspection Report

James F. Peebles Elementary School & Bournedale Elementary School Bourne, Massachusetts

# Flansburgh Architects

Boston, Massachusetts

December 2015



Fuss & O'Neill EnviroScience, LLC 50 Redfield Street, Suite 100 Boston, Massachusetts 02122



December 4, 2015

Mr. Kent Kovacs Vice President Flansburgh Architects 77 North Washington Street Boston, MA 02114

### RE: Limited Hazardous Building Materials Inspection James F. Peebles Elementary School Feasibility Study Bourne, Massachusetts Fuss & O'Neill EnviroScience No. 20150666.A1E

Dear Mr. Kovacs:

Enclosed is the limited hazardous building materials inspection summary report for the inspection conducted at the James F. Peebles Elementary School located at 70 Trowbridge Road in Bourne, Massachusetts and Bournedale Elementary School located at 41 Ernest Valeri Road in Bourne Massachusetts.

On October 26 and 28, 2015, Fuss & O'Neill EnviroScience, LLC state-certified Asbestos Inspectors performed a limited asbestos inspection, a lead-based paint screening, an inventory of fluorescent light ballasts and mercury-containing equipment, and a quantification of presumed polychlorinated biphenyl (PCB)-containing source building materials as part of a feasibility study that includes demolishing the James F. Peebles Elementary School. The inspection also included reviewing documents associated with the construction of the Bournedale Elementary School.

The information summarized in this report is solely for the abovementioned materials. The work was performed in accordance with our written revised scope of services dated September 25, 2015.

If you should have any questions regarding the contents of this report, please do not hesitate to contact me at 617-282-4375, extension 4703. Thank you for this opportunity to have served your environmental needs.

Sincerely,

Dustin A. Diedricksen Project Manager

DD/amf

Enclosure



## Table of Contents

Limited Hazardous Building Materials Inspection Report James F. Peebles Elementary School Feasibility Study Flansburgh Architects

1	Introd	uction	3
	1.1	Scope of Work	
	1.2	Building Description	
2		tos Inspection	
	2.1	Methodology	
	2.2	Results	
	2.3	Conclusions and Recommendations	7
3	Lead-	Based Paint Screening	7
	3.1	Methodology	8
	3.2	XRF Screening Results	8
	3.3	Discussion	8
	3.4	Conclusions and Recommendations	9
4	Presu	med Polychlorinated Biphenyls (PCBs) Source Building Ma	terials10
	4.1	Background	
	4.2	Results	
	4.3	Conclusions and Recommendations	
5	Fluore	escent Light Ballasts and Mercury-Containing Equipment	11
	5.1	Fluorescent Light Ballasts	11
	5.2	Mercury-Containing Equipment	11
	5.3	Results	11
	5.4	Conclusions and Recommendations	
Tables	i		End of Report
1.		nmary of Suspect Asbestos-Containing Materials Laboratory Analytical I	Data
2.		nmary of Asbestos-Containing Materials Inventory	
3.	Sur	nmary of Suspect PCB-Containing Source Building Materials	
Apper	ndices		End of Report
APPEN	IDIX A	LIMITATIONS	

APPENDIX A	LIMITATIONS
APPENDIX B	ENVIROSCIENCE ASBESTOS INSPECTOR STATE CERTIFICATIONS AND
	EPA ACCREDITATIONS
APPENDIX C	ASBESTOS LABORATORY ANALYTICAL REPORTS AND CHAIN-OF-
	CUSTODY FORMS
APPENDIX D	XRF LEAD-BASED PAINT SCREENING FIELD DATA SHEETS



# 1 Introduction

On October 26 and 28, 2015, Fuss & O'Neill EnviroScience, LLC (EnviroScience) representatives, Mr. Robert Mallett and Mr. Michael Coffey, performed a limited hazardous building materials inspection as part of a feasibility study to demolish the James F. Peebles Elementary School located at 70 Trowbridge Road in Bourne, Massachusetts (the "Site").

Limited hazardous building materials inspections were previously conducted at the Site; pertinent information from these reports was utilized during this inspection. These reports included six "Limited Hazardous Building Materials Inspection" reports, prepared by EnviroScience, dated as follows:

- December 2014;
- October 2014;
- July 2013;
- December 2012;
- April 2010; and
- August 2009.

The inspection also included reviewing AHERA documents associated with the construction of the Bournedale Elementary School.

### 1.1 Scope of Work

The work was performed for Flansburgh Architects (the "Client") in accordance with our revised written scope of services dated September 25, 2015. This report is subject to the limitations presented in *Appendix A*. The scope of work included the following:

- Limited Asbestos-Containing Materials (ACM) Inspection;
- Lead-Based Paint (LBP) Screening;
- Inventory of Fluorescent Light Ballasts and Mercury-Containing Equipment; and
- Quantification of presumed polychlorinated biphenyl (PCB)-containing source building materials.

Intrusive or destructive investigative techniques were conducted at the Site to access materials associated with the brick veneer and ceramic tiles only. These techniques were not performed at the Site to access and observe other hidden or concealed areas that may contain suspect ACM that were hidden or obstructed from normal view. Hard enclosures or obstructed areas typically include, but are not limited to, the following:

- Wall Cavities;
- Pipe Chases;
- Spaces above Fixed Ceilings;
- Beneath Window/Door Frames;
- Underneath Wooden or Raised Flooring;
- Behind Mirrors, Blackboards, and Signage;
- Areas behind and within Mechanical Equipment (Including Freezers and Refrigeration Units); and
- Vapor/Moisture Barrier under Floors or on Concrete Foundations.



EnviroScience did not conduct subsurface investigations to identify concealed suspect materials throughout the subject property.

We excluded collection and analysis of suspect materials for polychlorinated biphenyls (PCB) during this inspection. Sampling for PCBs is presently not mandated by the United States Environmental Protection Agency (EPA); however, significant liability risk for disposing PCB-containing wastes exists. Recent knowledge of PCBs within these matrices has become more prevalent, especially with remediation contractors, waste haulers, and disposal facilities. Many property owners have become subject to large changes in schedule, scope, and costs as a result of failure to identify this possible contaminant prior to renovation or demolition activities. Suspect materials recommended by the EPA for testing have instead been presumed to contain regulated concentrations of PCBs.

### 1.2 Building Description

The Site building is composed of two, two-story sections constructed of concrete masonry units with a brick façade; these are referenced as the "original building" and the "Annex" [building]. The original building was reportedly constructed in the late 1950s with the Annex reportedly being constructed in the early 1960s. The Site building contains approximately 60,000 square feet of interior floor space.

## 2 Asbestos Inspection

A property owner must ensure that a thorough asbestos inspection is performed prior to possible disturbance of suspect ACM during renovation or demolition activities. This is a requirement of the EPA National Emission Standards for Hazardous Air Pollutants (NESHAP) regulation located at Title 40 CFR, Part 61, Subpart M.

On October 26 and 28, 2015, Mr. Mallett and Mr. Coffey of EnviroScience conducted the inspection. Mr. Mallett and Mr. Coffey are both Commonwealth of Massachusetts Department of Labor Standards (MADLS)-certified Asbestos Inspectors. Refer to *Appendix B* for copies of each Asbestos Inspector state certification and EPA accreditation.

## 2.1 Methodology

The inspection was conducted by visually inspecting for suspect ACM and touching each of the suspect materials. The suspect materials were categorized into three EPA NESHAP groups: friable and non-friable Category I and Category II type ACM.

- A Friable Material is defined as material that contains greater than one percent (> 1%) asbestos that, when dry, **can** be crumbled, pulverized, or reduced to powder by hand pressure.
- A Category I Non-Friable Material refers to material that contains > 1% asbestos (i.e., packings, gaskets, resilient floor coverings, and asphalt roofing products) that when dry **cannot** be crumbled, pulverized, or reduced to powder by hand pressure.
- A Category II Non-Friable Material refers to any non-friable material excluding Category I materials that contain > 1% asbestos that when dry **cannot** be crumbled, pulverized, or reduced to powder by hand pressure.



The suspect ACM were also categorized into their applications including, Thermal System Insulation (TSI), Surfacing ACM, and Miscellaneous ACM. TSI includes those materials used to prevent heat loss/gain or water condensation on mechanical systems. Examples of TSI are pipe insulation, boiler insulation, duct insulation, and mudded pipe fitting insulations. Surfacing ACM includes those ACM that are applied by spray, trowel, or otherwise applied to an existing surface. Surfacing ACM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include those ACM not listed as thermal or surfacing, such as sheet flooring, floor tiles, ceiling tiles, caulking, mastics, construction adhesives, etc.

The EPA recommends collecting suspect ACM samples in a manner sufficient to determine asbestos content and to segregate each suspect type of homogenous (similar in color, texture, and date of application) materials. The EPA NESHAP regulation does not specifically identify a minimum number of samples to be collected for each homogeneous material, but the NESHAP regulation does recommend the use of sampling protocols included in EPA Title 40 CFR, Part 763, Subpart E: Asbestos Hazard Emergency Response Act (AHERA).

The EPA AHERA regulation requires a specific number of samples be collected based on the type of material and quantity present. This regulation includes the following protocol:

- 1. Surfacing Materials (i.e., plaster, spray-applied fireproofing, etc.) must be collected in a randomly distributed manner representing each homogenous area based on the overall quantity represented by the sampling as follows:
  - a. Three samples collected from each homogenous area that is less than or equal to 1,000 square feet.
  - b. Five samples collected from each homogenous area that is greater than 1,000 square feet but less than or equal to 5,000 square feet.
  - c. Seven samples collected from each homogenous area that is greater than 5,000 square feet.
- 2. Thermal System Insulation (i.e., pipe insulations, tank insulations, etc.) must be collected in a randomly distributed manner representing each homogenous area. Three samples must be collected from each material. Also, a minimum of one sample of any patching materials applied to TSI, presuming the patched area is less than six linear or square feet, should be collected.
- 3. Miscellaneous materials (i.e., floor tile, gaskets, construction mastics, etc.) should have a minimum of two samples collected for each type of homogenous material. Sample collection was conducted in a manner sufficient to determine asbestos content of the homogenous material as determined by the inspector.

The inspectors collected samples of suspect ACM and prepared proper chain-of-custody forms for transmission of collected samples to EMSL Analytical, Inc. (EMSL) for analysis. EMSL is a Commonwealth of Massachusetts-licensed and American Industrial Hygiene Association (AIHA)-accredited Asbestos Analytical Laboratory. Initial asbestos sample analysis was conducted using the EPA Interim Method for the Determination of Asbestos in Bulk Building Materials (EPA/600/R-93/116) via Polarized Light Microscopy with Dispersion Staining (PLM/DS).

The EPA recommends that non-friable, organically-bound (NOB) materials (e.g., asphaltic-based materials, adhesives, caulking, etc.) undergo further confirmatory analysis utilizing Transmission Electron Microscopy (TEM). Fourteen (14) of the collected NOB samples were analyzed by TEM.



If samples of suspect ACM could not be collected or were inaccessible but observed elsewhere, these materials were assumed to contain asbestos and the inspector approximated quantities.

### 2.2 Results

The EPA, the Occupational Safety and Health Administration (OSHA), and the MADLS, define a material that contains > 1% asbestos utilizing PLM/DS, as an ACM. The Massachusetts Department of Environmental Protection (MassDEP) further defines ACM as materials containing greater than or equal to ( $\geq$ ) 1% asbestos. MassDEP also defines an asbestos-containing waste material (ACWM) as:

- ACM removed during renovation or demolition activities;
- Materials contaminated by an ACM during renovation or demolition activities; or
- ACM on and/or in facility components that are inoperable or have been taken out of service.

The MassDEP further defines waste material containing any amount of asbestos as an ACWM which must be managed and disposed as asbestos waste. Materials that are identified as "none detected" are specified as not containing asbestos.

Utilizing the EPA, OSHA, MADLS, and MassDEP protocol and criteria, the following materials were determined to be either **ACM**, or **ACWM**:

- Louver Caulking;
- Door Caulking;
- Window Caulking;
- Window Glazing Compound;
- Damproofing;
- Ceiling Plaster Skim Coat;
- Boiler Components;
- Duct Vibration Isolators;
- Pipe Insulation;
- Mudded-Pipe Fitting Insulation;
- 9" x 9" Floor Tile;
- Fiber-Reinforced Cement Panels;
- Sub-Slab Damproofing Materials; and
- Contaminated Soil.

Refer to **Table 1** attached hereto for the complete list of ACM, ACWM, and non-ACM identified by sample identification, material type, sample location, and asbestos content as part of this inspection. Refer to **Table 2**, attached hereto, for the identified ACM inventory.

Refer to Appendix C for the asbestos laboratory analytical reports and chain-of-custody forms.



### 2.3 Conclusions and Recommendations

Based on visual observations, sample collection, and laboratory analysis, ACM/ACWM were identified at the James F. Peebles Elementary School. It should be noted that pieces of corrugated, paper-type and pre-formed, block-type pipe insulations were observed mixed into the soil in the pipe tunnels of both the original and the Annex buildings.

Due to the date of construction, the Bournedale Elementary School possesses a letter from the architect (Kaestle Boos Associates, Inc.) dated August 11, 2011 stating that "no asbestos-containing building materials were specified for use in, nor to the best of our knowledge installed in, the construction of the Bournedale Elementary School." This letter satisfies the EPA AHERA regulations governing asbestos in schools; however, prior to renovation or demolition, EPA NESHAP regulations still apply. This regulation requires a thorough asbestos inspection of all areas that will be impacted during renovation or demolition. Once a scope of work is defined, a supplemental inspection should be performed to ensure NESHAP requirements are met.

Prior to disturbance, ACM/ACWM that would likely be impacted by the proposed renovation/demolition activities must first be abated by a MADLS-licensed Asbestos Abatement Contractor. This is a requirement of MADLS, MassDEP, and EPA NESHAP regulations governing asbestos abatement.

Due to the inability to effectively separate some types of multi-layered ACM (e.g., floor tile/mastic, gypsum board/joint compound, mastic/plywood, etc.) from non-ACM, these materials are considered asbestos-contaminated and must be managed as ACWM for removal and disposal purposes.

Prior to renovation/demolition that may disturb hidden/inaccessible areas, we recommend conducting a supplemental asbestos inspection of these areas and spaces. These spaces include below grade foundation walls, gymnasium floor, and beneath the concrete slab.

If suspect materials should be encountered during renovation/demolition activities that are not identified in this report as being non-ACM, they should be assumed to be ACM until sample collection and laboratory analysis indicate otherwise.

<u>This report is not intended to be utilized as a bidding document or as a project specification document</u>. The report is designed to aid the building owner, architect, construction manager, general contractors, and asbestos abatement contractors in locating ACM and ACWM.

## 3 Lead-Based Paint Screening

On October 26 and 28, 2015, Mr. Mallett and Mr. Coffey of EnviroScience performed a LBP screening associated with painted building components at the Site that may be disturbed during renovation/demolition activities. An X-ray fluorescence (XRF) spectrum analyzer was used to perform the LBP screening. The screening was conducted in accordance with generally-accepted industry standards for non-residential (i.e., not child-occupied) buildings.



## 3.1 Methodology

A Radiation Monitoring Device Model LPA-1 (Serial Number 1395) was utilized for the LBP screening. The instrument was calibrated according to the manufacturer's Performance Characteristic Sheet (PCS) prior to each use.

For the purpose of this LBP screening, representative, coated building components were tested for LBP. Individual repainting efforts are not always discoverable in such a limited program. LBP issues involving properties that are not residential are only regulated to a limited degree for worker protection relating to LBPdisturbing work activities and waste disposal.

Worker protection is regulated by OSHA regulations, as well as MADLS regulations. These regulations include air monitoring of workers to determine exposure levels when disturbing lead-containing paint. A LBP screening cannot determine a safe level of lead, but is intended to provide guidance for implementing industry standards for lead in paint at identified locations. Contractors may better determine worker exposure to airborne lead by understanding the different concentrations of LBP on representative components and surfaces. Air monitoring can then be performed during activities that disturb paint on representative surfaces.

The EPA Resource Conservation and Recovery Act (RCRA) and MassDEP regulate lead-containing waste disposal. If lead is determined to be present, representative composite samples of the anticipated waste stream must be collected and analyzed using the Toxicity Characteristic Leaching Procedure (TCLP). The results are compared to a threshold value of 5.0 milligrams per liter (mg/L). If TCLP sample analytical results exceed this value, the waste is characterized as hazardous lead waste. If the result is below the threshold value, the waste material is not considered hazardous and may be disposed as construction and demolition debris.

A level of paint exceeding 1.0 milligram of lead per square centimeter (mg/cm<sup>2</sup>) of surface area is considered toxic or dangerous by EPA and the Massachusetts Department of Public Health (MADPH) child-occupied residential standards. For the purpose of this screening, the level of 1.0 mg/cm<sup>2</sup> has been utilized as a guide to segregate coated building materials from general demolition debris for disposal purposes.

### 3.2 XRF Screening Results

The LBP screening indicated consistent painting trends associated with representative building components that may be impacted by potential renovation/demolition work. Window supports and ceramic wall tiles were determined to contain levels of lead  $\geq 1.0 \text{ mg/cm}^2$ .

Refer to Appendix D for the XRF lead-based paint screening field data sheets.

### 3.3 Discussion

OSHA published a Lead in Construction Standard (OSHA Lead Standard) Title 29 CFR, Part 1926.62 in May of 1993. This Standard sets no limit for the content of lead in paint below which the OSHA standards do not apply. The OSHA Lead Standards are task-based and are also based on airborne exposures and blood lead levels.



The results of this LBP screening are intended to provide guidance to contractors for occupational lead exposure controls. Building components coated with lead levels above industry standards may cause exposures to lead above OSHA standards during proposed demolition/renovation activities. The results of this screening are also intended to provide insight into waste disposal requirements, in accordance with EPA RCRA regulations. At the Client's request, a TCLP sample to characterize the expected waste that may result from possible selective demolition/renovation activities was not collected as part of this inspection.

### 3.4 Conclusions and Recommendations

Based on our LBP screening results, LBP was identified on coated building components located at the Site.

Contractors must be made aware that OSHA has not established a level of lead in a material below which OSHA Title 29 CFR, Part 1926.62 does not apply. Contractors shall comply with exposure assessment criteria, interim worker protection, and other requirements of the regulation as necessary to protect workers during any renovation and/or demolition work that will impact LBP.

If disturbed by renovation/demolition activities, LBP-coated building components should be segregated from the general demolition waste stream for sample collection and analysis by TCLP to determine proper off-site waste disposal. If disturbed and managed off-site, non-porous LBP-coated building materials (i.e., metals) may be segregated and recycled as scrap metal. Metal LBP-coated building components cannot be subject to grinding, sawing, drilling, sanding, or torch cutting.

The building is presently characterized as a commercial property, which is not subject to the MADPH Childhood Lead Poisoning Prevention Program (CLPPP) Regulation 105 CMR, Part 460.000. The Site may be renovated using procedures required in accordance with OSHA Title 29 CFR, Part 1926.62 and MADLS Regulation 454 CMR, Part 22.11. In addition, the building is not considered a "child-occupied facility" and therefore, is not subject to MADPH CLPPP regulations.

Note that the information contained in this report concerning the presence or absence of lead in paint, does not constitute a comprehensive lead inspection in accordance with MADPH CLPPP regulations. The screened painted surfaces represent only a portion of those surfaces that would be screened to determine whether the premises are in compliance with the aforementioned regulations, which are specific to a child-occupied residence only, and not applicable to buildings of this type and current use.



## 4 Presumed Polychlorinated Biphenyls (PCBs) Source Building Materials

## 4.1 Background

On October 26 and 28, 2015, Mr. Mallett and Mr. Coffey of EnviroScience completed an inventory of presumed PCB-containing source building materials.

Sample collection and analysis of building materials for PCBs is presently not mandated by the EPA. However, significant liability risk exists for improperly disposing of PCB-containing waste materials. Recent knowledge and awareness of PCBs within matrices such as caulking, glazing compounds, paints, adhesives and ceiling tiles has become more prevalent, especially among remediation contractors, waste haulers, and disposal facilities. The EPA recommends sample collection and analysis of caulking and glazing compounds installed between 1950 and 1980 to determine PCB concentration.

The EPA requirements apply and require removal of PCBs once identified, regardless of project intent as an unauthorized use of PCBs. Once it is determined that PCBs are present and a building is to remain for re-use, the EPA still requires PCB-containing material removal. If PCBs are present at certain concentrations, additional sampling and analysis of adjacent surfaces in contact with PCB sources, or which may have been contaminated from a source of PCBs (e.g., masonry, soil), must also be performed or remediated.

EPA requirements apply only if PCBs are present in concentrations above a specified level. Presently, PCBcontaining materials at concentrations equal to or greater than ( $\geq$ ) 50 part per million (ppm), or equivalent units of milligrams per kilogram (mg/kg), are regulated. Note materials containing  $\geq$  1 ppm but less than (<) 50 ppm may also be regulated unless proven to be an "Excluded PCB Product". The definition of an Excluded PCB Product includes those products, or source of the products, containing < 50 ppm concentration PCBs that were legally manufactured, processed, distributed in commerce, or used before October 1, 1984.

### 4.2 Results

Utilizing the EPA guidelines, an inventory of presumed PCB-containing source building materials by material type, location, and quantity is included in **Table 3** attached hereto.

## 4.3 Conclusions and Recommendations

Identified materials should be presumed to contain regulated concentrations ( $\geq$  50 ppm) of PCBs until sample collection and analysis indicate otherwise. These materials should be removed and disposed at an EPA-approved facility as regulated PCB Bulk Product Waste.



# 5 Fluorescent Light Ballasts and Mercury-Containing Equipment

## 5.1 Fluorescent Light Ballasts

Fluorescent light ballasts manufactured prior to 1979 may contain capacitors that contain PCBs. Light ballasts installed as late as 1985 may contain PCB capacitors. Fluorescent light ballasts that are not labeled as "No PCBs" must be assumed to contain PCBs unless proven otherwise by quantitative analysis. Capacitors in fluorescent light ballasts labeled as non-PCB-containing may contain diethylhexl phthalate (DEHP). DEHP was the primary substitute to replace PCBs for small capacitors in fluorescent lighting ballasts in use until 1991. DEHP is a toxic substance, a suspected carcinogen, and is listed under RCRA and the Superfund Law as a hazardous waste. Therefore, Superfund liability exists for landfilling both PCB- and DEHP-containing light ballasts. These listed materials are considered hazardous waste under RCRA and require special handling and disposal considerations.

## 5.2 Mercury-Containing Equipment

Fluorescent lamps/tubes are presumed to contain mercury vapor, which is a hazardous substance to both human health and the environment. Thermostatic controls and electrical switch gear may contain a vial or bulb of liquid mercury associated with the control. Mercury-containing equipment is regulated for proper disposal by EPA RCRA regulations.

### 5.3 Results

On October 26 and 28, 2015, Mr. Mallett and Mr. Coffey of EnviroScience performed a visual inspection of representative fluorescent light fixtures in-place to identify possible PCB-containing ballasts in the building. The inspection involved visually inspecting labels on representative light ballasts to identify dates of manufacture and labels indicating "No PCBs". Ballasts manufactured after 1991 were not listed as PCB- or DEHP-containing ballasts and were not quantified for disposal. An in-place inventory of the fluorescent lamps/tubes and other mercury-containing equipment was completed concurrently. Approximately 1,200 DEHP-containing fluorescent light ballasts and 3,650 four-foot, mercury-containing lamps were identified in the building during this inspection. Mercury-containing switches were identified in the Boiler Room.

### 5.4 Conclusions and Recommendations

DEHP-containing fluorescent light ballasts and mercury-containing equipment were identified in the building during this inspection.

Light ballasts marked as "No PCBs" with date labels indicating manufacture prior to 1991 are presumed to contain DEHP. DEHP-containing light ballasts must be segregated for proper packaging, transporting, and disposal as non-PCB hazardous waste. Note that disposal requirements for DEHP-containing ballasts are slightly varied, and disposal costs are slightly less than PCB-containing light ballasts.



According to the EPA, mercury-containing equipment is characterized as a hazardous waste and mercury lamps/tubes are characterized as a Universal Waste. The mercury-containing equipment and fluorescent lamps/tubes identified in the proposed renovation areas must be recycled, reclaimed, or disposed as hazardous waste prior to disturbance.

Report prepared by Environmental Technician, Robert Mallett.

Reviewed by:

Dustin A. Diedricksen Project Manager

Finity Mon 

Timothy M. Downey Senior Project Manager



## Tables



 Table 1

 Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

#### James F. Peebles Elementary School Bourne, Massachusetts

Flansburgh Architects December 4, 2015 Fuss & O'Neill EnviroScience No. 20150666.A1E

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
	Lab R	eport dated N	November 30, 2015		
01A-MC-1130	Brown Window Frame Paper	Non-ACM	Exterior	ND	
01B-MC-1130	Brown Window Frame Paper	Non-ACM	Exterior	ND	
	Lab R	leport dated I	November 6, 2015		
01A-RCM-1026	Gray Flashing Sealant	Non-ACM	Connector Building Roof	ND	TEM
01B-RCM-1026	Gray Flashing Sealant	Non-ACM	Connector Building Roof	ND	
02A-RCM-1026	Black Flashing Sealant	Non-ACM	Annex Roof	ND	TEM
02B-RCM-1026	Black Flashing Sealant	Non-ACM	Annex Roof	ND	
03A-RCM-1026	Black Built-Up Roofing	Non-ACM	Annex Roof	ND	TEM
03B-RCM-1026	Black Built-Up Roofing	Non-ACM	Connector Roof	ND	
04A-RCM-1026	Black Hot Mop	Non-ACM	Annex Roof	ND	TEM
04B-RCM-1026	Black Hot Mop	Non-ACM	Connector Roof	ND	
05A-RCM-1026	Gray Asphalt Roof Shingle	Non-ACM	Annex Roof	ND	TEM
05B-RCM-1026	Gray Asphalt Roof Shingle	Non-ACM	Main Roof	ND	
06A-RCM-1026	White Louver Caulking	Cat 2 NF	Annex Roof	5% Chrysotile	
06B-RCM-1026	White Louver Caulking	Cat 2 NF	Annex Roof	Pos Stop	
07A-RCM-1026	White Flashing Sealant	Non-ACM	Annex Roof	ND	TEM
07B-RCM-1026	White Flashing Sealant	Non-ACM	Annex Roof	ND	
08A-RCM-1026	Gray Door Caulking	Cat 2 NF	Annex Roof	4% Chrysotile	
08B-RCM-1026	Gray Door Caulking	Cat 2 NF	Annex Roof	Pos Stop	
09A-RCM-1026	Black Roof Felt beneath 05	Non-ACM	Annex Roof	ND	
09B-RCM-1026	Black Roof Felt beneath 05	Non-ACM	Main Building Roof	ND	
11A-RCM-1026	Tan Pipe-Thread Sealant	Non-ACM	Attic	ND	TEM
11B-RCM-1026	Tan Pipe-Thread Sealant	Non-ACM	Cafeteria	ND	
12A-RCM-1026	Gray Drywall	Non-ACM	Above 1st Floor Classrooms	ND	
12B-RCM-1026	Gray Drywall	Non-ACM	Above 1st Floor Classrooms	ND	
13A-RCM-1026	24" x 24" Red with White Splotch Floor Tile	Non-ACM	Classroom 7	ND	
13B-RCM-1026	24" x 24" Red with White Splotch Floor Tile	Non-ACM	Classroom 7	ND	
14A-RCM-1026	24" x 24" Tan with White & Brown Splotch Floor Tile	Non-ACM	Classroom 5	ND	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
14B-RCM-1026	24" x 24" Tan with White & Brown Splotch Floor Tile	Non-ACM	Classroom 5	ND	
15A-RCM-1026	12" x 12" Dark Gray Mottled Floor Tile	Non-ACM	Classroom 3	ND	
15B-RCM-1026	12" x 12" Dark Gray Mottled Floor Tile	Non-ACM	Classroom 3	ND	
17A-RCM-1026	Black Caulking Associated with Window Wall Support Columns	Non-ACM	Classroom 8	ND	TEM
17B-RCM-1026	Black Caulking Associated with Window Wall Support Columns	Non-ACM	Classroom 4	ND	
18A-RCM-1026	Tan Caulking Associated with Window Wall Support Columns	Non-ACM	Classroom 8	ND	TEM
18B-RCM-1026	Tan Caulking Associated with Window Wall Support Columns	Non-ACM	Classroom 4	ND	
19A-RCM-1026	Gray Ceramic Floor Tile Grout	Non-ACM	Ground Floor Boy's Bathroom	ND	
19B-RCM-1026	Gray Ceramic Floor Tile Grout	Non-ACM	1st Floor Boy's Bathroom	ND	
20A-RCM-1026	Black Composite Windowsill	Non-ACM	Classroom 11	ND	
20B-RCM-1026	Black Composite Windowsill	Non-ACM	Classroom 4	ND	
21A-RCM-1026	Gray Ceramic Floor Tile Adhesive	Non-ACM	Ground Floor Boy's Bathroom	ND	
21B-RCM-1026	Gray Ceramic Floor Tile Adhesive	Non-ACM	1st Floor Boy's Bathroom	ND	
22A-RCM-1026	Dark Gray Ceramic Wall Tile Adhesive	Non-ACM	Ground Floor Boy's Classroom	ND	
22B-RCM-1026	Dark Gray Ceramic Wall Tile Adhesive	Non-ACM	1st Floor Boys' Room	ND	
23A-RCM-1026	Gray Ceramic Wall Tile Grout	Non-ACM	Ground Floor Boy's Bathroom	ND	
23B-RCM-1026	Gray Ceramic Wall Tile Grout	Non-ACM	1st Floor Boy's Bathroom	ND	
24A-RCM-1026	Tan Interior Window Caulking	Non-ACM	Ground Floor Boy's Bathroom	ND	TEM
24B-RCM-1026	Tan Interior Window Caulking	Non-ACM	1st Floor Boy's Bathroom	ND	
25A-RCM-1026	Gray Mud-Set Mortar	Non-ACM	1st Floor Boy's Bathroom	ND	
25B-RCM-1026	Gray Mud-Set Mortar	Non-ACM	Ground Floor Boy's Bathroom	ND	
26A-RCM-1026	Gray Mud-Set Mortar	Non-ACM	Annex - 2nd Floor Boy's Bathroom	ND	
26B-RCM-1026	Gray Mud-Set Mortar	Non-ACM	Annex - 1st Floor Boy's Bathroom	ND	
27A-RCM-1026	1' x 1' White Fissured Splined Ceiling Tile	Non-ACM	Connector Hallway-1st	ND	
27B-RCM-1026	1' x 1' White Fissured Splined Ceiling Tile	Non-ACM	Connector Hallway-Ground	ND	
28A-RCM-1026	Tan Window Glazing Compound	Non-ACM	Annex Hallway to Lobby Doors	ND	
28B-RCM-1026	Tan Window Glazing Compound	Non-ACM	Annex Hallway to Lobby Doors	ND	
29A-RCM-1026	Tan Interior Window Caulking	Cat 2 NF	Classroom 14	5% Chrysotile	
29B-RCM-1026	Tan Interior Window Caulking	Cat 2 NF	Classroom 18	Pos Stop	
30A-RCM-1026	White Interior Window Caulking	Non-ACM	Classroom 14	ND	TEM
30B-RCM-1026	White Interior Window Caulking	Non-ACM	Classroom 18	ND	
31A-RCM-1026	Tan Window Glazing Compound	Cat 2 NF	Wood Main Entrance Doors	2% Chrysotile	
31B-RCM-1026	Tan Window Glazing Compound	Cat 2 NF	Wood Main Entrance Doors	Pos Stop	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
32A-RCM-1026	Tan Interior Door Caulking	Cat 2 NF	Cafeteria Doors	6% Chrysotile	
32B-RCM-1026	Tan Interior Door Caulking	Cat 2 NF	Main Building Doors at Connector	Pos Stop	
33A-RCM-1026	White Plaster Skim Coat	Non-ACM	Annex - Ground Level Boy's Bathroom	ND	
33B-RCM-1026	White Plaster Skim Coat	Non-ACM	Annex - Ground Level Girl's Bathroom	ND	
33C-RCM-1026	White Plaster Skim Coat	Non-ACM	Annex - 1st Floor Girl's Bathroom	ND	
33D-RCM-1026	White Plaster Skim Coat	Non-ACM	Annex - 1st Floor Boy's Bathroom	ND	
33E-RCM-1026	White Plaster Skim Coat	Non-ACM	Annex - Hallway Outside 14 & 15	ND	
34A-RCM-1026	Gray Plaster Rough Coat	Non-ACM	Annex - Ground Level Boy's Bathroom	ND	
34B-RCM-1026	Gray Plaster Rough Coat	Non-ACM	Annex - Ground Level Girl's Bathroom	ND	
34C-RCM-1026	Gray Plaster Rough Coat	Non-ACM	Annex - 1st Floor Girl's Bathroom	ND	
34D-RCM-1026	Gray Plaster Rough Coat	Non-ACM	Annex - 1st Floor Girl's Bathroom	ND	
34E-RCM-1026	Gray Plaster Rough Coat	Non-ACM	Annex - Ground Level Girl's Bathroom	ND	
35A-RCM-1026	Tan Interior Door Caulking	Cat 2 NF	At Connector Hallway-Ground Floor	2% Chrysotile	
35B-RCM-1026	Tan Interior Door Caulking	Cat 2 NF	At Connector Hallway-1st Floor	Pos Stop	
36A-RCM-1026	Tan Interior Window Caulking	Cat 2 NF	Connector Window Walls	5% Chrysotile	
36B-RCM-1026	Tan Interior Window Caulking	Cat 2 NF	Connector Window Walls	Pos Stop	
37A-RCM-1026	Gray Window Glazing Compound	Cat 2 NF	Connector Window Walls	2% Chrysotile	
37B-RCM-1026	Gray Window Glazing Compound	Cat 2 NF	Connector Window Walls	Pos Stop	
38A-RCM-1026	Gray Interior Window Caulking	Cat 2 NF	Cafeteria	2% Chrysotile	
38B-RCM-1026	Gray Interior Window Caulking	Cat 2 NF	Cafeteria	Pos Stop	
39A-RCM-1026	Brown Exterior Window Caulking	Non-ACM	Exterior-Main Building	ND	TEM
39B-RCM-1026	Brown Exterior Window Caulking	Non-ACM	Exterior-Main Building	ND	
40A-RCM-1026	Black Through-Wall Flashing Mastic	Non-ACM	Exterior-Main Building	ND	
40B-RCM-1026	Black Through-Wall Flashing Mastic	Non-ACM	Exterior-Main Building	ND	
41A-RCM-1026	Tan Exterior Window Sill Caulking	Cat 2 NF	Annex - Exterior	5% Chrysotile	
41B-RCM-1026	Tan Exterior Window Sill Caulking	Cat 2 NF	Annex - Exterior	Pos Stop	
42A-RCM-1026	Gray Exterior Window Caulking	Non-ACM	Annex - Exterior	ND	
42B-RCM-1026	Gray Exterior Window Caulking	Non-ACM	Annex - Exterior	ND	
43A-RCM-1026	White Exterior Window Sill Caulking	Cat 2 NF	Annex - Exterior	8% Chrysotile	
43B-RCM-1026	White Exterior Window Sill Caulking	Cat 2 NF	Annex - Exterior	Pos Stop	
44A-RCM-1026	Off-White Door Caulking	Non-ACM	Door between Classrooms 17 & 18	ND	TEM
44B-RCM-1026	Off-White Door Caulking	Non-ACM	Door between Classrooms 23 & 24	ND	
45A-RCM-1026	Tan Door Caulking	Cat 2 NF	Door between Classrooms 16 & 15	2% Chrysotile	



Table 1
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
45B-RCM-1026	Tan Door Caulking	Cat 2 NF	Door between Classrooms 16 & 15	Pos Stop	
46A-RCM-1026	Tan Interior Window Caulking	Non-ACM	Classroom 9	ND	TEM
46B-RCM-1026	Tan Interior Window Caulking	Non-ACM	Classroom 11	ND	
47A-RCM-1026	Black Damproofing	Non-ACM	Behind Brick at Main Building	ND	
47B-RCM-1026	Black Damproofing	Non-ACM	Behind Brick at Main Building	ND	
50A-RCM-1026	Brown Concrete Paper	Non-ACM	Pipe Tunnel	ND	
50B-RCM-1026	Brown Concrete Paper	Non-ACM	Crawlspace	ND	
51A-RCM-1026	Black Mastic Associated with 50	Non-ACM	Pipe Tunnel	ND	
51B-RCM-1026	Black Mastic Associated with 50	Non-ACM	Crawlspace	ND	
	Lab R	eport dated l	December 9, 2014		
01A-RCM-1205	Smooth White Plaster Skim Coat	Non-ACM	Ground Floor Stairwell Landing	ND	
01B-RCM-1205	Smooth White Plaster Skim Coat	Non-ACM	Ground Floor Stairwell Landing	ND	
01C-RCM-1205	Smooth White Plaster Skim Coat	Non-ACM	Ground Floor Stairwell Landing	ND	
	Lab Results from Emerger	ncy Asbestos	Project Design dated October 6, 2014		
01A-JH-925	Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
01B-JH-925	Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
01C-JH-925	Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
02A-JH-925	White Window Glazing Compound	Cat 2 NF	Door D1	2% Chrysotile	
02B-JH-925	White Window Glazing Compound	Cat 2 NF	Door D1	Pos Stop	
02C-JH-925	White Window Glazing Compound	Cat 2 NF	Door D1	Pos Stop	
03A-JH-925	Gray Door Window Glazing Compound	Non-ACM	Door D1	ND	
03B-JH-925	Gray Door Window Glazing Compound	Non-ACM	Door D1	ND	
03C-JH-925	Gray Door Window Glazing Compound	Non-ACM	Door D1	ND	
04A-JH-925	Brown Backer Rope beneath Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
04B-JH-925	Brown Backer Rope beneath Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
04C-JH-925	Brown Backer Rope beneath Gray Exterior Door Caulking	Non-ACM	Door D1	ND	
05A-JH-925	Tan Interior Door Caulking	Cat 2 NF	Door D1	2% Chrysotile	
05B-JH-925	Tan Interior Door Caulking	Cat 2 NF	Door D1	Pos Stop	
05C-JH-925	Tan Interior Door Caulking	Cat 2 NF	Door D1	Pos Stop	
06A-JH-925	Black Damproofing Behind Brick Veneer	Cat 2 NF	Exterior	15% Chrysotile	
06B-JH-925	Black Damproofing Behind Brick Veneer	Cat 2 NF	Exterior	Pos Stop	
06C-JH-925	Black Damproofing Behind Brick Veneer	Cat 2 NF	Exterior	Pos Stop	
	Lat	o Report date	ed July 23, 2013		



Table 1
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
718DD-01A	Ceiling Skim Plaster	Non-ACM	Art Room	<1% Chrysotile	ACWM
718DD-01B	Ceiling Skim Plaster	Non-ACM	Art Room	< 1% Chrysotile	ACWM
718DD-01C	Ceiling Skim Plaster	Non-ACM	Art Room	< 1% Chrysotile	ACWM
718DD-02A	Ceiling Rough Plaster	Non-ACM	Art Room	< 1% Chrysotile	ACWM
718DD-02B	Ceiling Rough Plaster	Non-ACM	Art Room	ND	
718DD-02C	Ceiling Rough Plaster	Non-ACM	Art Room	ND	
718DD-03A	Ceiling Plaster Skim Coat	Non-ACM	Kitchen	ND	
718DD-03B	Ceiling Plaster Skim Coat	Non-ACM	Kitchen	ND	
718DD-03C	Ceiling Plaster Skim Coat	Non-ACM	Kitchen	ND	
718DD-03D	Ceiling Plaster Skim Coat	Non-ACM	Bathroom off Kitchen	ND	
718DD-03E	Ceiling Plaster Skim Coat	Non-ACM	Pantry	ND	
718DD-04A	Ceiling Rough Plaster	Non-ACM	Kitchen	ND	
718DD-04B	Ceiling Rough Plaster	Non-ACM	Kitchen	ND	
718DD-04C	Ceiling Rough Plaster	Non-ACM	Kitchen	ND	
718DD-04D	Ceiling Rough Plaster	Non-ACM	Bathroom off Kitchen	ND	
718DD-04E	Ceiling Rough Plaster	Non-ACM	Pantry	ND	
Lab Results from EnviroScience Report dated December 19, 2012					
1	Plaster Rough Coat Associated with Window Surround	Non-ACM	Basement Boy's Bathroom	ND	
2	Plaster Rough Coat Associated with Window Surround	Non-ACM	Basement Boy's Bathroom	ND	
3	Plaster Skim Coat Associated with Window Surround	Non-ACM	Basement Boy's Bathroom	ND	
4	Plaster Skim Coat Associated with Window Surround	Non-ACM	Basement Boy's Bathroom	ND	
817NG-01A	Plaster Skim Coat Associated with Window Surround	Non-ACM	Cafeteria	ND	
817NG-01B	Plaster Skim Coat Associated with Window Surround	Non-ACM	Cafeteria	ND	
817NG-01C	Plaster Skim Coat Associated with Window Surround	Non-ACM	Cafeteria	ND	
017310 021					
817NG-02A	Plaster Rough Coat Associated with Window Surround	Non-ACM	Cafeteria	ND	
817NG-02A 817NG-02B	Plaster Rough Coat Associated with Window Surround Plaster Rough Coat Associated with Window Surround	Non-ACM Non-ACM	Cafeteria Cafeteria	ND ND	
	~				
817NG-02B	Plaster Rough Coat Associated with Window Surround	Non-ACM	Cafeteria	ND	
817NG-02B 817NG-02C	Plaster Rough Coat Associated with Window Surround Plaster Rough Coat Associated with Window Surround	Non-ACM Non-ACM	Cafeteria Cafeteria	ND ND	
817NG-02B 817NG-02C 817NG-03A	Plaster Rough Coat Associated with Window Surround Plaster Rough Coat Associated with Window Surround Plaster Skim Coat Associated with Ceiling Drop Beams	Non-ACM Non-ACM Non-ACM	Cafeteria Cafeteria Cafeteria	ND ND ND	
817NG-02B 817NG-02C 817NG-03A 817NG-03B	Plaster Rough Coat Associated with Window Surround Plaster Rough Coat Associated with Window Surround Plaster Skim Coat Associated with Ceiling Drop Beams Plaster Skim Coat Associated with Ceiling Drop Beams	Non-ACM Non-ACM Non-ACM	Cafeteria Cafeteria Cafeteria Cafeteria	ND ND ND ND	
817NG-02B 817NG-02C 817NG-03A 817NG-03B 817NG-03C	Plaster Rough Coat Associated with Window Surround Plaster Rough Coat Associated with Window Surround Plaster Skim Coat Associated with Ceiling Drop Beams Plaster Skim Coat Associated with Ceiling Drop Beams Plaster Skim Coat Associated with Ceiling Drop Beams	Non-ACM Non-ACM Non-ACM Non-ACM	Cafeteria Cafeteria Cafeteria Cafeteria Cafeteria	ND ND ND ND ND	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
821DD-01A	Skim Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-01B	Skim Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-01C	Skim Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-02A	Rough Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-02B	Rough Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-02C	Rough Plaster	Non-ACM	Kitchen at Overhead Duct Associated with Range Hood	ND	
821DD-03A	Caulking at Ductwork to Plaster Joint	Cat 2 NF	Kitchen at Overhead Duct Associated with Range Hood	5% Chrysotile	Abated
821DD-03A	Caulking at Ductwork to Plaster Joint	Cat 2 NF	Kitchen at Overhead Duct Associated with Range Hood	Pos Stop	Abated
821DD-04A	Plaster Skim Coat Associated with Window Surround	Non-ACM	Kitchen	ND	
821DD-04B	Plaster Skim Coat Associated with Window Surround	Non-ACM	Kitchen	ND	
821DD-05A	Plaster Rough Coat Associated with Window Surround	Non-ACM	Kitchen	ND	
821DD-05B	Plaster Rough Coat Associated with Window Surround	Non-ACM	Kitchen	ND	
821DD-06A	Plaster Ceiling Smooth Skim Coat	Non-ACM	Basement Boy's Bathroom	ND	
821DD-06B	Plaster Ceiling Smooth Skim Coat	Non-ACM	Basement Boy's Bathroom	ND	
821DD-06C	Plaster Ceiling Smooth Skim Coat	Non-ACM	Girl's Basement Bathroom	ND	
821DD-06D	Plaster Ceiling Smooth Skim Coat	Non-ACM	1st Floor Boy's Bathroom	ND	
821DD-06E	Plaster Ceiling Smooth Skim Coat	Non-ACM	1st Floor Girl's Bathroom	ND	
821DD-07A	Plaster Ceiling Rough Coat	Non-ACM	Basement Boy's Bathroom	ND	
821DD-07B	Plaster Ceiling Rough Coat	Non-ACM	Basement Boy's Bathroom	ND	
821DD-07C	Plaster Ceiling Rough Coat	Non-ACM	Basement Girl's Bathroom	ND	
821DD-07D	Plaster Ceiling Rough Coat	Non-ACM	1st Floor Boy's Bathroom	ND	
821DD-07E	Plaster Ceiling Rough Coat	Non-ACM	1st Floor Girl's Bathroom	ND	
821DD-08A	Plaster Ceiling Smooth Skim Coat	Non-ACM	Annex Boy's Bathroom 1st Floor	ND	
821DD-08B	Plaster Ceiling Smooth Skim Coat	Non-ACM	Annex Girl's Bathroom 1st Floor	ND	
821DD-08C	Plaster Ceiling Smooth Skim Coat	Non-ACM	Annex Girl's Bathroom 1st Floor	ND	
821DD-08D	Plaster Ceiling Smooth Skim Coat	Non-ACM	Annex Boy's Basement Bathroom	ND	
821DD-08E	Plaster Ceiling Smooth Skim Coat	Non-ACM	Annex Girl's Basement Bathroom	ND	
821DD-09A	Plaster Ceiling Rough Coat	Non-ACM	Annex Boy's Bathroom 1st Floor	ND	
821DD-09B	Plaster Ceiling Rough Coat	Non-ACM	Annex Girl's Bathroom 1st Floor	ND	
821DD-09C	Plaster Ceiling Rough Coat	Non-ACM	Annex Girl's Bathroom 1st Floor	ND	
821DD-09D	Plaster Ceiling Rough Coat	Non-ACM	Boy's Bathroom Basement	ND	
821DD-09E	Plaster Ceiling Rough Coat	Non-ACM	Girl's Bathroom Basement	ND	
0826DD-01A	Plaster Ceiling Smooth Skim Coat	Non-ACM	Copy Room	ND	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
0826DD-01B	Plaster Ceiling Smooth Skim Coat	Non-ACM	Copy Room	ND	
0826DD-01C	Plaster Ceiling Smooth Skim Coat	Non-ACM	Music Room	ND	
0826DD-01D	Plaster Ceiling Smooth Skim Coat	Non-ACM	Teachers' Lounge	ND	
0826DD-01E	Plaster Ceiling Smooth Skim Coat	Non-ACM	Teachers' Lounge	ND	
0826DD-02A	Plaster Ceiling Rough Coat	Non-ACM	Copy Room	ND	
0826DD-02B	Plaster Ceiling Rough Coat	Non-ACM	Copy Room	ND	
0826DD-02C	Plaster Ceiling Rough Coat	Non-ACM	Music Room	ND	
0826DD-02D	Plaster Ceiling Rough Coat	Non-ACM	Teachers' Lounge	ND	
0826DD-02E	Plaster Ceiling Rough Coat	Non-ACM	Teachers' Lounge	ND	
827-NG-1	White Window Glazing Compound	Cat 2 NF	Classroom 2	2% Chrysotile	
827-NG-2	White Window Glazing Compound	Cat 2 NF	Classroom 2	2% Chrysotile	
827-NG-3	White Window Glazing Compound	Non-ACM	Classroom 6	ND	
827-NG-4	White Window Glazing Compound	Non-ACM	Classroom 6	ND	
827-NG-5	Vinyl Covering on Radiators	Non-ACM	Classroom 8	ND	
827-NG-6	Vinyl Covering on Radiators	Non-ACM	Classroom 8	ND	
827-NG-7	Gray with White Window Caulking	Cat 2 NF	Classroom 8	2% Chrysotile	
827-NG-8	Gray with White Window Caulking	Cat 2 NF	Classroom 7	2% Chrysotile	
827-NG-9	Newer Smooth Window Glazing Compound	Non-ACM	Classroom 5	ND	
827-NG-10	Newer Smooth Window Glazing Compound	Non-ACM	Classroom 5	ND	
827-NG-11	Gray with White Caulking	Cat 2 NF	Classroom 6	2% Chrysotile	
827-NG-12	White Window Glazing Compound	Non-ACM	Cafeteria Exterior	ND	
97NG-01A	Light-Weight Parging Material Behind Lally Columns	Non-ACM	Classroom	ND	
97NG-01B	Light-Weight Parging Material Behind Lally Columns	Non-ACM	Classroom	ND	
97NG-01C	Light-Weight Parging Material Behind Lally Columns	Non-ACM	Classroom	ND	
97NG-02A	Weather-Proofing Cushion Felt underneath Unit Vents	Non-ACM	South Exterior	ND	
97NG-02B	Weather-Proofing Cushion Felt underneath Unit Vents	Non-ACM	South Exterior	ND	
97NG-02C	Weather-Proofing Cushion Felt underneath Unit Vents	Non-ACM	South Exterior	ND	
97NG-03A	Grey Window Caulking	Non-ACM	North Exterior	ND	
97NG-03B	Grey Window Caulking	Non-ACM	North Exterior	ND	
97NG-03C	Grey Window Caulking	Non-ACM	North Exterior	ND	
97NG-04A	White/Gray Window Caulking	Non-ACM	North (front) Exterior	ND	
97NG-04B	White/Gray Window Caulking	Non-ACM	North (front) Exterior	ND	
97NG-04C	White/Gray Window Caulking	Non-ACM	North (front) Exterior	ND	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments		
Lab Results from EnviroScience Report dated April 16, 2010							
331DD-01 A	Friable Boiler-Jacket Insulation	Non-ACM	Boiler Exterior	ND			
331DD-01 B	Friable Boiler-Jacket Insulation	Non-ACM	Boiler Exterior	ND			
331DD-01 C	Friable Boiler-Jacket Insulation	Non-ACM	Boiler Exterior	ND			
331DD-02A	Friable TSI at Boiler Ribbing	Friable	Boiler Interior	40% Chrysotile			
331DD-02B	Friable TSI at Boiler Ribbing	Friable	Boiler Interior	Pos Stop			
331DD-02C	Friable TSI at Boiler Ribbing	Friable	Boiler Interior	Pos Stop			
331DD-03 A	Boiler Roping at Bottom Seams	Non-ACM	Boiler Exterior (Underside)	ND			
331DD-03 B	Boiler Roping at Bottom Seams	Non-ACM	Boiler Exterior (Underside)	ND			
331DD-03 C	Boiler Roping at Bottom Seams	Non-ACM	Boiler Exterior (Underside)	ND			
331DD-04 A	Hot Water Tank TSI	Non-ACM	Hot Water Tank (Boiler Room)	ND			
331DD-04 B	Hot Water Tank TSI	Non-ACM	Hot Water Tank (Boiler Room)	ND			
331DD-05	Cloth Insulation-Wrap	Non-ACM	Piping Underneath Hot Water Tank	ND			
331DD-06	Grey Flue Patch	Non-ACM	Boiler at Breeching Penetration	ND			
331DD-07	White Friable TSI at Front Circular Panel	Friable	Boiler Exterior (Front)	10% Chrysotile			
331DD-08	White Cloth Vibration Isolator	Non-ACM	Boiler Duct	ND			
331DD-09A	Exterior Gasket at Metal Fixed-Panels	Cat 1 NF	Boiler Exterior	25% Chrysotile			
331DD-09B	Exterior Gasket at Metal Fixed-Panels	Cat 1 NF	Boiler Exterior	Pos Stop			
331DD-10	Residual Door Gaskets	Non-ACM	Boiler Doors	ND			
331DD-11	Red Pipe-Gasket	Non-ACM	Piping Underneath Hot Water Tank	ND			
331DD-12A	Boiler Debris	Non-ACM	Boiler Interior	ND			
331DD-12B	Boiler Debris	Non-ACM	Boiler Interior	ND			
331DD-13	White Friable Pipe Gasket	Non-ACM	Piping at Backside of Boiler	ND			
331DD-14A	Interior Boiler Brick	Non-ACM	Boiler Interior	ND			
331DD-14B	Interior Boiler Brick	Non-ACM	Boiler Interior	ND			
331DD-14C	Interior Boiler Brick	Non-ACM	Boiler Interior	ND			
331DD-15A	Red Brick Boiler-Base (Solid Brick)	Non-ACM	Boiler Base	ND			
331DD-15B	Red Brick Boiler-Base (Solid Brick)	Non-ACM	Boiler Base	ND			
331DD-15C	Red Brick Boiler-Base (Solid Brick)	Non-ACM	Boiler Base	ND			
331DD-16A	Orange Open-Brick Base Insert (Hollow Center)	Non-ACM	Boiler Base (Center)	ND			
331DD-16B	Orange Open-Brick Base Insert (Hollow Center)	Non-ACM	Boiler Base (Center)	ND			
	Lab Results from E	EnviroScience	e Report dated August 11, 2009				
720JH-01 A	Hot Water Tank Insulation	Non-ACM	Boiler Room	ND			



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
720JH-01 B	Hot Water Tank Insulation	Non-ACM	Boiler Room	ND	
720JH-01 C	Hot Water Tank Insulation	Non-ACM	Boiler Room	ND	
720JH-02 A	Boiler Breeching	Non-ACM	Boiler Room (Boiler 2)	ND	
720JH-02 B	Boiler Breeching	Non-ACM	Boiler Room (Boiler 1)	ND	
720JH-02 C	Boiler Breeching	Non-ACM	Boiler Room (Boiler 1)	ND	
720JH-03 A	Boiler Insulation	Non-ACM	Boiler Room (Boiler 2)	ND	
720JH-03 B	Boiler Insulation	Non-ACM	Boiler Room (Boiler 1)	ND	
720JH-03 C	Boiler Insulation	Non-ACM	Boiler Room (Boiler 1)	ND	
720JH-04 A	Duct Vibration Isolator	Cat 2 NF	Boiler Room	ND	
720JH-04 B	Duct Vibration Isolator	Cat 2 NF	Boiler Room	60% Chrysotile	
720JH-04 C	Duct Vibration Isolator	Cat 2 NF	Boiler Room	Pos Stop	
720JH-05 A	Pre-Formed Block-Type Pipe Insulation	Friable	Office Near Classroom 9	5% Chrysotile 15% Amosite 6% Crocidolite	
720JH-05 B	Pre-Formed Block-Type Pipe Insulation	Friable	Office Near Classroom 9	Pos Stop	
720JH-05 C	Pre-Formed Block-Type Pipe Insulation	Friable	Office Near Classroom 9	Pos Stop	
720JH-06 A	Paper-Type Pipe Insulation	Friable	Storage near Classroom 13	70% Chrysotile	
720JH-06 B	Paper-Type Pipe Insulation	Friable	Chase near Classroom 7	70% Chrysotile	
720JH-06 C	Paper-Type Pipe Insulation	Friable	Stage	70% Chrysotile	
720JH-07 A	Mudded Pipe Fitting Insulation	Friable	Storage near Classroom 13	5% Chrysotile 15% Amosite 12% Crocidolite	
720JH-07 B	Mudded Pipe Fitting Insulation	Friable	Storage near Classroom 13	Pos Stop	
720JH-07 C	Mudded Pipe Fitting Insulation	Friable	Stage	Pos Stop	
720JH-08 A	Black Cove Base	Non-ACM	Classroom 10	ND	
720JH-08 B	Black Cove Base	Non-ACM	Classroom 8	ND	
720JH-08 C	Black Cove Base	Non-ACM	Classroom 5	ND	
720JH-09 A	Black Mastic Associated with Black Cove Base	Non-ACM	Classroom 10	ND	
720JH-09 B	Black Mastic Associated with Black Cove Base	Non-ACM	Classroom 8	ND	
720JH-09 C	Black Mastic Associated with Black Cove Base	Non-ACM	Classroom 5	ND	
720JH-10 A	Vinyl Windowsill	Non-ACM	Classroom 4	ND	
720JH-10 B	Vinyl Windowsill	Non-ACM	Classroom 10	ND	
720JH-10 C	Vinyl Windowsill	Non-ACM	Classroom 12	ND	
720JH-11 A	1' x 1' Pin Hole Ceiling Tile	Non-ACM	Loose in Attic	ND	
720JH-11 B	1' x 1' Pin Hole Ceiling Tile	Non-ACM	Loose in Attic	ND	



<u>Table 1</u>
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
720JH-11 C	1' x 1' Pin Hole Ceiling Tile	Non-ACM	Loose in Attic	ND	
720JH-12 A	Dark Brown Mastic Associated with 1' x 1' Pin Hole Ceiling Tiles	Non-ACM	Loose in Attic	ND	
720JH-12 B	Dark Brown Mastic Associated with 1' x 1' Pin Hole Ceiling Tiles	Non-ACM	Loose in Attic	ND	
720JH-12 C	Dark Brown Mastic Associated with 1' x 1' Pin Hole Ceiling Tiles	Non-ACM	Loose in Attic	ND	
720JH-13 A	Black Mastic Associated with 9" x 9" Floor Tile	Non-ACM	Classroom 22	ND	
720JH-13 B	Black Mastic Associated with 9" x 9" Floor Tile	Non-ACM	Main Lobby	ND	
720JH-13 C	Black Mastic Associated with 9" x 9" Floor Tile	Non-ACM	Ground Floor Hall	ND	
720JH-14 A	Black Mastic Associated with 12" x 12" Floor Tile	Non-ACM	Classroom 9	ND	
720JH-14 B	Black Mastic Associated with 12" x 12" Floor Tile	Non-ACM	Classroom 12	ND	
720JH-14 C	Black Mastic Associated with 12" x 12" Floor Tile	Non-ACM	Breezeway Between Classrooms 10 & 11	ND	
720JH-15 A	Blue/Grey with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 1	ND	
720JH-15 B	Blue/Grey with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 2	ND	
720JH-15 C	Blue/Grey with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 3	ND	
720JH-16 A	White/ Yellow/ Brown 12" x 12" Floor Tile	Non-ACM	Classroom 6	ND	
720JH-16 B	White/ Yellow/ Brown 12" x 12" Floor Tile	Non-ACM	Classroom 6	ND	
720JH-16 C	White/ Yellow/ Brown 12" x 12" Floor Tile	Non-ACM	Classroom 6	ND	
720JH-17 A	Tan with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 1	ND	
720JH-17 B	Tan with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 2	ND	
720JH-17 C	Tan with White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 3	ND	
720JH-18 A	White with Brown and Blue Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 8	ND	
720JH-18 B	White with Brown and Blue Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 8	ND	
720JH-18 C	White with Brown and Blue Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 8	ND	
720JH-19 A	Red with Pink Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-19 B	Red with Pink Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-19 C	Red with Pink Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-20 A	Brown with Light Brown and Dark Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-20 B	Brown with Light Brown and Dark Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-20 C	Brown with Light Brown and Dark Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 4	ND	
720JH-21 A	Grey with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 9	ND	
720JH-21 B	Grey with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 10	ND	
720JH-21 C	Grey with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 12	ND	
720JH-22 A	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Breezeway Between Classrooms 10 & 11	ND	
720JH-22 B	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Breezeway Between Classrooms 10 & 11	ND	



Table 1
Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments
720JH-22 C	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Breezeway Between Classrooms 10 & 11	ND	
720JH-23 A	Tan with Pink and Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 12	ND	
720JH-23 B	Tan with Pink and Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 12	ND	
720JH-23 C	Tan with Pink and Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 12	ND	
720JH-24 A	Tan with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-24 B	Tan with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-24 C	Tan with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-25 A	Brown with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-25 B	Brown with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-25 C	Brown with Brown and White Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 11	ND	
720JH-26 A	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 9	ND	
720JH-26 B	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 9	ND	
720JH-26 C	Tan with Brown Streaks 12" x 12" Floor Tile	Non-ACM	Classroom 9	ND	
720JH-27 A	Plaster Wall Rough Coat	Non-ACM	Stairwell Near 12	ND	
720JH-27 B	Plaster Wall Rough Coat	Non-ACM	Classroom 11	ND	
720JH-27 C	Plaster Wall Rough Coat	Non-ACM	Outside Boiler Room	ND	
720JH-27 D	Plaster Wall Rough Coat	Non-ACM	Attic	ND	
720JH-27 E	Plaster Wall Rough Coat	Non-ACM	Attic	ND	
720JH-27 F	Plaster Wall Rough Coat	Non-ACM	Classroom 10	ND	
720JH-27 G	Plaster Wall Rough Coat	Non-ACM	Custodial Closet Near Room 7	ND	
720JH-28 A	Plaster Wall Skim Coat	Non-ACM	Stairwell Near 12	ND	
720JH-28 B	Plaster Wall Skim Coat	Non-ACM	Classroom 11	ND	
720JH-28 C	Plaster Wall Skim Coat	Non-ACM	Outside Boiler Room	ND	
720JH-28 D	Plaster Wall Skim Coat	Non-ACM	Attic	ND	
720JH-28 E	Plaster Wall Skim Coat	Non-ACM	Attic	ND	
720JH-28 F	Plaster Wall Skim Coat	Non-ACM	Classroom 10	ND	
720JH-28 G	Plaster Wall Skim Coat	Non-ACM	Custodial Closet Near Room 7	ND	
720JH-29 A	Plaster Ceiling Rough Coat	Non-ACM	Classroom 10	ND	
720JH-29 B	Plaster Ceiling Rough Coat	Non-ACM	Classroom 11	ND	
720JH-29 C	Plaster Ceiling Rough Coat	Non-ACM	Classroom 12	ND	
720JH-29 D	Plaster Ceiling Rough Coat	Non-ACM	Classroom 1	ND	
720JH-29 E	Plaster Ceiling Rough Coat	Non-ACM	Classroom 2	ND	
720JH-29 F	Plaster Ceiling Rough Coat	Non-ACM	Classroom 3	ND	



 Table 1

 Summary of Suspect Asbestos-Containing Materials Laboratory Analytical Data

Sample Number	Material Type	NESHAP Category	Sample Location	Result	Comments		
720JH-29 G	Plaster Ceiling Rough Coat	Non-ACM	Classroom 6	ND			
720JH-30 A	Ceiling Plaster Skim Coat	Friable	Classroom 10	3% Chrysotile			
720JH-30 B	Ceiling Plaster Skim Coat	Friable	Classroom 11	Pos Stop			
720JH-30 C	Ceiling Plaster Skim Coat	Friable	Classroom 12	Pos Stop			
720JH-30 D	Ceiling Plaster Skim Coat	Friable	Classroom 1	Pos Stop			
720JH-30 E	Ceiling Plaster Skim Coat	Friable	Classroom 2	Pos Stop			
720JH-30 F	Ceiling Plaster Skim Coat	Friable	Classroom 3	Pos Stop			
720JH-30 G	Ceiling Plaster Skim Coat	Friable	Classroom 6	Pos Stop			
	Materials from 1988 & 1994 AHERA Initial and 3-Year Reinspection						
C1	9" x 9" Floor Tile	Cat 1 NF	Sample Location Unknown	> 1% Asbestos	* See Footnote		
C4	Gray Fiber-Reinforced Cement Panel	Cat 2 NF	Annex Attic	Assumed			

Cat 1 NF = Category I Non-Friable Material

Cat 2 NF = Category II Non-Friable Material

Pos Stop = Positive Stop

ND = None Detected

ACM = Asbestos-Containing Material

ACWM = Asbestos-Containing Waste Material

TEM = Transmission Electron Microscopy

\*Note: Material is identified in 1994 AHERA Reinspection report as being identified as ACM in 1988 AHERA Initial Inspection Report. 1988 AHERA Report and Lab Data are unavailable.



#### <u>Table 2</u> Summary of Asbestos-Containing Materials

#### James F. Peebles Elementary School Bourne, Massachusetts

Flansburgh Architects December 4, 2015 Fuss & O'Neill EnviroScience No. 20150666.A1E

Material Type	Locations(s)	Asbestos Content	Estimated Total Quantity	Comments
White Louver Caulking	Annex Roof	5% Chrysotile	50 LF	
Gray Door Caulking	Annex Roof	4% Chrysotile	10 LF	
Tan Interior Window Caulking	Annex Classrooms	5% Chrysotile	750 LF	
Tan Window Glazing Compound	Main Entrance	2% Chrysotile	1 EA	Door System is approximate 20' x 10'
Tan Interior Door Caulking	Throughout Interior	6% Chrysotile	375 LF	
Tan Interior Door Caulking	Connector Building	2% Chrysotile	2 EA	12' x 10'
Tan Interior Window Caulking	Connector Window Walls	5% Chrysotile	250 LF	
Gray Window Glazing Compound	Connector Window Walls	2% Chrysotile	8 EA	15' x 10'
Gray Interior Window Caulking	Cafeteria	2% Chrysotile	140 LF	
Tan Exterior Window Sill Caulking	Annex - Exterior	5% Chrysotile		
White Exterior Window Sill Caulking	Annex - Exterior	8% Chrysotile	250 LF	
Tan Door Caulking	Door between 16 & 15	2% Chrysotile	18 LF	
Black Damproofing	Annex Exterior behind Brick Veneer	15% Chrysotile	450 SF	
Ceiling Skim Plaster	Art Room	< 1% Chrysotile	300 SF	ACWM
White Window Glazing Compound	1950s Building Gymnasium, Cafeteria, Classrooms 1 - 13, Offices, & Teachers Lounge	2% Chrysotile	~35 EA	$ \begin{array}{c} \sim 13 @ 30' x \ 6.5' \\ \sim 3 @ 20' x \ 6.5' \\ \sim 10 @ 7.5' x \ 6.5' \\ \sim 2 @ 12' x \ 6.5' \\ \sim 2 @ 12' x \ 4.5' \\ \sim 1 @ 15' x \ 3' \\ \sim 1 @ 12' x \ 3' \end{array} $
Gray with White Window Caulking	1950s Building Gymnasium, Cafeteria, Classrooms 1 - 13, Offices, & Teachers Lounge	2% Chrysotile	3,575 LF	
Friable TSI at Boiler Ribbing	Boiler Room (Boilers 1 & 2)	40 % Chrysotile		
White Friable TSI at Front Circular Panel	Boiler Exterior (Front)	10% Chrysotile	2 EA	
Exterior Gasket at Metal Fixed-Panels	Boiler Exterior	25% Chrysotile		
Duct Vibration Isolator	Attic, Annex Lofts, Boiler Room, Stage, & 1st Floor Annex Custodian Closets	60% Chrysotile	15 EA	Associated with HVAC Ductwork
Pre-Formed, Block-Type Pipe Insulation	Concealed in Walls and Pipe Chases	5% Chrysotile 15% Amosite 6% Crocidolite	500 LF	
Corrugated, Paper-Type Pipe Insulation	Pipe Chases, Pipe Tunnels, & above Ceilings in the 1950s Building & Annex	70% Chrysotile	~ 1,500 LF	



<u>Table 2</u> Summary of Asbestos-Containing Materials

Material Type	Locations(s)	Asbestos Content	Estimated Total Quantity	Comments
Mudded Pipe Fitting Insulation	Building	5% Chrysotile 15% Amosite 12% Crocidolite		
Ceiling Plaster Skim Coat	Ground Floor Main Hallway, Storage Room Across from Classroom 13, Cafeteria, & Classrooms 9 - 13	3% Chrysotile	13,000 SF	
9" x 9" Floor Tile	1950s Building 1st Floor Hallway (from Lobby to Classroom 7), Main Office Spaces, Principals Office, Conference Room, Storage Room adjacent to Main Office, Special Education Office, Stairwell Landings & Stair Treads Across from Room 4, 1950's Building Ground Floor Hallway (Cafeteria to End of Hall), Teachers Room, Custodians Closet, Classroom 13 & Stairwell Landing & Stair Treads adjacent to Room 9	> 1% Asbestos	5,000 SF	
9" x 9" Floor Tile	Ground & 1st Floor Connector Building Hallways & Stairwell Landings between 1950s Building & Annex building	>1% Asbestos	1,200 SF	
9" x 9" Floor Tile	Annex Building Ground & 1st Floor Classrooms, Hallways, Library, Stairwell Landings, Stair Treads & Custodian Spaces (does not include Ground & 1st Floor Bathrooms)	>1% Asbestos	13,500 SF	
Gray Fiber-Reinforced Cement Panel	Annex Loft Along Edge & Boiler Room	Assumed	400 SF	
Sub-Slab Damproofing Mastics/Materials	1950s & Annex Buildings	Assumed	14,500 SF	
Contaminated Soil	Crawlspaces & Pipe Tunnels	Asbestos-Contaminated	45 CY	Assumes 2,200 SF Removed to a Depth of 6"

CY = Cubic Yard, EA = Each, LF = Linear Feet, SF = Square Feet

ACM = Asbestos-Containing Material

ACWM = Asbestos-Containing Waste Material

TSI = Thermal System Insulation



Material Type	Location	Estimated Quantity	
Exterior/Interior Window Caulking*	Original & Annex Buildings	5,000 LF	
Exterior Door Caulking*	Original & Annex Buildings	200 LF	
Interior Door Caulking	Original & Annex Buildings	375 LF	
Louver Caulking*	Annex Roof	50 LF	
Roof Door Caulking*	Annex Roof	10 LF	
Window Glazing Compound*	Original & Annex Building Windows	50 Systems	
Window Glazing Compound	Main Entrance	1 System	
Interior Door Caulking Associated with Connector Building Fire Doors	Connector Building	2 EA	
Window Sill Caulking	Annex Exterior	250 LF	
Door Caulking	Interior Door Between Room 15 & 16	20 LF	
Roof Flashing Caulking	Annex Roof	250 LF	

 Table 3

 Summary of Presumed PCB-Containing Source Building Materials

EA = Each, LF = Linear Feet

\* Denotes material type also contains, or is presumed to contain, asbestos



# Appendix A

Limitations



### APPENDIX A

### James F. Peebles Elementary School Bourne, MA

- This environmental report has been prepared for the exclusive use of the Client, and is subject to, and is issued in connection with, the general terms and conditions of the revised original Agreement (September 25, 2015) and all of its provisions. Any use or reliance upon information provided in this report, without the specific written authorization of the Client and EnviroScience, shall be at the User's individual risk. This report should not be used as an abatement specification. All quantities of materials identified during this inspection are approximate.
- 2. EnviroScience has obtained and relied upon information from multiple sources to form certain conclusions regarding likely environmental issues at and in the vicinity of the subject property in conducting this inspection. Except as otherwise noted, no attempt has been made to verify the accuracy or completeness of such information or verify compliance by any party with federal, state, or local laws or regulations.
- 3. EnviroScience has obtained and relied upon laboratory analytical results in conducting the inspection. This information was used to form conclusions regarding the types and quantities of ACM that must be managed prior to renovation or demolition activities that may disturb these materials at the subject property(ies). EnviroScience has not performed an independent review of the reliability of this laboratory data.
- 4. Unless otherwise noted, only suspect hazardous materials associated within or located on the building (aboveground) were included in this inspection. Suspect hazardous materials may exist below the ground surfaces that were not included in the scope of work of this inspection. EnviroScience cannot guarantee all asbestos or suspect hazardous materials were identified within the areas included in the scope of work. Only visible and accessible areas were included in the scope of work for this inspection.
- 5. The findings, observations, and conclusions presented in this report are limited by the scope of services outlined in our original Agreement, which reflects schedule and budgetary constraints imposed by the Client. Furthermore, the assessment has been conducted in accordance with generally accepted environmental practices. No other warranty, expressed or implied, is made.
- 6. The conclusions presented in this report are based solely upon information gathered by EnviroScience to date. Should further environmental or other relevant information be discovered at a later date, the Client should immediately bring the information to EnviroScience's attention. Based upon an evaluation and assessment of relevant information, EnviroScience may modify the letter report and its conclusions.



# Appendix B

EnviroScience Asbestos Inspector State Certifications and EPA Accreditations









This is to certify that

# Robert C Mallett



has completed the requisite training, and has passed an examination for Asbestos Inspector Refresher reaccreditation as:

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

**INSTITUTE FOR ENVIRONMENTAL EDUCATION** 

**Fraining Director** 

www.leetrains.com

Talephona 978.658.5272

16 Upton Drive, Wilmington, MA 01887

Wenterft

January 14, 2016 Expiration Date

Examination Date

January 14, 2015

Institute for Environmental Education, Inc. 16 Upton Drive Wilmington, MA 01887

**Course Location** 

15-0026-106-260110 Certificate Number

Course Dates

January 14, 2015



# Appendix C

Asbestos Laboratory Analytical Reports and Chain-of-Custody Forms

Fuss & 0 146 Har Manche <b>Proj:</b> Peebles	EMSL Analytic 200 Route 130 North Cir Phone/Fax: (800) 220-36 <u>http://www.EMSL.com / c</u> Diedricksen D'Neill EnviroScience, LLC tford Road ster, CT 06040 Elementary School Feasib	naminson, N 75 / (856) 78 innasblab@	6-5974 EMSL.com	-	(860) ( (880) ( (888) 8 10/26/ 11/02/ 11/06/ Road, Bourne	2015 2015 , MA	041532674 ENVI54 20150666.A1E
			-	t Microscopy			
Client Sample ID: Sample Description:	01A-RCM-1026 Connector bldg roof/Gray flas		<u> </u>		·	Lab Sample ID:	041532674-0001
	Analyzed		Non-Asb	estos			
TEST	Date	Color	Fibrous Nor	n-Fibrous	Asbestos	Comment	
PLM TEM Grav. Reduction	11/03/2015 11/05/2015	Gray Gray	0% 0.0%	100%	None Detected		
Client Sample ID:	01B-RCM-1026					Lab Sample ID:	041532674-0002
Sample Description:		hing sealant					
	Analyzed		Non-Asb	estos			
TEST	Date	Color	Fibrous Nor		Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID: Sample Description:	02A-RCM-1026 Annex roof/Black flashing sea	alant				Lab Sample ID:	041532674-0003
	Analyzed		Non-Asb	estos			
TEST	Date	Color	Fibrous Nor		Asbestos	Comment	
PLM TEM Grav. Reduction	11/03/2015 11/05/2015	Black	15% 0.0%	85% 100%	None Detected		
		Didck	0.070	100 /0			
Client Sample ID: Sample Description:	02B-RCM-1026 Annex roof/Black flashing sea	alant				Lab Sample ID:	041532674-0004
	Analyzed		Non-Asb	estos			
TEST	Date	Color	Fibrous Nor	n-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Black	0%	100%	None Detected		
Client Sample ID: Sample Description:	03A-RCM-1026 Annex roof/Black built-up roo	fing				Lab Sample ID:	041532674-0005
	Analyzed		Non-Asb	estos			
TEST	Date	Color	Fibrous Nor	n-Fibrous	Asbestos	Comment	
PLM TEM Grav. Reduction	11/03/2015 11/05/2015	Black Black	25% 0.0%	75% 100%	None Detected		
Client Sample ID: Sample Description:	03B-RCM-1026 Connector roof/Black built-up	roofing				Lab Sample ID:	041532674-0006
	Analyzod		Non-Asb	estos			
TEST	Analyzed Date	Color		estos 1-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Black	25%	75%	None Detected		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

Polarized	Liaht	Microscopy
i olulizou	Light	morecopy

		P0	Diarized Lig	ght Microso	сору		· · · · · · · · · · · · · · · · · · ·
Client Sample ID:	04A-RCM-1026					Lab Sample ID:	041532674-0007
Sample Description:	Annex roof/Black hot mop						
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous M	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Black	35%	65%	None Detected		
TEM Grav. Reduction	11/05/2015	Black	0.0%	100%	None Detected		
Client Sample ID:	04B-RCM-1026					Lab Sample ID:	041532674-0008
Sample Description:	Connector roof/Black hot mo	р					
	Analyzed			sbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Black	10%	90%	None Detected		
Client Sample ID:	05A-RCM-1026					Lab Sample ID:	041532674-0009
Sample Description:	Annex roof/Gray asphalt roo	f shingle					
	Analyzed		Non-A	sbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM TEM Gray, Reduction	11/03/2015	Gray/Black	25%	75%	None Detected		
	11/05/2015	Gray/Black	0.0%	100%	None Detected		
Client Sample ID:	05B-RCM-1026					Lab Sample ID:	041532674-0010
Sample Description:	Main roof/Gray asphalt roof	shingle					
	Analyzed		Non-A	sbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray/Black	10%	90%	None Detected		
Client Sample ID:	06A-RCM-1026					Lab Sample ID:	041532674-0011
Sample Description:	Annex roof/White louver cau	lking					
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous M	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	White	0%	95%	5% Chrysotile		
Client Sample ID:	06B-RCM-1026					Lab Sample ID:	041532674-0012
Sample Description:	Annex roof/White louver cau	lking					
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous N	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015			Stop P	Positive (Not Analyzed)		
Client Sample ID:	07A-RCM-1026					Lab Sample ID:	041532674-0013
Sample Description:	Annex roof/White flashing se	ealant					
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous M	Non-Fibrous	Asbestos	Comment	
PLM TEM Grav. Reduction	11/03/2015 11/05/2015	White White	0% 0.0%	100% 100%	None Detected None Detected		
Client Sample ID:	07B-RCM-1026					Lab Sample ID:	041532674-0014
Sample Description:	Annex roof/White flashing se	ealant					
	Analyzed		Non-A	sbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	White	0%	100%	None Detected		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

		P	olarized L	ight Microso	сору		
Client Sample ID:	08A-RCM-1026			-		Lab Sample ID:	041532674-0015
Sample Description:	Annex roof/Gray door caulking						
TEST	Analyzed Date	Color		-Asbestos Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Gray	Pibrous 0%		4% Chrysotile	Comment	
		Glay	070	50 %	476 Chrysothe		
Client Sample ID:	08B-RCM-1026					Lab Sample ID:	041532674-0016
Sample Description:	Annex roof/Gray door caulking						
	Analyzed		Non	-Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015			Stop P	ositive (Not Analyzed)		
Client Sample ID:	09A-RCM-1026					Lab Sample ID:	041532674-0017
Sample Description:	Annex roof/Black roof felt b/w (	)5					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Black	60%	40%	None Detected		
Client Sample ID:	09B-RCM-1026					Lab Sample ID:	041532674-0018
Sample Description:	Main bldg roof/Black roof felt b	/w 05					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Black	60%	40%	None Detected		
Client Sample ID:	11A-RCM-1026					Lab Sample ID:	041532674-0019
Sample Description:	Attic/Tan pipe-thread sealant						
	Analyzed			-Asbestos		<b>.</b> .	
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM TEM Grav. Reduction	11/03/2015 11/05/2015	Tan Tan	0% 0.0%		None Detected	Very limited samp	
			0.070	10070		Lab Comple ID:	044522674 0020
Client Sample ID:	11B-RCM-1026					Lab Sample ID:	041532674-0020
Sample Description:	Cafeteria/Tan pipe-thread seal	ant					
	Analyzed		Non	-Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan	0%		None Detected		
Client Sample ID:	12A-RCM-1026					Lab Sample ID:	041532674-0021
Sample Description:	Above 1st floor classrooms/Gr	ov dravoll					•••••
cample Decemption.	Above 1st hoor classicorns/Gr	ay urywali					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Gray	15%	85%	None Detected		
Client Sample ID:	12B-RCM-1026					Lab Sample ID:	041532674-0022
Sample Description:	Above 1st floor classrooms/Gr	av drywall					
		., .,					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Brown/Gray	70%	30%	None Detected		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

		Po	larized L	ight Microsc.	ору		
Client Sample ID:	13A-RCM-1026					Lab Sample ID:	041532674-0023
Sample Description:	Room 7/24x24 red w/white splo	otch floor tile					
TEST	Analyzed Date	Color	Non Fibrous	-Asbestos Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	White/Red	0%		None Detected	Comment	
Client Sample ID:	13B-RCM-1026					Lab Sample ID:	041532674-0024
Sample Description:	Room 7/24x24 red w/white sple	otch floor tile				Lub Gumpie iD.	041002014 0024
	Room m24x24 red w/winte spic						
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	White/Red	0%	100%	None Detected		
Client Sample ID:	14A-RCM-1026					Lab Sample ID:	041532674-0025
Sample Description:	Room 5/24x24 tan w/white & b	rown splotch flo	oor tile				
TEST	Analyzed Date	Color	Non Fibrous	-Asbestos Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Tan/White	0%		None Detected	oonnient	
Client Sample ID:	14B-RCM-1026					Lab Sample ID:	041532674-0026
Sample Description:		rown onlotab fla	or tilo			Lub Gumple ID.	041002074-0020
bumple Description.	Room 5/24x24 tan w/white & b	rown spioten ne					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan/White	0%	100%	None Detected		
Client Sample ID:	15A-RCM-1026					Lab Sample ID:	041532674-0027
Sample Description:	Room 3/12x12 dark gray mottle	ed floor tile					
TEST	Analyzed	Color		-Asbestos	Achastas	Comment	
TEST PLM	Date 11/03/2015	Color Gray	Pibrous 0%	Non-Fibrous	Asbestos None Detected	Comment	
						Lab Sampla ID;	041522674 0028
Client Sample ID: Sample Description:	15B-RCM-1026					Lab Sample ID:	041532674-0028
Sample Description.	Room 3/12x12 dark gray mottle	ed floor tile					
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	17A-RCM-1026					Lab Sample ID:	041532674-0029
Sample Description:	Room 8/Black caulking assoc v	w/window & wal	l ballads				
	Analyzed			-Asbestos		•	
TEST PLM	Date 11/03/2015	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
TEM Grav. Reduction	11/05/2015	Black Black	0.0%		None Detected		
Client Sample ID:	17B-RCM-1026		0.070			Lab Sample ID:	041532674-0030
Sample Description:						Lab Sample ID.	041552074-0050
Sample Description:	Room 4/Black caulking assoc v	w/window & wal	Dallads				
	Analyzed		Non	-Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Black	0%	100%	None Detected		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

### Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via Polarized Light Microscopy

		FU	plarized L	.g	opy		
Client Sample ID:	18A-RCM-1026			-		Lab Sample ID:	041532674-0031
Sample Description:	Room 8/Tan caulking assoc	w/ window wall ba	allads				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Tan	0%	100%	None Detected		
TEM Grav. Reduction	11/05/2015	Tan	2.8%	97.2%	None Detected		
Client Sample ID:	18B-RCM-1026					Lab Sample ID:	041532674-0032
Sample Description:	Room 4/Tan caulking assoc	w/ window wall ba	allads				
	Analyzed		Non-	Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan	0%	100%	None Detected		
Client Sample ID:	19A-RCM-1026					Lab Sample ID:	041532674-0033
Sample Description:	Ground floor boys' room/Gra	ay ceramic floor til	e grout				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Gray	0%	100%	None Detected		
Client Sample ID:	19B-RCM-1026					Lab Sample ID:	041532674-0034
Sample Description:	1st floor boys' room/Gray ce	ramic floor tile arc	out				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	<u>^</u>					
	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	20A-RCM-1026-Window Sill	Gray	0%	100%	None Detected	Lab Sample ID:	041532674-0035
	20A-RCM-1026-Window Sill	·····		100%	None Detected	Lab Sample ID:	041532674-0035
Client Sample ID:		·····	0%	100%	None Detected	Lab Sample ID:	041532674-0035
Client Sample ID:	20A-RCM-1026-Window Sill	·····		100%	None Detected	Lab Sample ID:	041532674-0035
Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite v	·····			None Detected	Lab Sample ID:	041532674-0035
Client Sample ID: Sample Description: TEST	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed	vindowsill	Non-	Asbestos			041532674-0035
Client Sample ID: Sample Description: TEST PLM	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date	vindowsill Color	Non- Fibrous	Asbestos Non-Fibrous	Asbestos		041532674-0035
Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026	vindowsill Color Tan/Black	Non- Fibrous	Asbestos Non-Fibrous	Asbestos	Comment	
Client Sample ID: Sample Description: TEST PLM	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015	vindowsill Color Tan/Black	Non- Fibrous	Asbestos Non-Fibrous	Asbestos	Comment	
Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026	vindowsill Color Tan/Black	Non- Fibrous 0%	Asbestos Non-Fibrous	Asbestos	Comment	
Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi	vindowsill Color Tan/Black	Non- Fibrous 0%	Asbestos Non-Fibrous 100%	Asbestos	Comment	
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed	vindowsill Color Tan/Black ndowsill	Non- Fibrous 0% Non-	Asbestos Non-Fibrous 100% Asbestos	Asbestos None Detected	Comment Lab Sample ID:	
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015	vindowsill Color Tan/Black ndowsill Color	Non- Fibrous 0% Non- Fibrous	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos	Comment Lab Sample ID:	
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 20B-RCM-1026 Room 4/Black composite w Analyzed Date 214-RCM-1026	vindowsill Color Tan/Black ndowsill Color Black	Non- Fibrous 0% Non- Fibrous 0%	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite v Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015	vindowsill Color Tan/Black ndowsill Color Black	Non- Fibrous 0% Non- Fibrous 0%	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 20B-RCM-1026 Room 4/Black composite w Analyzed Date 214-RCM-1026	vindowsill Color Tan/Black ndowsill Color Black	Non- Fibrous 0% Non- Fibrous 0% e adhesive	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015 21A-RCM-1026 Ground floor boys' room/Gra	vindowsill Color Tan/Black ndowsill Color Black	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non-	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100%	Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015 21A-RCM-1026 Ground floor boys' room/Gra	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non-	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100%	Asbestos None Detected Asbestos None Detected	Comment Lab Sample ID: Comment Lab Sample ID:	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 21A-RCM-1026 Ground floor boys' room/Gra Analyzed Date 11/03/2015	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til Color	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non- Fibrous	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015 21A-RCM-1026 Ground floor boys' room/Gra Analyzed Date 11/03/2015 21B-RCM-1026	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til Color Gray	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non- Fibrous 0%	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment Lab Sample ID:	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 21A-RCM-1026 Ground floor boys' room/Gra Analyzed Date 11/03/2015	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til Color Gray	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non- Fibrous 0%	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015 21A-RCM-1026 Ground floor boys' room/Gra 11/03/2015 21B-RCM-1026 1st floor boys' room/Gray ce	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til Color Gray	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non- Fibrous 0%	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100%	Asbestos None Detected Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0036
Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	20A-RCM-1026-Window Sill Room 11/Black composite w Analyzed Date 11/03/2015 20B-RCM-1026 Room 4/Black composite wi Analyzed Date 11/04/2015 21A-RCM-1026 Ground floor boys' room/Gra Analyzed Date 11/03/2015 21B-RCM-1026	vindowsill Color Tan/Black ndowsill Color Black ay ceramic floor til Color Gray	Non- Fibrous 0% Non- Fibrous 0% e adhesive Non- Fibrous 0% hesive Non-	Asbestos Non-Fibrous 100% Asbestos Non-Fibrous 100% Asbestos Non-Fibrous	Asbestos None Detected Asbestos None Detected Asbestos	Comment Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0036



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

Client Sample ID:       22A-RCM-1026       Lab Sample ID:       041532674-0039         Sample Description:       Ground floor boys' room/Dark gray ceramic wall tile adhesive       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected       Lab Sample ID:       041532674-0040         Client Sample ID:       22B-RCM-1026       Lab Sample ID:       041532674-0040         Sample Description:       1st floor boys' room/Dark gray ceramic wall tile adhesive       Non-Asbestos       Lab Sample ID:       041532674-0040         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Asbestos       Comment			P	olarized L	ight Microsc	ору		
TEST         Data         Color         Florous         Anabestos         Comment           ELM         11032/015         Gray         0/8         100%         Non-Abbestos         Comment           ELM         11032/015         Gray         0/8         100%         Non-Detected         Lab Sample ID:         041532674-0040           Sample Description:         151 floor boys' room/Dark gray ceramic wall tile adhealve         Lab Sample ID:         041532674-0040           ELM         11002/015         Gray         0/9         100%         Non-Abbestos         Comment           FEST         Date         Color         Fibrous         Non-Abbestos         Comment         Lab Sample ID:         041532674-0041           Sample Description:         22A-RCM-1026         Gound floor boys' room/Gray ceramic wall tile grout         Lab Sample ID:         041532674-0042           Sample Description:         22A-RCM-1026         Color         Fibrous         Abbestos         Comment           FEST         Date         Color         Fibrous         Non-Abbestos         Comment         Lab Sample ID:         041532674-0042           Sample Description:         248-RCM-1026         Color         Fibrous         Non-Abbestos         Comment           FEST	Client Sample ID:	22A-RCM-1026			-		Lab Sample ID:	041532674-0039
TEST         Date         Color         Fibrous         Non-Fibrous         Asbestos         Comment           PLM         110332015         Gray         0%         100%         None Detected           Gener Sample Description         128 FRCM-1020         Gray         0%         100%         None Detected           Sample Description         110042015         Gray         0%         None Abbestos         Comment           FEST         Date         Golor         Fibrous         None-Fibrous         Asbestos         Comment           Sample Description         23A-FICM-1020         Gray         0%         100%         None Detected           Sample Description         23A-FICM-1020         Gray         0%         100%         None Detected           Sample Description         Graun floor boys' room/Gray caramic wall tile grout         Lab Sample D:         041532674-0042           Sample Description         110042015         Gray         0%         None-Abbestos         Comment           FEST         Date         Color         Fibrous Non-Fibrous         Asbestos         Comment           Clant Sample Description         110042015         Gray         0%         100%         None Detected           Clant Sample Description<	Sample Description:	Ground floor boys' room/Da	ark gray ceramic w	all tile adhesive	e			
TEST         Date         Color         Fibrous         Non-Fibrous         Asbestos         Comment           PLM         110332015         Gray         0%         100%         None Detected           Gener Sample Description         128 FRCM-1020         Gray         0%         100%         None Detected           Sample Description         110042015         Gray         0%         None Abbestos         Comment           FEST         Date         Golor         Fibrous         None-Fibrous         Asbestos         Comment           Sample Description         23A-FICM-1020         Gray         0%         100%         None Detected           Sample Description         23A-FICM-1020         Gray         0%         100%         None Detected           Sample Description         Graun floor boys' room/Gray caramic wall tile grout         Lab Sample D:         041532674-0042           Sample Description         110042015         Gray         0%         None-Abbestos         Comment           FEST         Date         Color         Fibrous Non-Fibrous         Asbestos         Comment           Clant Sample Description         110042015         Gray         0%         100%         None Detected           Clant Sample Description<		Analyzed		Non	-Asbestos			
Client Sample ID:     228-RCM-1026     Lab Sample ID:     041532674-0040       Sample Description:     TEST     Date     Color     Fibrous     Anabyzed     Non-Asbestos       PLM     11/04/2015     Gray     O'S     100%     None Detected     Lab Sample ID:     041532674-0041       Sample Description:     Ground floor boys' room/Gray ceramic wall tile grout     Anabyzed     Non-Asbestos     Lab Sample ID:     041532674-0041       Sample Description:     Ground floor boys' room/Gray ceramic wall tile grout     Anabyzed     Non-Asbestos     Comment       FEM     11/04/2015     Gray     0%     100%     None Detected       Client Sample ID:     238-RCM-1026     Lab Sample ID:     041532674-0041       Sample Description:     11/04/2015     Gray     0%     100%       TEST     Date     Color     Fibrous     Non-Asbestos       TEST     Date     Color     Fibrous     Asbestos     Comment       PLM     11/04/2015     Gray     0%     100%     None Detected       Grant Sample ID:     244-RCM-1026     Lab Sample ID:     041532674-0043       Sample Description:     11/04/2015     Gray     0%     100%       TEST     Date     Color     Fibrous     Non-Asbestos     Comment <td>TEST</td> <td>-</td> <td>Color</td> <td></td> <td></td> <td>Asbestos</td> <td>Comment</td> <td></td>	TEST	-	Color			Asbestos	Comment	
Sample Description:         It thor boys' room/Dark gray oranic wall tile adhesive           TEST         Date         Color         Fibrous         Non-Asbestos         Roment           PIM         1104/2015         Gray         0.%         100%         None Detected           Client Sample Description:         23A-RCM-1028         Lab Sample Description:         Color         Fibrous         Non-Asbestos         Comment         M1532674-0041           Sample Description:         Ground floor boys' room/Gray ceramic wall tile grout         Asbestos         Comment         Comment         Color           PIM         1103/2015         Gray         0%         100%         None Detected         041532674-0042           Client Sample Description:         23B-RCM-1026         Lab Sample Description:         Color         Fibrous         Non-Fibrous         Asbestos         Comment         Fibrous         Sample Description:         041532674-0042           Sample Description:         Test floor bays' room/Gray ceramic wall tile grout         Lab Sample Description:         Color         Fibrous         Asbestos         Comment         Fibrous         Sample Description:         Color         Fibrous         Non-Fibrous         Asbestos         Comment         Color         Fibrous         Non-Fibrous         Asbestos <td>PLM</td> <td>11/03/2015</td> <td>Gray</td> <td>0%</td> <td>100%</td> <td>None Detected</td> <td></td> <td></td>	PLM	11/03/2015	Gray	0%	100%	None Detected		
Sample Description:       task toor boy's room/Dark gray ceramic wall tille adhesive         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       1104/2015       Gray       0.%       100%       Non-Dataceted         Cillent Sample Description:       224-RCM-102       Lab Sample Ceramic wall tille grout       Lab Sample Description:       041532674-0041         Sample Description:       Test       Date       Color       Fibrous       Non-Asbestos       Comment       -         PLM       1100/2015       Gray       0.%       100%       None Detected       041532674-0042         Sample Description:       238-RCM-1026       Golor       Fibrous       Non-Asbestos       Comment       -         FEST       Date       Color       Fibrous       Non-Asbestos       Comment       -         REST       Date       Color       Fibrous       Non-Asbestos       Comment       -         REST       Date       Color       Fibrous       Non-Mathesitos       Comment       -         Sample Description:       Gray       0.%       100%       None Detected       -       -         Color       Fibrous       Non-Asbestos       Comment       Lab Sa	Client Sample ID:	22B-RCM-1026					Lab Sample ID:	041532674-0040
TESTDateColorFibrousAsbestosCommentPLM1104/2015Gray0%100%None DetectedClam Sample Description:Gravent floor boys' room/Gray ceramic well tile groutLab Sample De041532574-0041Sample Description:Ground floor boys' room/Gray ceramic well tile groutNon-AsbestosCommentTESTDateColorFibrousNon-AsbestosCommentPLM1103/2015Gray0%100%None DetectedClent Sample De23B-RCM-1026Lab Sample De4452574-0042Sample Description:1st floor boys' room/Gray ceramic well tile groutNon-AsbestosCommentTESTDateColorFibrous Non-FibrousAsbestosCommentPLM1104/2015Gray0%100%None DetectedClent Sample De24A-RCM-1026Lab Sample ID:041532574-0043Sample Description:Ground floor boys' nom/Tan interior window calkingLab Sample ID:041532574-0043TESTDateColorFibrous Non-FibrousAsbestosCommentPLM1104/2015Tan0%100%None DetectedClent Sample De24A-RCM-1026Lab Sample ID:041532574-0043Sample Description:11052015Tan0%100%None DetectedFLM11032015Tan0%100%None DetectedColorFLM11042015Gray0%100%None DetectedColorFLM11042015Gr	-	1st floor boys' room/Dark gi	ray ceramic wall til	e adhesive				
TESTDateColorFibrousAsbestosCommentPLM1104/2015Gray0%100%None DetectedClam Sample Description:Gravent floor boys' room/Gray ceramic well tile groutLab Sample De041532574-0041Sample Description:Ground floor boys' room/Gray ceramic well tile groutNon-AsbestosCommentTESTDateColorFibrousNon-AsbestosCommentPLM1103/2015Gray0%100%None DetectedClent Sample De23B-RCM-1026Lab Sample De4452574-0042Sample Description:1st floor boys' room/Gray ceramic well tile groutNon-AsbestosCommentTESTDateColorFibrous Non-FibrousAsbestosCommentPLM1104/2015Gray0%100%None DetectedClent Sample De24A-RCM-1026Lab Sample ID:041532574-0043Sample Description:Ground floor boys' nom/Tan interior window calkingLab Sample ID:041532574-0043TESTDateColorFibrous Non-FibrousAsbestosCommentPLM1104/2015Tan0%100%None DetectedClent Sample De24A-RCM-1026Lab Sample ID:041532574-0043Sample Description:11052015Tan0%100%None DetectedFLM11032015Tan0%100%None DetectedColorFLM11042015Gray0%100%None DetectedColorFLM11042015Gr		Analyzed		Non	-Asbestos			
Citent Sample ID:       23A-RCM-1026       Lab Sample ID:       041532674-0041         Sample Description:       Ground floor boys' room/Gray caramic wall tile grout       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Client Sample ID:       23B-RCM-1026       Lab Sample ID:       041532674-0042         Sample Description:       1st floor boys' room/Gray caramic wall tile grout       Lab Sample ID:       041532674-0042         Sample Description:       1st floor boys' room/Gray caramic wall tile grout       Lab Sample ID:       041532674-0042         Sample Description:       1st floor boys' room/Gray caramic wall tile grout       Lab Sample ID:       041532674-0042         TEST       Date       Color       Fibrous Non-Fibrous       Asbestos       Comment         PLM       11/04/2015       Gray       0.0%       100%       None Detected         Client Sample ID:       24A-RCM-1026       Tan       0.0%       None Detected         FEST       Date       Color       Fibrous Non-Fibrous       Asbestos       Comment         FIM       11/05/2015       Tan       0.0%       None Detect	TEST	-	Color			Asbestos	Comment	
Sample Description:       Cound floor boys' room/Gray ceramic wall tile grout         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Clenr Sample ID:       238-RCM-1026       Lab Sample ID:       041532674-0042         Sample Description:       1st floor boys' room/Gray ceramic wall tile grout       Lab Sample ID:       041532674-0042         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         FLM       11/04/2015       Gray       0%       None Detected       041532674-0042         Clenr Sample ID:       24A-RCM-1026       Lab Sample ID:       041532674-0043       041532674-0043         Sample Description:       Ground floor boys' room/Tan interior window caulking       Lab Sample ID:       041532674-0043         TEST       Date       Color       Fibrous Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Tan       0.0%       None Detected       Comment         Clenr Sample ID:       24B-RCM-1026       Lab Sample ID:       041532674-0044         Sample Description:       1st floor boys' room/Tan interior window caulking       Lab Sample ID:       041532674-0044	PLM	11/04/2015	Gray	0%	100%	None Detected		
Sample Description:     Ground floor boys' room/Gray ceramic wall tile grout       TEST     Date     Color     Fibrous     Non-Asbestos     Comment       PLM     11/03/2015     Gray     0%     100%     None Detected       Clent Sample Dit:     238-RCM-1026     Lab Sample D:     041532674-0042       Sample Description:     11/04/2015     Gray     0%     100%     None Detected       TEST     Date     Color     Fibrous     Non-Asbestos     Comment       PLM     11/04/2015     Gray     0%     100%     None Detected       Clent Sample Di:     24A-RCM-1026     Lab Sample ID:     041532674-0043       Sample Description:     Ground floor boys' room/Tan interior window caulking     Lab Sample ID:     041532674-0043       TEST     Date     Color     Fibrous     Non-Asbestos     Comment       TEST     Date     Color     Fibrous     Non-Asbestos     Co	Client Sample ID:	23A-RCM-1026					Lab Sample ID:	041532674-0041
TESTDateColorFibrousNon-FibrousAbbestosCommentPLM11/03/2015Gray0%100%None DetectedCilent Sample ID:23B-RCM-1026Lab Sample ID:041532674-0042Sample Description:11/04/2015Gray0%100%None DetectedTESTDateColorFibrousNon-AsbestosCommentPLM11/04/2015Gray0%100%None DetectedClient Sample ID:24A-RCM-1026ColorFibrousNon-AsbestosCommentSample Description:Cround from boys' room/Tan interior window caulkingNon-AsbestosCommentLab Sample ID:Sample Description:ColorFibrousNon-AsbestosCommentCommentFESTDateColorFibrousNon-AsbestosCommentCommentPLM11/05/2015Tan0.0%100%None DetectedCommentPLM11/05/2015Tan0.0%100%None DetectedCommentSample Description:11/06/2015Tan0.0%100%None DetectedSample Description:11/06/2015GrayTan0%100%None DetectedClient Sample ID:26A-RCM-1026Lab Sample ID:26A-RCM-1026Lab Sample ID:Sample Description:11/06/2015GrayTan0%100%None DetectedClient Sample ID:25A-RCM-1026Sample Description:Lab Sample ID:26A-RCM-1026Sample Description:11/06/2015 <td>-</td> <td></td> <td>ay ceramic wall til</td> <td>e grout</td> <td></td> <td></td> <td>· · · · · ·</td> <td></td>	-		ay ceramic wall til	e grout			· · · · · ·	
TESTDateColorFibrousNon-FibrousAbbestosCommentPLM11/03/2015Gray0%100%None DetectedCilent Sample ID:23B-RCM-1026Lab Sample ID:041532674-0042Sample Description:11/04/2015Gray0%100%None DetectedTESTDateColorFibrousNon-AsbestosCommentPLM11/04/2015Gray0%100%None DetectedClient Sample ID:24A-RCM-1026ColorFibrousNon-AsbestosCommentSample Description:Cround from boys' room/Tan interior window caulkingNon-AsbestosCommentLab Sample ID:Sample Description:ColorFibrousNon-AsbestosCommentCommentFESTDateColorFibrousNon-AsbestosCommentCommentPLM11/05/2015Tan0.0%100%None DetectedCommentPLM11/05/2015Tan0.0%100%None DetectedCommentSample Description:11/06/2015Tan0.0%100%None DetectedSample Description:11/06/2015GrayTan0%100%None DetectedClient Sample ID:26A-RCM-1026Lab Sample ID:26A-RCM-1026Lab Sample ID:Sample Description:11/06/2015GrayTan0%100%None DetectedClient Sample ID:25A-RCM-1026Sample Description:Lab Sample ID:26A-RCM-1026Sample Description:11/06/2015 <td></td> <td></td> <td>-</td> <td>-</td> <td></td> <td></td> <td></td> <td></td>			-	-				
PLM       11/03/2015       Gray       0%       100%       None Detected         C/lent Sample /D:       23B-RCM-1026       Lab Sample /D:       041532674-0042         Sample Description:       1st floor boys' room/Gray caramic wall tile grout       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       11/04/2015       Gray       0%       10%       None Detected         Client Sample ID:       24A-RCM-1026       Lab Sample ID:       041532674-0043         Sample Description:       Ground floor boys' room/Tan interior window caulking       Lab Sample ID:       041532674-0043         Sample Description:       Ground floor boys' room/Tan interior window caulking       Comment       Lab Sample ID:       041532674-0043         TEST       Date       Color       Fibrous       Non-Asbestos       Comment       Distributica         PIM       11/05/2015       Tan       0.0%       100%       None Detected       Comment         Client Sample ID:       24B-RCM-1026       Lab Sample ID:       041532674-0044       Sample ID:       041532674-0044         Sample Description:       11/05/2015       Tan       0.0%       100%       None Detected       Comment <td></td> <td>-</td> <td></td> <td></td> <td></td> <td>A . I</td> <td>0</td> <td></td>		-				A . I	0	
Cilient Sample ID:     23B-RCM-1026     Lab Sample ID:     041532674-0042       Sample Description:     1st floor boys' room/Gray ceramic wall tile grout     Analyzed     Non-Asbestos     Comment       TEST     Date     Color     Fibrous     Non-Asbestos     Comment       PLM     11/04/2015     Gray     0%     100%     None Detected       Client Sample ID:     24A-RCM-1026     Lab Sample ID:     041532674-0043       Sample Description:     Ground floor boys' room/Tan interior window caulking     Analyzed     Non-Asbestos       TEST     Date     Color     Fibrous     Non-Fibrous     Asbestos       PLM     11/03/2015     Tan     0%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0043       Sample Description:     11/05/2015     Tan     0.0%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     1st floor boys' room/Tan interior window caulking     Non-Asbestos     Comment       PLM     11/04/2015     Gray/Tan     0%     100%     None Detected       Client Sample ID:     25A-RCM-1026     Lab Sample ID:     041532674-0045       Sample Description:     1st floor boys' roo							Comment	
Sample Description:         Ist filtor boys' room/Gray ceramic wall tile grout           Sample Description:         Ist filtor boys' room/Gray ceramic wall tile grout           TEST         Date         Color         Fibrous Non-Fibrous         Asbestos         Comment           PLM         11/04/2015         Gray         0%         100%         None Detected           Client Sample ID:         24A-RCM-1026         Lab Sample ID:         041532674-0043           Sample Description:         Ground floor boys' room/Tan interior window caulking         Non-Asbestos         Comment           TEST         Date         Color         Fibrous Non-Fibrous         Asbestos         Comment           PLM         11/05/2015         Tan         0.0%         100%         None Detected           TEST         Date         Color         Fibrous Non-Fibrous         Asbestos         Comment           PLM         11/05/2015         Tan         0.0%         100%         None Detected           Sample Description:         1st floor boys' room/Tan interior window caulking         Lab Sample ID:         041532674-0043           Sample Description:         1st floor boys' room/Can interior window caulking         Lab Sample ID:         041532674-0045           TEST         Date         Color			Glay	0 /8	100 /8			
Analyzed         Non-Asbestos         Comment           PLM         11/04/2015         Gray         0%         100%         None Detected           Client Sample ID:         24A-RCM-1026         Lab Sample ID:         041532674-0043           Sample Description:         Ground floor boys' room/Tan interior window caulking          Lab Sample ID:         041532674-0043           TEST         Date         Color         Fibrous         Non-Asbestos         Comment           PLM         11/03/2015         Tan         0.%         100%         None Detected           TEST         Date         Color         Fibrous         None Detected            Client Sample ID:         248-RCM-1026         Lab Sample ID:         041532674-0044            Sample Description:         1st floor boys' room/Tan interior window caulking         Lab Sample ID:         041532674-0044           Sample Description:         1st floor boys' room/Gray mud set         Lab Sample ID:         041532674-0044           Sample Description:         1st floor boys' room/Gray mud set         Lab Sample ID:         041532674-0045           Sample Description:         1st floor boys' room/Gray mud set         Lab Sample ID:         041532674-0045           Sample Description:         11051/2015 </td <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Lab Sample ID:</td> <td>041532674-0042</td>	-						Lab Sample ID:	041532674-0042
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/04/2015Gray0%100%None DetectedClient Sample ID:24A-RCM-1026Lab Sample ID:CatabaseCommentSample Description:Ground floor boys' room/Tan interior window caulkingNon-AsbestosCommentTESTDateColorFibrousNon-AsbestosCommentPLM11/03/2015Tan0.0%100%None DetectedClient Sample ID:24B-RCM-1026Tan0.0%100%None DetectedSample Description:11/05/2015Tan0.0%100%None DetectedClient Sample ID:24B-RCM-1026Lab Sample ID:041532674-0044Sample Description:1st floor boys' room/Tan interior window caulkingLab Sample ID:041532674-0044Sample Description:25A-RCM-1026Lab Sample ID:041532674-0044Sample Description:1st floor boys' room/Gray mud setLab Sample ID:041532674-0045Sample Description:11/05/2015Gray0%100%None DetectedClient Sample ID:25A-RCM-1026Lab Sample ID:041532674-0045Sample Description:1st floor boys' room/Gray mud setLab Sample ID:041532674-0045TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedUab Sample ID:Client Sample ID:25B-RCM-1026Gray0%100% <td>Sample Description:</td> <td>1st floor boys' room/Gray co</td> <td>eramic wall tile gro</td> <td>out</td> <td></td> <td></td> <td></td> <td></td>	Sample Description:	1st floor boys' room/Gray co	eramic wall tile gro	out				
PLM       11/04/2015       Gray       0%       100%       None Detected         Client Sample ID:       24A-RCM-1026       Lab Sample ID:       041532674-0043         Sample Description:       Ground floor boys' room/Tan interior window caulking       Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Tan       0.%       100%       None Detected         Client Sample ID:       24B-RCM-1026       Lab Sample ID:       041532674-0044         Sample Description:       11/05/2015       Tan       0.%       100%       None Detected         Sample Description:       24B-RCM-1026       Lab Sample ID:       041532674-0044         Sample Description:       1st floor boys' room/Tan interior window caulking       Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/04/2015       Gray/Tan       0%       100%       None Detected       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Lab Sample ID:       041532674-0045       Lab Sample ID:       041532674-0045 <t< td=""><td></td><td>Analyzed</td><td></td><td>Non</td><td>-Asbestos</td><td></td><td></td><td></td></t<>		Analyzed		Non	-Asbestos			
Client Sample ID:     24A-RCM-1026     Lab Sample ID:     041532674-0043       Sample Description:     Analyzed     Non-Asbestos     Comment       TEST     Date     Color     Fibrous     Non-Asbestos       PLM     11/03/2015     Tan     0.0%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0043       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     11/05/2015     Tan     0.0%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     1st floor boys' room/Tan interior window caulking     Lab Sample ID:     041532674-0044       Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     1st floor boys' room/Tan interior window caulking     Lab Sample ID:     041532674-0045       TEST     Date     Color     Fibrous     Non-Fibrous     Asbestos     Comment       PLM     11/04/2015     Gray/Tan     0%     100%     None Detected       Sample Description:     1st floor boys' room/Gray mud set     Lab Sample ID:     041532674-0045       Sample Description:     Sat floor boys' room/Gray mud set     Lab Sample	TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
Sample Description:     Ground floor boys' room/Tan interior window caulking       Analyzed     Non-Asbestos       TEST     Date     Color       PLM     11/03/2015     Tan     0.0%     100%     None Detected       TEM Grav. Reduction     11/05/2015     Tan     0.0%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     1st floor boys' room/Tan interior window caulking     Non-Asbestos     Comment       TEST     Date     Color     Fibrous     Non-Fibrous     Asbestos     Comment       PLM     11/04/2015     Gray/Tan     0%     100%     None Detected     41532674-0044       Sample Description:     1st floor boys' room/Gray mud seut     Ist floor boys' room/Gray mud set     Asbestos     Comment       PLM     11/04/2015     Gray     0%     100%     None Detected       Sample Description:     1st floor boys' room/Gray mud set     Lab Sample ID:     041532674-0045       Sample Description:     1st floor boys' room/Gray mud set     Lab Sample ID:     041532674-0045       Sample Description:     11/03/2015     Gray     0%     Non-Fibrous     Asbestos       TEST     Date     Color     Fibrous     Non-Fibrous     Asbest	PLM	11/04/2015	Gray	0%	100%	None Detected		
Analyzed     Non-Asbestos       TEST     Date     Color     Fibrous     Non-Fibrous     Asbestos     Comment       PLM     11/03/2015     Tan     0%     100%     None Detected       TEM Grav. Reduction     11/05/2015     Tan     0%     100%     None Detected       TEM Grav. Reduction     11/05/2015     Tan     0.%     100%     None Detected       TEM Grav. Reduction     11/05/2015     Tan     0.%     100%     None Detected       Client Sample ID:     24B-RCM-1026     Lab Sample ID:     041532674-0044       Sample Description:     1st floor boys' room/Tan interior window caulking     Asbestos     Comment       TEST     Date     Color     Fibrous     Non-Asbestos     Comment       TEST     Date     Color     Fibrous     None Detected       Client Sample ID:     25A-RCM-1026     Lab Sample ID:     041532674-0045       Sample Description:     1st floor boys' room/Gray mud set     Lab Sample ID:     041532674-0045       Sample Description:     1st floor boys' room/Gray mud set     Lab Sample ID:     041532674-0045       Sample Description:     11/03/2015     Gray     0%     100%     None Detected       Client Sample ID:     25B-RCM-1026     Lab Sample ID:	Client Sample ID:	24A-RCM-1026					Lab Sample ID:	041532674-0043
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Tan0%100%None DetectedTEM Grav. Reduction11/05/2015Tan0.0%100%None DetectedClient Sample ID:24B-RCM-1026Lab Sample ID:041532674-0044Sample Description:1st floor boys' room/Tan interior window caulkingLab Sample ID:041532674-0044TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/04/2015Gray/Tan0%100%None DetectedClient Sample ID:25A-RCM-1026Lab Sample ID:041532674-0045Sample Description:1st floor boys' room/Gray mud setLab Sample ID:041532674-0045Client Sample ID:25B-RCM-1026Lab Sample ID:041532674-0045TESTDateColorFibrousNon-AsbestosCommentPLM11/03/2015Gray0%100%None DetectedTESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046<	Sample Description:	Ground floor boys' room/Ta	n interior window	caulking				
PLM       11/03/2015       Tan       0%       100%       None Detected         TEM Grav. Reduction       11/05/2015       Tan       0.0%       100%       None Detected         Client Sample ID:       24B-RCM-1026       Lab Sample ID:       0.41532674-0044         Sample Description:       1st floor boys' room/Tan interior window caulking       Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/04/2015       Gray/Tan       0%       100%       None Detected          Client Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Lab Sample ID:       041532674-0045         Sample Description:       11/04/2015       Gray       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected       Lab Sample ID:       041532674-0046         Gray       0%       100%       Non-Fibrous       Asbestos       Comment       Comment         PLM       11		Analyzed		Non	-Asbestos			
TEM Grav. Reduction       11/05/2015       Tan       0.0%       100%       None Detected         Client Sample ID:       24B-RCM-1026       Lab Sample ID:       041532674-0044         Sample Description:       1st floor boys' room/Tan interior window caulking       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/04/2015       Gray/Tan       0%       100%       None Detected       Lab Sample ID:       041532674-0045         Client Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Non-Asbestos       Comment         FEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected       Lab Sample ID:       041532674-0045         Sample Description:       Test       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected       Lab Sample ID:       041532674-0046         Sample ID:       25B-RCM-1026 </td <td>TEST</td> <td>Date</td> <td>Color</td> <td>Fibrous</td> <td>Non-Fibrous</td> <td>Asbestos</td> <td>Comment</td> <td></td>	TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
Client Sample ID:       24B-RCM-1026       Lab Sample ID:       041532674-0044         Sample Description:       1st floor boys' room/Tan interior window caulking       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       11/04/2015       Gray/Tan       0%       100%       None Detected         Client Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Lab Sample ID:       041532674-0045         Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Lab Sample ID:       041532674-0045         TEST       Date       Color       Fibrous       Non-Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Client Sample ID:       25B-RCM-1026       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Lab Sample ID:       041532674-0046         Sample Description:<	PLM	11/03/2015	Tan	0%	100%	None Detected		
Sample Description: 1st floor boys' room/Tan interior window caulking         Analyzed       Non-Asbestos       Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/04/2015       Gray/Tan       0%       100%       None Detected       Lab Sample ID:       041532674-0045         Client Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set         Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected	TEM Grav. Reduction	11/05/2015	Tan	0.0%	100%	None Detected		
AnalyzedNon-AsbestosTESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/04/2015Gray/Tan0%100%None DetectedClient Sample ID:25A-RCM-1026Lab Sample ID:041532674-0045Sample Description:1st floor boys' room/Gray mud setNon-AsbestosCommentTESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Client Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046TESTDateColorFibrousNon-AsbestosCommentTESTDateColorFibrousNon-FibrousAsbestosComment	Client Sample ID:	24B-RCM-1026					Lab Sample ID:	041532674-0044
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/04/2015Gray/Tan0%100%None DetectedClient Sample ID:25A-RCM-1026Lab Sample ID:041532674-0045Sample Description:1st floor boys' room/Gray mud setNon-AsbestosCommentTESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Gray0%100%None DetectedPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046TESTDateColorFibrousNon-AsbestosComment	Sample Description:	1st floor boys' room/Tan int	erior window caul	king				
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/04/2015Gray/Tan0%100%None DetectedClient Sample ID:25A-RCM-1026Lab Sample ID:041532674-0045Sample Description:1st floor boys' room/Gray mud setNon-AsbestosCommentTESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Gray0%100%None DetectedPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setLab Sample ID:041532674-0046TESTDateColorFibrousNon-AsbestosComment		Analyzed		Non	-Asbestos			
Client Sample ID:       25A-RCM-1026       Lab Sample ID:       041532674-0045         Sample Description:       1st floor boys' room/Gray mud set       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Client Sample ID:       25B-RCM-1026       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Non-Asbestos         TEST       Date       Non-Asbestos       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Lab Sample ID:       041532674-0046         TEST       Date       Color       Fibrous       Non-Asbestos       Comment	TEST		Color	Fibrous	Non-Fibrous	Asbestos	Comment	
Sample Description: 1st floor boys' room/Gray mud set         Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Client Sample ID:       25B-RCM-1026       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment	PLM	11/04/2015	Gray/Tan	0%	100%	None Detected		
Sample Description: 1st floor boys' room/Gray mud set         Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment         PLM       11/03/2015       Gray       0%       100%       None Detected         Client Sample ID:       25B-RCM-1026       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Non-Asbestos       Comment         TEST       Date       Color       Fibrous       Non-Fibrous       Asbestos       Comment	Client Sample ID:	25A-RCM-1026					Lab Sample ID:	041532674-0045
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setImage: Color Sample ID:041532674-0046AnalyzedNon-AsbestosTESTDateColorFibrousNon-FibrousAsbestos	-		nud set				·	
TESTDateColorFibrousNon-FibrousAsbestosCommentPLM11/03/2015Gray0%100%None DetectedClient Sample ID:25B-RCM-1026Lab Sample ID:041532674-0046Sample Description:Ground floor boys' room/Gray mud setImage: Color Sample ID:041532674-0046AnalyzedNon-AsbestosTESTDateColorFibrousNon-FibrousAsbestos								
PLM     11/03/2015     Gray     0%     100%     None Detected       Client Sample ID:     25B-RCM-1026     Lab Sample ID:     041532674-0046       Sample Description:     Ground floor boys' room/Gray mud set     Analyzed     Non-Asbestos       TEST     Date     Color     Fibrous     Asbestos     Comment	TEST	-	Cala.			Ashartas	Comment	
Client Sample ID:       25B-RCM-1026       Lab Sample ID:       041532674-0046         Sample Description:       Ground floor boys' room/Gray mud set       Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Asbestos       Comment							Comment	
Sample Description:       Ground floor boys' room/Gray mud set         Analyzed       Non-Asbestos         TEST       Date       Color       Fibrous       Asbestos			Giay	0%	100%			
Analyzed Non-Asbestos TEST Date Color Fibrous Non-Fibrous Asbestos Comment	-	25B-RCM-1026					Lab Sample ID:	041532674-0046
TEST Date Color Fibrous Non-Fibrous Asbestos Comment	Sample Description:	Ground floor boys' room/Gr	ay mud set					
TEST Date Color Fibrous Non-Fibrous Asbestos Comment		Analvzed		Non	-Asbestos			
	TEST	-	Color			Asbestos	Comment	



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

Polarized Light Microscopy
----------------------------

		Po	Diarized L	ight Microso	сору		
Client Sample ID:	26A-RCM-1026					Lab Sample ID:	041532674-0047
Sample Description:	Annex-2nd floor boys' room/Gra	ay mud set					
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Gray	0%	100%	None Detected		
Client Sample ID:	26B-RCM-1026					Lab Sample ID:	041532674-0048
Sample Description:	Annex-1st floor boys' room/Gra	y mud set					
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	27A-RCM-1026					Lab Sample ID:	041532674-0049
Sample Description:	Connector hallway-1st/1x1 whit	e fissured spli	ned ceiling tile				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	White	90%	10%	None Detected		
Client Sample ID:	27B-RCM-1026					Lab Sample ID:	041532674-0050
Sample Description:	Connector hallway-Ground/1x1	white fissured	splined ceiling	tile			
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	White	0%	100%	None Detected		
Client Sample ID:	28A-RCM-1026					Lab Sample ID:	041532674-0051
Sample Description:	Annex hallway to lobby doors/T	an window gla	izing compound	I			
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Tan	0%	100%	None Detected	Very limited samp	le
Client Sample ID:	28B-RCM-1026					Lab Sample ID:	041532674-0052
Sample Description:	Annex hallway to lobby doors/T	an window gla	zing compound	i			
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan	0%	100%	None Detected		
Client Sample ID:	29A-RCM-1026					Lab Sample ID:	041532674-0053
Sample Description:	Room 14/Tan interior window c	aulking					
	Analyzed			Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	Tan	0%	95%	5% Chrysotile		
Client Sample ID:	29B-RCM-1026					Lab Sample ID:	041532674-0054
Sample Description:	Room 18/Tan interior window c	aulking					
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015			Stop P	ositive (Not Analyzed)		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: 041532674 ENVI54 Customer ID: Customer PO: Project ID:

20150666.A1E

TEST	Analyzed Date 11/03/2015	Color Tan		Asbestos Non-Fibrous 94%	Asbestos 6% Chrysotile	Comment	
TEST	-	Color			Ashastas	Comment	
Sample Description:	Cafeteria doors/Tan interior of	loor caulking					
Client Sample ID:	32A-RCM-1026					Lab Sample ID:	041532674-0059
	11/03/2015	<u></u>		Stop P	ositive (Not Analyzed)		
TEST PLM	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
	Analyzed			Asbestos		<b>.</b> .	
Sample Description:	Wood entry doors/Tan windo	w glazing compo	ound				
Client Sample ID:	31B-RCM-1026					Lab Sample ID:	041532674-0058
PLM	11/03/2015	Tan	0%	98%	2% Chrysotile		
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
	Analyzed			Asbestos		<b>.</b> .	
Sample Description:	Wood entry doors/Tan windo	w glazing compo	ound				
Client Sample ID:	31A-RCM-1026					Lab Sample ID:	041532674-0057
						Lab Commis IC	044520674 0057
TEST PLM	Date 11/04/2015	Color White	0%	Non-Fibrous 100%	Asbestos None Detected	Comment	
	Analyzed	<b>0</b> .1		Asbestos	A . I	0	
Sample Description:	Room 18/White interior windo	w caulking					
Client Sample ID:	30B-RCM-1026					Lab Sample ID:	041532674-0056
EM Grav. Reduction	11/05/2015	White	0.0%	100%	None Detected		
PLM	11/03/2015	White	0%	100%	None Detected		
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
	Analyzed		Non-A	Asbestos			
		our occurring					
Sample Description:	Room 14/White interior windo	w caulking				-	



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

		Р	olarized L	ight Microsc	ору		
Client Sample ID:	33C-RCM-1026					Lab Sample ID:	041532674-0063
Sample Description:	Annex-1st floor girls' room/V	/hite plaster skin	n coat				
	Analyzed		Nan	Achaetee			
TEST	Analyzed Date	Color		-Asbestos Non-Fibrous	Asbestos	Comment	
PLM	11/03/2015	White	0%		None Detected		
Client Sample ID:	33D-RCM-1026					Lab Sample ID:	041532674-0064
Sample Description:	Annex-1st floor boys' room/\	N/hite plaster skir	n coat				
	Annex-13t noor boys toomr		ncoat				
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	White	0%	100%	None Detected		
Client Sample ID:	33E-RCM-1026					Lab Sample ID:	041532674-0065
Sample Description:	Annex-Hallway o/s 14 & 15/	White plaster ski	m coat				
	· · · · ·						
	Analyzed		Non	-Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	White	0%	100%	None Detected		
Client Sample ID:	34A-RCM-1026					Lab Sample ID:	041532674-0066
Sample Description:	Annex-Ground level boys' ro	om/Gray plaster	rough coat				
	-		-				
	Analyzed		Non	-Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	34B-RCM-1026					Lab Sample ID:	041532674-0067
Sample Description:	Annex-Ground level girls' ro	om/Gray plaster	rough coat				
	Analyzed			Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	34C-RCM-1026					Lab Sample ID:	041532674-0068
Sample Description:	Annex-1st floor girls' room/G	Fray plaster roug	n coat				
	Analyzed			-Asbestos		•	
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	100%	None Detected		
Client Sample ID:	34D-RCM-1026					Lab Sample ID:	041532674-0069
Sample Description:	Annex-1st floor girls' room/G	Fray plaster roug	n coat				
TEST	Analyzed	0		Asbestos	Achester	Comment	
TEST PLM	Date	Color	Fibrous 0%	Non-Fibrous 100%	Asbestos	Comment	
	11/04/2015	White	U%	100%	None Detected		
Client Sample ID:	34E-RCM-1026					Lab Sample ID:	041532674-0070
Sample Description:	Annex-Ground level girls' roo	om/Gray plaster	rough coat				
TEST	Analyzed	Color		Asbestos	Ashestas	Comment	
TEST PLM	Date 11/04/2015	Color	Pibrous 0%	Non-Fibrous 100%	Asbestos	Comment	
	11/04/2015	White	0%	100%	None Detected		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

		P	olarized L	ignt Microso	сору		
Client Sample ID:	35A-RCM-1026					Lab Sample ID:	041532674-0071
Sample Description:	At connector hallway-Ground	d floor/Tan interio	or door caulking				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan	0%	98%	2% Chrysotile		
Client Sample ID:	35B-RCM-1026					Lab Sample ID:	041532674-0072
Sample Description:	At connector hallway-1st floo	or/Tan interior do	or caulking				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015			Stop P	Positive (Not Analyzed)		
Client Sample ID:	36A-RCM-1026					Lab Sample ID:	041532674-0073
Sample Description:	Connector window walls/Tan	interior window	caulking				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Tan	0%	95%	5% Chrysotile		
Client Sample ID:	36B-RCM-1026					Lab Sample ID:	041532674-0074
Sample Description:	Connector window walls/Tan	interior window	caulking				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015			Stop P	Positive (Not Analyzed)		
Client Sample ID:	37A-RCM-1026					Lab Sample ID:	041532674-0075
Sample Description:	Connector window walls/Gra	y window glazin	g compound				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	98%	2% Chrysotile		
Client Sample ID:	37B-RCM-1026					Lab Sample ID:	041532674-0076
Sample Description:	Connector window walls/Gra	y window glazin	g compound				
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015			Stop P	Positive (Not Analyzed)		
Client Sample ID:	38A-RCM-1026					Lab Sample ID:	041532674-0077
Sample Description:	Cafeteria/Gray interior windo	w caulking					
	Analyzed		Non-	Asbestos			
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015	Gray	0%	98%	2% Chrysotile		
Client Sample ID:	38B-RCM-1026					Lab Sample ID:	041532674-0078
Sample Description:	Cafeteria/Gray interior windo	w caulking				·	
	Analyzed		Non-	Asbestos			
TEST	Date	Color		Non-Fibrous	Asbestos	Comment	
PLM	11/04/2015				Positive (Not Analyzed)		



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID: 041532674 ENVI54 Customer ID: Customer PO: Project ID:

20150666.A1E

			larized Lig	<i>.</i>						
Client Sample ID:	39A-RCM-1026					Lab Sample ID:	041532674-0079			
Sample Description:	Exterior-Main bldg/Brown e	exterior window caul	king							
	Analyzed Non-Asbestos									
TEST	Date	Color		Non-Fibrous	Asbestos	Comment				
PLM	11/04/2015	Brown	0%	100%	None Detected					
TEM Grav. Reduction	11/05/2015	Brown	0.0%	100%	None Detected					
Client Sample ID:	39B-RCM-1026					Lab Sample ID:	041532674-0080			
Sample Description:	Exterior-Main bldg/Brown e	exterior window caul	king							
	Analyzed		Non-A	sbestos						
TEST	Date	Color	Fibrous N	Ion-Fibrous	Asbestos	Comment				
PLM	11/04/2015	Brown	0%	100%	None Detected					
Client Sample ID:	40A-RCM-1026					Lab Sample ID:	041532674-0081			
Sample Description:	Exterior-Main bldg/Black th	rough-wall flashing	mastic							
	Analyzad		Non A	sbestos						
TEST	Analyzed Date	Color		Spesios Ion-Fibrous	Asbestos	Comment				
PLM	11/04/2015	Black	0%	100%	None Detected					
Client Sample ID:	40B-RCM-1026					Lab Sample ID:	041532674-0082			
Sample Description:		novel the shine				Lub Gumple ID.	041002014-0002			
Sample Description.	Exterior-Main bldg/Black th	rougn-wall flashing	mastic							
	Analyzed		Non-A	sbestos						
TEST	Date	Color		Ion-Fibrous	Asbestos	Comment				
PLM	11/04/2015	Brown/Black	5%	95%	None Detected					
Client Sample ID:	41A-RCM-1026					Lab Sample ID:	041532674-0083			
Sample Description:	Annex-Exterior/Tan exterio	r windowsill caulking	g		n: Annex-Exterior/Tan exterior windowsill caulking					
	Analyzed Non-Asbestos									
	Analyzed		Non-A	sbestos						
TEST	Analyzed Date	Color		sbestos Ion-Fibrous	Asbestos	Comment				
	-	<b>Color</b> Tan			Asbestos 5% Chrysotile	Comment				
PLM	Date		Fibrous N	Non-Fibrous		Comment	041532674-0084			
PLM	Date 11/04/2015	Tan	Fibrous N 0%	Non-Fibrous			041532674-0084			
PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterio	Tan	Fibrous M	Non-Fibrous 95%			041532674-0084			
PLM Client Sample ID: Sample Description:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed	Tan r windowsill caulkin	Fibrous N 0%	Non-Fibrous 95% sbestos	5% Chrysotile	Lab Sample ID:	041532674-0084			
PLM Client Sample ID: Sample Description: TEST	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterio	Tan	Fibrous N 0%	Non-Fibrous 95% sbestos Non-Fibrous			041532674-0084			
PLM Client Sample ID: Sample Description: TEST PLM	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date	Tan r windowsill caulkin	Fibrous N 0%	Non-Fibrous 95% sbestos Non-Fibrous	5% Chrysotile	Lab Sample ID:	041532674-0084			
PLM Client Sample ID: Sample Description: TEST	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015	Tan r windowsill caulkin Color	Fibrous N 0%	Non-Fibrous 95% sbestos Non-Fibrous	5% Chrysotile	Lab Sample ID: Comment				
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior	Tan r windowsill caulkin Color	Fibrous M 0% g Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P	5% Chrysotile	Lab Sample ID: Comment				
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior Analyzed	Tan r windowsill caulkin Color or window caulking	Fibrous M 0% g Non-A Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P	5% Chrysotile Asbestos ositive (Not Analyzed)	Lab Sample ID: Comment Lab Sample ID:				
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior	Tan r windowsill caulkin Color	Fibrous M 0% g Non-A Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P	5% Chrysotile	Lab Sample ID: Comment				
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior Analyzed Date 11/04/2015	Tan r windowsill caulkin Color or window caulking Color	Fibrous M 0% 9 Non-A Fibrous M Non-A Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P sbestos Non-Fibrous	5% Chrysotile Asbestos ositive (Not Analyzed) Asbestos	Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0085			
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior Analyzed Date 11/04/2015 42B-RCM-1026	Tan r windowsill caulkin Color or window caulking Color Gray	Fibrous M 0% 9 Non-A Fibrous M Non-A Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P sbestos Non-Fibrous	5% Chrysotile Asbestos ositive (Not Analyzed) Asbestos	Lab Sample ID: Comment Lab Sample ID:				
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior Analyzed Date 11/04/2015	Tan r windowsill caulkin Color or window caulking Color Gray	Fibrous M 0% 9 Non-A Fibrous M Non-A Fibrous M	Non-Fibrous 95% sbestos Non-Fibrous Stop P sbestos Non-Fibrous	5% Chrysotile Asbestos ositive (Not Analyzed) Asbestos	Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0085			
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior Analyzed Date 11/04/2015 42B-RCM-1026	Tan r windowsill caulkin Color or window caulking Color Gray	Fibrous M 0% g Non-A Fibrous M Fibrous M 0%	Non-Fibrous 95% sbestos Non-Fibrous Stop P sbestos Non-Fibrous	5% Chrysotile Asbestos ositive (Not Analyzed) Asbestos	Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0085			
PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID: Sample Description: TEST PLM Client Sample ID:	Date 11/04/2015 41B-RCM-1026 Annex-Exterior/Tan exterior Analyzed Date 11/04/2015 42A-RCM-1026 Annex-Exterior/Gray exterior 11/04/2015 42B-RCM-1026 Annex-Exterior/Gray exterior	Tan r windowsill caulkin Color or window caulking Color Gray	Fibrous M 0% 9 Non-A Fibrous M 0% Non-A	Non-Fibrous 95% sbestos Non-Fibrous Stop P sbestos Non-Fibrous 100%	5% Chrysotile Asbestos ositive (Not Analyzed) Asbestos	Lab Sample ID: Comment Lab Sample ID: Comment	041532674-0085			



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

	-	Po	larized L	ight Micros	сору			
Client Sample ID:	43A-RCM-1026			-	-	Lab Sample ID:	041532674-0087	
Sample Description:	Annex-Exterior/White exter	ior windowsill caulk	ing					
TEST	Analyzed Date	Color		Asbestos Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	White	0%		8% Chrysotile	Common		
	43B-RCM-1026					Lab Sample ID:	041532674-0088	
Client Sample ID:		· · · · · · · · · · · · · · · · · · ·	•			Lab Sample ID.	041552074-0086	
Sample Description:	Annex-Exterior/White exter	for windowsill caulk	ing					
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015			Stop F	Positive (Not Analyzed)			
Client Sample ID:	44A-RCM-1026					Lab Sample ID:	041532674-0089	
Sample Description:	Door b/w 17 & 18/Off-white	e door caulking						
	Analyzed			Asbestos	• • •	0		
TEST	Date	Color		Non-Fibrous	Asbestos	Comment		
PLM TEM Grav. Reduction	11/04/2015 11/05/2015	White	0% 0.0%		None Detected			
			0.070			Lab Sample ID:	041532674-0090	
Client Sample ID: Sample Description:	44B-RCM-1026	door ooulling				Lab Salliple ID:	0710320/4-0030	
Sample Description.	Door b/w 23 & 24/Off-white	e door caulking						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Brown/White	0%	100%	None Detected			
Client Sample ID:	45A-RCM-1026					Lab Sample ID:	041532674-0091	
Sample Description:	Door b/w 16 & 15/Tan door	r caulking						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Tan	0%	98%	2% Chrysotile			
Client Sample ID:	45B-RCM-1026					Lab Sample ID:	041532674-0092	
Sample Description:	Door b/w 16 & 15/Tan door	r caulking						
	Amelunad		New	A - h				
TEST	Analyzed Date	Color		Asbestos Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	00101	1151043		Positive (Not Analyzed)	Common		
Client Sample ID:	46A-RCM-1026				· · · · · · · · · · · · · · · · · · ·	Lab Sample ID:	041532674-0093	
Sample Description:		ulking				Lub Gumple ID.	041002014-0000	
	Room 9/Tan int window ca	unting						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Gray/Tan	0%		None Detected			
TEM Grav. Reduction	11/06/2015	Gray/Tan	0.0%	100%	None Detected			
Client Sample ID:	46B-RCM-1026					Lab Sample ID:	041532674-0094	
Sample Description:	Room 11/Tan int window c	aulking						
	<b>.</b>			• · • · · · ·				
TEST	Analyzed	Color		Asbestos Non-Fibrous	Asbestos	Comment		
PLM	Date 11/04/2015	Color Tan	Fibrous 0%		None Detected	Comment		
· LIVI	11/04/2013	1 ali	0%	100 /0				



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 http://www.EMSL.com / cinnasblab@EMSL.com EMSL Order ID:041532674Customer ID:ENVI54Customer PO:20150666.A1EProject ID:

Polarized Light Microscopy								
Client Sample ID:	47A-RCM-1026					Lab Sample ID:	041532674-0095	
Sample Description:	Behind brick at main bldg/Blac	k dampproofing	ng					
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Black	40%	60%	None Detected			
Client Sample ID:	47B-RCM-1026					Lab Sample ID:	041532674-0096	
Sample Description:	Behind brick at main bldg/Blac	k dampproofing						
	Analyzed		Non	Asbestos				
TEST	Date	Color		Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Black	30%	70%	None Detected			
Client Sample ID:	50A-RCM-1026					Lab Sample ID:	041532674-0097	
Sample Description:	Pipe tunnel/Brown concrete pa	aper						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Brown	80%	20%	None Detected			
Client Sample ID:	50B-RCM-1026					Lab Sample ID:	041532674-0098	
Sample Description:	Crawlspace/Brown concrete p	aper						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Brown/Black	95%	5%	None Detected			
Client Sample ID:	51A-RCM-1026					Lab Sample ID:	041532674-0099	
Sample Description:	Pipe tunnel/Black mastic asso	c w/50						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Black	0%	100%	None Detected			
Client Sample ID:	51B-RCM-1026					Lab Sample ID:	041532674-0100	
Sample Description:	Crawlspace/Black mastic asso	oc w/50						
	Analyzed		Non	Asbestos				
TEST	Date	Color	Fibrous	Non-Fibrous	Asbestos	Comment		
PLM	11/04/2015	Black	0%	100%	None Detected			



200 Route 130 North Cinnaminson, NJ 08077 Phone/Fax: (800) 220-3675 / (856) 786-5974 <u>http://www.EMSL.com</u> / <u>cinnasblab@EMSL.com</u> 
 EMSL Order ID:
 041532674

 Customer ID:
 ENVI54

 Customer PO:
 20150666.A1E

 Project ID:
 ENUSCONSERVICE

Summary Test Report for Asbestos Analysis of Bulk Material via EPA 600/R-93/116 Method via Polarized Light Microscopy

### Analyst(s):

Alexis KumPLM (45)Dave PoitrasPLM (10)Debbie LittleTEM Grav. Reduction (14)Seri SmithPLM (33)

Reviewed and approved by:

Zella

Benjamin Ellis, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036

Initial report from: 11/04/201513:03:05

OrderID: 041532674

Л

٦Ĭ

-

04, 532674

EMSL Customer No. ENVI54

Phone (617) 282-4675 Fax (617) 282-8253

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

FUSS & O'NEILL EnviroScience, LLC

ĺ		Sheet $1 \text{ of } 7$		
·	Project Name:	Peebles Elementary School Feasibili	ity Study Project No.: 2	0150666.A1E
	Building Name/Num	ber: Peebles Elementary Sc	hool Project Manager:	D Diedricksen
	Site Address:70 Trowbridge Road, Bourne, MA		Total # of Samples:	100 96405
	Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Location	Comments/ Quantities
X	6 OIA -RCM-1026	Gray Flashing Sabrt	Connector Bldg. Rach	
	OIB -RCM-1026		L L	
H	7 OLA -RCM-1026	Black Flashing Sealant	Annex Raf	
1	02B -RCM-1026		2	
+	-	Black Built-up Roufing	Annex Roof	
	03B -RCM-1026.		Connector Rast	
-	704A -RCM-1026	Black Hot Mop	Annex Raf	5/n Poly IJO
	04.6 -RCM-1026	<u> </u>	Conneder Rauf	
202		Gray Asphalt Roof Shingle	Annex Reef	
	059 -RCM-1026	L L	Main Raif	
	106A -RCM-1026	White Louver Caulking	Annex Rouf	
	06B -RCM-1026	L d	U	
-	-RCM-1026	White Flashing Scalant	Annex Ray f	CINN 5 NO
I	07B -RCM-1026	۲. d	e .	V - MAREC
92	3 CEROSA-RCM-1026	Gray Dar Carlleing	Annex Rauf	INSC INSC INSC INSC INSC INSC
	Analysis Method: 🛛 P			
	Please call EnviroScience	at (617) 282-4675 if analyses will not be compl	leted for requested t/a/t listed above.	$(\#_0^{0^{-}})$
	Email Results to:	ddiedricksen@fando.com	n Do Not Mail Hard Copy Report FAX R	esults to: 888 838-1160.
	Special Instructions: Ste	op analysis on first positive sample in each hom	ogeneous set of samples unless otherwise noted	Do not layer samples
		<sup>*</sup> · · ·	negative by PLM, analyze the sample denoted with	a star (*) by
	<u>18M NOB on a 48-h</u>	our t/a/t. Analyze a MAXIMUM of 20	samples by TEM in noted order:	
	Samples Collected by: _	Ros Mallet + Mike	Coffe Date: 10/26	/2015 + 10/28/2015
	Samples Sent by:	-	Date: 10/30/15 Time:	
	Shipped To: 🛛 EMS	L Other		ה הובשניט שוקן
	Method of Shipment:	Fed Ex 🛛 Lab Drop Off	□ Other	NOV 02 2015
	Blocatu	ONDER Page 1 Of	1337 E	3y_118:44

L'I

# FUSS & O'NEILL EnviroScience, LLC

50 Redfield Street, Suite 100, Boston, MA 02122

EMSL Customer No. ENVI54

www.fando.com

Phone (617) 282-4675 Fax (617) 282-8253

04,532694

Asbestos Bulk Sample Chain-of-Custody Sheet					
Project Name:	Peebles Elementary School Feasibil	ity Study	Project No.:2	<u>0150666.A1E</u>	
	ber: Peebles Elementary Sc				
Site Address:	70 Trowbridge Road, Bourne, MA		Total # of Samples:	00 96 108	
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)		Location	Comments/ Quantities	
08BRCM-1026	Gray Door Caulting	Annez F	2a, f		
07A -RCM-1026	Black Reuf Felt 5/1 05	Annex R	A	· · ·	
09B -RCM-1026	2 2	Main Bldg.	_ A		
IIA -RCM-1026	Tan Pipe - Thread Sealant	Attic		G/U File ( magan	
//B -RCM-1026	4	Cafeteria		System	
/2A -RCM-1026	Gray Dywall	Above 1st Floor	- Classions		
128 -RCM-1026	<u> </u>	<u>.</u>			
13A -RCM-1026	24,24 Red w/ white Solder	Room	7		
13B -RCM-1026.	24x24 Red w/ white Splotch 2 Flar Tile	Room			
14/4 -RCM-1026	24x24 Ton c/white + Boun	Poom 5			
14B -RCM-1026	L splotos	L.			
15A -RCM-1026		Rcom 3			
150 -RCM-1026	12x12 Dark Gray Mottled L Plan Till	L.	•		
17A -RCM-1026	Black Caulking of Window	Room 8			
RCM-1026	Black Caulking of Window L. Vall Ballords	Room 4			
Analysis Method: 🛛 P	LM TEM Other		Turnaround Tr	me: C 48:bour	
Please call EnviroScience	at (617) 282-4675 if analyses will not be compl	leted for requested t/a/t li	sted above.	VON VON	
Email Results to:	ddiedricksen @fando.com	n Do Not Mail Hard	Copy Report FAX R	esultsto: 888-538-1160.	
	p analysis on first positive sample in each hom				
	point count. If NOB group samples are ALL to $t/a/t$ . Analyze a MAXIMUM of 20			a stat (★) br	
		samples by 1 Elvi in n	oted order;		
Samples Collected by: _		ke Cothy	<b>Date:</b> <u>10/26</u> /	/2015 + 10/28/2015	
Samples Sent by:	pen I	Date: 10/30/15		MEBEIWEI	
Shipped To: 🛛 EMS		· · ·			
Method of Shipment:	🛿 Fed Ex 🛛 Lab Drop Off	□ Other			
	Page 2 Of	7	E	3y M 8:46	

04,532674

EMSL Customer No. ENVI54

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

FUSS & O'NEILL EnviroScience, LLC

Phone (617)	) 282-4675	Fax	(617)	282-825	3
					-

	Asbestos Bulk Sample Chain-of-Custody					
Project Name:	_Peebles Elementary School_Feasibili	ity Study	Project No.:2	150666.A1E		
Building Name/Nu	mber: <u>Peebles Elementary Sc</u>	ebles Elementary School P				
Site Address:	70 Trowbridge Road, Bourne, MA		Total # of Samples: _	961070		
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample	Location	Comments/ Quantities		
2 18A -RCM-1026	Tan Caulking a/w Window	Room 8				
18B -RCM-1026	d wall Ballads	Room 4				
1914 -RCM-1026	Gray Gramic Flar Tile Grat	-	Bays Room			
19B -RCM-1026	່ <u>ເ</u>	1st Flass Bay	-			
<b>२७А</b> -RCM-1026	Black Compessik Under Sill	Room 11	_			
205 -RCM-1026		Room 4				
21A -RCM-1026	Gray Gramic Flar Tile Aller	Grand Plan	Boys Rar			
218 -RCM-1026	· L S	15t Fleer Bays	•			
22A -RCM-1026	Dark Gray Coranic Wall Tile	· · ·	r Boys Room			
220 -RCM-1026	d Adhesik	1sh Flar Bay	•			
23A -RCM-1026	Gray Coronic Vall Tile	Grund Flow				
RCM-1026 -RCM-1026	d Grat	1st Fleer Bay				
3 24A -RCM-1026	Tan Interior Window Carlking		r Bays Reon			
24B -RCM-1026		1 <sup>sh</sup> Floor (	Joys Ram	<b>5</b> , 0		
25A -RCM-1026	Gray Mud Set	1th Floor Be		S NON S		
Analysis Method: 🛛	PLM TEM Other		Turnaround Tu			
Please call EnviroScience	ce at (617) 282-4675 if analyses will not be compl	leted for requested t/a/t li	sted above.	VED SON		
Email Results to:	ddiedricksen @fando.com	Do Not Mail Hard	Copy Report FAX Re	esults 4: 888 938-1160.		
-	Stop analysis on first positive sample in each hom	о I				
	t point count If NOB group samples are ALL r -hour $t/a/t$ . Analyze a MAXIMUM of 20		-	a star (★) by		
			·			
Samples Collected by		like Coffey	Date:0/26/	<u>/2015 + 10/28/2015</u>		
Samples Sent by:		Date: 10/30/15	Time:			
Shipped To: 🛛 EN						
Method of Shipment:	🛛 Fed Ex 🛛 Lab Drop Off	Other	(UL			
	Page 3 Of	7	B	, <u> 11 8:46</u>		

FUSS & O'NEILL EnviroScience, LLC

50 Redfield Street, Suite 100, Boston, MA 02122

04,532674

EMSL Customer No. ENVI54

www.fando.com

Phone (617) 282-4675 Fax (617) 282-8253

·	Asbestos Bulk	Sample Chain-of-Cus	tody	Sheet <u>4</u> of <u>7</u>		
Project Name:	Peebles Elementary School Feasibili	ty Study Project	t No.: <u>201</u>	50666.A1E		
Building Name/Numl	ber: <u>Peebles Elementary Sc</u>		_			
Site Address:	70 Trowbridge Road, Bourne, MA	Total #	# of Samples:	96+0×100		
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Locatio	<u>מ</u> ו	Comments/ Quantities		
253 -RCM-1026	Gray Mudset	Grand Floor	Boys Res			
26A -RCM-1026	Gray Mudset	Annex - and Flour				
26B -RCM-1026	· L	Annex - 15th Flur				
27A -RCM-1026	1x/ White Fisched Splind					
27B -RCM-1026	2 Ceilor Tilc	, ' °	- Grand			
28A -RCM-1026	Tan Window Glozing Congent	Annex Hallway to L.				
250 -RCM-1026		۲,		1		
29A -RCM-1026	Tan Interior Window	Room 14				
29B -RCM-1026	Tan Interior Window 2 Carling	Room 1.8				
30A -RCM-1026	While Interor Window	Rean 14				
30ß -RCM-1026	1 Caulleig	Room 18				
JIA -RCM-1026	Tan Window Clarine Comprond	Wass Entry Deors				
310 -RCM-1026	Tan Wundow Charring Comprond	d				
32A -RCM-1026	Tan Intern Der Caulking	Cafederia Da				
329 -RCM-1026	2 2	Main Blog Deers @		<b>C</b> (X) <b>5</b> N		
	LM	-				
unless indicated Do not p	p analysis on first positive sample in each hom oint count. If NOB group samples are ALL r ourt/a/t. Analyze a MAXIMUM of20	egative by PLM, analyze the samp	le denoted with a			
Samples Collected by: Samples Sent by: Shipped To: 🛛 EMSI Method of Shipment: 🕅	D	4 <u>e_Collay</u> pate: <u>10/30/15</u>	_ Date: _10/26/2 _ Time: _ N	015 + 10/28/2015 □ E I V E IIIIIIIIIIIIIIIIIIIIIIIIIIIIII		
Page 4 Of 7						

≹

FUSS & O'NEILL EnviroScience, LLC

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

÷.

	Asbestos Bulk	Sample Chain-of-Custody	Sheet $5^{-}$ of $2$
Project Name:	Peebles Elementary School Feasibil	ity Study Project No.:201	150666.A1E
Building Name/Num	ber:Peebles Elementary Sc	hool Project Manager:	D Diedricksen
Site Address:	70 Trowbridge Road, Bourne, MA	Total # of Samples!	U 26 FOF
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Location	Comments/ Quantities
33A -RCM-1026	White Plaster Stom Coat	Annex - Grend level Bus Ren	•
33 S -RCM-1026		Annex - Grend level Bys Ren Curls Ran	
33C -RCM-1026		Plan L	
RCM-1026 -RCM-1026		L Bas	
33E -RCM-1026		- Hallway ofs 19715	
34A -RCM-1026	Gray Plaster Righ Coat	Annex - Grand level Bys Res	
74B -RCM-1026			
34c -RCM-1026		1 <sup>sh</sup> Flur L L Boys Ram	
340 -RCM-1026		L Boys Ran	
34E -RCM-1026		I Grand level Gody Ran	
735A -RCM-1026	Tan Interior Dor Carlking	@ Connector Hallver - Gal Pb	
35 -RCM-1026	Tan Inter-Dar Calking	@ Connector Hallway - Crail Pb C -1× Pkn	
б <b>КА</b> -RCM-1026	Too John Winda - Collary	Connector Linda Valls	
-RCM-1026	Tan Inter Winder Callary	L L	
37 A -RCM-1026	Gray Winder Glazing Congrued		NON
Analysis Method: 🛛 P	7 $3$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$ $1$	Turnaround Tim	
Please call EnviroScience	at (617) 282-4675 if analyses will not be comp	leted for requested t/a/t listed above.	AM
Email Results to:	ddiedricksen@fando.com	n Do Not Mail Hard Copy Report FAX Res	
•	- · •	nogeneous set of samples unless otherwise noted. De	, ,
	point count. If NOB group samples are ALL out t/a/t. Analyze a MAXIMUM of 20	negative by PLM, analyze the sample denoted with a	star (★) by
		samples by 1 E.W in noted order?	
Samples Collected by: _		Mike Colly Date: 10/26/2	015 + 10/28/2015
Samples Sent by:	,	Date:/ 30 / 15 Time:	ECENTER
Shipped To: 🛛 EMS		Mí	NOV 02 2015
Method of Shipment:	🛿 Fed Ex 🛛 Lab Drop Off	□ Other  ∪∪	
	Page 5 Of	7 (By	N 8:46

--

www.fando.com

	)rd	lerID: 041532674		04,53	2674
		<b>FUSS</b>	S & O'NEILL		SL Customer No. ENVI54
		Envir	oScience, ILC		www.fando.com
		50 Redfield Street, Suite	100, Boston, MA 02122	Phone (617) 282	-4675 Fax (617) 282-8253
			Asbestos Bulk	Sample Chain-of-Custody	Sheet <u>&amp;</u> of <u></u>
		Project Name:	Peebles Elementary School Feasibili	ty Study Project No.:	
				hool Project Manager:	
:		Site Address:	70 Trowbridge Road, Bourne, MA	Total # of Sample	:s: 1W 96 10F
		Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Location	Comments/ Quantities
		37B -RCM-1026	Gray Under Clazing Compil	Connector Linda, Uglis	
+	9	38A -RCM-1026	Cray Interior Window Calley	Calebora	
		380 -RCM-1026	<u>'</u>	Ŀ	
ł	z/D	<b>39A</b> -RCM-1026	Brown Estator Window Caullein	Extern Main Bldg.	-HOLD
		37B -RCM-1026		-1	HOLD
		40A -RCM-1026	Black Through-Usll Flashing L Mastric	Exterior - Main Bldg	Brice to
		40B -RCM-1026	2 Mastre	L	
-	11	41A -RCM-1026	Tan Exterior Window Sill	Annex - Exterior	
		41B -RCM-1026	Tan Extenser Windar Sill 2 Caulting	Ś	
×	n	42A -RCM-1026	Gray Extern Winder Calloing	Annex Exterior	
		420 -RCM-1026		Ŧ	
R	13	43A -RCM-1026	White Ester Winder Sill L carleing		
		49 -RCM-1026	L caulking	Ŀ	15
ł	24	ЧЦА -RCM-1026	aff-white Der Calking	Dovor 6/0 17 -18	CINHAMINS 15 NOV - 3
		440 -RCM-1026	<u> </u>	1 5/4 23+24	-3
		Analysis Method: 🛛 Pl	LM TEM Other	Turnaround	
		Please call EnviroScience a	at (617) 282-4675 if analyses will not be comple	eted for requested t/a/t listed above.	II: 5
		Email Results to:	ddiedricksen@fando.com	Do Not Mail Hard Copy Report FAX	K Results to: 888-838-1160.
				ogeneous set of samples unless otherwise note	
			oint count. If NOB group samples are ALL n our t/a/t. Analyze a MAXIMUM of 20	egative by PLM, analyze the sample denoted w	rith a star (★) by
		Samples Collected by:	•	ce Celley Date: 10/	(26/2015 + 10/28/2015
		Samples Sent by:		Date:	NE CEIVEN
		Shipped To: 🛛 EMSI Method of Shipment: 🖂		☐ Other	NOV 02 2015
		Action of Surpment:			
			Page 6 Of	7	y 8.46

rd	erID: 041532674		04,532674	L
	FUSS	& O'NEILL		Customer No. ENVI54
	Enviro	oScience, LLC		www.fando.com
	50 Redfield Street, Suite	100, Boston, MA 02122	Phone (617) 282-467	75 Fax (617) 282-8253
-		Asbestos Bulk	Sample Chain-of-Custody	Sheet 7 of 7
	Project Name:		ty Study Project No.: 20	
	Building Name/Numl	ber: Peebles Elementary Sc	hool Project Manager:	<u>D Diedricksen</u>
			Total # of Samples:	_
	Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Location	Comments/ Quantities
	L/SA -RCM-1026	Tan Door Caulking	Door 5/6 16115	
	45B -RCM-1026		<u>ل</u>	
4	46A -RCM-1026	Tan Int. Window Caulky	Room 9	
	460 -RCM-1026		Leon 11	
	47A -RCM-1026	Black Dampperton	Dehnd bree @ Main Aldg	
	470 -RCM-1026	e l'	d and a second	
X	45	Soit	Crawlspace	
Y	49RCM-1026	-P.p. 7- Soit	Pipe Tunnel	-
/	50A -RCM-1026	Brown Concode Papar	Pipe Tunnel	
	50B -RCM-1026	L.	Crawspace	
	51A -RCM-1026	Black Maste al 50	Pipe Tinnel	
	51B -RCM-1026	!	GrayIspace.	CINI 15 NO
	-RCM-1026			HHAM
	-RCM-1026		·	B NSC
	-RCM-1026			HII N.N.
	Analysis Method: 🛛 PI	LM [] TEM [] Other	Turnaround Tir	me: <u>+ 48-hour</u>
	Please call EnviroScience a	at (617) 282-4675 if analyses will not be comple	eted for requested t/a/t listed above.	
	Email Results to:	ddiedricksen @fando.com	Do Not Mail Hard Copy Report FAX Re	sults to: 888-838-1160.
			ogeneous set of samples unless otherwise noted. D	• •
			regative by PLM, analyze the sample denoted with a	a star (★) by
		$\frac{1}{20}$	samples by TEM in noted order!	
	Samples Collected by:	_ Mald +	Mike Cally Date: 10/26/	2015 + 10/28/2015
	Samples Sent by:	p D	Date: 10/30/1 - Time: 1	
	Shipped To: 🛛 EMSI		IŇ	NOV 02 2015
	Method of Shipment:	Fed Ex 🗆 Lab Drop Off [	□ Other	
			By	<u> N 8:46</u>

OrderID: 041532674



EMSL Analytical, Inc. 7 Constitution Way, Suite 107, Woburn, MA 01801 Phone/Fax: (781) 933-8411 / (781) 933-8412 http://www.EMSL.com bostonlab@emsl.com 
 EMSL Order:
 131405507

 CustomerID:
 ENVI54

 CustomerPO:
 20121141.B2E

 ProjectID:
 Environmentation

Fuss & O'Neill EnviroScience, LLC       Fax:       (a)         146 Hartford Road       Received:       1         Manchester, CT 06040       Analysis Date:       1	(860) 646-2469 (888) 838-1160 12/08/14 9:00 AM 12/9/2014 12/5/2014
--	--

Project: 20121141.B2E / Bourne Public Schools; Peebles Elementary

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			<u>Non-A</u>	sbestos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
01A-RCM-1205 131405507-0001	Ground Floor Stairwell Landing - Smooth White Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
01B-RCM-1205 131405507-0002	Ground Floor Stairwell Landing - Smooth White Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
01C-RCM-1205 131405507-0003	Ground Floor Stairwell Landing - Smooth White Plaster Skim Coat	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

Analyst(s)

Kevin Pine (3)

the P.A

Steve Grise, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 12/09/2014 12:33:28

1

OrderID:	131405507

# $1\,3\,1\,4\,0\,5\,5\,0\,7$

www.fando com

FUSS & O'NEILL EnviroScience, LLC

Phone (617) 282-4675 Fax (617) 282-8253

0	Asbestos Bulk	Sample Chain-of-Custody	Sheet / of
Project Name: <u>Bour</u>	ne tutic schools- kes	bs Elementon Project No.: 2012 Project Manager: D	1141. BZE
Building Name/Numb	er: Teesks Elementary		
Site Address:		Total # of Samples: _	
Sample ID (#-Initials-Date)	Material Type	Sample Location	Comments/ Quantities
1 01A - RCM -1205	the White Plater Stim Cat	Grand Flor Stanuell Landing	
2 01B -RM-1205 3 01C -RCM-1205			
3 OIL -RCM-1205	V		
		<u>+</u>	
			-
			_
	· · · · · · · · · · · · · · · · · · ·		
·			
Analysis Method 🛛 🛛 PI		Turnaround Ti	ime: 24hr
	it (617) 282-4675 if analyses will not be comp	·	
Email Results to:	) edicese @fando.com	n Do Not Mail Hard Copy Report FAX R	esults to: 888-838-1160.
Special Instructions: Stop	o analysis on first positive sample in each hor	nogeneous set of samples unless otherwise noted. I	20 not layer samples
		negative by PLM, analyze the sample denoted with	a star (A) by
TEM NOB on a	<u>t/a/t</u> . Analyze a <b>MAXIMUM</b> of	samples by TEM in noted order.	
Samples Collected by:	2M_	Datg:	105/2014
Samples Sent by:	100	Date: 12/5/14 Time	RETTER
Shipped To: 🛛 EMSI	2 Other	FedEx# 7900	
Method of Shipment:	Fed Ex 🛛 Lab Drop Off	□ Other <u>4/19 003/</u>	
		By S	U 0900



EMSL Analytical, Inc. 7 Constitution Way, Suite 107, Woburn, MA 01801 Phone/Fax: (781) 933-8411 / (781) 933-8412 http://www.EMSL.com bostonlab@emsl.com EMSL Order: 131404197 CustomerID: ENVI54 CustomerPO: 20121141.B1E ProjectID:

Fu 14	ustin Diedricksen uss & O'Neill EnviroScience, LLC l6 Hartford Road anchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 09/25/14 1:00 PM 9/25/2014 9/25/2014
----------	--	---	--

Project: 20121141.B1E / Peebles Elementary School, 70 Trowbridge rd, Bourne, MA

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			<u>Non-As</u>	<u>sbestos</u>	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
01A-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0001	exterior door caulking	Non-Fibrous Homogeneous			
01B-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0002	exterior door caulking	Non-Fibrous Homogeneous			
01C-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0003	exterior door caulking	Non-Fibrous Homogeneous			
02A-JH-925	Door D1 - White	Gray		98% Non-fibrous (other)	2% Chrysotile
131404197-0004	window glazing compound	Non-Fibrous Homogeneous			
02B-JH-925	Door D1 - White				Stop Positive (Not Analyzed)
131404197-0005	window glazing compound				
02C-JH-925	Door D1 - White				Stop Positive (Not Analyzed)
131404197-0006	window glazing compound				
03A-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0007	door widnow glazing compound	Non-Fibrous Homogeneous			
03B-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0008	door widnow glazing compound	Non-Fibrous Homogeneous			
03C-JH-925	Door D1 - Gray	Gray		100% Non-fibrous (other)	None Detected
131404197-0009	door widnow glazing compound	Non-Fibrous Homogeneous			

Analyst(s)

Kevin Pine (12)

the P.J.

Steve Grise, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 09/25/2014 15:40:17



EMSL Analytical, Inc. 7 Constitution Way, Suite 107, Woburn, MA 01801 Phone/Fax: (781) 933-8411 / (781) 933-8412 http://www.EMSL.com bostonlab@emsl.com EMSL Order: 131404197 CustomerID: ENVI54 CustomerPO: 20121141.B1E ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 09/25/14 1:00 PM 9/25/2014 9/25/2014
-------	--	---	--

Project: 20121141.B1E / Peebles Elementary School, 70 Trowbridge rd, Bourne, MA

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				Non-Asbes	stos	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
04A-JH-925	Door D1 - Brown	Tan	98%	Cellulose	2% Non-fibrous (other)	None Detected
131404197-0010	backer rope underneath-01	Fibrous Homogeneous				
04B-JH-925	Door D1 - Brown	Tan	98%	Cellulose	2% Non-fibrous (other)	None Detected
131404197-0011	backer rope underneath-01	Fibrous Homogeneous				
04C-JH-925	Door D1 - Brown	Tan	98%	Cellulose	2% Non-fibrous (other)	None Detected
131404197-0012	backer rope underneath-01	Fibrous Homogeneous				
05A-JH-925	Door D1 - Tan	Tan	8%	Fibrous (other)	90% Non-fibrous (other)	2% Chrysotile
131404197-0013	interior door caulking	Non-Fibrous Homogeneous				
05B-JH-925	Door D1 - Tan					Stop Positive (Not Analyzed)
131404197-0014	interior door caulking					
05C-JH-925	Door D1 - Tan					Stop Positive (Not Analyzed)
131404197-0015	interior door caulking					
06A-JH-925	Exterior - Black	Black	15%	Cellulose	70% Non-fibrous (other)	15% Chrysotile
131404197-0016	dampproofing behind brick veneer	Fibrous Homogeneous				
06B-JH-925	Exterior - Black					Stop Positive (Not Analyzed)
131404197-0017	dampproofing behind brick veneer					
06C-JH-925	Exterior - Black					Stop Positive (Not Analyzed)
131404197-0018	dampproofing behind brick veneer					

Analyst(s)

Kevin Pine (12)

the P.A

Steve Grise, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 09/25/2014 15:40:17

2

# 131404197 -

FUSS & O'NEILL
EnviroScience, цс

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

	ASBESTOS BULK SAMPI	LE CHAIN OF CUSTODY	Sheet $\underline{l}$ of $\underline{2}$
Project Name:lee	ebles Elementery School	Project No. 2012.	141. BIE
Site Address: <u>70</u>	Trowbordge Rd. Bourne, M	1AProject Manager:	Juston D.
	Publics Elementary S.	A	18
Sample ID (01A-Initials-Date)	Material Type	Sample Location	Comments/ Quantities
01A-JH-925	Gray Extentor Door Caulking	Deen DI	
BiB			
olc -	L	<u> </u>	
072 -	what wondow Glazmy		
orh -	· · · · ·		
orc-			
034-	Gray Door Wonday Glazon		
038-	Compound	· · · · · · · · · · · · · · · · · · ·	
030-	L		
011-	Brown Backer Rope, Undermeath -01		
0413-			
046 -			
05A-	Tan Interior Door Cambon		
05B·			
OFC.		↓	
Analysis Method: 🔀 PLM	1 TEM Dother	Turnaround Ti	me 3-hour
	ime indicated above, analyses are due to Envir eted for requested t/a/t at (617) 282-4675.	roScience on or before this date: Plea	se call EnviroScience If
Email Results to:	J.Hand@fando.com	n Do Not Mail Hard Copy Report FAX Re	sults to: 888-838-1160.
Special Instructions: Sto	p analysis on first positive sample in each hom	nogeneous set of samples unless otherwise noted. D	o not layer samples
unless indicated Do not p	oint count. If NOB group samples are all nega	trve by PLM; analyze only the "A" comple (as note	d bestar (Mabove)
by TEM NOB, on a	t/a/t. Analyze a maximum of	Isamples by TEM Call Jon @	101-595-5270
Samples Collected by: _		Date: 9/	25/14-
Samples Sent by:	D	Date:	
Shipped To: 🕅 EMSI		IVE 6	
Method of Shipment:	70		25 2014
Q'\EnviroScience\Admin\FO	RMS\Asbestos\Inspections\Boston\BSN Asb Bulk C Page 1 Of	2 By Sup	1100 m2

www.fando.com

# 131404197=

FUSS & O'NEILL EnviroScience, LLC

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

www.fando.com

	<b>ASBESTOS BULK</b>				Sheet <u>2</u> of <u>2</u>
Project Name:	ebles Elementary	School_	Project 1	No. 20/21141	.BLE
Site Address:	ebles Elementary : Tracebordge Ad, Peebles Element	Bourne, M	A Project I	Manager:	ta D.
Building Name/Number.	Peebles Element	any Salar	<u>l</u> Total #	of Samples:	8
Sample ID (01A-Initials-Date)	Material Type		Sample Location	n	Comments/ Quantities
ach-511-925	Black Damproof on Behand Brick		Exterior		
OB-	Veneer				
966-	L		<u> </u>		
· · · · · · · · · · · · · · · · · · ·					
		<u></u>			
Analysis Method: 🔀 PLN		<u> </u>		Turnaround Time	•
	ime indi <mark>ca</mark> ted above, analyses are c eted for requested t/a/t at (617) 2		on or before this date:	Please ca	all EnviroScience if
Email Results to:	J Hand @	fando.com Do N	lot Mail Hard Copy Re	port FAX Resul	ts to: 888-838-1160.
-	p analysis on first positive sample .	0	•		, ,
unless indicated. Do not p	oint count. If NOB group samples	,	LM: analyze only the "A" nples by TEM.	- <u>sample (as noted by</u>	<u>' star [<b>‡</b>]above)</u>
Samples Collected by:	gon /4a			Date:	
Samples Sent by:	ğH		9/25/14	_ Time:	
Shipped To: 🛛 EMSL				- IN	SEP 2 5 2014
Method of Shipment:				- <u> </u> _ (	$\frac{1}{1R}$ $1.00$
Q:\Enviro <b>Sci</b> ence\Admin\FO	RMS\Asbestos\Inspections\Boston\BS Pag	SN Asb Bulk CoC.docx ge 2 Of 2		By_	u.T



EMSL Order: CustomerID: CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 07/19/13 9:30 AM 7/23/2013
-------	--	---	---

20121141.A1E / Bourne Public Schools; Peebles Elementary School Cafeteria Project:

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using **Polarized Light Microscopy**

			Non-Asbestos			Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	%	Туре
718DD-01A	Art Room - Ceiling	White	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
131303044-0001	Skim Plaster	Non-Fibrous Homogeneous					
718DD-01B	Art Room - Ceiling	White	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
131303044-0002	Skim Plaster	Non-Fibrous Homogeneous					
718DD-01C	Art Room - Ceiling	White	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
131303044-0003	Skim Plaster	Non-Fibrous Homogeneous					
718DD-02A	Art Room - Ceiling	White	5%	Cellulose	95% Non-fibrous (other)	<1%	Chrysotile
131303044-0004	Rough Plaster	Non-Fibrous Homogeneous					
		riomogeneous	Sample ap	pears to be skim plas	ter.		
718DD-02B	Art Room - Ceiling	Gray			100% Non-fibrous (other)		None Detected
131303044-0005	Rough Plaster	Non-Fibrous Homogeneous					
718DD-02C	Art Room - Ceiling	Gray			100% Non-fibrous (other)		None Detected
131303044-0006	Rough Plaster	Non-Fibrous Homogeneous					
718DD-03A	Kitchen - Ceiling	White			100% Non-fibrous (other)		None Detected
131303044-0007	Skim Plaster	Non-Fibrous Homogeneous					
718DD-03B	Kitchen - Ceiling	White			100% Non-fibrous (other)		None Detected
131303044-0008	Skim Plaster	Non-Fibrous Homogeneous					

Analyst(s)

Kevin Pine (10) Steve Grise (6)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 07/23/2013 12:46:56



Attn:	Dustin Diedricksen	Phone:	(860) 646-2469
	146 Hartford Road Manchester, CT 06040	Fax:	
		Received:	07/19/13 9:30 AM
		Analysis Date:	7/23/2013
		Collected:	

Project: 20121141.A1E / Bourne Public Schools; Peebles Elementary School Cafeteria

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-As	Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
718DD-03C	Kitchen - Ceiling	White		100% Non-fibrous (other)	None Detected
131303044-0009	Skim Plaster	Non-Fibrous Homogeneous			
718DD-03D	Bathroom off	White		100% Non-fibrous (other)	None Detected
131303044-0010	Kitchen - Ceiling Skim Plaster	Non-Fibrous Homogeneous			
718DD-03E	Pantry - Ceiling	White		100% Non-fibrous (other)	None Detected
131303044-0011	Skim Plaster	Non-Fibrous Homogeneous			
718DD-04A	Kitchen - Ceiling	Gray		100% Non-fibrous (other)	None Detected
131303044-0012	Rough Plaster	Non-Fibrous Homogeneous			
718DD-04B	Kitchen - Ceiling	Gray		100% Non-fibrous (other)	None Detected
131303044-0013	Rough Plaster	Non-Fibrous Homogeneous			
718DD-04C	Kitchen - Ceiling	Gray		100% Non-fibrous (other)	None Detected
131303044-0014	Rough Plaster	Non-Fibrous Homogeneous			
718DD-04D	Bathroom off	Gray		100% Non-fibrous (other)	None Detected
131303044-0015	Kitchen - Ceiling Rough Plaster	Non-Fibrous Homogeneous			
718DD-04E	Pantry - Ceiling	Gray		100% Non-fibrous (other)	None Detected
131303044-0016	Rough Plaster	Non-Fibrous Homogeneous			

Analyst(s)

Kevin Pine (10) Steve Grise (6)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 07/23/2013 12:46:56

Test Report PLM-7.28.9 Printed: 7/23/2013 12:46:56 PM

2

131303044 131303044 24 HOUR FUSS + O'NETLL ENVIRASCIENCE - CHAINTO BE EMATLED PROTECT MANAGER - DUSTIN DIEDRICKSEN PROTECT NAME - BOURNE PUBLIC SCHOOLS-PEEBLES P.O. = 2012114 AIE ELEMENTARY SCHOOL (CAFETERIA) , SAMPLE NUMBER LOCATION MATERIAL Anarysus 71800-01A ART ROOM CETUNG SKIM PLASTER 2 - OIB 3 -dic 71800-02A 4 CETLING ROUGH PLASTER 5 -OZB 6 -OZC 718DD-03A KITCHEN 7 CEILING SKIM RASTER -03B 8 KITCHEN 9 -03c KITCHEN 10 -031 BATHROOM OFFKITCHEN -03E PANTAY 11 71800- 044 KITCHEN 12 CEILING ROUGH PLASTER 13 - OYB KITCHEN -OYC KITCHEH 14 15 - OYD BATHROOM OFF KITCHEN - OYE PANTRY 16 HOUR TURNAROUND DEGEIVEI JUL 1 9 2013 5/ 0930 FedEx# 7995 5206 4577



EMSL Order: 131204023 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Bob May	Phone:	(860) 646-2469	
	Fuss & O'Neill EnviroScience, LLC	Fax:	(888) 838-1160	
	•	Received:	08/15/12 4:30 PM	
	146 Hartford Road	Analysis Date:	8/16/2012	
Manchester, CT 06040	Collected:	8/15/2012		

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-A	<u>sbestos</u>	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
1 131204023-0001	Boy's Bath Basement - Rough Plaster Window Surround	Gray/W hite Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
2 131204023-0002	Boy's Bath Basement - Rough Plaster Window Surround	Gray/W hite Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
<b>3</b> 131204023-0003	Boy's Bath Basement - Skim Coat Window Surround	White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
<b>4</b> 131204023-0004	Boy's Bath Basement - Skim Coat Window Surround	White Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Renaldo Drakes (4)

Renaldo Drakes, Laboratory Manager or other approved signatory

1

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/16/2012 17:56:13

3	E 1 1			1395		VTICAL INC
EMSL		A COMPANY OF A COMPANY OF A COMPANY	umber (Lab Use Only):	15 4	EMSL ANAL 7 CONSTI	TUTION WAY SUITE 107
EMSL ANALYTICAL, INC.		13120			WOBURN PHONE: (78	N, MA 01801
LABORATORY · PRODUCTS · TRAINING						1)-933-8412
Company: Fu	55 & Oneill	(Enviroscient	EMSL If Bill to is	-Bill to: Same Different note instructi		
Street: 50 Red				requires written au	thorization from	third party
City: Dorchester MA State/Province:		Province: MA	Zip/Postal Code:	Cou	untry:	M. Cale
Report To (Name): Bob May / D. Diedo			Telephone #:	223A) - 34		
Email Address:			Fax #:	Pur	chase Order	:
	er: Peebles Element	hary Schoel	Please Provide Resul		Email	atial
U.S. State Samples			TAT) Options* – Please C			Iudi
3 Hour 6	Hour 24 Hou	r/ 48 Hou		96 Hour	1 Week	
an authorization 1	form for this service. Analys	is completed in acco	rdance with EMSL's Terms and	Conditions located in	the Analytical P	Price Guide.
	if samples are from NY		4-4.5hr TAT (AHERA only)	TEM-Dust		
NIOSH 7400			0 CFR, Part 763	Microvac	- ASTM D 57	55
w/ OSHA 8hr. TW		D NIOSH 74			onication (EP/	A 600/1-93/16
PLM-Bulk (reportin		☐ ISO 10312		Soil/Rock/V		00010 00110
D PLM EPA 600/R-93/116 (<1%)		TEM - Bulk			PLM CARB 435 - A (0.25% sensitivi	
Point Count	,		NOB		RB 435 - B (0.	1% sensitivity
☐ 400 (<0.25%) ☐ 1000 (<0.1%) Point Count w/Gravimetric			198.4 (non-friable-NY)		TEM CARB 435 - B (0.1% sensitivit	
		Chatfield SOP		I I I TEM CAP	TEM CARB 435 - C (0.01% sensitiv TEM Qual. via Filtration Technique	
					and the second se	
□ 400 (<0.25%) □ 1	1000 (<0.1%)	TEM Mass	Analysis-EPA 600 sec. 2.8	5 TEM Qua	I. via Filtration	n Technique
□ 400 (<0.25%) □ 1 □ NYS 198.1 (friable	1000 (<0.1%) e in NY)		Analysis-EPA 600 sec. 2.8	5 TEM Qua	and the second se	n Technique
□ 400 (<0.25%) □ 1	1000 (<0.1%) e in NY) (non-friable-NY)	TEM Mass TEM – Water Fibers >10µm	Analysis-EPA 600 sec. 2.8 EPA 100.2	5 TEM Qua	I. via Filtration	n Technique
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19)	1000 (<0.1%) e in NY) (non-friable-NY)	TEM Mass TEM – Water Fibers >10µm All Fiber Sizes	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Waste Drinking	5 TEM Qua	I. via Filtration	n Technique
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19)	1000 (<0.1%) e in NY) (non-friable-NY) %)	TEM Mass TEM – Water Fibers >10µm All Fiber Sizes	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Waste Drinking	5 TEM Qua TEM Qua Other: 0 e (Air Samples):	II. via Filtration II. via Drop-Me	n Technique ount Techniq
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19)     Check For Positive	1000 (<0.1%) e in NY) (non-friable-NY) %)	TEM Mass TEM – Water Fibers >10µm All Fiber Sizes	Analysis-EPA 600 sec. 2.3 EPA 100.2 Waste Drinking Waste Drinking Group Filter Pore Size Samplers Signatur	5 TEM Qua TEM Qua Other: 0 e (Air Samples):	II. via Filtration II. via Drop-Me D 0.8µm	n Technique ount Techniq
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19)     Check For Positive Samplers Name:	1000 (<0.1%) e in NY) (non-friable-NY) <u>%)</u> ve Stop – Clearly Ident	TEM Mass TEM – Water Fibers >10µm All Fiber Sizes ify Homogenous Sample Descri	Analysis-EPA 600 sec. 2.5 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signature ption Window Surray	5   TEM Qua TEM Qua Other: c (Air Samples): re: Volume/Are HA # (Bu	I. via Filtration II. via Drop-Me D 0.8µm Pa (Air) ulk)	n Technique ount Techniq
400 (<0.25%) ☐ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19     Check For Positive Samplers Name:     Sample #     \	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B	TEM Mass TEM – Water Fibers >10µm All Fiber Sizes ify Homogenous Sample Descrit Osement Cov	Analysis-EPA 600 sec. 2.5 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption Window Surra Window Surra	5   TEM Qua TEM Qua Other: c (Air Samples): re: Volume/Are HA # (Bu	I. via Filtration II. via Drop-Me D 0.8µm 2a (Air) ulk)	n Technique ount Techniq 0.45µm Date/Time Sampled -\5
400 (<0.25%)      1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19     Check For Positive     Samplers Name:     Sample #     \     Z	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B Boy's Bath B	TEM Mass TEM - Water Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descri asement Four General Four	Analysis-EPA 600 sec. 2.3 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Window Surra Window Surra Window Surra	5 □ TEM Qua □ TEM Qua <u>Other:</u> □ e (Air Samples): re: Volume/Are HA # (Bi	I. via Filtration II. via Drop-Me D 0.8µm a (Air) ulk) 3	Date/Time Sampled
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19     Check For Positive     Samplers Name:     Sample #     \	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B Boy's Bath B Boy's Bath B	TEM Mass <u>TEM - Water</u> Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four asement Four	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Composition N Rlaster Composition Samplers Signatur	5   TEM Qua TEM Qua Other: 0 e (Air Samples): re: Volume/Are HA # (Bu	I. via Filtration I. via Drop-Me D 0.8µm a (Air) ulk) S S S S	n Technique ount Techniq 0.45µm Date/Time Sampled -15 -15
400 (<0.25%)      1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19     Check For Positive     Samplers Name:     Sample #     \     Z	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B Boy's Bath B Boy's Bath B	TEM Mass <u>TEM - Water</u> Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four asement Four	Analysis-EPA 600 sec. 2.3 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Window Surra Window Surra Window Surra	5   TEM Qua TEM Qua Other: 0 e (Air Samples): re: Volume/Are HA # (Bu	I. via Filtration I. via Drop-Me D 0.8µm a (Air) ulk) S S S S	Date/Time Sampled
400 (<0.25%) □ 1     NYS 198.1 (friable     NYS 198.6 NOB (     NIOSH 9002 (<19     Check For Positive     Samplers Name:     Sample #     \	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B Boy's Bath B Boy's Bath B	TEM Mass <u>TEM - Water</u> Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four asement Four	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Composition N Rlaster Composition Samplers Signatur	5   TEM Qua TEM Qua Other: 0 e (Air Samples): re: Volume/Are HA # (Bu	I. via Filtration I. via Drop-Me D 0.8µm a (Air) ulk) S S S S	Date/Time Sampled
□       400 (<0.25%)	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath B Boy's Bath B Boy's Bath Bas Boy's Bath Bas	TEM Mass TEM - Water Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four sement Skim	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Common Window Surray Coat Window Surray Coat Window Surray	5   TEM Qua DEPENDENT Conter: Conte:	I. via Filtration I. via Drop-Ma D 0.8µm Pa (Air) ulk) S S S S S S S S S S S S S	n Technique ount Techniq 0.45µm Date/Time Sampled -15 -15 -15 -15
<ul> <li>400 (&lt;0.25%) □ 1</li> <li>□ NYS 198.1 (friable</li> <li>□ NYS 198.6 NOB (</li> <li>□ NIOSH 9002 (&lt;19</li> <li>☑ Check For Positin</li> <li>Samplers Name:</li> <li>Sample #</li> <li>1</li> <li>2</li> <li>3</li> <li>Ч</li> </ul>	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath Ba Boy's Bath Ba Boy's Bath Bas Boy's Bath Bas	TEM Mass TEM - Water Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four sement Skim	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Composition N Rlaster Composition Samplers Signatur	5   TEM Qua DEPENDENT Conter: Conte:	I. via Filtration I. via Drop-Ma D 0.8µm Pa (Air) UIK) S S S S S S S S S S S S S	n Technique ount Techniq 0.45µm Date/Time Sampled -15 -15 -15 -15
<ul> <li>400 (&lt;0.25%) □ 1</li> <li>NYS 198.1 (friable</li> <li>NYS 198.6 NOB (</li> <li>NIOSH 9002 (&lt;19</li> <li>✓ Check For Positiv</li> <li>Samplers Name:</li> <li>Sample #</li> <li>\</li> <li>2</li> <li>3</li> <li>4</li> <li>Client Sample # (s):</li> <li>Relinquished (Client</li> <li>Received (Lab):</li> </ul>	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath Ba Boy's Bath Ba Boy's Bath Bas Boy's Bath Bas (Boy's Bath Bas (Boy's Bath Bas) (Cholas Grave)	TEM Mass TEM - Water Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four sement Skim sement Skim a - Nallese Da	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Common Window Surray Coat Window Surray Coat Window Surray	5    TEM Qua    TEM Qua <u>Other:</u>    e (Air Samples): re: Volume/Are HA # (Bi ))                         	a (Air) ulk) 3 3 3 3 3 3 3 3 3 3 3 3 3	n Technique ount Techniq 0.45µm Date/Time Sampled -15 -15 -15 -15
□       400 (<0.25%) □	1000 (<0.1%) e in NY) (non-friable-NY) %) ve Stop - Clearly Ident Boy's Bath Ba Boy's Bath Ba Boy's Bath Bas Boy's Bath Bas (Boy's Bath Bas (Boy's Bath Bas) (Cholas Grave)	TEM Mass TEM - Water Fibers > 10µm All Fiber Sizes ify Homogenous Sample Descrit asement Four asement Four sement Skim sement Skim a - Nallese Da	Analysis-EPA 600 sec. 2.4 EPA 100.2 Waste Drinking Group Filter Pore Size Samplers Signatur ption gh plaster Control Window Surray Coat Window Surray Coat Window Surray Coat Window Surray	5    TEM Qua    TEM Qua <u>Other:</u>    e (Air Samples): re: Volume/Are HA # (Bu ) ) ) ) ) ) ) ) ) ) ) ) )	a (Air) ulk) 3 3 3 3 3 3 3 3 3 3 3 3 3	n Technique ount Techniq □ 0.45µm Date/Time Sampled -15 -15 -15 -15 -15 -15 -15 -15 -15 -15

Page 1 of \_\_\_\_\_ pages

1.0 1



EMSL Order: 131204082 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/20/12 10:50 AM 8/20/2012 8/17/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-	Asbestos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
817NG-01A 131204082-0001	Cafeteria Window Bank (#6 L-R) - Window Surround Skim Plaster (Underside)	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
817NG-01B 131204082-0002	Cafeteria Window Bank (#10) - Window Surround Skim Plaster (Underside)	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
817NG-01C 131204082-0003	Cafeteria Window Bank (#7) - Window Surround Skim Plaster (Frontside)	White Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
817NG-02A 131204082-0004	Cafeteria Window Bank (#6 L-R) - Window Surround Skim Plaster (Under)	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
817NG-02B 131204082-0005	Cafeteria Window Bank (#10) - Window Surround Skim Plaster (Under)	Brown Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected

Analyst(s)

Renaldo Drakes (8) Steve Grise (4)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/20/2012 17:09:39



EMSL Order: 131204082 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/20/12 10:50 AM 8/20/2012 8/17/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			<u>Non-A</u>	sbestos	<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
817NG-02C	Cafeteria Window	Gray		100% Non-fibrous (other)	None Detected
131204082-0006	Bank (#7) - Window Surround Skim Plaster (Front)	Non-Fibrous Homogeneous			
817NG-03A	Cafeteria	White		100% Non-fibrous (other)	None Detected
131204082-0007	Dropbeam at Ceiling (Near Door) - Skim Plaster	Non-Fibrous Heterogeneous			
817NG-03B	Cafeteria	White		100% Non-fibrous (other)	None Detected
131204082-0008	Dropbeam at Ceiling (Middle Beam) - Skim Plaster	Non-Fibrous Heterogeneous			
817NG-03C	Cafeteria	White		100% Non-fibrous (other)	None Detected
131204082-0009	Dropbeam at Ceiling (Corner Near Kitch.) - Skim Plaster	Non-Fibrous Homogeneous			
817NG-04A	Cafeteria	White		100% Non-fibrous (other)	None Detected
131204082-0010	Dropbeams (Door) - Rough Plaster	Non-Fibrous Heterogeneous			
817NG-04B	Cafeteria	White		100% Non-fibrous (other)	None Detected
131204082-0011	Dropbeams (Middle) - Rough Plaster	Non-Fibrous Heterogeneous			

Analyst(s)

Renaldo Drakes (8) Steve Grise (4)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/20/2012 17:09:39

Test Report PLM-7.16.0 Printed: 8/20/2012 5:16:39 PM



EMSL Order: 131204082 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/20/12 10:50 AM 8/20/2012 8/17/2012

Project: 20121141.A1E / Peebles Elementary School

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	sbestos	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
817NG-04C	Cafeteria	Gray			100% Non-fibrous (other)	None Detected
131204082-0012	Dropbeams (Kitchen) - Rough Plaster	Non-Fibrous Homogeneous				

Analyst(s)

Renaldo Drakes (8) Steve Grise (4)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/20/2012 17:09:39

3

2	204082
$\mathbf{\nabla}$	20 1002

www.fando.com

0 Redfield St, Suite 100, Boston, MA 02122

FUSS & O'NEILL EnviroScience, LLC

131204082

(617) 282-4675 Fax (617) 282-8253

Project Name:	S ELEMENTARY SCHO	R ASBESTOS BULKS	Sheet of 0121141. AIE
Building: AFEBLET	ELEMENTARY SCHOOL	Project Manager:	DUSTIN DIEDRICK
Sample ID	Sample Location	Material	Result (%)
81716-014	CATER MA WINDOW BANK	WINDOW SUPPOUND STIM	PLASTER (UNDER
-OIB	(#10)	1	UNDER
-010	(#7)		(FRONTS
817NG-024	CAFETERIA WINDOW BAT	WINDOW SURPOUND	A - /
-023	(#10) (#	6 L F )	(UND
-020	(#7)		(Fran
817NG-03A	CAFERENA DROPBE	AMS (DOUR) SKIM PLASTE	Crit
-03B	1 @ CEILING/M	LIDDLE GEAM)	
-036	1 (Ropron	NEAR KITCHED	
SANG-OYA		Borns (Dorop) Roug	H PLASTER
- 04B		(MIDDLE)	
-040		(KITCHEN) 1	
aboratory if analyses will be lat	ence Laboratory at: 888-838-1160.	Descience on or before this date: 8 12 P	Amp Les
amples collected by:		e: <u>8/17/12</u> Time:	Pm
amples [Rec'd] [Sent by] [	][ <u><u></u><u></u><u></u><u></u><u></u>]Dat</u>	te: [][ <b>D</b> /20/12 ] Time:	HM
mples Received by:	Date:	Time:	
ipped To: EMSL Stat	e Other		
ethod of Shipment: 🗌 Fed I	Ex 🔲 UPS Overnight 🔲 UPS Grou	nd Drap OFF	
\EnviroScience\Admin\FORMS\M	fass Forms\Asbestos Bulks Chain of Custody Bo	By_	<u>50 1050</u>



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Fuss & O'Neill EnviroScience, LLC	Phone: Fax: Received:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM	
	146 Hartford Road Manchester, CT 06040	Analysis Date:	8/22/2012	
	Manchester, CT 00040	Collected:	8/21/2012	

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	sbestos	Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type	
821DD-01A 131204139-0001	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
821DD-01B 131204139-0002	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
821DD-01C 131204139-0003	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
821DD-02A 131204139-0004	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
821DD-02B 131204139-0005	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM 8/22/2012 8/21/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-A	sbestos	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
821DD-02C 131204139-0006	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-03A 131204139-0007	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Caulking @ Ductwork and Plaster Ceiling	Tan Non-Fibrous Homogeneous			95% Non-fibrous (other)	5% Chrysotile
821DD-03B 131204139-0008	Kitchen @ OverheadDuct a/w Range Hood Drop Ceiling - Caulking @ Ductwork and Plaster Ceiling					Stop Positive (Not Analyzed)
821DD-04A 131204139-0009	Kitchen Window Surround - Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-04B 131204139-0010	Kitchen Window Surround - Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-05A 131204139-0011	Kitchen Window Surround - Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM 8/22/2012 8/21/2012
D			

Project: 20121141.A1E / Peebles Elementary School

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-As	sbestos	Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
821DD-05B	Kitchen Window	Gray		100% Non-fibrous (other)	None Detected	
131204139-0012	Surround - Rough Plaster	Non-Fibrous Homogeneous				
821DD-06A	Basement Boys	White		100% Non-fibrous (other)	None Detected	
131204139-0013	Bathroom - Smooth Skim Plaster Ceiling	Non-Fibrous Homogeneous				
821DD-06B	Basement Boys	White		100% Non-fibrous (other)	None Detected	
131204139-0014	Bathroom - Smooth Skim Plaster Ceiling	Non-Fibrous Homogeneous				
821DD-06C	Basement Girls	White		100% Non-fibrous (other)	None Detected	
131204139-0015	Bathroom - Smooth Skim Plaster Ceiling	Non-Fibrous Homogeneous				
821DD-06D	1st Fl Boys	White		100% Non-fibrous (other)	None Detected	
131204139-0016	Bathroom - Smooth Skim Plaster Drop Ceiling	Non-Fibrous Homogeneous				
821DD-06E	1st Fl Girls	White		100% Non-fibrous (other)	None Detected	
131204139-0017	Bathroom - Smooth Skim Plaster Drop Ceiling	Non-Fibrous Homogeneous				
821DD-07A	Basement Boys	Gray		100% Non-fibrous (other)	None Detected	
131204139-0018	Bathroom - Rough Ceiling Plaster	Non-Fibrous Homogeneous				

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05

Test Report PLM-7.16.0 Printed: 8/22/2012 2:33:05 PM



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM 8/22/2012 8/21/2012
Projec	ct: 20121141.A1E / Peebles Elementary School		

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA

600/M4-82-020 Method(s) using Polarized Light Microscopy

				<u>Non-Asl</u>	<u>bestos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
821DD-07B 131204139-0019	Basement Boys Bathroom - Rough Ceiling Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-07C 131204139-0020	Basement Girls Bathroom - Rough Ceiling Plaster	Gray Non-Fibrous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
821DD-07D 131204139-0021	1st Fl Boys Bathroom - Rough Drop Ceiling Plaster	Homogeneous Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-07E 131204139-0022	1st Fl Girls Bathroom - Rough Drop Ceiling Plaster	Gray Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
821DD-08A 131204139-0023	Annex Boys Bathroom 1st FI - Smooth Ceiling Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-08B 131204139-0024	Annex Girls Bathroom 1st FI - Smooth Ceiling Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-08C 131204139-0025	Annex Girls Bathroom 1st FI - Smooth Ceiling Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05

Test Report PLM-7.16.0 Printed: 8/22/2012 2:33:05 PM



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC	Phone: Fax: Received:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM
	146 Hartford Road Manchester, CT 06040	Analysis Date:	8/22/2012
	Marchester, CT 00040	Collected:	8/21/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	sbestos	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
821DD-08D 131204139-0026	Annex Boys Ground/Basement Bathroom - Smooth Ceiling Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-08E 131204139-0027	Annex Girls Ground/Basement Bathroom - Smooth Ceiling Skim Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-09A 131204139-0028	Annex Boys Bathroom 1st FI - Smooth Ceiling Rough Plaster	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-09B 131204139-0029	Annex Girls Bathroom 1st FI - Smooth Ceiling Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-09C 131204139-0030	Annex Girls Bathroom 1st FI - Smooth Ceiling Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
821DD-09D 131204139-0031	Annex Boys Ground/Basement Bathroom - Smooth Ceiling Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05



EMSL Order: 131204139 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/22/12 9:30 AM 8/22/2012 8/21/2012

Project: 20121141.A1E / Peebles Elementary School

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	sbestos	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
821DD-09E 131204139-0032	Annex Girls Ground/Basement Bathroom - Smooth Ceiling Rough Plaster	Gray Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (31)

Renaldo Drakes, Laboratory Manager or other approved signatory

6

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/22/2012 14:33:05

1204139	www.fando.com
(617) 2	82-4675 Fax (617) 282-8253
ASBESTOS BULKS	: 2
	Sheet $1 \text{ of } 3$
Project Manager	DUSTIN DIEDRICKS
Material	Result (%)
SKIM PLASTER	APPROX SOSF
1 1	1
und)	
ROUGH PLASTER	
V.	
CAULKING AT DUC	WORK 25LF
SPRAND SKIM PU	ASTER
1	
POVER PLASTER	
V	A
Turnaround Time	6 HOUR)
	Please call the EnviroScience
	-
IVE IN EACH HOM	OGENEOUSSET
	•
0/01/12	Dan
e: 8/21/12 Time:	P/1.
te: [][ <b>8/4/12</b> ] Time:	pm
Time:	
	DEGEUVE
and Other	AUG 2 2 2012
and Other	AUG 2 2 2012
	(617) 2 ASBESTOS BULKS $M_{1} \\ Stim Project No Material Material Stim PLASTER I CAULKING AT DUCK AND PLASTER CAULKING AT DUCK AND PLASTER CAULKING AT DUCK AND PLASTER Scence on or before this date: M_{1} \\ Rough PLASTER V Turnaround Time Science on or before this date: M_{2} \\ Rough PLASTER V Turnaround Time Science on or before this date: M_{2} \\ Rough PLASTER V Turnaround Time Time: M_{2} \\ Rough PLASTER V Turnaround Time Time: M_{2} \\ Rough PLASTER V Turnaround Time Time: M_{2} \\ M_{2$

Q:\EnviroScience\Admin\FORMS\Mass Forms\Asbestos Bulks Chain of Custody Boston rev 0611.doc

131204139				
	& O'NEILL Science, LLC	131204139		www.fando.com
Redfield St, Suite 100, B	oston, MA 02122		(617) 282-4	675 Fax (617) 282-8253
•	SAMPLE LOG	FOR ASBESTOS E	BULKS	
*				Sheet $2_{of} 3_{d}$
Project Name:	EBLES ELEMENTA	try SCHOOL	_ Project No. 2012	21141. AIE
Building:	S ELEMENTARY S	EMOOL	_ Project Manager:	STIN DIEDRICKSEN
Sample ID	Sample Location	M	laterial	Result (%)
13 821 DD-06A	BASIGMENT BUYS B	ATHRON SMOTH	SKIM PLASTER	2 CAUNG
14 -OGB	BASEMENT BAYS B		1	On al Al Xala
15 -06C	CARAS BASEMENT			Carrierog
16 -060	IST FLOOR BASBA		(DAD	(ETLING)
17 -06E	ISTFEEDR GIRLS B.			/
18 821DD-07A	BASEMENT Bays	BATHROOM RO	NGH CEILING	PLASTER
19 -078	1 4			
26 -070	BASEMENT GIRLS	BATHROOM		
2 -070	Ist Frank Bays	BATTHRoom	ľ A	Rup CEILING)
22 -07E	IST Fron Gines	BATHROM	y c	1
23 821 DD-08A	ANNET BOYS BATTY	earn Ist Fran S	MOOTH CEILIN	6 SKIM PLASTER
24 -08B	AND GIRLS BATT	yrum lo Fran	- 1	
Analysis Method: PLM	🗌 Other	1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Turnaround Time6	HOUR
Based on the turnaround time	indicated above, analyses are due to	EnviroScience on or before th	nis date: Please	call the EnviroScience
Laboratory if analyses will be				
/	cience Laboratory at: 888-838-1160	•		
Special Instruction:	LE BI MGE			
			•	
Samples collected by:	<u>.</u>	Date: 8/21/12	Time: PA	7
Samples [Rec'd] [Sent by] [	ING	Date: [ ]8/21	/12 ] Time: P	n
Samples Received by:	Date	:T	/ ime:	
Shipped To: EMSL S	tate Ma Othe	er		
Method of Shipment:	· · ·	'S Ground 🔲 Other		
			ШU	AUG 2 2 2012
	2		By	50 0930
			<u></u>	

Q:\EnviroScience\Admin\FORMS\Mass Forms\Asbestos Bulks Chain of Custody Boston rev 0611.doc

÷

131204139			
FUSS & O'NEI EnviroScience, Redfield St, Suite 100, Boston, MA 0212	LLC <b>1312</b>	<b>0 4 1 3 9</b> (617) 282	www.fando.com -4675 Fax (617) 282-8253
SAN	MPLE LOG FOR ASBE	STOS BULKS	Sheet 3 of 3
Project Name: ACERLES E	ELEMENTARY SCHOOL	L Project No. Z	0121141, AIE
Building: PEEBLES ELEA	MENTARY & HOOL		AUTIN BIEDRICKSEN
Sample ID S	ample Location	Material	Result (%)
25 - UBC	1 Grang		
26 -080 ANNOR	- Buys BASEMENT BATT	yram	
27 - OBE ANNER	GIRLS GRAND/BASEN		
28 821DD-094 ANNER	- Bays BATH IST I	E. SMOOTHCE	UNG PAUGU PLASTER
29 - 09B	GIRLS BATH IST	F.	
30 - OGC	GIRES BATH IST	F.	
31 -09D	Boys BATH BGAN	NO/BASOMENT	
32 -OPEV	GIRLS BATH GROUI	BASENOUT /	
		/ /	
•			1. F.
	2	/	
Analysis Method: PLM 🔲 Other		Turnaround Time	6 Har
Based on the turnaround time indicated above	e, analyses are due to EnviroScience o	n or before this date: Ple	ease call the EnviroScience
• Laboratory if analyses will be late at (860) 646	-2469.		
Fax Results to the EnviroScience Laborate			
Special Instruction: STOP A	T IST POSITI	VE	
$\Delta \Delta$		chilip	Da
Samples collected by: $\underline{\mathcal{P}}$ .	Date:	5/21/12 Time:	219
Samples [Rec'd] [Sent by] [	1[ 106 ] Date: [	<u>[8/21/12]</u> Time:	
Samples Received by:	Date:	Time:	DROFINED
Shipped To: EMSL State MF	7 🗌 Other		DECEUVEN
Method of Shipment: Fed Ex UPS	Overnight UPS Ground	Other	AUG 2 2 2012
0			~ ~ 0930
			By on a first

Q:\EnviroScience\Admin\FORMS\Mass Forms\Asbestos Bulks Chain of Custody Boston rev 0611.doc



EMSL Order: 131204211 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/23/12 5:05 PM 8/24/2012 8/22/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

		Non-Asbestos			Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
0826DD-01A	Copy Room - Skim	White		100% Non-fibrous (other)	None Detected	
131204211-0001	Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-01B	Copy Room - Skim	White		100% Non-fibrous (other)	None Detected	
131204211-0002	Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-01C	Music Room -	White		100% Non-fibrous (other)	None Detected	
131204211-0003	Skim Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-01D	Teacher's	White		100% Non-fibrous (other)	None Detected	
131204211-0004	Lounge - Skim Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-01E	Teacher's	White		100% Non-fibrous (other)	None Detected	
131204211-0005	Lounge - Skim Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-02A	Copy Room -	Gray		100% Non-fibrous (other)	None Detected	
131204211-0006	Rough Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-02B	Copy Room -	Gray		100% Non-fibrous (other)	None Detected	
131204211-0007	Rough Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-02C	Music Room -	Gray		100% Non-fibrous (other)	None Detected	
131204211-0008	Rough Ceiling Plaster	Non-Fibrous Homogeneous				

Analyst(s)

Kevin Pine (4) Steve Grise (6)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/24/2012 16:24:04



EMSL Order: 131204211 CustomerID: ENVI54 CustomerPO: ProjectID:

(860) 646-2469 (888) 838-1160 08/23/12 5:05 PM	Phone: Fax: Received:	ttn: Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC
8/24/2012	Analysis Date:	146 Hartford Road
8/22/2012	Collected:	Manchester, CT 06040
8/22/2012	Collected:	

Project: 20121141.A1E / Peebles Elementary School

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

		Non-Asbestos Asbestos				
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
0826DD-02D	Teacher's	Gray			100% Non-fibrous (other)	None Detected
131204211-0009	Lounge - Rough Ceiling Plaster	Non-Fibrous Homogeneous				
0826DD-02E	Teacher's	Gray			100% Non-fibrous (other)	None Detected
131204211-0010	Lounge - Rough Ceiling Plaster	Non-Fibrous Homogeneous				

Analyst(s)

Kevin Pine (4) Steve Grise (6)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/24/2012 16:24:04

131204211
-----------

FUSS & O'NEILL EnviroScience, LLC

131204211

50 Redfield St, Suite 100, Boston, MA 02122

www.fando.com

(617) 282-4675 Fax (617) 282-8253

	BLES ELEMENTARY SCHOL	Project No.	20121141. 415
Building: PEEBL	ES ECEMENTARY SCHOOL	Project Manager	BUSTIN DIEDI
Sample ID	Sample Location	Material	Result (%)
826DD-01A	Copy Room	SKIM CALING PLAST	Er-
-013	Copy Room		
-oic	Music Room		
-01D	TEACHERS' LUNGE		
-015	TEACHERS' LOUNGE		
82600-024	Copy Room	Rach COUNG PLAS	TER
-02B	Copy Room		
- 020	Music Room		:
-020	TEACHERS' LOUNGE		
-02E	TEACHERS' LOUNGE		
aboratory if analyses will be ax Results to the Enviros	e late at (860) 646-2469. Science Laboratory at: 888-838-1160. STOP AT IST POSITI	NE. No POINT CO	UNTING
amples collected by: amples [Rec'd] [Sent by] amples Received by:	Date:	-122/1-	PM PM
amples collected by: amples [Rec'd] [Sent by] amples Received by: ampled To:EMSL	Date: Date: Date: Date: Date: Date: Date: Date:	Time:	PM PM
amples collected by: amples [Rec'd] [Sent by] amples Received by: hipped To:	Date: Date: Date: Date: Date: Date: Date: Date:	[[5/23/]2_] Time:	PM PM E C E I V E AUG 2 3 2012



EMSL Order: 131204268 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Bob May Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/27/12 4:09 PM 8/27/2012 8/27/2012
Projec	ct: Peebles Elem. School; Bourne, MA		

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-As	bestos	Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
827-NG-1 131204268-0001	Classroom 2 - Window Glazing White Thin Coat	White Non-Fibrous Heterogeneous		98% Non-fibrous (other)	2% Chrysotile	
827-NG-2 131204268-0002	Classroom 2 - Window Glazing White Thin Coat	White Non-Fibrous Heterogeneous		98% Non-fibrous (other)	2% Chrysotile	
827-NG-3 131204268-0003	Classroom 6 - Window Glazing White/Thin	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected	
827-NG-4 131204268-0004	Classroom 6 - Window Glazing White/Thin	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected	
827-NG-5 131204268-0005	Classroom 8 - Vinyl Covering on Radiators Tan/Purple	Tan Non-Fibrous Heterogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected	
827-NG-6 131204268-0006	Classroom 8 - Vinyl Covering on Radiators Tan/Purple	Brown Fibrous Heterogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected	
827-NG-7 131204268-0007	Classroom 8 - Caulking Window Gray	Gray Fibrous Heterogeneous	15% Cellulose	83% Non-fibrous (other)	2% Chrysotile	
827-NG-8 131204268-0008	Classroom 7 - Caulking Window Gray	Gray Non-Fibrous Heterogeneous	15% Cellulose	83% Non-fibrous (other)	2% Chrysotile	

Analyst(s)

Renaldo Drakes (12)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/27/2012 18:22:21

Test Report PLM-7.16.0 Printed: 8/27/2012 6:25:04 PM



EMSL Order: 131204268 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Bob May Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 08/27/12 4:09 PM 8/27/2012 8/27/2012
Proje	ct: Peebles Elem. School; Bourne, MA		

# Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

			Non-As	bestos	Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
827-NG-9 131204268-0009	Classroom 5 - Newer Smooth Glazing Win	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected	
827-NG-10 131204268-0010	Classroom 5 - Newer Smooth Glazing Win	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected	
827-NG-11 131204268-0011	Classroom 6 Ext Caulking Win. Gray, White	White Non-Fibrous Heterogeneous		98% Non-fibrous (other)	2% Chrysotile	
827-NG-12 131204268-0012	Café Ext White Window Glazing	White Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected	

Analyst(s)

Renaldo Drakes (12)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 08/27/2012 18:22:21

8 Aug. 27. 2012 3	:47PM 131	204268	No. 0355 P. 2
(A):		201200	10.0555 1.2
FUSS a	& O'NEILL		
Enviros	Science, LLC		6 A
			www.fando.com
50 Redfield St, Suite 100, Be	ston, MA 02122	(617	) 282-4675 Fax (617) 282-8253
			,,
	SAMPLE LOG FO	R ASBESTOS BULKS	
0	Dourne,	769	Sheet of
Project Name: <u>Pee</u>	blus Elen J	6500/ Project No.	BSIJH. 74-A
Building Pec		110jeet 140	BUSH THE
Duncing,	Star Elen Se	Project Manage	PEDRICKS
Sample ID	Sample Location		· · · · · · · · · · · · · · · · · · ·
867		Material	Result (%)
×22-1	/	ELAZING th.	e e
12	CLASSINON 1210		s/[
. 3	CLASSTONY	WINdow Glacin	
2	~ ~ ~	whitether	7
7	+		
5	CLASSION	VINYI comerine	2
6	L.	OA radiatory	
	CLAIJ.		TIC
	£	WINGAULKING	
1 8	CASI	in the starty	
6	ELAJJ.	NEWERSMON	200
		CLAZING WI	31
1 10	4	L	
10	CAJI T	CALKING	
17 4	CATEXT	White WILLOW	4000
16	ERT	GLAZING	
Analysis Method: DFLM	Other		31
locad on the human data	AR 8/27/12	Turnaround Time	
Aboratory if analyses will be late	dicated above, analyses are due to Enviro	oScience on or before this date:	Please call the EnviroScience
ax Results to the BaviroScier	ace Laboratory at: 888-838-1160.		
pecial Instruction:	10 KOLAI	T EDMANT	
A.	VACULA	ALL IBAC	61
C/	36 - 6/7-	778-37	-62
amples collected by:	16-	5/ 1	
ampies conected by:	Date		pn
amples [Rec'd] [Seat by]	Def Dat	re: [][ ] Time;	pm pl
mples Received by:			<u> </u>
mpice acceived by:	Date:	Time:	<u></u>
ipped To: DEMSL State	MAI Dother	· · · · · · · · · · · · · · · · · · ·	
ethod of Shipment: 🔲 Fed Ex		- 6 - 7- 15	
and a complicat: U red Ex	UPS Overnight 🗍 UPS Grou	nd Dother DIJOR	100
			DECEDUEN
			5
		1	AUG 2 7 2012
EnviroScience Admin FORMS Ma	ss Ponns Asbestos Bulks Chain of Custody Bos	ton sev 0611.doc	
	4		By DAR 1609



EMSL Order: 131204500 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 09/12/12 9:15 AM 9/12/2012 9/7/2012
Projec	ct: 20121141.A1E / Peebles Elementary School		

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				Non-As	bestos	Asbestos	
Sample	Description	Appearance	% F	ibrous	% Non-Fibrous	% Type	
97NG-01A 131204500-0001	Classroom - Lightweight Parging Matl behind Lally Column	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-01B 131204500-0002	Classroom - Lightweight Parging Matl behind Lally Column	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-01C 131204500-0003	Classroom - Lightweight Parging Matl behind Lally Column	White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-02A 131204500-0004	South Exterior - Weatherproofing Cushion Felt under Unit Vents	Black Fibrous Heterogeneous	15%	Cellulose	85% Non-fibrous (other)	None Detected	
97NG-02B 131204500-0005	South Exterior - Weatherproofing Cushion Felt under Unit Vents	Black Fibrous Heterogeneous	15%	Cellulose	85% Non-fibrous (other)	None Detected	
97NG-02C 131204500-0006	South Exterior - Weatherproofing Cushion Felt under Unit Vents	Black Fibrous Heterogeneous	15%	Cellulose	85% Non-fibrous (other)	None Detected	

Analyst(s)

Kevin Pine (4) Steve Grise (8)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 09/12/2012 15:31:44



EMSL Order: 131204500 CustomerID: ENVI54 CustomerPO: ProjectID:

Attn:	Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040	Phone: Fax: Received: Analysis Date: Collected:	(860) 646-2469 (888) 838-1160 09/12/12 9:15 AM 9/12/2012 9/7/2012

Project: 20121141.A1E / Peebles Elementary School

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

				<u>Non-Asl</u>	<u>bestos</u>	Asbestos	
Sample	Description	Appearance	% F	ibrous	% Non-Fibrous	% Type	
97NG-03A 131204500-0007	South Exterior - Brown/Tan Window & Expansion Joint Caulking	Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-03B 131204500-0008	South Exterior - Brown/Tan Window & Expansion Joint Caulking	Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-03C 131204500-0009	South Exterior - Brown/Tan Window & Expansion Joint Caulking	Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
97NG-04A 131204500-0010	North Front Exterior - White/Gray Window Caulking	Gray Non-Fibrous Homogeneous	5%	Cellulose	95% Non-fibrous (other)	None Detected	
97NG-04B 131204500-0011	North Front Exterior - White/Gray Window Caulking	Gray Non-Fibrous Homogeneous	5%	Cellulose	95% Non-fibrous (other)	None Detected	
97NG-04C 131204500-0012	North Front Exterior - White/Gray Window Caulking	Gray Non-Fibrous Homogeneous	5%	Cellulose	95% Non-fibrous (other)	None Detected	

Analyst(s)

Kevin Pine (4) Steve Grise (8)

Renaldo Drakes, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1% Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3 and VT AL357102

Initial report from 09/12/2012 15:31:44

FUSS & O'NEILL EnviroScience, LLC 131204500

www.fando.com

50 Redfield St, Suite 100, Boston, MA 02122

131204500

(617) 282-4675 Fax (617) 282-8253

Sample ID	Sample Location	Material	ET AVSTN ALEDRIC
7.14		LIGHTWEIGHT PAPE	Result (%)
7NG-01A	CLASSROOM	MATERIAL BEHIND LA	LLY COLUMN
-01B		1	1
-010	V	V .	· · · · ·
TNG-02A	South Etterior	WEATHERPROTIN	6
	i	CUSHION FELT, UNDI	HALE ATH UNIT VENI.
-02B			
- 02C			
HIG-03A	DOUTH EXTERIOR		W+ EXPANSION
-03B		1 7	OINT CAULKING
-030			
	LORTH (FRONT) ETTER	and hundred in	
the second se	WICH ( 100M) ETIEN	HOR WHITE GREY WIN	DOW CAUKING
-04B			
-040	V	$\vee$	
ed on the turnaround time into oratory if analyses will be late	licated above, analyses are due to Envir	Turnaround Time roScience on or before this date:	Please call the EnviroScience
Results to the EnviroScien	ce Laboratory at: 888-838-1160. TOP AT 15T Pos 1	TIVE COUNT IN E	TCH HOMOGENE
SET. No		Hold Samples Fo	R IEM
SET. No ANALYSIS G	DOINT COUNTING. 1	HOLD SAMPLES FO	PM
SET. No ANALY SIS ( aples collected by: aples [Rec'd] Sent by)[	IPONT CUNTING. 1 IPON REQUEST. CHEGRAVALLESE Da IL AD IDA	Hold Samples For te: $\frac{9/7/12}{12}$ Time: ate: $\left[ \frac{9}{7} \right]$ Time:	PM PM
SET. No ANALYSIS G aples collected by: <u>NI</u>	DOINT CUNTING. 1 IPON REQUEST. CH-GRAVALLESE Da II AD IDa Date:	te: 9/7/12 Time:	PM PM DEGEDVEN

Q:\EnviroScience\Admin\FORMS\Mass Forms\Asbestos Bulks Chain of Custody Boston rev 0611.doc



I	Bob May Fuss & O' Neill Envir	oScier	nce, LLC	Customer ID: Customer PO:	ENVI54
	146 Hartford Road			Received:	04/06/10 3:35 PM
I	Manchester, CT 0604	0		EMSL Order:	131001366
Fax:	(413) 647-0018	Phone:	(860) 646-2469	EMSL Proj:	
Project:	20070914.A6E / Bourne Pu Elementary School; Boiler		ools; Peebles	Analysis Date:	4/8/2010

			Asbestos			
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
331DD-01A	Boiler Exterior;	Gray	25%	Glass	50% Non-fibrous (other)	None Detected
131001366-0001	Boiler Jacket Insulation	Fibrous Heterogeneous	25%	Min. Wool		
331DD-01B	Boiler Exterior;	Gray	25%	Min. Wool	65% Non-fibrous (other)	None Detected
131001366-0002	Boiler Jacket Insulation	Fibrous Homogeneous	10%	Glass		
331DD-01C	Boiler Exterior;	Gray	15%	Glass	60% Non-fibrous (other)	None Detected
131001366-0003	Boiler Breeching TSI	Fibrous Homogeneous	25%	Min. Wool		
331DD-02A	Boiler Interior;	Brown			60% Non-fibrous (other)	40% Chrysotile
131001366-0004	Friable TSI @ Int Boiler Ribbing	Fibrous Homogeneous				
331DD-02B	Boiler Interior;					Stop Positive (Not
131001366-0005	Friable TSI @ Int Boiler Ribbing					Analyzed)
331DD-02C	Boiler Interior;					Stop Positive (Not
131001366-0006	Friable TSI @ Int Boiler Ribbing					Analyzed)
331DD-03A	Boiler Ext	White	95%	Glass	5% Non-fibrous (other)	None Detected
131001366-0007	underside; Boiler Roping @ Bottom Seams	Fibrous Homogeneous				

Analyst(s)

Steve Grise (27)

Renaldo Drakes or other approved signatory



F 1	Bob May Fuss & O' Neill Envi 46 Hartford Road Manchester, CT 060	Customer ID: Customer PO: Received: EMSL Order:	ENVI54 04/06/10 3:35 PM 131001366
Fax: Project:	(413) 647-0018 20070914.A6E / Bourne P Elementary School; Boile	EMSL Proj: Analysis Date:	4/8/2010

				Non-Asb	Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
331DD-03B 131001366-0008	Boiler Ext underside; Boiler Roping @ Bottom Seams	White Fibrous Homogeneous	95%	Glass	5% Non-fibrous (other)	None Detected
331DD-03C 131001366-0009	Boiler Ext underside; Boiler Roping @ Bottom Seams	White Fibrous Homogeneous	95%	Glass	5% Non-fibrous (other)	None Detected
331DD-04A 131001366-0010	Hot Water Tank; Boiler Rm; Hot Water Tank TSI	Gray Fibrous Homogeneous	25% 15%	Min. Wool Glass	60% Non-fibrous (other)	None Detected
331DD-04B 131001366-0011	Hot Water Tank; Boiler Rm; Hot Water Tank TSI	Gray Fibrous Homogeneous	15% 25%		60% Non-fibrous (other)	None Detected
331DD-05 131001366-0012	Piping under Hot Water Tank; Cloth Insulation Wrap	Tan Fibrous Homogeneous	95%	Glass	5% Non-fibrous (other)	None Detected
331DD-06 131001366-0013	Boiler @ Breeching Pentration; Flue Patch Material	Gray Fibrous Heterogeneous	20%	Min. Wool	80% Non-fibrous (other)	None Detected
331DD-07 131001366-0014	Boiler Ext Front; Insul @ Front Circular Panel	Gray Fibrous Heterogeneous			90% Non-fibrous (other)	10% Chrysotile

Analyst(s)

Steve Grise (27)

Renaldo Drakes or other approved signatory



F 1	Bob May Fuss & O' Neill Er 46 Hartford Road Manchester, CT 0		Customer ID: Customer PO: Received: EMSL Order:	ENVI54 04/06/10 3:35 PM 131001366	
Fax: Project:	(413) 647-0018 20070914.A6E / Bourn Elementary School; B	Phone: (860) 646-2469 e Public Schools; Peebles oiler	EMSL Proj: Analysis Date:	4/8/2010	

			Asbestos			
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
331DD-08 131001366-0015	Boiler Duct; White Cloth Vibration Isolator	White Fibrous Homogeneous	95%	Glass	5% Non-fibrous (other)	None Detected
331DD-09A 131001366-0016	Boiler Exterior; Ext Gasket @ Metal Fixed Panels	Tan/White Fibrous Heterogeneous			75% Non-fibrous (other)	25% Chrysotile
331DD-09B 131001366-0017	Boiler Exterior; Ext Gasket @ Metal Fixed Panels					Stop Positive (Not Analyzed)
331DD-10 131001366-0018	Boiler Doors; Residual Door Gaskets	Tan Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
331DD-11 131001366-0019	Piping under Hot Water Tank; Red Gasket a/w Piping	Red/Beige Non-Fibrous Heterogeneous	10%	Wollastonite	90% Non-fibrous (other)	None Detected
331DD-12A 131001366-0020	Boiler Interior; Boiler Debris	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
331DD-12B 131001366-0021	Boiler Interior; Boiler Debris	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (27)

Renaldo Drakes or other approved signatory



F 1	Bob May Fuss & O' Neill Envir 46 Hartford Road Manchester, CT 0604		ice, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54 04/06/10 3:35 PM 131001366
Fax: Project:	(413) 647-0018 20070914.A6E / Bourne Pu Elementary School; Boiler	Phone: blic Scho	(860) 646-2469 ools; Peebles	EMSL Proj: Analysis Date:	4/8/2010

				Non-Asb	estos	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
331DD-13 131001366-0022	Backside of Boiler; White Friable Gaskets	Gray Non-Fibrous Homogeneous	20%	Min. Wool	80% Non-fibrous (other)	None Detected
331DD-14A 131001366-0023	Boiler Interior; Boiler Brick	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
331DD-14B 131001366-0024	Boiler Interior; Boiler Brick	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
331DD-14C 131001366-0025	Boiler Interior; Boiler Brick	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
331DD-15A 131001366-0026	Boiler Base; Red Brick Boiler Base; Solid	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
331DD-15B 131001366-0027	Boiler Base; Red Brick Boiler Base; Solid	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
331DD-15C 131001366-0028	Boiler Base; Red Brick Boiler Base; Solid	Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected

Analyst(s)

Steve Grise (27)

Renaldo Drakes or other approved signatory



F 1	3ob May Fuss & O' Neill Envir 46 Hartford Road Manchester, CT 0604	, ,	Customer ID: Customer PO: Received: EMSL Order:	ENVI54 04/06/10 3:35 PM 131001366
Fax:	(413) 647-0018	Phone: (860) 646-2469	EMSL Proj:	
Project:	20070914.A6E / Bourne Pu Elementary School; Boiler	,	Analysis Date:	4/8/2010

				Non-As	bestos	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
331DD-16A	Boiler Base	Orange			100% Non-fibrous (other)	None Detected
131001366-0029	Center; Orange Open Brick Base Insert	Non-Fibrous Homogeneous				
331DD-16B	Boiler Base	Orange			100% Non-fibrous (other)	None Detected
131001366-0030	Center; Orange Open Brick Base Insert	Non-Fibrous Homogeneous				

Analyst(s)

Steve Grise (27)

Renaldo Drakes or other approved signatory



#### FUSS & O'NEILL EnviroScience, LLC

131001366

30 SAMPLES

www.fando.com

50 Redfield Street, Suite 100 Boston, MA 02122

(617) 282-4675 Fax: (617) 282-8253

331DD -01A -01B -01C 331DD -02A	BOILER ETTERIOR	BOILER JACKET INSULATION (FRIADI	E)
-olc			
and the second second		V	
31DD-02A	V	BOILER BREECHING	
	BOILER INTERIOR	FRIABLE TSIQ INTERIOR BOILER RIDE	LINK
-028			Y
-070			
31DD-03A	BOILER ETTERIOR (UNDERSEDE)	BOILETZ POPING@ BOTTOM SEAMS	
-03B			
-03C			
31DD-04A	(BOILER ROOM)	HOT WATER TANK TSI	
-04B		Ţ	
alysis Method: X PLM	Other	Turnaround Time _ 48	Houp
sed on the turnaround time	e indicated above, analyses are due to Enviro (860) 953-2700 if analyses will be late.	Science on or before this date: $\frac{4/8/10}{2}$	. Please call the
	nce Consultants, Inc. Laboratory at 413-647-	-0018	
ecial Instructions:	7	11	EXHERUS S
mples Collected By:	Date: 3	/31/10 . Time: A.M	1.
nples [Rec'd] [Sent By]:	[][ <b>)</b> . <b>D</b> .] Date: [	1[ <b>4</b> / <b>6</b> ] Time: [	An.

131001366

**FUSS & O'NEILL** EnviroScience, LLC

131001366

www.fando.com

the second se		
50 Redfield Street, Suite	100 Postan MA	00100
JU Reuliela Sucer, Suite	100 DOSTON, IVLA	UZIZZ
	the second s	

(617) 282-4675 Fax: (617) 282-8253

	SAMPLE LOG FOR A		Sheet $2_{of} 3$
Project Name: Boo	UR NE PUBLIC SCHOOL	LS Project No. 20	070914 AGE
	5 ELEMENTARY SCHOOL - 1		
Sample ID	Sample Location	Material	Result (%)
331DD-05	PIPING UNDER HOT WATER TANK	CLOTH INSULATION WRAP	
331DD -06	BOILET Q BREECHING	FLUE PATCH MATETHAL (6	(AEY)
331DD-07	BOILER ETTEROR FRONT	INSULATION @ TRONT CIRCULAR PATNER	
331DD-08	Boiler Duct	WHATE CLOTH VIBRATION ISOLATER	
331 DD-09A	BOILER EFFERIOR	MATTAL FITED PANE	
-0913			
331DD -10	BOILER Doors	Pesidum Door GASKETS	
331DD-11	PIPING UNDER HOT WATER TANK	PED GASKET A/W PIPING	2 EA (75F)
331DD-12A	BOILER INTERNOR	Bauer Dages De	BRIS
-12B	V	4	
331 PD - 13	BACKSIDE OF BOILER (PRING)	WHITE FRAME GASKETS	6EA
Analysis Method: PLM	f Other	Turnaround Time	8 Houp
	e indicated above, analyses are due to Enviros (860) 953-2700 if analyses will be late.	Science on or before this date: 4/8/10	. Please call the
Fax Results To: EnviroScie	ence Consultants, Inc. Laboratory at 413-647-(		
Special Instructions:	PIER @ IST POSITIVE	IN EACH Homos	EXHECUS SET
Samples Collected By:	). D	31/10 Time: A.N	4.
Samples [Rec'd] [Sent By]:	Date: D.D	$\frac{31}{46}$ Time: $\frac{9.1}{2}$	A.M.
Samples Received By:	Date:		
Shipped To: EMSI		her	
Method of Shipment:		Ground Dicher Dicepoi	F RECEIVED
· · · · · · · · ·			APR 06 2010
			BY: 50 1535

131001366

FUSS & O'NEILL
EnviroScience, LLC

131001366

www.fando.com

5	0 Redfield Street	t, Suite 100	Boston,	MA	02122	
	THE STREET ADDRESS OF THE OWNER OF THE OWNER OF THE A. O				and the second se	22

(617) 282-4675 Fax: (617) 282-8253

	SAMPLE LOG FOR	ASBESTOS BULKS	Sheet 3 of 3
Project Name: Bou	PLAE PUBLIC SCHOO	7LS Project No.	20070914.46
	ELEMETHTARY SCHOOL -		
Sample ID	Sample Location	Material	Result (%)
331DD-14A	BOILER INTERIOR	FATERIOR BOILER	-BANCIL
-14B			
-140			
331 DD - 15A	BOILER BASE	RED BRICK BOIL	-
-15B			
-150		$\downarrow$ $\downarrow$	
331 DD - 16A	BOILER BASE (CENTER)	OPANGE OPEN-B BASE /NSERF	(Harow Center)
-16B		1	
Analysis Method: PLM	Other	Turnaround Time	
EnviroScience Laboratory at (8	indicated above, analyses are due to Enviro 860) 953-2700 if analyses will be late. Ince Consultants, Inc. Laboratory at 413-647	7-0018	06 ENERUS SET



F 5	3ob May Fuss & O' Neill Envir 50 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proj:	
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

				<u>Non-Asb</u>	<u>estos</u>	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-01A 030918779-0001	BOILER ROOM/ HOT WATER TANK INSULATION	Tan Fibrous Heterogeneous		Glass Synthetic	40% Ca Carbonate 40% Non-fibrous (other)	None Detected
720JH-01B 030918779-0002	BOILER ROOM/ HOT WATER TANK INSULATION	Tan/White Fibrous Heterogeneous	20% 5%	Glass Synthetic	40% Ca Carbonate 35% Non-fibrous (other)	None Detected
720JH-01C 030918779-0003	BOILER ROOM/ HOT WATER TANK INSULATION	Tan Fibrous Heterogeneous	15% 5%		40% Ca Carbonate 40% Non-fibrous (other)	None Detected
720JH-02A 030918779-0004	BOILER ROOM/ BOILER BREACHING BOILER INSULATION #2	White/Blue Fibrous Heterogeneous	10% 20%	Glass Synthetic	50% Ca Carbonate 20% Non-fibrous (other)	None Detected
720JH-02B 030918779-0005	BOILER ROOM/ BOILER BREACHING BOILER INSULATION #1	Gray/White Fibrous Heterogeneous	5% 25%	Glass Synthetic	50% Ca Carbonate 20% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James Della

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:37:54 PM



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: manhattanlab@emsl.com

F 5	Bob May Suss & O' Neill Enviro 0 Redfield Street	oScience, LLC	Customer ID: Customer PO: Received:	ENVI54C 07/24/09 9:00 AM
E	Boston, MA 02122		EMSL Order:	030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proj:	
Project:	20070914.A4E/ BOURNE PI ELEMATARY	JBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

#### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				<u>Non-Ast</u>	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-02C 030918779-0006	BOILER ROOM/ BOILER BREACHING BOILER INSULATION #1	Tan/Blue Fibrous Heterogeneous	15% 15%		50% Ca Carbonate 20% Non-fibrous (other)	None Detected
720JH-03A 030918779-0007	BOILER ROOM/ BOILER INSULATION BOILER #2	Gray Fibrous Heterogeneous	25%	Glass	40% Ca Carbonate 35% Non-fibrous (other)	None Detected
720JH-03B 030918779-0008	BOILER ROOM/ BOILER INSULATION BOILER #1	Gray Fibrous Heterogeneous	35%	Glass	40% Ca Carbonate 25% Non-fibrous (other)	None Detected
720JH-03C 030918779-0009	BOILER ROOM/ BOILER INSULATION BOILER #1	Gray Fibrous Heterogeneous	15%	Glass	35% Ca Carbonate 50% Non-fibrous (other)	None Detected
720JH-04A 030918779-0010	BOILER ROOM/ VIBRATION ISOLATOR	Gray/White Fibrous Heterogeneous	95%	Glass	5% Non-fibrous (other)	None Detected
720JH-04B 030918779-0011	ATTIC/ VIBRATION ISOLATOR	Tan/White Fibrous Heterogeneous	25%	Cellulose	15% Non-fibrous (other)	60% Chrysotile

Analyst(s)

Williams John (111)

James P. D. W

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:37:55 PM



 {	Bob May Fuss & O' Neill Er 50 Redfield Street Boston, MA 02122		Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779	
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proj:		
Project:	20070914.A4E/ BOURI ELEMATARY	NE PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009	

			<u>Non-Asbestos</u>		<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-05A 030918779-0012	OFFICE NEAR ROOM 9/ PREFOUND B DOCK TYPE PIPE	White Fibrous Heterogeneous	·		50% Ca Carbonate 24% Non-fibrous (other)	15% Amosite 5% Chrysotile 6% Crocidolite
720JH-05B 030918779-0013	OFFICE NEAR ROOM 9/ PREFOUND B DOCK TYPE PIPE					Stop Positive (Not Analyzed)
720JH-05C 030918779-0014	OFFICE NEAR ROOM 9/ PREFOUND B DOCK TYPE PIPE					Stop Positive (Not Analyzed)
720JH-06A 030918779-0015	STORAGE NEAR ROOM 13/ AIRCELL PIPE INSULATION	White Fibrous Homogeneous	20%	Cellulose	10% Non-fibrous (other)	70% Chrysotile
720JH-06B 030918779-0016	CHASE NEAR ROOM 7 (CUSTODIAN)/ AIRCELL PIPE					Stop Positive (Not Analyzed)
720JH-06C 030918779-0017	STAGE/ AIRCELL PIPE INSULATION					Stop Positive (Not Analyzed)

Analyst(s)

Williams John (111)

James P. Q. W

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170



F 5	3ob May Fuss & O' Neill Er 60 Redfield Stree 3oston, MA 02123		Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779	
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proj:		
Project:	20070914.A4E/ BOUR ELEMATARY	NE PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009	

		<u>Non-Asbestos</u>				<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре	
720JH-07A 030918779-0018	STORAGE NEAR ROOM 13/ MUDDED FITTINGS	White Fibrous Homogeneous			50% Ca Carbonate 18% Non-fibrous (other)	15% Amosite 5% Chrysotile 12% Crocidolite	
720JH-07B 030918779-0019	STORAGE NEAR ROOM 13/ MUDDED FITTINGS					Stop Positive (Not Analyzed)	
720JH-07C 030918779-0020	STAGE/ MUDDED FITTINGS					Stop Positive (Not Analyzed)	
720JH-08A 030918779-0021	ROOM 10/ BLACK COVE BASE	Black Non-Fibrous Homogeneous	990 M. M. ( ) / F - 1		100% Non-fibrous (other)	None Detected	
720JH-08B 030918779-0022	ROOM 8/ BLACK COVE BASE	Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
720JH-08C 030918779-0023	ROOM 5/ BLACK COVE BASE	Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected	
720JH-09A 030918779-0024	ROOM 10/ BLACK MASTIC A/W BLACK COVE BASE	White/Black Non-Fibrous Heterogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected	

Analyst(s)

Williams John (111)

firms P 2120

James Hall, Laboratory Manager or other approved signatory

4

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:37:58 PM



:	Bob May Fuss & O' Neill En <sup>,</sup> 50 Redfield Street Boston, MA 02122		ce, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone:	(617) 282-4675	EMSL Proi:	
Project:	20070914.A4E/ BOURN ELEMATARY	E PUBLIC SC	HOOLS/ PEEBLES	Analysis Date:	7/25/2009

		<u>Non-Asbestos</u>			<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-09B 030918779-0025	ROOM 8/ BLACK MASTIC A/W BLACK COVE BASE	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
720JH-09C 030918779-0026	ROOM 5/ BLACK MASTIC A/W BLACK COVE BASE	Black Non-Fibrous Heterogeneous			100% Non-fibrous (other)	None Detected
720JH-10A 030918779-0027	ROOM 4/ VINYL WINDOW SILL	Gray/Tan Non-Fibrous Heterogeneous	20%	Celluiose	15% Ca Carbonate 65% Non-fibrous (other)	None Detected
720JH-10B 030918779-0028	ROOM 10/ VINYL WINDOW SILL	Brown/Gray Non-Fibrous Heterogeneous	25%	Cellulose	10% Ca Carbonate 65% Non-fibrous (other)	None Detected
720JH-10C 030918779-0029	ROOM 12/ VINYL WINDOW SILL	Brown/Gray Non-Fibrous Heterogeneous	20%	Cellulose	10% Ca Carbonate 70% Non-fibrous (other)	None Detected
720JH-11A 030918779-0030	LOOSE IN ATTIC/ 1X1 CEILING TILE PIN HOLE	Brown/White Fibrous Heterogeneous	85%	Cellulose	15% Non-fibrous (other)	None Detected
720JH-11B 030918779-0031	LOOSE IN ATTIC/ 1X1 CEILING TILE PIN HOLE	Brown/White Fibrous Heterogeneous	85%	Cellulose	15% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James De 20

James Hall, Laboratory Manager or other approved signatory



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattanlab@emsl.com</u>

F E	Bob May Fuss & O' Neill Env 50 Redfield Street Boston, MA 02122	/iroScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi:	
Project:	20070914.A4E/ BOURNI ELEMATARY	E PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

# Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-11C 030918779-0032	LOOSE IN ATTIC/ 1X1 CEILING TILE PIN HOLE	Brown/White Fibrous Heterogeneous	85%	Cellulose	15% Non-fibrous (other)	None Detected
720JH-12A 030918779-0033	LOOSE IN ATTIC/ DARK BROWN MASTIC A/W 1X1 CEILING	Brown Non-Fibrous Heterogeneous	5%	Cellulose	95% Non-fibrous (other)	None Detected
720JH-12B 030918779-0034	LOOSE IN ATTIC/ DARK BROWN MASTIC A/W 1X1 CEILING	Brown Non-Fibrous Heterogeneous	3%	Cellulose	97% Non-fibrous (other)	None Detected
720JH-12C 030918779-0035	LOOSE IN ATTIC/ DARK BROWN MASTIC A/W 1X1 CEILING	Brown Non-Fibrous Heterogeneous	5%	Cellulose	95% Non-fibrous (other)	None Detected
720JH-13A 030918779-0036	ROOM 22/ BLACK MASTIC A/W 9X9 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-13B 030918779-0037	MAIN LOBBY/ BLACK MASTIC A/W 9X9 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James D. D. W.

James Hall, Laboratory Manager or other approved signatory



	Bob May Fuss & O' Neill Env	iroScience, LLC	Customer ID: Customer PO:	ENVI54C	
	50 Redfield Street		Received:	07/24/09 9:00 AM	
	Boston, MA 02122		EMSL Order:	030918779	
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi:		
Project:	20070914.A4E/ BOURNE ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009	

		<u>Non-Asbestos</u>				<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре	
720JH-13C 030918779-0038	GROUND F <b>L</b> OOR HALL/ BLACK MASTIC A/W 9X9 FT	Black Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected	
<b>72</b> 0JH-14A 030918779-0039	ROOM 9/ BLACK MASTIC A/W 12X12 FT	Ēlack Non-Fibrous Heterogeneous	3%	Cellulose	97% Non-fibrous (other)	None Detected	
720JH-14B 030918779-0040	ROOM 12/ BLACK MASTIC A/W 12X12 FT	Black Non-Fibrous Heterogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected	
720JH-14C 030918779-0041	BREEZEWAY BETWEEN ROOM 10 & 11 / BLACK MASTIC A/W	Brown/Black Non-Fibrous Heterogeneous	15%	Cellulose	85% Non-fibrous (other)	None Detected	
720JH-15A 030918779-0042	ROOM 1/ BLUE/GREY W/ WHITE STREAKS 12X12	Gray/White Non-Fibrous Heterogeneous	INSUFFICE	INT MASTIC	20% Ca Carbonate 80% Non-fibrous (other)	None Detected	
720JH-15B 030918779-0043	ROOM 2/ BLUE/GREY W/ WHITE STREAKS 12X12	Gray/White Non-Fibrous Heterogeneous	INSUFFICE	NT MASTIC	20% Ca Carbonate 80% Non-fibrous (other)	None Detected	

Analyst(s)

Williams John (111)

James DOLD

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:01 PM



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattanlab@emsl.com</u>

F	3ob May Fuss & O' Neill Envir 50 Redfield Street	roScience, LLC	Customer ID: Customer PO: Received:	ENVI54C 07/24/09 9:00 AM
			Received.	07724709 9:00 AM
Ε	Boston, MA 02122		EMSL Order:	030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi;	
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Ast	Non-Asbestos		
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре	
720JH-15C 030918779-0044	ROOM 3/ BLUE/GREY W/ WHITE STREAKS 12X12	Gray/White Non-Fibrous Heterogeneous		15% Ca Carbonate 85% Non-fibrous (other)	None Detected	
			INSUFFICENT MASTIC			
720JH-16A 030918779-0045	ROOM 6/ WHITE/YELLOW/ BORWN 12X12 FT	Beige Non-Fibrous Heterogeneous		85% Non-fibrous (other) 15% Quartz	None Detected	
· · · · · · · · · · · · · · · · · · ·			INSUFFICENT MASTIC			
720JH-16B TILE 030918779-0046	ROOM 6/ WHITE/YELLOW/ BORWN 12X12 FT	Beige Non-Fibrous Heterogeneous		90% Non-fibrous (other) 10% Quartz	None Detected	
720JH-16B MASTIC 030918779-0046A	ROOM 6/ WHITE/YELLOW/ BORWN 12X12 FT	Brown Non-Fibrous Heterogeneous	3% Cellulose	97% Non-fibrous (other)	None Detected	
720JH-16C TILE 030918779-0047	ROOM 6/ WHITE/YELLOW/ BORWN 12X12 FT	Beige Non-Fibrous Heterogeneous		85% Non-fibrous (other) 15% Quartz	None Detected	
720JH-16C MASTIC 030918779-0047A	ROOM 6/ WHITE/YELLOW/ BORWN 12X12 FT	Brown Non-Fibrous Heterogeneous	2% Cellulose	98% Non-fibrous (other)	None Detected	

Analyst(s)

Williams John (111)

James P. D. D. D.

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:02 PM



F E	Bob May Fuss & O' Neill En 50 Redfield Street Boston, MA 02122		Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779	
Fax: Project:	(413) 647-0018 20070914.A4E/ BOURN ELEMATARY	Phone: (617) 282-4675	EMSL Proj: Analysis Date:	7/25/2009	

		<u>Non-Asbestos</u>				<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре	
720JH-17A TILE 030918779-0048	ROOM 1/ TAN W/ WITE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected	
720JH-1 <b>7</b> A MASTIC 030918779-0048A	ROOM 1/ TAN W/ WITE STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected	
720JH-17B TILE 030918779-0049	ROOM 2/ TAN W/ WITE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous			10% Ca Carbonate 90% Non-fibrous (other)	None Detected	
720JH-17B MASTIC 030918779-0049A	ROOM 2/ TAN W/ WITE STREAKS 12X12 FT	Black Non-Fibrous Heterogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected	
720JH-17C TILE 030918779-0050	ROOM 3/ TAN W/ WITE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected	
720JH-17C MASTIC 030918779-0050A	ROOM 3/ TAN W/ WITE STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected	
720JH-18A 030918779-0051	ROOM 8/ WHITE W/ BROWN & BLUE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous	INSUFFICE		90% Non-fibrous (other) 10% Quartz	None Detected	

Analyst(s)

Williams John (111)

James D Q UD

James Hall, Laboratory Manager or other approved signatory



F 5	3ob May <sup>F</sup> uss & O' Neill Envi 50 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi:	
Project:	20070914.A4E/ BOURNE ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

		<u>Non-Asbestos</u>			Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре	
720JH-18B 030918779-0052	ROOM 8/ WHITE W/ BROWN & BLUE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous		90% Non-fibrous (other) 10% Quartz	None Detected	
			INSUFFICENT MASTIC			
720JH-18C 030918779-0053	ROOM 8/ WHITE W/ BROWN & BLUE STREAKS 12X12 FT	Gray/White Non-Fibrous Heterogeneous		85% Non-fibrous (other) 15% Quartz	None Detected	
			INSUFFICENT MASTIC			
720JH-19A 030918779-0054	ROOM 4/ RED W/ PINK STREAKS 12X12 FT	Red Non-Fibrous Homogeneous	INSUFFICENT MASTIC	100% Non-fibrous (other)	None Detected	
720JH-19B <sup>030918779-0055</sup>	ROOM 4/ RED W/ PINK STREAKS 12X12 FT	Red Non-Fibrous Homogeneous	INSUFFICENT MASTIC	100% Non-fibrous (other)	None Detected	
720JH-19C 030918779-0056	ROOM 4/ RED W/ PINK STREAKS 12X12 FT	Red Non-Fibrous Homogeneous	INSUFFICENT MASTIC	100% Non-fibrous (other)	None Detected	

Analyst(s)

Williams John (111)

James DQUD

James Hall, Laboratory Manager or other approved signatory



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattaniab@emsl.com</u>

Fu 50	ob May uss & O' Neill Envir ) Redfield Street oston, MA 02122	oScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Project:	(413) 647-0018 20070914.A4E/ BOURNE P ELEMATARY	Phone: (617) 282-4675 UBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

# Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

		<u>Non-Asbestos</u>			<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-20A TILE 030918779-0057	ROOM 4/ BROWN W/ LT BROWN & DARK BROWN STREAKS	Gold Non-Fibrous Homogeneous		,	15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-20A MASTIC 030918779-0057A	ROOM 4/ BROWN W/ LT BROWN & DARK BROWN STREAKS	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-20B TILE 030918779-0058	ROOM 4/ BROWN W/ LT BROWN & DARK BROWN STREAKS	Gold Non-Fibrous Homogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-20B MASTIC 030918779-0058A	ROOM 4/ BROWN W/ LT BROWN & DARK BROWN STREAKS	Black Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
720JH-20C TILE 030918779-0059	ROOM <b>4</b> / BROWN W/ LT BROWN & DARK BROWN STREAKS	Gold Non-Fibrous Homogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James P. 2.10

James Hall, Laboratory Manager or other approved signatory



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: manhattanlab@emsl.com

F 5	Bob May Fuss & O' Neill Enviro 50 Redfield Street Boston, MA 02122	oScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi:	
Project:	20070914.A4E/ BOURNE P ELEMATARY	UBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asb	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
720JH-20C MASTIC 030918779-0059A	C ROOM 4/ BROWN W/ LT BROWN & DARK BROWN STREAKS	Black Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (other)	None Detected
720JH-21A 030918779-0060	ROOM 9/ GREY W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Heterogeneous		15% Ca Carbonate 85% Non-fibrous (other)	None Detected
· · · · · · · · · · · · · · · · · · ·			INSUFFICENT MASTIC		
720JH-21B 030918779-0061	ROOM 10/ GREY W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Heterogeneous		10% Ca Carbonate 90% Non-fibrous (other)	None Detected
			INSUFFICENT MASTIC		
720JH-21C 030918779-0062	ROOM 12/ GREY W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Heterogeneous		15% Ca Carbonate 85% Non-fibrous (other)	None Detected
			INSUFFICENT MASTIC		
720JH-22A TILE 030918779-0063	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Tan Non-Fibrous Heterogeneous		15% Ca Carbonate 85% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James Della

James Hall, Laboratory Manager or other approved signatory



ł	Bob May Fuss & O' Neill Env 50 Redfield Street Boston, MA 02122	·	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779	
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proi:		
Project:	20070914.A4E/ BOURNI ELEMATARY	E PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009	

				<u>Non-Ast</u>	pestos	Asbestos
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
720JH-22A MASTIC 030918779-0063A	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Brown Non-Fibrous Homogeneous	3%	Cellulose	97% Non-fibrous (other)	None Detected
720JH-22B TILE 030918779-0064	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Tan Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-22B MASTIC 030918779-0064A	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Brown Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-22C TILE 030918779-0065	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Tan Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-22C MASTIC 030918779-0065A	BREEZEWAY BETWEEN ROOM 10 & 11/ TAN W/ BROWN	Brown Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-23A TILE 030918779-0066	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Tan Non-Fibrous Homogeneous			20% Ca Carbonate 80% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James P. O. W

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:07 PM



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: manhattanlab@emsl.com

F 5	3ob May Fuss & O' Neill Envii 60 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO; Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675		
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

# Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				<u>Non-Asl</u>	<u>pestos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-23A MASTIC 030918779-0066A	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-23B TILE 030918779-0067	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Tan Non-Fibrous Homogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-23B MASTIC 030918779-0067A	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Black Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
720JH-23C TILE 030918779-0068	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Brown Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-23C MASTIC 030918779-0068A	ROOM 12/ TAN W/ PINK & BROWN STREAK 12X12 FT	Black Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
720JH-24A TILE 030918779-0069	ROOM 11/ TAN W/ BROWN & WHITE STREAKS 12X12 FT	Beige Non-Fibrous Homogeneous			10% Ca Carbonate 90% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James P. Q. W

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:08 PM



F 5	3ob May <sup>-</sup> uss & O' Neill Envir 50 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax: Project:		Phone: (617) 282-4675 PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analvsis Date:	7/25/2009
	ELEMATARY		Analysis Date.	112012000

				<u>Non-Ast</u>	<u>estos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-24A MASTIC 030918779-0069A	ROOM 11/ TAN W/ BROWN & WHITE STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-24B 030918779-0070	ROOM 11/ TAN W/ BROWN & WHITE STREAKS 12X12 FT	Beige Non-Fibrous Heterogeneous	2%	Cellulose	10% Ca Carbonate 88% Non-fibrous (other)	None Detected
			INSUFFICE	INT MASTIC		
720JH-24C 030918779-0071	ROOM 11/ TAN W/ BROWN & WHITE STREAKS 12X12 FT	Beige Non-Fibrous Heterogeneous	3%	Cellulose	15% Ca Carbonate 82% Non-fibrous (other)	None Detected
			INSUFFICE	NT MASTIC		
720JH-25A TILE 030918779-0072	ROOM 11/ BROWN W/ BROWN & WHITE STREAKS 12X12 FT	Brown Non-Fibrous Heterogeneous			20% Ca Carbonate 80% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James P 240

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:09 PM



F 5	3ob May Fuss & O' Neill Envir 50 Redfield Street 3oston, MA 02122	oScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675		
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

		<u>Non-Asbestos</u>				Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре	
720JH-25A MASTIC 030918779-0072A	ROOM 11/ BROWN W/ BROWN & WHITE STREAKS 12X12 FT	Brown Non-Fibrous Heterogeneous	3%	Cellulose	97% Non-fibrous (other)	None Detected	
720JH-25B 030918779-0073	ROOM 11/ BROWN W/ BROWN & WHITE STREAKS 12X12 FT	Brown Non-Fibrous Heterogeneous			10% Ca Carbonate 90% Non-fibrous (other)	None Detected	
			INSUFFICE	NT MASTIC			
720JH-25C 030918779-0074	ROOM 11/ BROWN W/ BROWN & WHITE STREAKS 12X12 FT	Brown Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected	
			INSUFFICE	NT MASTIC			
720JH-26A TILE 030918779-0075	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Tan Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected	

Analyst(s)

Williams John (111)

James DOUD

James Hall, Laboratory Manager or other approved signatory



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattanlab@emsl.com</u>

F	3ob May <sup>:</sup> uss & O' Neill En 0 Redfield Street		, LLC	Customer ID: Customer PO:	ENVI54C	
				Received:	07/24/09 9:00 AM	
E	30ston, MA 02122			EMSL Order:	030918779	
Fax:	(413) 647-0018	Phone: (6	17) 282-4675	EMSL Proj:		
Project:	20070914.A4E/ BOURN ELEMATARY	E PUBLIC SCHO	OOLS/ PEEBLES	Analysis Date:	7/25/2009	

# Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				Non-Asb	<u>estos</u>	<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-26A MASTIC 030918779-0075A	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	<1%	Cellulose	100% Non-fibrous (other)	None Detected
720JH-26B TILE 030918779-0076	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Tan Non-Fibrous Heterogeneous			20% Ca Ċarbonate 80% Non-fibrous (other)	None Detected
720JH-26B MASTIC 030918779-0076A	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-26C TILE 030918779-0077	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Tan Non-Fibrous Heterogeneous			15% Ca Carbonate 85% Non-fibrous (other)	None Detected
720JH-26C MASTIC 030918779-0077A	ROOM 9/ TAN W/ BROWN STREAKS 12X12 FT	Black Non-Fibrous Homogeneous	2%	Cellulose	98% Non-fibrous (other)	None Detected
720JH-27A 030918779-0078	STAIRWELL NEAR 12/ PLASTER WALL ROUGH	Gray Non-Fibrous Heterogeneous			30% Gypsum 35% Non-fibrous (other) 35% Quartz	None Detected

Analyst(s)

Williams John (111)

James D D LD

James Hall, Laboratory Manager or other approved signatory



F 5	3ob May 5uss & O' Neill Envir 50 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMOL Drok	
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

		<u>Non-Asbestos</u>				<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре	
720JH-27B	ROOM 1/	Gray			20% Gypsum	None Detected	
030918779-0079	PLASTER WALL ROUGH	Non-Fibrous			35% Non-fibrous (other)		
	ROUGH	Heterogeneous			45% Quartz		
720JH-27C	OUTSIDE	Gray	3%	Cellulose	20% Gypsum	None Detected	
030918779-0080	BOILER ROOM/ PLASTER WALL	Non-Fibrous			37% Non-fibrous (other)		
	ROUGH	Heterogeneous			40% Quartz		
720JH-27D	ATTIC/ PLASTER	Gray	2%	Cellulose	20% Gypsum	None Detected	
030918779-0081	WALL ROUGH	Non-Fibrous			45% Mica		
		Heterogeneous			33% Non-fibrous (other)		
720JH-27E	ATTIC/ PLASTER	Gray	3%	Cellulose	15% Gypsum	None Detected	
030918779-0082	WALL ROUGH	Non-Fibrous			37% Non-fibrous (other)		
		Heterogeneous			45% Quartz		
720JH-27F	ROOM 10/	Gray	<1%	Cellulose	15% Gypsum	None Detected	
030918779-0083	PLASTER WALL	Non-Fibrous			40% Non-fibrous (other)		
	ROUGH	Heterogeneous			45% Quartz		
720JH-27G	-27G COSTODIAL G	Gray	2%	Cellulose	15% Gypsum	None Detected	
030918779-0084	CLOSET NEAR	Non-Fibrous			43% Non-fibrous (other)		
	ROOM 7/ PLASTER WALL ROUGH	Heterogeneous			40% Quartz		
				101000			

Analyst(s)

Williams John (111)

James D D W

James Hall, Laboratory Manager or other approved signatory



ELEMATARY

	Bob May Fuss & O' Neill Env 50 Redfield Street Boston, MA 02122	iroScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675		
Project:	20070914.A4E/ BOURNE	EPUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

		<u>Non-Asbestos</u>		bestos	<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type
720JH-28A 030918779-0085	STAIRWELL NEAR 12/ PLASTER WALL SKIM	White/Green Non-Fibrous Heterogeneous			50% Ca Carbonate 50% Non-fibrous (other)	None Detected
720JH-28B 030918779-0086	ROOM 11/ PLASTER WALL SKIM	White Non-Fibrous Heterogeneous			50% Ca Carbonate 50% Non-fibrous (other)	None Detected
720JH-28C 030918779-0087	OUTSIDE BOILER ROOM/ PLASTER WALL SKIM	White Non-Fibrous Heterogeneous			60% Ca Carbonate 40% Non-fibrous (other)	None Detected
720JH-28D 030918779-0088	ATTIC/ PLASTER WALL SKIM	White/Green Non-Fibrous Heterogeneous			65% Ca Carbonate 35% Non-fibrous (other)	None Detected
720JH-28E 030918779-0089	ATTIC/ PLASTER WALL SKIM	White/Green Non-Fibrous Heterogeneous			65% Ca Carbonate 35% Non-fibrous (other)	None Detected
720JH-28F 030918779-0090	ROOM 1D/ PLASTER WALL SKIM	White Non-Fibrous Heterogeneous			60% Ca Carbonate 40% Non-fibrous (other)	None Detected

Analyst(s)

Williams John (111)

James P. 2.10

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:13 PM



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattanlab@emsl.com</u>

F 5	3ob May Fuss & O' Neill Envir 50 Redfield Street 3oston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675	EMSL Proj:	
Project:	20070914.A4E/ BOURNE F ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	Analysis Date:	7/25/2009

### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			<u>Non-Asbestos</u>			<u>Asbestos</u>
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-28G 030918779-0091	CUSTODIAN CLOSET NEAR ROOM 7/ PLASTER WALL SKIM	White/Green Non-Fibrous Heterogeneous			50% Ca Carbonate 50% Non-fibrous (other)	None Detected
720JH-29A 030918779-0092	ROOM 10/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	2%	Cellulose	53% Non-fibrous (other) 45% Quartz	<1% Chrysotile
720JH-29B 030918779-0093	ROOM 11/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	2%	Cellulose	53% Non-fibrous (other) 45% Quartz	<1% Chrysotile
720JH-29C 030918779-0094	ROOM 12/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	<1%	Cellulose	50% Non-fibrous (other) 50% Quartz	<1% Chrysotile
720JH-29D 030918779-0095	ROOM 1/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	2%	Cellulose	53% Non-fibrous (other) 45% Quartz	<1% Chrysotile
720JH-29E 030918779-0096	ROOM 2/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	3%	Celluiose	52% Non-fibrous (other) 45% Quartz	<1% Chrysotile
720JH-29F 030918779-0097	ROOM 3/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	2%	Cellulose	48% Non-fibrous (other) 50% Quartz	<1% Chrysotile

Analyst(s)

Williams John (111)

James P. 2.10

James Hall, Laboratory Manager or other approved signatory



EMSL Analytical, Inc. 307 West 38th Street, New York, NY 10018 Phone: (212) 290-0051 Fax: (212) 290-0058 Email: <u>manhattanlab@emsl.com</u>

F 5	Bob May Fuss & O' Neill Envi 60 Redfield Street Boston, MA 02122	roScience, LLC	Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675		
Project:	20070914.A4E/ BOURNE I ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

# Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				<u>Non-Asb</u>	Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-29G 030918779-0098	ROOM 6/ PLASTER CEILING ROUGH	Tan Non-Fibrous Heterogeneous	2%	Cellulose	53% Non-fibrous (other) 45% Quartz	<1% Chrysotile
720JH-30A 030918779-0099	ROOM 10/ PLASTER <u>Sk</u> CEILING <del>ROUGH</del>	White Non-Fibrous Heterogeneous	5%	Cellulose	50% Ca Carbonate 42% Non-fibrous (other)	3% Chrysotile
720JH-30B 030918779-0100	ROOM 11/ PLASTER CEILING SKIM		6.1 iz - 1111			Stop Positive (Not Analyzed)
720JH-30C 030918779-0101	ROOM 12/ PLASTER CEILING SKIM					Stop Positive (Not Analyzed)
720JH-30D 030918779-0102	ROOM 1/ PLASTER CEILING SKIM					Stop Positive (Not Analyzed)
720JH-30E 030918779-0103	ROOM 2/ PLASTER CEILING SKIM					Stop Positive (Not Analyzed)
720JH-30F 030918779-0104	ROOM 3/ PLASTER CEILING SKIM			<b></b>		Stop Positive (Not Analyzed)

Analyst(s)

Williams John (111)

James D. D. M.

James Hall, Laboratory Manager or other approved signatory



Attn: Bob May Fuss & O' Neill EnviroScience, LLC 50 Redfield Street Boston, MA 02122			Customer ID: Customer PO: Received: EMSL Order:	ENVI54C 07/24/09 9:00 AM 030918779
Fax:	(413) 647-0018	Phone: (617) 282-4675		
Project:	20070914.A4E/ BOURNE ELEMATARY	PUBLIC SCHOOLS/ PEEBLES	EMSL Proj: Analysis Date:	7/25/2009

<u>Non-Asbestos</u>					<u>Asbestos</u>	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Туре
720JH-30G	ROOM 6/					Stop Positive (Not
030918779-0105	PLASTER CEILING SKIM					Analyzed)

Analyst(s)

Williams John (111)

June DOW

James Hall, Laboratory Manager or other approved signatory

Samples analyzed by EMSL Analytical, Inc. New York 307 West 38th Street, New York NY NVLAP Lab Code 101048-9, AIHA IHLAP 102581, NYS ELAP 11506, CT PH-0170, MA AA000170

Test Report PLM-7.12.0 Printed: 7/26/2009 4:38:16 PM

THIS IS THE LAST PAGE OF THE REPORT.

830918779	<b>FUSS</b>	& O'NEILL	105	
	Enviro	oScience, LLC 03	0918779	www.fando.com
	50 Redfield Street, Su	uite 100 Boston, MA 02122	(617) 282-	4675 Fax: (617) 282-8253
		SAMPLE LOG FO	R ASBESTOS BULKS	9:50 Sheet <u>l</u> of <u>10</u>
	Project Name:	core Public Schols	Project Nen	10070914.A 4E
	Building: <u><u>lechle</u></u>	s Flementary	Project Mana	ger: Bay May
	Sample ID	Sample Location	Material	Result (%)
	7805H-01A	Miler Room	Hot water Ta	
	-01B			
	-010	L		
	72054-024			v:ler #2
	-on B			iler
	-02 C	F		L l
	720JH -03A		Boiler insulation F.	o:ler
	-03 B		) 12	iler
	-03C			
	720JH-04A	L	vibration isolat	or
	-04 B	Attic	K	
	Analysis Method: 🚺 PLM	Other	Turnaround Time	48 hours
	Based on the turnaround time EnviroScience Laboratory at (6	indicated above, analyses are due to Env. 360) 953-2700 if analyses will be late.		PICE BEIVEN
	Fax Results To: EnviroScient	ce Consultants, Inc. Laboratory at 413-64		JUL 2 3 2609
	Special Instructions:5/2	p Q First posit	ire in each s	et By Sa 0940
	Samples Collected By: Samples [Rec'd] [Sent By]:		7/2-0/29 Time:	Am/Pm
	Samples Received By:		1121 7	:50 Am
	Shipped To: 🔀 EMSL ( Method of Shipment: 🛛 Fee		Other JPS Ground D Other	
			JPS Ground 🔲 Other	
	Y:\Admin\FORMS\Asbestos Bulks (	Chain of Custody-Boston rev 0407.doc		1

<b>FUSS</b>			
Enviro	Science, цс озоч	918779	www.fando.com
50 Redfield Street, Su	ite 100 Boston, MA 02122	the is the provide the end of the second of the second second sector and the test of the second s	75 Fax: (617) 282-8253
	SAMPLE LOG FOR A	ASBESTOS BULKS 24	AM 9: 50
		in the the	HAITAT or T
	ine Public Schools	Project No	0070914. AIE
Building: <u>feet</u> le	s Elementary	Project Manag	er: Bob May
 Sample ID	Sample Location	Material	Result (%)
720JH-05A	Office near from	Pre-torned block pipe insulat:	ype
-05B	j		
-05C		L L	
720 54-06A	storage near Room	AirCell pipe insolution	
-063	Chase rear Room 7 (custod):		
-06 C	stage		
720JH-07A	Storage near Room	mudded F:++	ر کر
-07B	Ļ		
-076	stage		
72054-08A	foom 10	Black Care Das.	د
-08B	Room 8	L	
Analysis Method: 🔽 PLM	f 🗌 Other	Turnaround Time	48 h-
Based on the turnaround tim EnviroScience Laboratory at	e indicated above, analyses are due to Enviro (860) 953-2700 if analyses will be late.	oScience on or before this date:	Please call the
Fax Results To: EnviroScie	ence Consultants, Inc. Laboratory at 413-647	-0018	
Special Instructions:	See lit Page		
Samples Collected By:	~!!	7/20/09 Time:	Ampha
Samples [Rec'd] [Sent By]: Samples Received By:			: 50 Am
Shipped To: DEMSI		Dther	
Method of Shipment:	• • •	PS Ground D Other	
•			
Y:\Admin\FORMS\Asbestos Bull	ss Chain of Custody-Boston rev 0407.doc		

FUSS Envir	o Science, LLC 0 309	18779	www.fando.com		
50 Redfield Street, S	uite 100 Boston, MA 02122	(617) 282-	4675 Fax: (617) 282-8253		
	SAMPLE LOG FOR	ASBESTOS BULKS:	50 Sheet $3 \text{ of } 10$		
	ume Public Schools		2007,0914.A4E		
Building: <u>Peeble</u>	5 Elementerry	the state of the set	ger: Bob My		
Sample ID	Sample Location	Material	Result (%)		
-086	Room 5	L			
720JH-09A	from 10	Black magtre A	1ω		
-09B	Room 8	Black core Bas	e		
-09C	Acom 5				
720JH-10A	Room 4	Vinyl window			
~10B	Room 10				
-10C	· Room 12				
720JH-11 A	Loose in Attic	IXI ceiling T	12		
-116		pin hole			
-112	L				
MroJH-12A	L	Dark Brown might A/W 1×1 ceil:			
Analysis Method: 🖙 PLM	Other				
Based on the turnaround time EnviroScience Laboratory at (	indicated above, analyses are due to EnviroS 860) 953-2700 if analyses will be late.				
	ice Consultants, Inc. Laboratory at 413-647-0	2018			
Samples Collected By:					
Samples [Rec'd] [Sent By]:	<u> </u>	1/20/09 Time:	AM/PM 11 PM 1		
Samples Received By:	Samples [Rec'd] [Sent By]:         Time:          Samples Received By:        Date:        7/24000000000000000000000000000000000000				
Shipped To: 🛛 EMSL ( Method of Shipment: 🔀 Fe		her			
A IC	UPS	Ground Other			
Y:\Admin\FORMS\Asbestos Bulks	Chain of Custody-Boston rev 0407.doc				

		& O'NEILL Science, LLC 03091	8779		www.fando.com
	50 Redfield Street, Su	75	Fax: (617) 282-8253		
		SAMPLE LOG FOR .	ASBESTOS BULKS 09 JUL 24 AM 9: 50	125 (11 & 124) (	Sheet <u>4</u> of <u>(0</u>
	Project Name: <u>Bou</u>	inc Puebre Schools	Project No.	00	70914. A4E
	Building: <u>Peeble</u>	5 elementary	Project Manag	er:4	Bab May
	Sample ID	Sample Location	Material		Result (%)
	-123		1		
	-176	Ļ	L		
	72054-13A	Room 22	Black mastra A/W 9×9 FT		
	-138	main hobby			
	-13C	Ground Flar Hall	L		
	72054-14A	Roon 9	plack martice A/2 12×12 FT	~	
	-14B	Room 12			
	-14C	Breezeway Between Room 10 + 11			
[	72054-15A	Room 1	Blue/grey w/ white streaks	2, XI	2
	-15B	2	1		
	-15C	1 3	L		
	Analysis Method: 🕅 PLM	Other	Turnaround Time	48	hr.
	Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: EnviroScience Laboratory at (860) 953-2700 if analyses will be late.				Please call the
	Fax Results To: EnviroScience Consultants, Inc. Laboratory at 413-647-0018 Special Instructions: <u>Sec</u> 177 Poe C				
		poz c			· · · · · · · · · · · · · · · · · · ·
	Samples Collected By:		7/20/09 Time:	A	n/pm
	Samples [Rec'd] [Sent By]: _	1	[] G t		
	Samples Received By: Shipped To: 🛛 🔀 EMSL		Dther Time:	100	un
	Method of Shipment: A Fo	· · · · · · · · · · · · · · · · · · ·	PS Ground Other		· · · · · · · · · · · · · · · · · · ·
					5
1	Y:\Admin\FORMS\Asbestos Bulk	s Chain of Custody-Boston rev 0407.doc			

	FUSS Enviro	www.fando.com					
	50 Redfield Street, Su	uite 100 Boston, MA 02122	(617) 282-4	1675 Fax: (617) 282-8253			
SAMPLE LOG FOR ASBESTÖS BULKS: 50							
	Project Name:	Sheet <u>5</u> of <u>10</u> 00070914. AIE					
			Project Manag				
	Sample ID	Sample Location	Material	Result (%)			
	720JH-16A	Room 4	White/Yellow/ Pr 12×12 FT	pun			
	-16B		)				
	-16C	L	L				
	72054-17A	Room 1	Tan w/ white streaks 12×12 Fi				
	-17B	2					
	-176	1 3					
	72054-18A	Room 8	whote ~/ Brown Streaks 12×12 F				
	-183						
	-18C	L					
	7205H-19A	Room 4	Red w/ Pink Stree 12×12 FT	iks			
	—19 B	L	V				
	Analysis Method: 🕅 PLM	Other	Turnaround Time	48 Ar			
	Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: Please call the EnviroScience Laboratory at (860) 953-2700 if analyses will be late.						
	Fax Results To: EnviroScien						
	Special Instructions:	Seve 1st page					
	Samples Collected By: Samples [Rec'd][Sent By]: _ Samples Received By:	<u>JU</u> Date: Date: Date:	] Time:[	Am/Pm 11 1 140 an			
	Shipped To: DE EMSL Method of Shipment: DF Fe		Other				
		Chain of Custody-Boston rev 0407.doc	'S Ground D Other				

FUSS Envire	www.fando.com		
50 Redfield Street, St	675 Fax: (617) 282-8253		
		RASBESTOS9BULKS	Sheet <u>6</u> of <u>6</u>
Project Name: <u>Bor</u>	ume Public School	<u>S RECEIVE</u> (Project No	2007 0914. A HE
	ume Public School 5 Elementary	Project Manag	er: Bob My
 Sample ID	Sample Location	Material	Result (%)
-19C	L	L	
7205H-20A	Room 4	Brown w/ LTB + Dark Brown S	rom
-20B		+ Dark Brown 5 12×12 FT	
- 706	L	F	
7205H-21A	Room 9	Grey w/ Brow Streaks 12×12	
-213	10		, ,
-21C	12		
720JH-22A	Breezeway between Reon 10411	- tan w/ Brown Streaks 12×12	=7-
-220	1		
-270	L	L	
72054-23A	Room 12	Tan w/ pink a Drown Streck 12	XI2 FT
Analysis Method: 🔀 PLM	Other	Turnaround Time	
Based on the turnaround time EnviroScience Laboratory at (	e indicated above, analyses are due to Env (860) 953-2700 if analyses will be late.	riroScience on or before this date:	Please call the
Fax Results To: EnviroScient	nce Consultants, Inc. Laboratory at 413-6	47-0018	
Special Instructions: 5	ce 1st page		
	<u> </u>		Am/ph/
Samples Received By:	Date:	24 109 Time: 9	:40an
Shipped To: D EMSL Method of Shipment: D Fo	<b></b>	Other UPS Ground D Other	
•			
Y:\Admin\FORMS\Asbestos Bulks	Chain of Custody-Boston rev 0407.doc		

**p**30918779

Enviro	Science, LLC	5918775	www.fando.com
50 Redfield Street, Sui	te 100 Boston, MA 02122	(617) 282-4	675 Fax: (617) 282-825
	SAMPLE LOG FOR	ASBÊSTOS BULKS50	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
Project Name:	me Public Schools	Project No	Sheet <u>7</u> of <u>10</u> 20070914. <b>#4</b> E
Building: Publes	Elencitary selve	Project Manag	er: hob Mony
Sample ID	Sample Location	Material	Result (%)
-23B			
-23C	Ł		
7205H-24A	Room 11	Tan w/ Brown white streaks	- arb FT
-24B		)	
-24C	L	L	
72054-25A	1	brown w/ Drown white streaks 12	a- -x12=1
-25B			
-25C	F	K	
720JH-26A	Room 9	Tan w/ Brian streaks 12×12	
-26B			
->6C	L	L	
Analysis Method: 🔀 PLM	Other	Turnaround Time	48 hr
Based on the turnaround time EnviroScience Laboratory at ()	indicated above, analyses are due to Envi 360) 953-2700 if analyses will be late.	iroScience on or before this date:	Please call the
	ce Consultants, Inc. Laboratory at 413-64	17-0018	
Special Instructions:	see lest page		
amples Collected By:	JH Date:	7/20109 Time:	Am/pm
Samples [Rec'd] [Sent By]:		] [] Time:[	][]
amples Received By:	Date: 9	24 09 Time: 9	11000

05555075550.201

030918779

8779	1			
	FUS Envir	www.fando.com		
	50 Redfield Street, S	4675 Fax: (617) 282-8253		
		SAMPLE LOG FOR		
		9:50 Sheet <u></u> of <u>10</u>		
	Project Name:	whe Bublic Schools	Project No.	2007 0914.A4E
	Building: Pecble	5 Elentary School		ger: Bob May
	Sample ID	Sample Location	Material	Result (%)
	720 JH- 27A	stair-well near 12	Plaster wall Rough	
	- r7B	Raom 11	1	
	-276	outside boiler Room		
	-27D	Attic		
	-27E	$\downarrow$		
	-27F	Room 10		
	-276	Costodial closet near Room 7		· ·
	720 JH-28A	stairnell near 12	Plaster wall Skim	
	-286	from 11	OK.in	
	-28 C	outside boiler Room		
	- 28 B	attic		
	Analysis Method: PLM	Other	Turnaround Time	46 har
	Based on the turnaround time EnviroScience Laboratory at (			
	Fax Results To: EnviroScier	nce Consultants, Inc. Laboratory at 413-647-0	1	
	Special Instructions:5			
	Samples Collected By:	Am/Am		
		Date: 174	][] Time:_[ 0[ Time:_9].	
	Shipped To: 🛛 EMSL : Method of Shipment: 🗹 Fe	(State) Oth	er	
-	ompinent. [2] Fe	d Ex 🔲 UPS Overnight 🔲 UPS	Ground 🗌 Other	
Y	:\Admin\FORMS\Asbestos Bulks	Chain of Custody-Boston rev 0407.doc		

18779	9					
	FUSS Enviro	& O'NEILL Science, LLC	030918779			www.fando.com
	50 Redfield Street, Su	iite 100 Boston, MA 0	2122	(617) :	282-4 <b>6</b> 75 J	Fax: (617) 282-8253
		SAMPLEL	OG FOR ASBES			and the second
						9 010
	Project Name:	m Aublic	Schuls	Project N	NMA IAN \$8.E[] <b>7@0</b>	70914. KH17
	Building: <u>feeble</u>	m Aublic 2 Elemtery	,			Bob May
	Sample ID	Sample Loca	ation	Material		Result (%)
	-28E	Attre				
	-28F	Room ID				
	- 286	Castodial Cli near from 7				
	720571-29A	from 10	P	laster ce Rough	: (	
	-29B	Room 11				
	-296	Room 12				
	-29D	Room 🔮				
	-29E	Room 2	-			
	-29F	Room 3	>			
	- 29 C	hoom 6				
ł	720JH-30A	Room 10	Pla	ster Ceil skim	·~;	
	Analysis Method: 🔀 PLM	Other		Tumaround Ti	me_44	hors
	Based on the turnaround time EnviroScience Laboratory at (	indicated above, analyses ar 860) 953-2700 if analyses wi	e due to EnviroScience or 11 be late.		I -	Please call the
	Fax Results To: EnviroScier					
	Special Instructions:	tee fst pa	<u>z</u> L			
		TH				
	Samples Collected By: Samples [Rec'd] [Sent By]: _		Date: 7/2010	Time:	-	111
	Samples Received By:	(SV)	Date: 71409		<u>q:40</u> a	<u>~</u>
	Shipped To: 🕅 EMSL Method of Shipment: 🖉 Fe	. ,	Other			
	reality of one philite in the second se	ed Ex 🔲 UPS Overnigi	ht 🔲 UPS Ground	Other		
	Y:\Admin\FORMS\Asbestos Bulks	Chain of Custody-Boston rev 040	07.doc			

----

18779	an an an an Anna Anna Anna Anna Anna A Anna Anna	and a second		
	FUSS Enviro	& O'NEILL ச3அ	18739	www.fando.com
	50 Redfield Street, Su	ite 100 Boston, MA 02122	(617) 282-	.4675 Fax: (617) 282-8253
		SAMPLE LOG FOR		nanganangan kutaré kanantan dinénangangan pana manangan panangan panangan
	D	and the second		Sheet <u>10</u> of <u>10</u>
	Project Name: Dou	rne Public School	Project No.	200 70914-14E
	Building: Peebleg	Elementary School	Project Man	ager: _ Bde May
	Sample ID	Sample Location	Material	Result (%)
	-30B	Room 11	pluster ceili Skim	
	-30c	12	1	
	-30D	1		
	-30E	<u>ک</u>		
	-30F	3		
F	-306			
F			V	
-	· · · · · · · · · · · · · · · · · · ·			
-				
-				
A	nalysis Method: 🔀 PLM	Other	Turnaround Time	48 hrs
B E	ased on the turnaround time i nviroScience Laboratory at (8	Please call the		
	ax Results To: EnviroScience			
Sj	pecial Instructions:			
 				·
	mples Collected By:	AM/PM		
Şa	mples Received By:	1.40 an		
	ipped To: 🔄 EMSL (		)ther	• • • • • • • • • • • • • • • • • • •
171	ethod of Shipment: 📈 Fee	Ex 🗍 UPS Overnight 🗍 UP	S Ground D Other	
Y:\	Admin\FORMS\Asbestos Bulks (			



Attention:	Dustin Diedricksen	Phone:	(617) 778-3750
	Fuss & O'Neill EnviroScience, LLC	Fax:	(888) 838-1160
	146 Hartford Road	Received Date:	11/30/2015 12:27 PM
	Manchester, CT 06040	Analysis Date:	11/30/2015
		Collected Date:	11/30/2015
Project:	20150666.A1E / Peebles Elementary School, 70 Trowbridge Rd,	Bourne, MA	

			Non-Asbe	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
01A-MC-1130	Exterior - Brown Exterior Window	Brown Fibrous	60% Cellulose	40% Non-fibrous (Other)	None Detected
131506942-0001	Frame Paper	Homogeneous			
01B-MC-1130	Exterior - Brown	Brown	60% Cellulose	38% Non-fibrous (Other)	None Detected
	Exterior Window	Fibrous	2% Synthetic		
131506942-0002	Frame Paper	Homogeneous	-		

Analyst(s)

Michael Mink (2)

Alexander Maxinoski, Asbestos Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-107T3, VT AL998919, Maine Bulk Asbestos BA039

Initial Report From: 11/30/2015 17:50:05

PLM - 1.65 Printed: 11/30/2015 5:50 PM

EMSL Customer No. ENVI54

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

FUSS & O'NEILL EnviroScience, LLC

Phone (617) 282-4675 Fax (617) 282-8253

		ample Chain-of-Cust		Sheet <u>1</u> of 1	
	Peebles Elementary School				
Building Name/Numb	Peebles Elementary Scho	pol Project	Manager:	D. Diedricksen	
Site Address:	70 Trowbridge Rd, Bourne, Ma	Total #	t of Samples:	2	
Sample ID (#-Initials-Date)	Material Type (Size, Color, Description, Material)	Sample Locatio	n	Comments/ Quantities	
01A-MC-1130	Brown Exterior Window Frame Paper	Exterior			
01B-MC-1130	Brown Exterior Window Frame Paper	Exterior			
			-		
Analysis Method:	.M			e:6 hr	
Email Results to:	Ddiedricksen @fando.com	Do Not Mail Hard Copy Re	port FAX Rest	ults to: 888-838-1160.	
	o analysis on first positive sample in each homogonit count. If NOB group samples are <b>ALL</b> neg t/a/t. Analyze a <b>MAXIMUM</b> of	gative by PLM, analyze the samp	le denoted with a s		
			DR		
		te:11/30/15	Time:	Cpm I W E	
Shipped To: 🛛 EMSI Method of Shipment: 🗆		Other	- 10 •	10V 30 2015	
			WI By_	UL 12:27	

Page 1 Of 1



# Appendix D

# XRF Lead-Based Paint Screening Field Data Sheets



50 Redfield Street, Suite 100, Boston MA 02122

50 Redfield Street, Suite 100,	(617) 282-4675 Fax (617) 282-8253		
	XRF Lead-Based Paint Screening Field Data Sheet	Page $1$ of $3$	
Inspector:	XRF Model: RMD – LPA-1	Serial:	
Project Name:	Peebles Elementary School Feasibility Study	Date: 10 28 15	
Building Name/Number:	Peebles Elementary School Project Number:	20150666.A1E	
Site Address:7	70 Trowbridge Road, Bourne, Massachusetts Project Manager:	Dustin Diedricksen	

XRF Calibration Check - RMD (0.7 to 1.3 mg/cm<sup>2</sup> inclusive)

	First Reading	Second Reading	Third Reading	Average
Start Check	1.0	1.0	1.0	1.0
Finish Check	1.0	1.0	1.0	1.0

Room	Side	Surface/Component	Color	Substrate*	XRF Reading	Positive
BaseMent Corridor	ABC	Wall	light purple		0,1	
	A	Wall	White		0.2	
	<u>A</u> .	wall	Vellow		0:2	
	A	Wall	purple		0.1	
	A	wall	pinic		-0.2	
	A	Wall	lightbla		-0.1	
	ABED	Ceramic 1111 basebaard	green_	CT_	1,0	
	Floor	9x9 floor tile	Brown		-0,3	
	C	Worlden France	white	<u>u</u>	0.0	
YRM 13	AKD	Wall	white	D	-0,0	
	ALCD	Buschouite	Black	VR	-02	
	A_	C10.5-7 4000	NTOWN	$\omega$	~0.X	
		Li Franke	tan		-0.1	
	ß	Door frame	plue	ül	-0.2	
HBRick	ABOD	BathBorn Wall	apile	Ø	-011	
	-	4 Granuc tile	YALOU	CT	0,0	
UGINS BR	ARD	Wall (upper)	white	ρ	-0.1	
	ABCU	loer wall	Pink	C	-0.1	
	floor	floor	Fine	CT	-0.1	
* Substrate Type: M = Motel W/ = W/	A_	Dat	Brown	hey	00	

\* Substrate Type: M = Metal, W = Wood, P = Plaster, D = Drywall, C = Concrete, B = Brick, CMU = Concrete Masonry Unit, A = Aluminum, CT = Ceramic Tile  $N/\Lambda = Not \Lambda ccessible, N/C = Not Coated, COV = Covered, VR = Vinyl Replacement, POS = Positive$ 



50 Redfield Street, Suite 100, Boston MA 02122

www.fando.com

(617) 282-4675 Fax (617) 282-8253

XRF Lead-Based Paint Screening Field Data Sheet

Page 2 of 3

Project Name: \_\_\_\_\_ Peebles Elementary School Feasibility Study \_\_\_\_ Project Number: \_\_\_\_\_ 20150666.A1E

Room	Side	Surface/Component	Color	Substrate*	XRF Reading	Positive
Elter	<i>6</i> .	Liframe	Blue	M	Oid	
Larm	ALLO	Wall	White	P	-0,1	
	С	Windae Components	Silver	M	~0.(	
	C	Ballards	White	Kt	2.3	
	B	Closed Wall	Blue Streen	p	-0.0	
	AKD	lower wan	Grown	<u>lui</u>	6.1	
	ABCO	Vinyl Basebauki	Bleack	VR	-0.3	
	C	Horning UMH	blean ( Bloc	<u>k1</u>	-0,1	
	Ċ	Camposte SIII	Black		0.0	
	<u> </u>	Door	Breen	W	-0,1	
		Herenne	blue	M	-0.1	
4 BussRoom	AKD	Upper wall	while	P	-011	
/	ABCI)	lower wall	YEllae	CT	-0.2	
	Ceilvry	Gilling	in 14e		-0.1	
Youstochan RM	AKD	Wan	light Brun	1)	+0,1	
	A	poor	Brewn	W	-0.1	
		4 Frame	Bue	M	0.6	
	C	Chuse Door	PINIC	M	0.2	
4 Girls Rocin	AKN	Upper wall	unite	_β	-0.(	
	Aixn	ower wall	Pinte	CT	0.0	
	floor	flour	Pinte	CT	-0.2	
LARCOM 11	AVEC I)	Upperwall	white	<u>p</u>	-0.1	
	C	white ballard	uh#e	M	2.3	
	AXD	Unyl Basebard	Blue	U	-0.5	
GRMIO	AND	Wall	White	f	- 6.0	
4 Storage	Anco	Pipe S	White?	_P	0:0	
· · · ·	B		ulite		OI	
4RM	AVED		white	_ρ	-0.1	
4 afelona	ABCI	lacer Wall	green	CT	0.5	
	AGO	Upper Wall	lehnje	P	-0.6	
$f \text{Substarts Theorem } \mathbf{M} = \mathbf{M} + \mathbf{M} = \mathbf{W} + \mathbf{D}$		Bahards	Yellow	M	2.2	

\* Substrate Type:  $M = Metal, W = Wood, P = Plaster, D = Drywall, C = Concrete, B = Brick, CMU = Concrete Masonry Unit, <math>\Lambda = Aluminum, CT = Ceramic Tile$ N/A = Not Accessible, N/C: = Not Coated, COV = Covered, VR = Vinyl Replacement, POS = Positive



50 Redfield Street, Suite 100, Boston MA 02122

www.fando.com

(617) 282-4675 Fax (617) 282-8253

XRF Lead-Based Paint Screening Field Data Sheet

Page 3 of 3

Project Name: \_\_\_\_\_ Peebles Elementary School Feasibility Study \_\_\_\_\_ Project Number: \_\_\_\_\_

20150666.A1E

Room	Side	Surface/Component	Color	Substrate*	XRF Reading	Positive
Gymnasium	ABCD	UpperWall	Blue	p	0.2	
1		Upper Wall lower wall	Braun	W	0.0	
· · · · · · · · · · · · · · · · · · ·						
			· · · · ·			
		·····	ļ			
			· · · · ·			
• · · · · · · · · · · · · · · · · · · ·						
					-	
· · · · · · · · · · · · · · · · · · ·	-					
· · · · · · · · · · · · · · · · · · ·						

\* Substrate Type: M = Metal, W = Wood, P = Plaster, D = Drywall, C = Concrete, B = Brick, CMU = Concrete Masonry Unit, A = Aluminum, CT = Ceramic Tile N/A = Not Accessible, N/C: = Not Coated, COV = Covered, VR = Vinyl Replacement, POS = Positive